

Report Generated by Test Manager

Title: Branch: 28-hexarotor-UTs-optimWIP
Author: Previous Commit Hash: d733bbe2db570e
b4d626c09eff304f1e9f1d87f8
Date: 26-Oct-2025 11:36:50

Test Environment

Platform: PCWIN64
MATLAB: (R2024a)

Summary - failed test results only

Name	Outcome	Duration (Seconds)
Results: 2025-Oct-26 11:36:30	11 ✓ 1 ✗	18.662
hexarotor	4 ✓ 1 ✗	6.337
Vehicle Tests	4 ✓ 1 ✗	6.337
hexMotorModel	✗	0.278

Results: 2025-Oct-26 11:36:30

Result Type: Result Set
Parent: None
Start Time: 26-Oct-2025 11:36:31
End Time: 26-Oct-2025 11:36:49
Outcome: Total: 12, Passed: 11, Failed: 1

[Back to Report Summary](#)

hexarotor

Test Result Information

Result Type: Test File Result
Parent: [Results: 2025-Oct-26 11:36:30](#)
Start Time: 26-Oct-2025 11:36:31
End Time: 26-Oct-2025 11:36:37
Outcome: Total: 5, Passed: 4, Failed: 1

Test Suite Information

Name: hexarotor

[Back to Report Summary](#)

Vehicle Tests

Test Result Information

Result Type: Test Suite Result
Parent: [hexarotor](#)
Start Time: 26-Oct-2025 11:36:31
End Time: 26-Oct-2025 11:36:37
Outcome: Total: 5, Passed: 4, Failed: 1

Test Suite Information

Name: Vehicle Tests

[Back to Report Summary](#)

hexMotorModel

Test Result Information

Result Type: Test Case Result
Parent: [Vehicle Tests](#)
Start Time: 26-Oct-2025 11:36:36
End Time: 26-Oct-2025 11:36:36
Outcome: Failed
Cause of Failure: Errors running test case

Test Case Information

Name: hexMotorModel
Type: Baseline Test

Simulation

System Under Test Information

Model: hexMotorModel
Harness: hexMotorModelTestHarness
Harness Owner: hexMotorModel
Release: Current
Simulation Mode: Normal
Override SIL or PIL Mode: 0
Start Time: 0
Stop Time: 0

Simulation Error:

Test Sequence block 'hexMotorModelTestHarness/Test Sequence' not found.

[Back to Report Summary](#)

Test Logs:

No baseline criteria evaluation performed as no baseline data is available for this test.

[Back to Report Summary](#)