



$$Q_{CO} = \begin{bmatrix} 1 & 0 & 0 & X_T \\ 0 & 1 & 0 & Y_T \\ 0 & 0 & 1 & 2_T \\ 0 & 0 & 0 & 1 \end{bmatrix} \begin{bmatrix} 0.50 & -3 \text{mil} & 0 & 0 \\ 5 \text{mil} & 0.50 & 0 \\ 0 & 0 & 0 & 1 \end{bmatrix} \begin{bmatrix} -1 & 0 & 0 & 0 \\ 0 & 1 & 0 & 0 \\ 0 & 0 & -1 & 0 \\ 0 & 0 & 0 & 1 \end{bmatrix} \begin{bmatrix} 1 & 0 & 0 & 0 \\ 0 & -1 & 0 & 0 \\ 0 & 0 & -1 & 0 \\ 0 & 0 & 0 & 1 \end{bmatrix}$$