

N/	O MATERIAL					В										
N		1414	- 4		0.150	В	+	0.100	C	+	-	D 530	+	- 0.000	E 1 470	+
60	18% N/S HARD	MM		50 0.200	0.150			0.100	0.910	0.050	0.050	0.530		0.080	1.470	
64.6	00	IN.	0.008 0.1			0.118		0.004	0.036						0.058	
61	18% N/S HARD	MM	0.200 3.1			2.790		0.200	0.810	0.050	0.050	0.530			1.400	
		IN.	0.008 0.1			0.110		0.008		0.002		0.021			0.055	
61	05 18% N/S HARD	MM	0.200 3.0			2.360		0.100		0.050		0.559			1.500	
		IN.	0.008 0.1			0.093		0.004		0.002					0.059	
61	10 18% N/S HARD	MM	0.100 2.8			2.920		0.050		0.100		0.510			1.270	
		IN.	0.004 0.1			0.115		0.004	0.036	0.002						0.030
61	20 18% N/S HARD	MM	0.150 3.0			2.900		0.050	0.500	0.030	0.050	0.600			1.300	
		IN.	0.006 0.1	18 0.006		0.114		0.002	0.020	0.001	0.002	0.024			0.051	
61	30 18% N/S HARD	MM	0.203 2.7	94 0.203		2.692		0.076	0.914	0.076	0.051	0.508	0.051	0.051	0.914	0.051
		IN.	0.008 0.1	10 0.008	0.002	0.106	0.002	0.003	0.036	0.003	0.002	0.020	0.002	0.002	0.036	0.002
61	40 18% N/S HARD	MM	0.150 2.8	00 0.150	0.050	2.700	0.050	0.050	0.950	0.050	0.030	0.600	0.030	0.050	1.000	0.050
	10/01/01////	IN.	0.006 0.1	10 0.006	0.002	0.106	0.002	0.002	0.037	0.002	0.001	0.024	0.001	0.002	0.039	0.002
61	50 18% N/S HARD	MM	0.020 2.7	50 0.100	0.150	2.550	0.050	0.100	0.760	0.050	0.050	0.500	0.050	0.075	1.120	0.075
	10% N/3 HAND	IN.	0.001 0.1	08 0.004	0.006	0.100	0.002	0.004	0.030	0.002	0.002	0.020	0.002	0.003	0.044	0.003
61	55 18% N/S SOFT	MM	0.203 2.8	70 0.203	0.051	2.616	0.051	0.076	0.787	0.076	0.051	0.533	0.051	0.051	1.168	0.051
	10/6 11/3 301 1	IN.	0.008 0.1	13 0.008	0.002	0.103	0.002	0.003	0.031	0.003	0.002	0.021	0.002	0.002	0.046	0.002
61	60 18% N/S SOFT	MM	0.150 2.8	00 0.150	0.050	2.700	0.050	0.050	0.950	0.050	0.020	0.600	0.020	0.020	1.000	0.020
	18% N/S SUFT	IN.	0.006 0.1	10 0.006	0.002	0.106	0.002	0.002	0.037	0.002	0.001	0.024	0.001	0.001	0.039	0.001
61	70	MM	0.250 3.2	80 0.250	0.020	2.500	0.100	0.250	1.220	0.260	0.030	0.600	0.020	0.050	1.100	0.050
	12% N/S HARD	IN.	0.010 0.1	29 0.010	0.001	0.098	0.004	0.010	0.048	0.010	0.001	0.024	0.001	0.002	0.043	0.002
61	80	MM	0.250 2.5	70 0.250	0.240	2.000	0.100	0.250	0.890	0.250	0.030	0.500	0.180	0.050	1.100	0.050
	BRASS	IN.	0.010 0.1	01 0.010	0.009	0.079	0.004	0.010	0.035	0.010	0.001	0.020	0.007	0.002	0.043	0.002
61	90	MM	0.210 2.3	90 0.200	0.050	2.130	0.050	0.080	0.740	0.070	0.050	0.510	0.050	0.050	0.990	0.050
	18% N/S HARD	IN.	0.008 0.0	94 0.008	0.002	0.084	0.002	0.003	0.029	0.003	0.002	0.020	0.002	0.002	0.039	0.002
62	00	MM	0.260 2.5	40 0.280	0.020	2.100	0.100	0.250	1.140	0.260	0.030	0.600	0.020	0.100	0.900	0.050
	12% N/S HARD	IN.	0.010 0.1	00 0.011	0.001	0.083	0.004	0.010	0.045	0.010	0.001	0.024	0.001	0.004	0.035	0.002
62	10	MM	0.250 2.5	40 0.250	0.050	2.000	0.150	0.270	0.860	0.250	0.040	0.500	0.040	0.050	1.100	0.050
	12% N/S SOFT	IN.	0.010 0.1	00 0.010	0.002	0.079	0.006	0.011	0.034	0.010	0.002	0.020	0.002	0.002	0.043	0.002
62	20	MM	0.250 2.4	00 0.250	0.020	2.000	0.100	0.250	0.960	0.250	0.040	0.500	0.040	0.050	1.100	0.050
	12% N/S HARD	IN.	0.010 0.0	94 0.010	0.001	0.079	0.004	0.010	0.038	0.010	0.002	0.020	0.002	0.002	0.043	0.002
62	30	MM	0.260 2.4	80 0.240	0.010	2.000	0.100	0.100	0.900	0.100	0.060	0.500	0.020	0.050	1.100	0.070
	18% N/S HARD	IN.	0.010 0.0	98 0.009	0.000	0.079	0.004	0.004	0.035	0.004	0.002	0.020	0.001	0.002	0.043	0.003
62	40	MM	0.203 2.3	88 0.203	0.051	2.032	0.051	0.076	0.787	0.076	0.051	0.483	0.051	0.051	0.940	0.051
·	18% N/S HARD	IN.	0.008 0.0	94 0.008	0.002	0.080	0.002	0.003	0.031	0.003	0.002	0.019	0.002	0.002	0.037	0.002
62	50	MM	0.203 2.4	13 0.203	0.051	1.905	0.051	0.076	0.914	0.076	0.051	0.508	0.051		0.762	
	18% N/S HARD	IN.	0.008 0.0	95 0.008	0.002	0.075	0.002	0.003	0.036	0.003	0.002	0.020	0.002	0.002	0.030	0.002
62	60	MM	0.150 2.8	00 0.150	0.100	2.000	0.100	0.050	0.950	0.050	0.050	0.600	0.050	0.030	1.000	0.030
	18% N/S HARD	IN.	0.006 0.1		0.004	0.079	0.004	0.002	0.037	0.002		0.024		ł		0.001
62	65	MM	0.150 2.8	00 0.150		2.000		0.050	0.950	0.050		0.600				0.030
	18% N/S SOFT	IN.	0.006 0.1			0.079		0.002		0.002	1	0.024				0.001
62	70	MM	0.203 2.5			1.905		0.076		0.076		0.508				0.051
	18% N/S HARD	IN.	0.008 0.1			0.075		0.003		0.003		0.020				0.002
62	90	MM	0.203 2.3			1.981		0.076		0.076		0.508				0.051
02	18% N/S HARD	IN.	0.008 0.0			0.078		0.003		0.003	1	0.020		ł		0.002
63	00	MM	0.250 1.9		1	1.600		0.250		0.250		0.600				0.060
	12% N/S HARD	IN.	0.010 0.0			0.063		0.010		0.010		0.024				0.002
63	10	MM	0.203 2.3		1	1.346		0.076		0.016		0.559				0.051
	18% N/S HARD	IN.	0.008 0.0			0.053		0.003		0.003	1	0.022		i		0.002
63	20	MM	0.203 2.1			1.194		0.076		0.076		0.533				0.051
	18% N/S HARD	IN.	0.008 0.0			0.047		0.003		0.003		0.021		ł		0.002
63	30	MM	0.203 2.3			1.092		0.003		0.003		0.508				0.002
03	18% N/S HARD	IN.	0.203 2.3			0.043		0.003		0.076	1	0.020				0.001
		IIV.	0.000 0.0	J-7 U.UUO	0.002	0.043	0.002	1 0.003	0.031	0.003	1 0.002	0.020	0.002	0.002	0.031	0.002

