Syndicate Fire Protection Service Ltd
1 Manston Rd
Ramsgate,
Kent,
CT11 0RB
01843 265389
info@syndicatefireprotection.co.uk
Job # 1782
PO#

FIRE EXTINGUISHER INSPECTION & SERVICE CERTIFICATE

Date of service	02/03/2026	Arrival Time		Departed Time	
Site Address	West End Rd Ruislip Middlesex HA4 6JB				

Logbook:

Product	Total No. Serviced	Total No. Condemned	No. Extended Service Due	No. of units Replaced
Water 3L	2			
Water 6L	3	1		
Water 9L				
Foam 2L				
Foam 3L				
Foam 6L	2	1		
Foam 9L				
CO2 2KG	3			
CO2 5KG				
DP 1KG				
DP 2KG	1	1		
DP 4KG				
DP 6KG				
DP 9KG				
Wet Chem 3L				
Wet Chem 6L	1			
Fire Blanket	3			
Fire Bucket				
Total	15	3		

Extinguisher Checks	Qty
Tamper Seals Replaced	12
"O" Rings Replaced	12
Date Sticker Replaced	10

Routine service visit

Carried out the annual extinguisher checks successfully

Failed Units

Outside linen store 6ltr water has been used

Foam 6ltr and 2kg powder inside boiler room failed. They have been used.

Failed 3 in total


Extinguishers on site do not match the signage and should be re designed to suit

FPA Fire Protection Association Member 2020
The UK Fire Association
FIRE ALARMS
ACCESS CONTROL
EMERGENCY LIGHTS
FIRE EXTINGUISHERS
HD CCTV
Constructionline

Syndicate Fire Protection Service Ltd
1 Manston Rd
Ramsgate,
Kent,
CT11 0RB
01843 265389
info@syndicatefireprotection.co.uk
Job # 1782
PO#

5 x co2 extinguishers and signs
2 x water extinguisher and signs

Apart from Non-conforming extinguishers as recorded, all portable fire extinguishers have been inspected and serviced in accordance with BS 5306-3:2009

Engineers Name	Engineers Signature	Customer Name	Customer Signature
Terry Owen			

Fire Protection Association Member 2020
The UK Fire Association
FIRE ALARMS
ACCESS CONTROL
EMERGENCY LIGHTS
FIRE EXTINGUISHERS
HD CCTV
Constructionline