Oryx DataSafe
Pharmaceutical Compliance & Data Security

Oryx Calibration

Calibration workflow management software

Every calibration step, backed by clear records

Field records, review and approval, certificates and customer access



From field records
to digital certificates

Record · Review and approve · Issue and access

Design considerations: 21 CFR Part 11 · ALCOA++

01 INTRODUCTION

Connect every calibration record

Manage equipment, schedules, field measurements, and results in one job.
Help calibration providers and in-house teams see what comes next.



Field records

Measurements and photo evidence



Review & approval

Checks by assigned role



Certificate access

Issued originals and customer access

Designed for your team

Service providers

Connect customer equipment intake and assignment through to certificate release.

In-house teams

Manage calibration schedules, work records, and outsourced results for your equipment.

Find the records you need, with measurement results and workflow status tracked separately.

Calibration management software by Oryx DataSafe

02 WORKFLOW

From intake to customer access

Carry each stage's records into the next.
Manage submission, approval and issuance, and customer release as separate steps.



01 Intake & scheduling

Check equipment and due dates, then assign schedules and staff.



02 Field records

Record measurements, environmental conditions, and supporting references for each calibration type.



03 E-sign & submit

The operator checks the record, verifies their identity, and formally submits it.



04 Review & issue

An approver other than the operator reviews the record and issues the certificate.



05 Release & access

After recipient and access checks, customers can view released certificates and print copies marked COPY.

An issued certificate remains unavailable to customers until it is released for customer access.

03 FEATURES FIELD RECORDS

Field entry for each calibration type

Capture field records in a tablet or mobile web browser.
Link measurements and photo evidence to the same job.

General calibration

Reference and measured values
and errors at each test point

Balance calibration

Raw values and assessment basis
for repeatability, sensitivity, and more

Recorder calibration

Test points by channel
and as-found / as-left readings

Online photo OCR

Server-based OCR reads photos of digital displays while online. Only operator-confirmed values are entered, and original photos are retained.

Offline fieldwork

Use prepared job data to store photos and manually entered values on the device. Upload them when connected, then continue review and formal submission.

OCR is not applied to offline photos. Camera recognition performance and extended offline operation must be checked in the intended deployment environment.

04 FEATURES STANDARDS & CERTIFICATES

From measurement basis to customer results

Preserve the reference standards, SOPs, and templates used.
Deliver certificates with agreed customer formats and controlled access.

Reference standards

Calibration cycle and expiry

SOPs

Version in force on the measurement date

Templates

Revision and effective period

Preserved context

Keep the reference standard's calibration cycle and applicable SOP details available, even when master data changes.

Your formats

Review your certificate fields and requirements to agree on the output format. Previously issued PDF originals are retained.

Controlled customer access

Issued original → **Customer release** → **View & COPY**

Preserve the results document

Check recipients and access

Provide clearly marked copies

05 APPROVAL & AUDIT

Keep a record of who checked what

Identity-verified electronic signatures and role-based access help trace record submission, approval, and subsequent actions.



Operator check

Review values and references



E-sign & submit

Lock records after submission



Separate approval

Independent review and issuance

Distinct roles

Separate the calibration signer's responsibility from the approver's. Drafts and formally submitted records also have distinct statuses.

Audit trail & PDF

View who acted, when, and why a change was made, and export the audit history to PDF. Review issued originals alongside records of subsequent actions.

Review both what a record contains and how it was handled.

21 CFR Part 11 and ALCOA++ are design considerations. Assess suitability with supported features, settings, intended use, customer procedures, training and validation. Regulatory references and the logo do not mean external certification, full compliance or guaranteed security performance.

06 GET IN TOUCH

See how it fits your calibration work

Start with representative equipment and the forms you use today.
Explore field entry, review, issuance, and customer access.



Equipment scope

Choose the initial equipment groups and the scope of in-house and outsourced calibration.



Forms & roles

Review your certificate formats and the roles of operators, approvers, and customers.



Field setup

Check devices, connectivity constraints, and operating arrangements to agree on the rollout scope.

Oryx DataSafe

Calibration management software

Talk to us · Representative

Seung-cheol Hong

+82 10-6545-0415

schong@oryxsystem.co.kr

oryxdatasafe.com

Device compatibility, camera OCR, extended offline operation, and calibration label printing must be checked separately in the intended deployment environment.