SNextTypeSRsrc Return information about sResources of a specified type.

#include <<u>Slots.h</u>> <u>Slot Manager</u>

OSErr SNextTypeSRsrc(spBlkPtr);

<u>SpBlockPtr</u> spBlkPtr; address of 56-byte <u>Slot Parameter Block</u>

structure

returns Error Code; 0=no error

SNextTypeSRsrc behaves the same as **SNextSRsrc** except that it returns information only about sResources of the specified type.

spBlkPtr is the address of a 56-byte **Slot Parameter Block** structure. The relevant fields are as follows:

Out-In Name		<u>Type</u>	Size Offset		<u>Description</u>
\leftarrow	spsPointer	<u>Ptr</u>	4	4	Structure pointer
\leftarrow	spIOReserved short		2	36	Reserved field of Slot Resource Table
\leftarrow	spRefNum	<u>short</u>	2	38	Slot Resource Table reference number
\leftrightarrow	spCategory	<u>short</u>	2	40	sResource type: Category
\leftrightarrow	spCType	<u>short</u>	2	42	sResource type: Type
\leftrightarrow	spDrvrSW	<u>short</u>	2	44	sResource type: Driver software identifier
\leftrightarrow	spDrvrHW	<u>short</u>	2	46	sResource type: Driver hardware identifier
\rightarrow	spTBMask	<u>char</u>	1	48	Type bit mask (bits 03 mask words 03)
\leftrightarrow	spSlot	<u>char</u>	1	49	Slot number
\leftrightarrow	spID	<u>char</u>	1	50	sResource list ID
\leftrightarrow	spExtDev	<u>char</u>	1	51	External device identifier
\leftrightarrow	spHwDev	<u>char</u>	1	52	Hardware device identifier

Returns: an operating system Error Code. It will be one of:

```
noErr (0)
                           No error
   smEmptySlot (-300)
                           No card in slot.
      smCRCFail (-301)
                           CRC check failed.
   smFormatErr (-302)
                           FHeader format is not Apple's
  smRevisionErr (-303)
                           The revision of the card's declaration ROM is wrong.
        smNoDir (-304)
                           Directory offset is NIL
smNosInfoArray (-306)
                           The SDM could not allocate memory for the sInfo
                           array.
    smResrvErr (-307)
                           A reserved field of the declaration ROM was used.
  smUnExBusErr (-308)
                          An unexpected bus error occurred.
   smBLFieldBad (-309)
                           A valid ByteLanes field was not found.
 smDisposePErr (-312)
                           An error occurred during execution of DisposPointer.
smNoBoardSRsrc (-313)
                           There is no board sResource.
    smGetPRErr (-314)
                           Error during execution of sGetPRAMRec.
   smNoBoardId (-315)
                           There is no board ID.
 smInitStatVErr (-316)
                           The InitStatus_V field was negative after Primary or
                           Secondary Init.
  smInitTblVErr (-317)
                           Error while trying to initialize the sResource Table.
    smNoJmpTbl (-318)
                           Slot Manager jump table could not be created
  smBadBoardId (-319)
                           Board ID was wrong; reinit the PRAM record
```

Notes: Given an sResource type (category, cType, software, and hardware) and spTBMask, and starting from a given slot number, spSlot, and sResource list identification number, spID, the trap macro **SNextTypeSRsrc** returns the slot number, spSlot, sResource list identification number, spID, and Slot Resource Table ioReserved field (spIOReserved) for the next sResource of that type, as masked. If there are no more sResources of that type, SNextTypeSRsrc returns a nonfatal error report, which can be one of the following:

smBadRefId	(-330)	Reference ID was not found in the given sResource list.
smBadsList	(-331)	The IDs in the sResource list are not in ascending order.
smReservedErr	(-332)	A reserved field was not zero.
smCodeRevErr	(-333)	Wrong revision of the code to be executed by sExec.
smCPUErr	(-334)	The CPU field of the code was wrong.
smsPointerNil	(-335)	LPointer is nil From sOffsetData. If this error occurs; check sInfo rec for more information.
smNilsBlockErr	(-336)	
	` ,	The physical block size (of an sBlock) was zero.
smSlotOOBErr	(-337)	The given slot was out of bounds (or does not exist).
smSelOOBErr	(-338)	Selector out of bounds error
smNewPErr	(-339)	An error occurred during execution of NewPointer.
smCkStatusErr	(-341)	Status of slot is bad (InitStatus_A,V).
smGetDrvrNamErr	(-342)	An error occurred during execution of
		sGetDrvrName.
smNoMoresRsrcs	(-344)	No more sResources.
smsGetDrvrErr	(-345)	An error occurred during execution of sGetDrvr.
smBadsPtrErr	(-346)	A bad sPointer was presented to sCalcsPointer.
smByteLanesErr	(-347)	NumByteLanes was determined to be zero.
smŚRTOvrFIErr	(-350)	Slot Resource Table overflow.
smRecNotFnd	(-351)	Record not found in the Slot Resource Table.
on too toti na	(00 1)	reservation and the clot resource rable.

The <u>spTBMask</u> field lets you mask off specific fields of the sResource type that you do not care about, by setting any of bits 0-3. Bit 3 masks off the <u>spCategory</u> field; bit 2 the <u>spCType</u> field; bit 1 the <u>spDrvrSW</u> field; and bit 0 the <u>spDrvrHW</u> field.