

Workshop Process · Steps 4 to 6


OVERVIEW


Notification to the floor, technical inspection, estimation, review, customer approval



Full diagram. The 6 pages that follow show it at readable size.


Notification - request raised
STEP 4 · The floor picks it up
Supervisor
Foreman
Team Leader
Technical Inspection
Inspection report · the faults found
1. AC Compressor


2. Shock absorber
3. Brake pad
STEP 5 · Estimation, one line per job
Parts After Market - priced by the Storekeeper
Parts Genuine - priced by the Storekeeper
Labour - priced by the Service Advisor
Is that part type available?
No
Mark the line N/A
Yes



Per job: Total Genuine and Total After Market


Example - Job 1: Labour 100 plus Genuine 500 equals 600, Labour 100 plus After Market 300 equals 400


Review before it leaves the workshop

- Format 1
- Format 2
- Format 3

Workshop Process · Steps 4 to 6

Notification to the floor, technical inspection, estimation, review, customer approval




STEP 6 -
Customer decision
Reject all
Partial approval - approved lines only
Approve all
Job card opens
Main job card
Sub job card, if needed
Email the customer: we regret, and ask for the reason
Closed - no work carried out
Notify Supervisor, Foreman and Team Leader
Team Leader assigns the job to a technician

Workshop Process · Steps 4 to 6

Notification to the floor, technical inspection, estimation, review, customer approval

