

PROBLEM 15.22 Working drawing (in.)


Assembly Name: Table Vise

SPECIFIC INSTRUCTIONS: Prepare a complete set of working drawings with one detail drawing per sheet and the assembly and parts list on another sheet. When preparing the assembly drawing, use separate balloons for each part




in each view or use only one balloon in the view that most clearly identifies the part. This is an engineering prototype project. Errors are likely in this problem. Verify dimensions during assembly. Establish tolerances between mating parts.

PARTS LIST



KEY	QTY	DESCRIPTION	KEY	QTY	DESCRIPTION
1	2	CLAMP JAWS	9	1	1/4-28UNF NYLOCK NUT
2	1	1/4 -28UNF X 2" LG HEX HD MACH. SCREW	10	2	3/8 FLAT WASHER
3	1	PIVOT	11	2	ADJUSTING ROD
4	2	SCREW ADJUSTER	12	2	ADJUSTING ROD HANDLE
5	2	1/4-28UNF X 1" LG STANDARD SLOT FLAT COUNTERSUNK HD CAP SCREW	13	2	ADJUSTING HANDLE KNOB
6	1	TABLE	14	2	8-32UNC X 5/8" LG SLOTTED ROUND HD. MACHINE SCREW
7	1	BASE	15	2	1/8 SPRING PIN
8	1	LOCKING HANDLE	16	2	1/4-28UNF X 1" LG STANDARD SLOT PAN HEAD MACHINE SCREW



PROBLEM 15.22 (Continued)





SECTION A-A
③ PIVOT




VIEW A
④ SCREW ADJUSTER


PROBLEM 15.22 (Continued)




PROBLEM 15.22 (Continued)





⑧ LOCKING HANDLE



⑪ ADJUSTING ROD



⑫ ADJUSTING ROD HANDLE



⑬ ADJUSTING HANDLE KNOB