

Artifact template

A09 – SCADA

ID	A09 – SCADA
Category	Traffic analysis
Difficulty	Easy
Description	
(This text could be	
shared with the	
participants if	
necessary)	
Additional material	Traffic capture
Technical	None
requirements/	
others	
Preparation	
	Participants will be tasked with investigating why some wind turbines have stopped working. At the moment, the only clue available is a traffic capture from Schneider Electrics SR3 B261BD SCADA systems.
Resolution	Analyzing the file, it can be easily observed that the system's usual behavior consists of the exchange of 04: Input Registers (FC=04) messages, which read the values of certain registers. At a given moment, it is observed that a multitude of consecutive messages of type 05: Single Coil (FC=05) are sent, with the aim of opening or closing a valve.