IC Design Lab Hw5 Report

學號:B08502141 姓名:石旻翰 系級:電機三

1 LVS/DRC Result

```
REPORT FILE NAME:
LAYOUT NAME:
SOURCE NAME:
RULE FILE:
RULE FILE:
HCELL FILE:
               cvs_test.rep
svdb/CHIP.sp ('CHIP')
CHIP.spi ('CHIP')
G-DF-MIXED_MODE_RFCMOS18-1.8V_3.3V-1P6M-MMC_CALIBRE-LVS-2.1-P8.txt
LVS of UMC 0.18um 1.8V/3.3V 1P6M MMC Mixed Mode/RFCMOS Process
(-automatch)
Mon_Mar_21_21_25_40_2328
HCELL FILE:
CREATION TIME:
CURRENT DIRECTORY:
USER NAME:
CALIBRE VERSION:
               Mon Mar 21 21:25:48 2022
/home/raid7_2/userb08/b8502141/Lab5_LVS
               v2021.1_33.19 Mon Mar 1 16:10:01 PST 2021
                  OVERALL COMPARISON RESULTS
                    CORRECT
                    RULECHECK 4.1M ...... TOTAL Result Count = 1
RULECHECK 4.29NOTICE .....
RULECHECK 4.31A.8KA ......NOT EXECUTED
RULECHECK 4.31B.a.8KA ......NOT
RULECHECK 4.31B.b.8KA ......NOT EXECUTED
RULECHECK 4.31C.a_d.8KA ......NOT
RULECHECK 4.31C.b_c_e.8KA ..... NOT EXECUTED
RULECHECK 4.31D.8KA ......NOT
RULECHECK 4.31A.12KA ......NOT EXECUTED
RULECHECK 4.31B.a.12KA ......NOT
RULECHECK 4.31B.b.12KA ......NOT EXECUTED
RULECHECK 4.31C.12KA .....
                                      NOT EXECUTED
RULECHECK 4.31D.12KA .....
                                      NOT EXECUTED
RULECHECK 4.20F .....
                                      TOTAL Result Count =
                                      TOTAL Result Count =
RULECHECK 4.22F .....
                                      TOTAL Result Count =
RULECHECK 4.22G .....
                                      TOTAL Result Count =
RULECHECK 4.24F .....
                                      TOTAL Result Count =
RULECHECK 4.24G .....
                                      TOTAL Result Count =
RULECHECK 4.26F .....
                                      TOTAL Result Count
RULECHECK 4.26G .....
                                      TOTAL Result Count =
RULECHECK 4.28F .....
                                      TOTAL Result Count
RULECHECK 4.28G .....
                                      TOTAL Result Count =
RULECHECK 4.31E .....
                                      TOTAL Result Count =
RULECHECK 4.31F .....
                                      TOTAL Result Count = 1
RULECHECK 4.28C .....
                                      TOTAL Result Count =
RULECHECK 6Ab.ME1 ..... NOT EXECUTED
RULECHECK 6Ba.ME1 ......NOT EXECUTED
RULECHECK 6Bb.ME1 ......NOT EXECUTED
RULECHECK 6Aa.ME2 ......NOT EXECUTED
RULECHECK 6Ab.ME2 ......NOT
RULECHECK 6Ba.ME2 ..... NOT
RULECHECK 6Aa.ME3 ......NOT EXECUTED
```

2 Discussion

I have no problem in LVS. Yet, I saw some errors in my drc.rep, but I find that those errors were acceptable, by checking those errors on the website that TA has provided.