

ORIGINAL NAME

LINE -7045BBR01T167

AREA: Barreirinhas

CLIENT: Exploration Services/TGS Nopec

NEW NAME

LINE: 0258-5045

AREA: 0258-2D_SPEC_BM_BAR

CLIENT: TGS-Nopec.



ACQUISITION REPORT Sequence-0167



Survey:

Exploration Services Client Para-Maranhao Area GECO_TAU Vessel 7443B **JobNumber**

Survey Type

Sequence:

7045BBR1T167 Linename 7045BBR **Preplot**

6.0° Direction

00:04:19utc 27-Mar-2001 **SOL Date** 07:59:36utc 27-Mar-2001

2D

EOL Date

Attributes:

Wind Force 15.0 [knots] Dir E Swell Height 1.5 [meters] \$(swell_dir)

Propellor rpm [avg] Propellor pitch 45 [avg]

SOL EOL

22.0 3633.0 Waterdepth [meters] Bottomspeed 5.7 5.5 [knots] port -22.1 [deg] Featherangle 0.0 Cable noise 79.7 11.37 [µBar rms]

Lowcut filter 3 3 [hz] Filter slope 18 18 [dB] 10.5 7

Streamer

Depth

Production

_				
Γ		Shotpoint	File	Time [utc]
	SOL Noise Record(s)		2800 - 2801	
	SOL Dummy Record(s)	2803 - 2811	2803 - 2811	00:02:21 - 00:04:06
	FSP Start of Line	2812	2812	00:04:19
	MSP			
	LSP End of Line	4880	4880	07:59:36
	EOL Dummy Record(s)	4881 - 4890	4881 - 4890	07:59:49 - 08:01:47
	EOL Noise Record(s)		4891 - 4892	
	Line-seaments:			

<u>.iiic-segiiieiits</u>

SPs 2812 - 2869	Files 2812 -	Times [utc] 00:04:19-	Type Prime	# CMPs 0		Remarks dcable still bent
2870 - 4880	2870 - 4880	00:16:48-07:59:36	Prime	1	Valid	First good SP 2870 @ 00:16

Remarks:

Navigation

Cable bent at SOL noise test and at SOL, FGSP 2870 with first Recording QC 160 traces good.

Tape-list

		Stream 2		
Shot(s)	Files	DeckReel	Remark	
2800 - 4674	2800 - 4674	1 301		
4675 - 4892	4675 - 4892	2 302		
		Stream 4		
Shot(s)	Files	DeckReel	Remark	
2800 - 4674	2800 - 4674	3 1305		
4675 - 4892	4675 - 4892	4 1306		
		Stream 1001		
Shot(s)	Files	DeckReel	Remark	
1003 - 4891	1003 - 4891	1001 2		

Seismic Data Annotations

	NTBP					
Shot(s)	File(s)	Trace(s)	Туре	Remark		
2860	2860	ALL	Gun timing error	Gun 4-1 error (ms) : 2.10		
2869		ALL	Missing File	File not recorded by recording system		
3039	3039	ALL	Gun timing error	Gun 4-1 error (ms) : 2.20		
3101	3101	ALL	Gun timing error	Gun 4-1 error (ms) : 2.50		
3166	3166	ALL	Gun timing error	Gun 4-1 error (ms) : 2.40		
3285	3285	ALL	Gun timing error	Gun 4-1 error (ms) : 2.10		
3484	3484	ALL	Gun timing error	Gun 4-1 error (ms) : 2.10		
3695	3695	ALL	Gun timing error	Gun 2-1 error (ms) : 2.10		
3720	3720	ALL	Gun timing error	Gun 4-1 error (ms) : 2.90		
3732	3732	ALL	Gun timing error	Gun 4-1 error (ms) : 2.20		
3979	3979	ALL	Gun timing error	Gun 4-1 error (ms) : 2.60		
4018	4018	ALL	Gun timing error	Gun 4-1 error (ms) : 2.30		
4312	4312	ALL	Gun timing error	Gun 4-1 error (ms) : 2.20		
4313	4313	ALL	Gun timing error	Gun 4-1 error (ms) : 2.20		
4446	4446	ALL	Gun timing error	Gun 4-1 error (ms) : 3.20		
4647	4647	ALL	Gun timing error	Gun 4-1 error (ms) : 2.10		

Warning

vvarning						
Shot(s)	File(s)	Trace(s)	Type	Remark		
2800-4892		73, 118, 193	Weak traces	6.0dB down		
2825	2825	ALL	Gun timing error	Gun 4-1 error (ms) : 2.00		
2830	2830	ALL	Cable depth	set from 7m to 9m depth		
2844	2844	ALL	Gun timing error	Gun 4-1 error (ms) : 1.70		
2870	2870	ALL	First SP	First good Sp, traces 1-160 straight		
2884	2884	ALL	Gun timing error	Gun 6-2 error (ms) : -1.70		
2918	2918	ALL	Gun timing error	Gun 4-1 error (ms) : 1.80		
2922	2922	ALL	Gun timing error	Gun 2-2 error (ms) : -1.60		
2930	2930	ALL	Gun timing error	Gun 4-1 error (ms) : 2.00		
2937	2937	ALL	Gun timing error	Gun 4-1 error (ms) : 2.00		
2945	2945	ALL	Cable straight	All traces with swellnoise only		
2950	2950	ALL	Swell noise	affecting approx 5-10% of traces, 8 µBar		
				avg. , 50-100 µBar peak		
2980	2980	ALL	Gun timing error	Gun 2-1 error (ms) : 1.70		
3001	3001	ALL	Gun timing error	Gun 2-2 error (ms) : -1.60		
3002	3002	ALL	Gun timing error	Gun 1-2 error (ms) : -1.70		
3009	3009	ALL	Gun timing error	Gun 1-2 error (ms) : -1.70		
3047	3047	ALL	Gun timing error	Gun 4-1 error (ms) : 1.90		
3141	3141	ALL	Gun timing error	Gun 4-1 error (ms) : 1.60		
3209	3209	ALL	Gun timing error	Gun 3-1 error (ms) : 1.60		
3212	3212	ALL	Gun timing error	Gun 4-1 error (ms) : 2.00		
3216	3216	ALL	Gun timing error	Gun 4-1 error (ms) : 1.80		
3233	3233	ALL	Gun timing error	Gun 2-2 error (ms) : -2.00		
3267	3267	ALL	Gun timing error	Gun 6-2 error (ms) : -1.90		

Gun timing error

Gun timing error

Gun 3-1 error (ms): -1.60

Gun 2-1 error (ms): 1.70

4340

4358

4340

4358

ALL

TIM Line Acqu	isition Report			
4404	4404	ALL	Gun timing error	Gun 2-2 error (ms) : -2.00
4474	4474	ALL	Gun timing error	Gun 2-1 error (ms) : 1.80
4482	4482	ALL	Gun timing error	Gun 2-2 error (ms) : -1.70
4578	4578	ALL	Gun timing error	Gun 2-1 error (ms) : 1.90
4587	4587	ALL	Gun timing error	Gun 4-1 error (ms) : 2.00
4605	4605	ALL	Gun timing error	Gun 2-1 error (ms) : 2.00
4676	4676	ALL	Gun timing error	Gun 4-1 error (ms) : 1.60
4689	4689	ALL	Gun timing error	Gun 4-1 error (ms) : 1.80
4707	4707	ALL	Gun timing error	Gun 2-2 error (ms) : -1.60
4759	4759	ALL	Gun timing error	Gun 2-1 error (ms) : 1.60
			Comment	
Shot(s)	File(s)	Trace(s)	Type	Remark
2812-4881	2812-488	1ALL `´	Gun disabled	Spare guns, Source volume at shot 2812: 7918 cu.in.

List of used abbreviations:		
SOL/EOL FSP/LSP FIRST/Last shotpoint of the line. FCSP/LCSP FIRST/Last chargeable shotpoint MSP Midnight (last) shotpoint of the day FGSP/LGSP FIRST/Last Good Shotpoint FOSP/LOSP FIRST/Last Overlap Shotpoint FSP/LSP R/O FIRST/Last Shotpoint Runout	Deg rev utc SPs CMPs NTBP SI	Degrees: e[0,360] Revolutions Universal Time Coordinated Shotpoints Common midpoints Not to be processed Seismic interference

TRILOGY INFORMATION MANAGER - ACQUISITION REPORT - GENERATED 08:07:42utc 27-Mar-2001