

ORIGINAL NAME

LINE -6939BBR1T113

AREA: Barreirinhas

CLIENT: Exploration Services/TGS Nopec

NEW NAME

LINE: 0258-5939

AREA: 0258-2D_SPEC_BM_BAR

CLIENT: TGS-Nopec.



ACQUISITION REPORT Sequence-0113



Survey:

Exploration Services Client Para-Maranhao Area GECO_TAU Vessel 7443B **JobNumber**

2D

Survey Type

Sequence: 6939BBR1T113 Linename

6939BBR **Preplot** 32.0° Direction

03:58:11utc 02-Mar-2001 **SOL Date** 09:31:19utc 02-Mar-2001

EOL Date

Attributes:

Wind Force 10.0 Dir SE [knots] Swell Height 2.0 [meters] Dir SE Propellor rpm 161 [avg]

Propellor pitch 56 [avg]

> **EOL** SOL

907.0 3275.0 Waterdepth [meters] Bottomspeed 5.14 4.5 [knots] Featherangle sb +0.4 port -18.8 [deg] Cable noise 47.99 11.04 [µBar rms]

Lowcut filter 3 3 [hz] Filter slope 18 18 [dB]

Streamer 9.0 10.5

Depth

Production

_				
		Shotpoint	File	Time [utc]
	SOL Noise Record(s)		2988 - 2989	
	SOL Dummy Record(s)	2990 - 3064	2990 - 3064	03:41:45 - 03:57:57
	FSP Start of Line	3065	3065	03:58:11
	MSP			
	LSP End of Line	4386	4386	09:31:19
	EOL Dummy Record(s)	4387 - 4396	4387 - 4396	09:31:35 - 09:33:59
	EOL Noise Record(s)		4397 - 4398	
	· · ·			

Line-segments:

Files Times [utc] Type # CMPs Status Remarks 3065 - 4386 3065 - 4386 03:58:11-09:31:19 Prime Valid

3000-3064 NTBP due to

turn noise

Remarks:

Navigation

Turn noise on streamer at SOL. Swell noise affecting <5 % of Recording QC

traces. Channel 70 occasionally spiking.

Tape-list

		Stream 2		
Shot(s)	Files	DeckReel	Remark	
2988 - 4398	2988 - 4398	1 199		
		Stream 4		
Shot(s)	Files	DeckReel	Remark	
2988 - 3060	2988 - 3060	3 1202		
3061 - 4398	3061 - 4398	4 1203		
		Stream 1001		
Shot(s)	Files	DeckReel	Remark	
1821 - 4398	1821 - 4398	1001 4		

Seismic Data Annotations

N	ľ	Г	R	P
			_	

Shot(s)	File(s)	Trace(s)	Туре	Remark
ALL	ALL-	2	Killed traces	
ALL	ALL-	136	Killed traces	unsummed trace# 271, 6.0dB down
ALL	ALL-	197	Killed traces	unsummed trace# 393, 6.0dB down
3249	3249	ALL	Gun timing error	Gun 3-1 error (ms) : 2.20
3444	3444	ALL	Gun timing error	Gun 3-1 error (ms) : 2.30
3461	3461	ALL	Gun timing error	Gun 3-1 error (ms) : 2.40
3471	3471	ALL	Gun timing error	Gun 3-1 error (ms) : 2.80
3479	3479	ALL	Gun timing error	Gun 3-1 error (ms) : 2.50
3489	3489	ALL	Gun timing error	Gun 3-1 error (ms) : 2.30
3491	3491	ALL	Gun timing error	Gun 3-1 error (ms) : 2.80
3564	3564	ALL	Gun timing error	Gun 3-1 error (ms) : 2.10
3566	3566	ALL	Gun timing error	Gun 1-1 error (ms) : 2.40
3567	3567	ALL	Gun timing error	Multi-gun errors
3568	3568	ALL	Gun timing error	Gun 1-1 error (ms) : -2.20
3673	3673	ALL	Gun timing error	Multi-gun errors
3674	3674	ALL	Gun timing error	Multi-gun errors
3753	3753	ALL	Gun timing error	Gun 1-2 error (ms) : -2.30
3975	3975	ALL	Gun timing error	Gun 3-1 error (ms) : 2.20
3987	3987	ALL	Gun timing error	Gun 3-1 error (ms) : 2.10
3991	3991	ALL	Gun timing error	Gun 3-1 error (ms) : 2.10
4018	4018	ALL	Gun timing error	Gun 3-1 error (ms) : 2.30
4019	4019	ALL	Gun timing error	Gun 3-1 error (ms) : 2.30
4052	4052	ALL	Gun timing error	Gun 3-1 error (ms) : 2.10
4086	4086	ALL	Gun timing error	Gun 1-2 error (ms) : -2.10
4196	4196	ALL	Gun timing error	Gun 6-2 error (ms) : -2.30
4368	4368	ALL	Gun timing error	Gun 3-1 error (ms) : 2.10
			Morning	

Warning					
Shot(s)	File(s)	Trace(s)	Туре	Remark	
2998	2998	ALL	Turn Noise	Streamer still in turn at tail-end	
3014	3014	ALL	Gun timing error	Gun 5-1 error (ms) : -1.70	
3019	3019	ALL	Gun timing error	Gun 1-2 error (ms) : -1.70	
3027	3027	ALL	Gun timing error	Gun 2-1 error (ms) : 1.70	
3033	3033	ALL	Gun timing error	Gun 3-1 error (ms) : 2.00	
3068	3068	ALL	Gun timing error	Gun 2-1 error (ms) : 1.60	
3100	3100	ALL	Gun timing error	Gun 3-1 error (ms) : 1.60	
3261	3261	ALL	Gun timing error	Gun 1-2 error (ms) : -1.60	
3343	3343	ALL	Gun timing error	Gun 3-1 error (ms) : -1.70	
3367	3367	ALL	Gun timing error	Gun 3-1 error (ms) : 1.60	
3381	3381	ALL	Gun timing error	Gun 3-1 error (ms) : -1.60	
3388	3388	ALL	Gun timing error	Gun 3-1 error (ms) : -2.00	
3407	3407	ALL	Gun timing error	Gun 3-1 error (ms) : 2.00	
3411	3411	ALL	Gun timing error	Gun 3-1 error (ms) : 1.70	
3417	3417	ALL	Gun timing error	Gun 3-1 error (ms) : 1.70	
3425	3425	ALL	Gun timing error	Gun 3-1 error (ms) : 1.90	
3426	3426	ALL	Gun timing error	Gun 3-1 error (ms) : -1.60	
3432	3432	ALL	Gun timing error	Gun 3-1 error (ms) : -1.60	
3445	3445	ALL	Gun timing error	Gun 3-1 error (ms) : -1.80	
3446	3446	ALL	Gun timing error	Gun 3-1 error (ms) : 1.60	
3473	3473	ALL	Gun timing error	Gun 3-1 error (ms) : 1.60	
3483-3760	3483-376	6070	Spiking Trace(s)	Trace 70 (summed) occasionally spiking - edit 70 for these SPs	
3500	3500	ALL	Gun timing error	Gun 3-1 error (ms) : 1.90	
3522	3522	ALL	Gun timing error	Gun 3-1 error (ms) : 1.90	
3527	3527	ALL	Gun timing error	Gun 3-1 error (ms) : 1.90	
3531	3531	ALL	Gun timing error	Gun 3-1 error (ms) : -1.90	

Gun 1-1. Source volume at shot 3000

End: Gun Array # 3 enabled. Volume

Gun 3-3. Source volume: 7723 cu.in.

Start: Gun Array # 3 disabled for repair. Volume equals 7164 cu.in.

: 7918 cu.in.

equals 7918 cu.in.

Gun disabled

Gun not fired

Reduced Volume

Reduced Volume

file:///C|/Documents and Settings/summit1/My Docum...ginais Geco/7443b/acquisitionreports/seq-0113.html (3 de 4) [8/3/2002 09:06:02]

3000-3565

3674-4387

3565

4258

3000-3565ALL

3674-4387 ALL

ALL

ALL

3565

4258

4287 4287 ALL Gun not fired Gun 3-3. Source volume: 7723 cu.in.

List of used abbreviations:

SOL/EOL Start/End of line.

FSP/LSP First/Last shotpoint of the line.
FCSP/LCSP First/Last chargeable shotpoint
MSP Midnight (last) shotpoint of the day

FGSP/LGSP First/Last Good Shotpoint
FOSP/LOSP First/Last Overlap Shotpoint
FSP/LSP R/O First/Last Shotpoint Runout

Deg Degrees: e[0,360]
rev Revolutions
utc Universal Time
Coordinated
SPs Shotpoints
CMPs Common midpoints
NTBP Not to be processed
SI Seismic interference

 $TRILOGY\ INFORMATION\ MANAGER\ -\ ACQUISITION\ REPORT\ -\ GENERATED\ 11:44:29 utc\ 02-Mar-2001$