

## **ORIGINAL NAME**

LINE -7009BBR01T177

AREA: Barreirinhas

CLIENT: Exploration Services/TGS Nopec

# **NEW NAME**

LINE: 0258-5009

AREA: 0258-2D\_SPEC\_BM\_BAR

**CLIENT: TGS-Nopec.** 



# **ACQUISITION REPORT Sequence-0177**



Survey:

Client Exploration Services
Area Para-Maranhao
Vessel GECO\_TAU
JobNumber 7443B
Survey Type 2D

Sequence:

Linename 7009BBR1T177
Preplot 7009BBR

Direction 186.0°

SOL Date 18:29:53utc 30-Mar-2001

EOL Date 02:57:00utc 31-Mar-2001

**Attributes:** 

Wind Force 6.0 [knots] Dir E Swell Height 1.5 [meters] Dir E Propellor rpm [avq]

Propellor pitch 50 [avg]

SOL EOL

Waterdepth 3413.0 21.3 [meters]
Bottomspeed 5.34 5.25 [knots]
Featherangle sb +15.8 sb +3.0 [deg]
Cable noise 4.73 6.53 [µBar rms]

Lowcut filter 3 3 [hz]
Filter slope 18 18 [dB]

Streamer 9 9

Depth

#### **Production**

		Shotpoint	File	Time [utc]
	SOL Noise Record(s)		4784 - 4783	
	SOL Dummy Record(s)	4782 - 4773	4782 - 4773	18:27:35 - 18:29:40
	FSP Start of Line	4772	4772	18:29:53
	MSP	3441		
	LSP End of Line	2706	2706	02:57:00
	EOL Dummy Record(s)	2705 - 2696	2705 - 2696	02:58:04 - 03:00:23
	EOL Noise Record(s)		2695 - 2694	
ı	. ,			

**Line-segments:** 

SPs Files Times [utc] Type # CMPs Status Remarks

4772 - 2706 4772 - 2706 18:29:53-02:57:50 Prime 1 Valid

**Remarks:** 

**Navigation** 

Recording QC

### **Tape-list**

		Stream 2		
Shot(s)	Files	DeckReel	Remark	
4784 - 2912	4784 - 2912	1 320		
2911 - 2694	2911 - 2694	2 321		
		Stream 4		
Shot(s)	Files	DeckReel	Remark	
4784 - 4319	4784 - 4319	3 1322		
4318 - 2694	4318 - 2694	4 1323		
		Stream 1001		
Shot(s)	Files	DeckReel	Remark	
752 - 2696	752 - 2696	1001 2		

## **Seismic Data Annotations**

ı	N	٦	R	D
ı	V			

Shot(s)	File(s)	Trace(s)	Туре	Remark
4758	4758	ALL	Gun timing error	Gun 5-2 error (ms) : 2.20
4346	4346	ALL	Gun timing error	Gun 2-1 error (ms) : 2.30
4303	4303	ALL	Gun timing error	Gun 5-1 error (ms) : 2.20
4214	4214	ALL	Gun timing error	Gun 2-1 error (ms) : 2.10
3690		ALL	Gun timing error	Gun 2-1 error (ms) : 3.70
3649		ALL	Gun timing error	Gun 1-2 error (ms) : -2.10
3634		ALL	Gun timing error	Gun 6-2 error (ms) : -2.60
3633		ALL	Gun timing error	Gun 6-2 error (ms) : -2.30
3632		ALL	Gun timing error	Gun 6-2 error (ms) : -2.70
3532		ALL	Gun timing error	Gun 2-5 error (ms) : 2.60
			Warning	, ,
Shot(s)	File(s)	Trace(s)	Type	Remark

			v v ai i i i i g	
Shot(s)	File(s)	Trace(s)	Type	Remark
4784-2694	. ,	73, 118, 193	Killed traces	6.0dB down
4772	4772	ALL	Gun timing error	Gun 5-2 error (ms) : 1.70
4737	4737	ALL	Gun timing error	Gun 6-2 error (ms) : -1.60
4718	4718	ALL	Gun timing error	Gun 2-1 error (ms) : 1.60
4561	4561	ALL	Gun timing error	Gun 2-1 error (ms) : 1.60
4500	4500	ALL	Gun timing error	Gun 5-2 error (ms) : 1.60
4492	4492	ALL	Gun timing error	Gun 5-2 error (ms) : -1.60
4491	4491	ALL	Gun timing error	Gun 5-2 error (ms) : -1.80
4442	4442	ALL	Gun timing error	Gun 2-1 error (ms) : 1.70
4429	4429	ALL	Gun timing error	Gun 5-1 error (ms) : -1.60
4420	4420	ALL	Gun timing error	Gun 2-1 error (ms) : 1.60
4314	4314	ALL	Gun timing error	Gun 2-1 error (ms) : 1.70
4255	4255	ALL	Gun timing error	Gun 5-2 error (ms) : 1.80
4223	4223	ALL	Gun timing error	Gun 5-2 error (ms) : 2.00
4222	4222	ALL	Gun timing error	Gun 5-2 error (ms) : 1.90
4206	4206	ALL	Gun timing error	Gun 5-2 error (ms) : 1.60
4194	4194	ALL	Gun timing error	Gun 2-1 error (ms) : 1.60
4184	4184	ALL	Gun timing error	Gun 2-1 error (ms) : 1.60
3938	3938	ALL	Gun timing error	Gun 5-2 error (ms) : 1.70
3937	3937	ALL	Gun timing error	Gun 5-2 error (ms) : 1.70
3886	3886	ALL	Gun timing error	Gun 5-1 error (ms) : 1.60
3872	3872	ALL	Gun timing error	Gun 5-2 error (ms) : -1.60
3870	3870	ALL	Gun timing error	Gun 5-2 error (ms) : -1.90
3869	3869	ALL	Gun timing error	Gun 5-2 error (ms) : -1.60
3674		ALL	Gun timing error	Gun 2-1 error (ms) : -1.60
3650		ALL	Gun timing error	Gun 1-1 error (ms) : 1.90
3635		ALL	Gun timing error	Gun 6-1 error (ms) : 1.80
3532		ALL	Gun timing error	Gun 2-3 error (ms) : 1.60
3531		ALL	Gun timing error	Gun 6-2 error (ms) : 1.70
3530		ALL	Gun timing error	Gun 6-2 error (ms) : 1.60
3529		ALL	Gun timing error	Gun 6-2 error (ms) : 1.60
3266	3266	ALL	Gun timing error	Gun 5-2 error (ms) : -1.60
3235	3235	ALL	Gun timing error	Gun 5-2 error (ms) : -1.60
2925	2925	ALL	Gun timing error	Gun 2-2 error (ms) : -1.60
2898	2898	ALL	Gun timing error	Gun 5-2 error (ms) : 1.90
2725	2725	ALL	Gun timing error	Gun 2-2 error (ms) : -1.60
			Comment	

## Comment

<b>Shot(s)</b> 4772-3651	<b>File(s)</b>	<b>Trace(s)</b>	<b>Type</b>
	4772-	ALL	Gun disabled
3650		ALL	Gun disabled/ON

### Remark

Spares OFF. Source volume at shot

4772 : 7918 cu.in.

Gun 2-10FF/1-1 ON. Source

volume: 7758 cu.in.

TIM Line Acquisition Report

3635 ALL Array disabled Array 2 OFF/ Spares ON. Source

volume: 7118 cu.in.

3532 ALL Array enabled/OFF Array 2 ON/Spares OFF. Source

volume: 7918 cu.in.

List of used abbreviations:

SOL/EOL Start/End of line.

FSP/LSP First/Last shotpoint of the line.
FCSP/LCSP First/Last chargeable shotpoint
MSP Midnight (last) shotpoint of the day

FGSP/LGSP First/Last Good Shotpoint
FOSP/LOSP First/Last Overlap Shotpoint
FSP/LSP R/O First/Last Shotpoint Runout

Deg Degrees: e[0,360] rev Revolutions

utc Revolutions
Universal Time
Coordinated
SPs Shotpoints

CMPs Common midpoints
NTBP Not to be processed
SI Seismic interference

TRILOGY INFORMATION MANAGER - ACQUISITION REPORT - GENERATED 03:08:41utc 31-Mar-2001