

## **ORIGINAL NAME**

LINE -5148BBR01T198

AREA: Barreirinhas

CLIENT: Exploration Services/TGS Nopec

# **NEW NAME**

LINE: 0258-5148

AREA: 0258-2D\_SPEC\_BM\_BAR

**CLIENT: TGS-Nopec.** 



# **ACQUISITION REPORT Sequence-0198**



Survey:

**Exploration Services** Client Para-Maranhao Area GECO\_TAU Vessel 7443B **JobNumber** 

Survey Type Sequence:

0148BBR1T198 Linename

0148BBR **Preplot** 96.0° Direction

16:57:27utc 07-Apr-2001 **SOL Date** 

2D

13:20:44utc 08-Apr-2001 **EOL Date** 

**Attributes:** 

Wind Force 17.0 [knots] Dir E Swell Height 1.5 [meters] Dir E Propellor rpm [avg] Propellor pitch 24

> SOL **EOL**

1574.0 [meters] 872.0 Waterdepth Bottomspeed 5.78 5.3 [knots] Featherangle sb +18.2 sb +5.0 [deg] Cable noise 16.39 [µBar rms] 5.82

[avg]

Lowcut filter 3 3 [hz] Filter slope 18 18 [dB]

7.0 Streamer 7.0

Depth

#### **Production**

notpoint	File	Time [utc]
	2588 - 2589	
590 - 2599	2590 - 2599	16:55:22 - 16:57:15
800	2600	16:57:27
584	4584	23:59:58
281	8281	13:20:44
282 - 8291	8282 - 8291	13:20:56 - 13:22:57
	8292 - 8293	
5	90 - 2599 00 84 81 82 - 8291	2588 - 2589 90 - 2599 2590 - 2599 00 2600 84 4584 81 8281

### **Line-segments:**

SPs	Files	Times [utc]	Type	# CMPs	Status Remarks
2600 - 8284	2600 - 8281	16.57.27-13.20.44	Drimo	1	\/alid

**Remarks: Navigation** 

Trace # 136 intermittent noisy. (High freq. noise). Recording QC

### **Tape-list**

Stream 2				
Shot(s)	Files	DeckReel	Remark	
2588 - 2823	2588 - 2823	1 354		
2824 - 4701	2824 - 4701	2 355		
4702 - 5411	4702 - 5411	1 356		
5412 - 7286	5412 - 7286	2 357		
7287 - 8293	7287 - 8293	1 358		
		Stream 4		
Shot(s)	Files	DeckReel	Remark	
2588 - 4465	2588 - 4465	3 1352		
4466 - 6339	4466 - 6339	4 1353		
6340 - 8216	6340 - 8216	3 1354		
8217 - 8293	8217 - 8293	4 1355		
Stream 1001				
Shot(s)	Files	DeckReel	Remark	
1837 - 8291	1837 - 8291	1001 6		

### **Seismic Data Annotations**

## **NTBP**

Shot(s)	File(s)	Trace(s)	Туре	Remark
ALL	ALL` ´	136	Noisy trace	Intermittently noisy (high frequency)
3253		ALL	Missing File	File not recorded by recording system
3266		ALL	Missing File	File not recorded by recording system
4080		ALL	Missing File	File not recorded by recording system
4095		ALL	Missing File	File not recorded by recording system
4110	4110	ALL	Bad shot	Early fire of guns
4111		ALL	Missing File	File not recorded by recording system
4834		ALL	Missing File	File not recorded by recording system
6708		ALL	Missing File	File not recorded by recording system
7075		ALL	Missing File	File not recorded by recording system
7279		ALL	Missing File	File not recorded by recording system
7589		ALL	Missing File	File not recorded by recording system
Warning				

Shot(s)	File(s)	Trace(s)	Туре	Remark
ALL	ALL-	68, 73, 118, 140, 186, 188, 193	Weak traces	6.0dB down
2600-2737	2600-273	7NONE	Bird depth out of spec	Birds 1-3 @ average of 8.5m
2690	2690	ALL	Gun timing error	Gun 1-2 error (ms) : -1.80
2712	2712	ALL	Gun timing error	Gun 3-1 error (ms) : -1.60
2750	2750	NONE	Bird depth out of spec	Bird C1-6
2753-2757	2753-275	7NONE	Bird depth out of spec	Bird C1-6
2758	2758	NONE	Bird depth out of spec	Bird C1-6
2759-2761	2759-276		Bird depth out of spec	Bird C1-6
2767-2768	2767-276		Bird depth out of spec	Bird C1-29
2770-2782	2770-278		Bird depth out of spec	Bird C1-29
2784	2784	ALL	Gun timing error	Gun 5-2 error (ms) : -1.90
2802	2802	1-40	Current Noise	Affecting 10 % of traces @ 200 uB rms.
2810	2810	NONE	Bird depth out of spec	Bird C1-6
2817	2817	1-100	Current Noise	Affecting 20 % of traces @ 200 uB rms.
2826	2826	NONE	Bird depth out of spec	Bird C1-6
2829	2829	NONE	Bird depth out of spec	Bird C1-6
2834	2834	NONE	Bird depth out of spec	Bird C1-6
2859-2860	2859-286	0NONE	Bird depth out of spec	Bird C1-6
2880	2880	40-200	Current Noise	Affecting 30 % of traces @ 200 uB rms.

TIM Line Acqu	isition Report			
2950	2950	100-260	Current Noise	Affecting 50 % of traces 20-150 uB RMS.
3000	3000	180-260	Current Noise	Affecting 30 % of traces 20-150 uB RMS.
3061	3061	ALL	Gun timing error	Gun 5-2 error (ms) : -1.60
3070	3070	ALL	Current noise	ceased
3181	3181	ALL	Gun timing error	Gun 3-1 error (ms) : -1.60
3810	3810	ALL	Gun timing error	Gun 4-1 error (ms) : 2.00
3848	3848	ALL	Gun timing error	Gun 1-2 error (ms) : -1.90
3935	3935	ALL	Gun timing error	Gun 3-1 error (ms) : -1.80
4245	4245	ALL	Gun timing error	Gun 1-2 error (ms) : -1.60
4329	4329	ALL	Gun timing error	Gun 5-2 error (ms) : -1.70
4536	4536	ALL	Gun timing error	Gun 5-2 error (ms) : -1.60
4710	4710	ALL	Gun timing error	Gun 3-1 error (ms) : -1.60
4913	4913	ALL	Gun timing error	Gun 5-2 error (ms) : -1.70
5086	5086	ALL	Gun timing error	Gun 5-2 error (ms) : -1.70
5308	5308	ALL	Gun timing error	Gun 3-1 error (ms) : -1.60
5512	5512	ALL	Gun timing error	Gun 5-1 error (ms) : 1.60
5543	5543	ALL	Gun timing error	Gun 1-2 error (ms) : -1.80
5575	5575	ALL	Gun timing error	Gun 1-2 error (ms) : -1.70
5749	5749	ALL	Gun timing error	Gun 5-2 error (ms) : -1.60
6285	6285	ALL	Gun timing error	Gun 2-2 error (ms) : -1.80
6563	6563	ALL	Gun timing error	Gun 5-1 error (ms) : -1.60
7140	7140	ALL	Gun timing error	Gun 2-2 error (ms) : -1.60
7219	7219	ALL	Gun timing error	Gun 3-1 error (ms) : -1.60
7758	7758	ALL	Gun timing error	Gun 2-2 error (ms) : -1.60
8235	8235	ALL	Gun timing error	Gun 1-2 error (ms) : -1.60
8254	8254	ALL	Gun timing error	Gun 5-2 error (ms) : -1.60
			Comment	
Shot(s)	File(s)	Trace(s)	Туре	Remark
2600-8282	2600-828	2ALL	Gun disabled	Spares OFF. Source volume at shot 2600: 7918 cu.in.

List of used abbrev	viations:		
SOL/EOL FSP/LSP FCSP/LCSP MSP FGSP/LGSP FOSP/LOSP FSP/LSP R/O	Start/End of line. First/Last shotpoint of the line. First/Last chargeable shotpoint Midnight (last) shotpoint of the day First/Last Good Shotpoint First/Last Overlap Shotpoint First/Last Shotpoint Runout	Deg rev utc SPs CMPs NTBP SI	Degrees: e[0,360] Revolutions Universal Time Coordinated Shotpoints Common midpoints Not to be processed Seismic interference

TRILOGY INFORMATION MANAGER - ACQUISITION REPORT - GENERATED 14:38:47utc 08-Apr-2001