

ORIGINAL NAME

LINE -7025BBR01T173

AREA: Barreirinhas

CLIENT: Exploration Services/TGS Nopec

NEW NAME

LINE: 0258-5025

AREA: 0258-2D_SPEC_BM_BAR

CLIENT: TGS-Nopec.



ACQUISITION REPORT Sequence-0173



Survey:

Exploration Services Client Para-Maranhao Area GECO_TAU Vessel 7443B **JobNumber** 2D

Survey Type

Sequence:

7025BBR1T173 Linename 7025BBR **Preplot**

186.0° Direction

06:15:00utc 29-Mar-2001 **SOL Date**

13:23:24utc 29-Mar-2001 **EOL Date**

Attributes:

Wind Force 10.0 [knots] Dir E Swell Height 1.0 [meters] \$(swell_dir)

Propellor rpm [avg] Propellor pitch 52 [avg]

> SOL **EOL**

3538.0 20.0 Waterdepth [meters] Bottomspeed 5.6 5.2 [knots] Featherangle sb + 19.8 sb + 2.0[deg] Cable noise 5.35 5.06 [µBar rms]

Lowcut filter 3 3 [hz] Filter slope 18 18 [dB]

Streamer 9 9 Depth

Production

	Shotpoint	File	Time [utc]
SOL Noise Record(s)		4785 - 4784	
SOL Dummy Record(s)	4783 - 4774	4783 - 4774	06:12:51 - 06:14:47
FSP Start of Line	4773	4773	06:15:00
MSP			
LSP End of Line	2930	2930	13:23:24
EOL Dummy Record(s)			
EOL Noise Record(s)		2695 - 2694	
Line-segments:			

SPs	Files	Times [utc]	Туре	# CMPs	Status R	emarks
1773 - 2	930 4773 - 2930	06.15.00-13.23.24	Prima	1	\/alid	

Remarks:

Navigation

Stopped recording @ SP 2930 due to shallow water. Recording QC

Tape-list

		Stream 2	
Shot(s)	Files	DeckReel	Remark
4785 - 4782	4785 - 4782	1 313	SOL noise records + 2 dummy shots; write failure
4781 - 2694	4781 - 2694	2 314	
		Stream 4	
Shot(s)	Files	DeckReel	Remark
4785 - 2694	4785 - 2694	3 1315	
		Stream 1001	
Shot(s)	Files	DeckReel	Remark
4234 - 2694	4234 - 2694	1001 8	

Seismic Data Annotations

NTBP						
Shot(s)	File(s)	Trace(s)	Туре	Remark		
			Warning			
Shot(s)		Trace(s)	Туре	Remark		
ALL	ALL-	73, 118, 193	Weak traces	6.0dB down		
4766	4766	ALL	Gun timing error	Gun 2-1 error (ms) : 1.80		
4669 4612	4669 4612	ALL ALL	Gun timing error	Gun 4-1 error (ms) : 1.60 Gun 5-2 error (ms) : -1.60		
4603	4603	ALL	Gun timing error Gun timing error	Gun 5-2 error (ms) : 1.80		
4567	4567	ALL	Gun timing error	Gun 4-1 error (ms): -1.60		
4562	4562	ALL	Gun timing error	Gun 2-1 error (ms): 1.70		
4425	4425	ALL	Gun timing error	Gun 2-2 error (ms) : -1.60		
4288	4288	ALL	Gun timing error	Gun 4-1 error (ms) : 1.60		
4244	4244	ALL	Gun timing error	Gun 5-2 error (ms) : -1.60		
4236	4236	ALL	Gun timing error	Gun 2-2 error (ms) : -1.80		
4217	4217	ALL	Gun timing error	Gun 4-1 error (ms) : 1.60		
4151	4151	ALL	Gun timing error	Gun 2-2 error (ms) : -1.90		
4145	4145	ALL	Gun timing error	Gun 2-2 error (ms) : -1.60		
4060	4060	ALL	Ship noise	From abeam, Noise level 4-8 ubar		
4015	4015	ALL	Gun timing error	Gun 4-1 error (ms) : 1.60		
3980	3980	ALL	Ship noise	From abeam/slightly ahead, Noise level		
2020	2020	٨١١	Cup timing arror	10-15 ubar		
3929 3924	3929 3924	ALL ALL	Gun timing error	Gun 5-2 error (ms) : 1.80		
3892	3892	ALL	Gun timing error Gun timing error	Gun 1-2 error (ms) : -1.70 Gun 4-1 error (ms) : 1.60		
3726	3726	ALL	Gun timing error	Gun 4-1 error (ms) : 1.60		
3710	3710	ALL	Gun timing error	Gun 4-1 error (ms) : 1.60		
3693	3693	ALL	Gun timing error	Gun 4-1 error (ms) : 1.60		
3669	3669	1-60	Current Noise	50-200 uB.		
3614	3614	ALL	Gun timing error	Gun 2-1 error (ms) : 1.90		
3542	3542	ALL	Gun timing error	Gun 2-1 error (ms) : 1.70		
3533	3533	ALL	Gun timing error	Gun 2-2 error (ms) : -1.60		
3531	3531	ALL	Gun timing error	Gun 2-1 error (ms) : 1.70		
3512	3512	ALL	Gun timing error	Gun 2-1 error (ms) : 1.70		
3511	3511	ALL	Gun timing error	Gun 2-1 error (ms) : 1.70		
3500	3500	ALL	Gun timing error	Gun 4-1 error (ms) : 1.60		
3430	3430	ALL	Gun timing error	Gun 4-1 error (ms) : 1.70		
3401 3379	3401 3379	ALL ALL	Gun timing error Gun timing error	Gun 2-1 error (ms) : 1.80 Gun 2-1 error (ms) : 1.70		
3278	3278	ALL	Gun timing error	Gun 2-1 error (ms) : 1.70		
3195	3195	ALL	Gun timing error	Gun 2-1 error (ms) : 1.80		
3167	3167	ALL	Gun timing error	Gun 4-1 error (ms) : 1.60		
3122	3122	ALL	Gun timing error	Gun 4-1 error (ms) : 1.80		
3112	3112	ALL	Gun timing error	Gun 2-2 error (ms) : -1.60		
3083	3083	ALL	Gun timing error	Gun 2-2 error (ms) : -1.70		
3082	3082	ALL	Gun timing error	Gun 4-1 error (ms) : 1.70		
3030	3030	ALL	Gun timing error	Gun 4-1 error (ms) : 1.60		
3026	3026	ALL	Gun timing error	Gun 2-1 error (ms) : 1.60		
3020	3020	ALL	Gun timing error	Gun 2-1 error (ms) : -1.90		
3004	3004	ALL	Gun timing error	Gun 2-2 error (ms) : -1.70		
2934	2934	ALL	Gun timing error	Gun 2-1 error (ms) : 1.60		
			Comment			
Shot(s)	File(s)	Trace(s)	Туре	Remark		
4773-2929	4773-	ALL	Gun disabled	Gun 1-1. Source volume at shot		
				4773 : 7918 cu.in.		

4773-2929 4773-

ALL

Gun disabled

Gun 6-1. Source volume at shot 4773: 7918 cu.in.

\mathbf{T}	• 4	e	1	11	•	4 •	
•	AST.	OT.	used	abi	revi	ลนเด	ns:

SOL/EOL Start/End of line.

FSP/LSP First/Last shotpoint of the line.
FCSP/LCSP First/Last chargeable shotpoint
MSP Midnight (last) shotpoint of the day

FGSP/LGSP First/Last Good Shotpoint
FOSP/LOSP First/Last Overlap Shotpoint
FSP/LSP R/O First/Last Shotpoint Runout

Deg Degrees: e[0,360]
rev Revolutions
Universal Time
Coordinated
SPs Shotpoints
CMPs Common midpoints
NTBP Not to be processed

Seismic interference

TRILOGY INFORMATION MANAGER - ACQUISITION REPORT - GENERATED 13:59:18utc 29-Mar-2001

SI