

### **ORIGINAL NAME**

LINE -7093BBR01T157

AREA: Barreirinhas

CLIENT: Exploration Services/TGS Nopec

## **NEW NAME**

LINE: 0258-5093

AREA: 0258-2D\_SPEC\_BM\_BAR

**CLIENT: TGS-Nopec.** 



# **ACQUISITION REPORT Sequence-0157**



Survey:

Client Exploration Services
Area Para-Maranhao
Vessel GECO\_TAU
JobNumber 7443B
Survey Type 2D

**Sequence:** 

Linename 7093BBR1T157
Preplot 7093BBR
Direction 6.0°

 Direction
 6.0°

 SOL Date
 22:28:19utc 22-Mar-2001

 EOL Date
 05:57:23utc 23-Mar-2001

**Attributes:** 

Wind Force 4.0 [knots] Dir NE
Swell Height 1.5 [meters] Dir NE
Propellor rpm [avg]
Propellor pitch 51 [avg]

SOL **EOL** 23.0 3545.0 Waterdepth [meters] Bottomspeed 5.5 5.5 [knots] Featherangle port -15.9 port -19.6 [deg] Cable noise 33.0 4.77 [µBar rms] Lowcut filter 3 3 [hz] Filter slope 18 18 [dB] Streamer 7.0 7.0

Depth

#### **Production**

	Shotpoint File	Time [utc]
SOL Noise Record(s)	2800 - 2801	
SOL Dummy Record(s)	2802 - 2811 2802 - 2811	22:26:08 - 22:28:05
FSP Start of Line	2812 2812	22:28:19
MSP	3236 3236	23:59:52
LSP End of Line	4881 4881	05:57:23
EOL Dummy Record(s)	4882 - 4891 4882 - 4891	05:57:35 - 05:59:32
EOL Noise Record(s)	4892 - 4893	

**Line-segments:** 

 SPs
 Files
 Times [utc]
 Type
 # CMPs Status
 Remarks

 2812 - 4881
 2812 - 4881
 22:28:19-05:57:23
 Prime
 1
 Valid

Remarks:

**Navigation** 

Recording QC Cable bent at SOL noise test. From Sp 3227 bird # 7 shallow depth range from 3.9 - 6 m.

### Tape-list

		Stream 2			
Shot(s)	Files	DeckReel	Remark		
2800 - 4682	2800 - 4682	1 281			
4683 - 4893	4683 - 4893	2 282			
		Stream 4			
Shot(s)	Files	DeckReel	Remark		
2800 - 4685	2800 - 4685	3 1285			
4686 - 4893	4686 - 4893	4 1286			
Stream 1001					
Shot(s)	Files	DeckReel	Remark		
738 - 1172	738 - 1172	1001 2			

### **Seismic Data Annotations**

V	٦	Γ	R	1	P
			_	л	

NIDE					
Shot(s)	File(s)	Trace(s)	Туре	Remark	
2800-4893		69-70	Killed traces		
2961		ALL	Missing File	File not recorded by recording system	
2971	2971	ALL	Bad shot	Early fire of guns	
2972		ALL	Missing File	File not recorded by recording system	
2985		ALL	Missing File	File not recorded by recording system	
2987		ALL	Missing File	File not recorded by recording system	
3010	3010	ALL	Gun timing error	Gun 1-2 error (ms) : -2.20	
3070	3070	ALL	Gun timing error	Gun 1-2 error (ms) : -2.80	
3106	3106	ALL	Bad shot	Early source fire	
3107		ALL	Missing File	File not recorded by recording system	
3123		ALL	Missing File	File not recorded by recording system	
3139	3139	ALL	Bad shot	Early source fire	
3140		ALL	Missing File	File not recorded by recording system	
3774		ALL	Missing File	File not recorded by recording system	
3777	3777	ALL	Gun timing error	Gun 4-1 error (ms) : 2.30	
4020	4020	ALL	Gun timing error	Gun 2-1 error (ms) : 2.40	
4057		ALL	Missing File	File not recorded by recording system	
4066		ALL	Missing File	File not recorded by recording system	
4182-4272	4182-427	21-24	Cross current noise	Edit traces due to high current noise	
4187-4275	4187-427	524-40	Cross current noise	Edit traces due to high current noise	
4194-4282	4194-428	240-55	Cross current noise	Edit traces due to high current noise	
4206-4289	4206-428	955-68	Cross current noise	Edit traces due to high current noise	
4226-4293	4226-429	371-91	Cross current noise	Edit traces due to high current noise	
4240-4315	4240-431	591-118	Cross current noise	Edit traces due to high current noise	
4247		ALL	Missing File	File not recorded by recording system	
4263-4328	4263-432	8119-140	Cross current noise	Edit traces due to high current noise	
4278-4334	4278-433	4141-165	Cross current noise	Edit traces due to high current noise	
4293-4359	4293-435	9166-192	Cross current noise	Edit traces due to high current noise	
4315-4366	4315-436	6193-213	Cross current noise	Edit traces due to high current noise	
4329-4372	4329-437	2214-232	Cross current noise	Edit traces due to high current noise	
4342-4380	4342-438		Cross current noise	Edit traces due to high current noise	
4374	4374	ALL	Gun timing error	Gun 2-1 error (ms) : 2.30	
			Warning		

			vvarriing	
Shot(s)	File(s)	Trace(s)	Туре	Remark
2800-4893		73, 94, 118, 136, 193, 197, 214	Weak traces	6.0dB down
2812	2812	240-320	Noise	Noise at tail of bent cable, 100-300 µBar
2840	2840	ALL	Gun timing error	Gun 2-1 error (ms) : 1.60
2855	2855	240-320	Noise	Noise gone
2867	2867	ALL	Gun timing error	Gun 2-1 error (ms) : 1.70
3017	3017	ALL	Gun timing error	Gun 2-1 error (ms) : 1.60
3066-3069	3066-3069	ALL	Manifold pressure low	Subarray 5 below 1800 psi
3070	3070	ALL	Gun timing error	Gun 6-2 error (ms) : -2.00
3072	3072	ALL	Gun timing error	Gun 6-2 error (ms) : -1.90
3074	3074	ALL	Gun timing error	Gun 1-2 error (ms) : -1.90
3162	3162	ALL	Gun timing error	Gun 5-1 error (ms) : -1.80
3162	3162	ALL	Gun timing error	Gun 6-2 error (ms) : 1.60
3164	3164	ALL	Gun timing error	Gun 6-2 error (ms) : 1.70
3179	3179	ALL	Gun timing error	Gun 2-1 error (ms) : 1.90
3227-3244	3227-3244	52-55	Bird depth out of spec	Bird C1-7, depth range 3.9-4.9m
3245-3252	3245-3252	52-55	Bird depth out of spec	Bird C1-7, depth range 4.9-5.3 m
3253-3264	3253-3264	52-55	Bird depth out of spec	Bird C1-7, depth range 3.9 - 4.9 m
3261-3272	3261-3272	64-67	Bird depth out of spec	Bird C1-8, depth range 4.7-5.4 m
3265-OPEN	3265-OPEN	N52-55	Bird depth out of spec	Bird C1-7, depth range 5 - 6.5 m

TIM Line Acqu	isition Report			
3367	3367	ALL	Gun timing error	Gun 1-2 error (ms) : -1.60
3394	3394	ALL	Gun timing error	Gun 2-1 error (ms) : 1.70
3507	3507	ALL	Gun timing error	Gun 2-2 error (ms) : -1.60
3602	3602	ALL	Gun timing error	Gun 2-2 error (ms) : -1.70
3702	3702	ALL	Gun timing error	Gun 2-1 error (ms) : 1.60
3821	3821	ALL	Gun timing error	Gun 4-1 error (ms) : 1.60
3834	3834	ALL	Gun timing error	Gun 2-1 error (ms) : 1.60
3868	3868	ALL	Gun timing error	Gun 4-1 error (ms) : -1.80
3871	3871	ALL	Gun timing error	Gun 2-1 error (ms) : 1.60
3951	3951	ALL	Gun timing error	Gun 4-1 error (ms) : 1.60
4000	4000	ALL	Gun timing error	Gun 6-2 error (ms) : -1.60
4074	4074	ALL	Gun timing error	Gun 2-1 error (ms) : 1.60
4146	4146	ALL	Gun timing error	Gun 2-1 error (ms) : 1.90
4183	4183	ALL	Gun timing error	Gun 4-1 error (ms) : -1.80
4399	4399	ALL	Gun timing error	Gun 4-1 error (ms) : 2.00
4406	4406	ALL	Gun timing error	Gun 2-1 error (ms) : 1.60
4437	4437	ALL	Gun timing error	Gun 3-1 error (ms) : -1.80
4478	4478	ALL	Gun timing error	Gun 1-2 error (ms) : -1.60
4511	4511	ALL	Gun timing error	Gun 2-2 error (ms) : -1.70
4593	4593	ALL	Gun timing error	Gun 2-1 error (ms) : 1.90
4699	4699	ALL	Gun timing error	Gun 2-2 error (ms) : -1.80
4725	4725	ALL	Gun timing error	Gun 2-1 error (ms) : 1.70
4804	4804	ALL	Gun timing error	Gun 3-1 error (ms) : -1.90
4808	4808	ALL	Gun timing error	Gun 2-1 error (ms) : 1.60
4841	4841	ALL	Gun timing error	Gun 4-1 error (ms) : 1.70
			Comment	
Shot(s)	File(s)	Trace(s)	Туре	Remark
2812	2812	ALL	Gun disabled	Spare guns, Source volume at shot 2812 : 7918 cu.in.
3069	3069	ALL	Array disabled	Array # 5, spares ON, Source volume at shot 3069 : 7118 cu.in.
3160-4882	3160-488	32ALL	Array enabled	Array # 5, spares OFF, Source volume at shot 3160 : 7918 cu.in.

List of used abbre	viations:		
SOL/EOL FSP/LSP FCSP/LCSP MSP FGSP/LGSP FOSP/LOSP FSP/LSP R/O	Start/End of line. First/Last shotpoint of the line. First/Last chargeable shotpoint Midnight (last) shotpoint of the day First/Last Good Shotpoint First/Last Overlap Shotpoint First/Last Shotpoint Runout	Deg rev utc SPs CMPs NTBP SI	Degrees: e[0,360] Revolutions Universal Time Coordinated Shotpoints Common midpoints Not to be processed Seismic interference

TRILOGY INFORMATION MANAGER - ACQUISITION REPORT - GENERATED 06:15:03utc 23-Mar-2001