
2026 National Mine Rescue Contest

Coal Day 2

Mine Rescue

Judges Packet



2026 National Mine Rescue Contest

Thank you for answering our call for help here at the Wild Eagle Mine. You are located at the fresh air base of our Timber Ridge Section where we recently completed an air shaft in the #3 entry. This shaft is currently not in use but is available if needed.

Late last night, a five-man crew entered this section to do maintenance and clean up work. At approximately 2:00 AM, we started getting high CO readings on the section and attempts to contact the crew have been unsuccessful.


We evacuated the rest of the mine and sent in our mine rescue team but they had to exit the mine during their rescue attempt due to nearby lightning strikes in the area. The storms have left the area and we are asking you to continue where they left off and help rescue our missing miners. State and Federal Agencies have been notified and are on site. Backup mine rescue teams are available if needed.


This mine is ventilated with a blowing fan. Typical ventilation on this section has air coming up the #3 entry and exits in the #1 and #2 entries. The fan is currently running and cannot be stopped, stalled, or reversed. The power to this area of the mine has been de-energized but can be re-energized if needed.

You have 75 minutes to complete the problem. Thank you for coming to help us and good luck.


Written Instructions

- Account for all missing miners
- Bring all survivors to the fresh air base
- Explore all areas of the mine that can be explored safely
- Team can only carry two brattice cloths at a time
- The name and location of any of the missing miners discovered shall be reported to the Superintendent prior to the team leaving that team stop
- Team cannot leave the field with any materials that they picked up during the problem



Face
Face
Face
8 Timbers
Shovel
Cap Lamp
Conscious
Shawn Maxwell
Continuous
Miner
Methane
Probe
Vent Tubing
Air Shaft
2.5 % CH4
20 PPM CO
19.0 % O2
B
BC
2.5 % CH4
8 PPM CO
19.5 % O2
Operable
Battery Scoop
Unconscious
Jerry Matthers
Copper Tubing
Battery
Scoop
Great Smoky
Mountains
Lunch Box
D
Open
D
Open
BC
5.2 % CH4
8 PPM CO
19.0 % O2
Shuttle Car
2.5 % CH4
8 PPM CO
19.0 % O2
B
Cap Light
Battery
Johnny
Sky
Unconscious
Jeff Batty
5.2 % CH4
0 PPM CO
19.0 % O2
5.2 % CH4
8 PPM CO
19.0 % O2
Battery Scoop
D
Open
D
Open
Roof Bolter
4 Timbers
Airtight
Conscious
Phil Billy
B
Battery Mine
Phone
5.2 % CH4
8 PPM CO
12.0 % O2
Used SCSR
10mm Socket
3/8" Drive Ratchet
Pick Hammer
Oil Bucket on Fire
5.2 % CH4
8 PPM CO
19.0 % O2
Not
Intact
BC
Briefing
Officer
CCA
BC
BC
Battery
Scoop



Face
Face
Face
RR GT DI
RR GT DI
RR GT DI
Cap Lamp
8 Timbers
Shovel
Continuous Miner
Conscious Shawn Maxwell
Methane Probe
Vent Tubing
Air Shaft
2.5 % CH4
20 PPM CO
19.0 % O2
GT
GT DI
B
BC
NOTE: TEAMS NOW DO VENT 3 & 4
12
10/11
10/11
GT
GT
2.5 % CH4
8 PPM CO
19.5 % O2
Operable Battery Scoop
Copper Tubing
Great Smoky Mountains Lunch Box
Unconscious Jerry Matthers
NOTE: GT DI ON OC WALLS WILL BE ACOORDING TO TEAM TRAVEL
Battery Scoop
GT
GT
GT DI
7/9
7/8
8/9
D
Open
5.2 % CH4
8 PPM CO
19.0 % O2
Shuttle Car
2.5 % CH4
8 PPM CO
19.0 % O2
Cap Light Battery
Johnny Sky
Unconscious Jeff Batty
5.2 % CH4
0 PPM CO
19.0 % O2
5.2 % CH4
8 PPM CO
19.0 % O2
Battery Scoop
NOTE: AFTER TEAMS GET TIMBERS AT THIS STOP THEY CAN NOW DO VENT 1 & 2 TO RESCUE PATIENT BEHIND BARRIACADE IN #1
6
5
4
DI GT
Roof Bolter
4 Timbers
RR GT DI
Airtight
Conscious Phil Billy
Battery Mine Phone
Used SCSR
10mm Socket
3/8" Drive Ratchet
Pick Hammer
Oil Bucket on Fire
GT RR @ FIRE
NOTE: EACH TIMETHE TEAM PASSES THE FIRE A RR IS REQUIRED
1
2/3
2/3
DI
Not Intact
Briefing Officer
CCA
Battery Scoop


Extent of Gases





1st Vent


Face
Face
Face
Cap Lamp
8 Timbers
Shovel
Conscious
Shawn Maxwell
Continuous
Miner
Methane
Probe
Vent Tubing
Air Shaft
2.5 % CH4
20 PPM CO
19.0 % O2
BC
2.5 % CH4
8 PPM CO
19.5 % O2
Operable
Battery Scoop
Unconscious
Jerry Matthers
Copper Tubing
Battery
Scoop
Great Smoky
Mountains
Lunch Box
D
Open
D
Open
5.2 % CH4
8 PPM CO
19.0 % O2
BC
Shuttle Car
2.5 % CH4
8 PPM CO
19.0 % O2
Cap Light
Battery
Johnny
Sky
Unconscious
Jeff Batty
5.2 % CH4
0 PPM CO
19.0 % O2
5.2 % CH4
8 PPM CO
19.0 % O2
Battery Scoop
D
Open
D
Open
Roof Bolter
4 Timbers
Airtight
Conscious
Phil Billy
Battery Mine
Phone
5.2 % CH4
8 PPM CO
12.0 % O2
Used SCSR
10mm Socket
3/8" Drive Ratchet
Pick Hammer
Oil Bucket on Fire
Cleared
5.2 % CH4
8 PPM CO
19.0 % O2
Not
Intact
BC
Set
Timbers
Briefing
Officer
CCA
BC
BC
Battery
Scoop


2nd Vent
Face
Face
Face
Cap Lamp
8 Timbers
Shovel
Conscious
Shawn Maxwell
Continuous
Miner
Methane
Probe
Vent Tubing
Air Shaft
2.5 % CH4
20 PPM CO
19.0 % O2
2.5 % CH4
8 PPM CO
19.5 % O2
Operable
Battery Scoop
Unconscious
Jerry Matthers
Copper Tubing
Battery
Scoop
Great Smoky
Mountains
Lunch Box
Open
Open
5.2 % CH4
8 PPM CO
19.0 % O2
Shuttle Car
2.5 % CH4
8 PPM CO
19.0 % O2
Cap Light
Battery
Johnny
Sky
Unconscious
Jeff Batty
5.2 % CH4
0 PPM CO
19.0 % O2
5.2 % CH4
8 PPM CO
19.0 % O2
Battery Scoop
Open
Open
Roof Bolter
4 Timbers
Airtight
Conscious
Phil Billy
Battery Mine
Phone
Used SCSR
10mm Socket
3/8" Drive Ratchet
Cleared
5.2 % CH4
8 PPM CO
12.0 % O2
Pick Hammer
Oil Bucket on Fire
Cleared
5.2 % CH4
8 PPM CO
19.0 % O2
Not
Intact
Briefing
Officer
CCA
Battery
Scoop



3rd Vent
Face
Face
Face
8 Timbers
Shovel
Cap Lamp
Conscious
Shawn Maxwell
Continuous
Miner
Methane
Probe
Vent Tubing
Air Shaft
2.5 % CH4
20 PPM CO
19.0 % O2
B
BC
2.5 % CH4
8 PPM CO
19.5 % O2
Cleared
Operable
Battery Scoop
Unconscious
Jerry Matthers
Copper Tubing
Battery
Scoop
Great Smoky
Mountains
Lunch Box
D
Open
D
Open
BC
5.2 % CH4
8 PPM CO
19.0 % O2
Shuttle Car
2.5 % CH4
8 PPM CO
19.0 % O2
Cap Light
Battery
Johnny
Sky
B
5.2 % CH4
8 PPM CO
19.0 % O2
Unconscious
Jeff Batty
B
5.2 % CH4
0 PPM CO
19.0 % O2
Cleared
5.2 % CH4
8 PPM CO
19.0 % O2
5.2 % CH4
8 PPM CO
19.0 % O2
Battery Scoop
D
Closed
D
Closed
Roof Bolter
4 Timbers
Airtight
Conscious
Phil Billy
B
Cleared
Battery Mine
Phone
5.2 % CH4
8 PPM CO
12.0 % O2
Used SCSR
10mm Socket
3/8" Drive Ratchet
Pick Hammer
Oil Bucket on Fire
Cleared
5.2 % CH4
8 PPM CO
19.0 % O2
Cleared
Not
Intact
BC
Briefing
Officer
CCA
BC
BC
Battery
Scoop


4th Vent
Face
Face
Face
Cap Lamp
8 Timbers
Shovel
Conscious
Shawn Maxwell
Continuous
Miner
Methane
Probe
Vent Tubing
Air Shaft
2.5 % CH4
20 PPM CO
19.0 % O2
Cleared
B
BC
2.5 % CH4
8 PPM CO
19.5 % O2
Cleared
Operable
Battery Scoop
Copper Tubing
Great Smoky
Mountains
Lunch Box
Unconscious
Jerry Matthers
Battery
Scoop
D
Open
D
Open
5.2 % CH4
8 PPM CO
19.0 % O2
BC
Shuttle Car
2.5 % CH4
8 PPM CO
19.0 % O2
B
5.2 % CH4
8 PPM CO
19.0 % O2
Cap Light
Battery
Johnny
Sky
Unconscious
Jeff Batty
B
5.2 % CH4
0 PPM CO
19.0 % O2
Cleared
5.2 % CH4
8 PPM CO
19.0 % O2
5.2 % CH4
8 PPM CO
19.0 % O2
Battery Scoop
D
Closed
D
Closed
Roof Bolter
4 Timbers
Airtight
Conscious
Phil Billy
B
Battery Mine
Phone
5.2 % CH4
8 PPM CO
12.0 % O2
Cleared
Used SCSR
10mm Socket
3/8" Drive Ratchet
Pick Hammer
Oil Bucket on Fire
Cleared
5.2 % CH4
8 PPM CO
19.0 % O2
Cleared
Not
Intact
BC
Briefing
Officer
CCA
BC
BC
Battery
Scoop


5th Vent
Face
Face
Face
Cap Lamp
8 Timbers
Shovel
Continuous Miner
Conscious Shawn Maxwell
Methane Probe
Vent Tubing
Air Shaft
2.5 % CH4
20 PPM CO
19.0 % O2
Cleared
BC
Cleared
2.5 % CH4
8 PPM CO
19.5 % O2
Operable Battery Scoop
Copper Tubing
Great Smoky Mountains Lunch Box
Unconscious Jerry Matthers
Battery Scoop
Cleared
5.2 % CH4
8 PPM CO
19.0 % O2
D Open
D Open
Cleared
BC
Shuttle Car
Cleared
5.2 % CH4
8 PPM CO
19.0 % O2
2.5 % CH4
8 PPM CO
19.0 % O2
B
Cap Light Battery
Johnny Sky
Unconscious Jeff Batty
5.2 % CH4
0 PPM CO
19.0 % O2
Cleared
5.2 % CH4
8 PPM CO
19.0 % O2
Cleared
5.2 % CH4
8 PPM CO
19.0 % O2
Battery Scoop
D Closed
D Closed
Roof Bolter
4 Timbers
Airtight
Set Timbers
Conscious Phil Billy
B
Battery Mine Phone
Move Phone
5.2 % CH4
8 PPM CO
12.0 % O2
Cleared
Pick Hammer
Used SCSR
10mm Socket
3/8" Drive Ratchet
Oil Bucket on Fire
Cleared
5.2 % CH4
8 PPM CO
19.0 % O2
Cleared
Not Intact
BC
Briefing Officer
CCA
BC
Battery Scoop
BC

Team No. _____

Final Vent Map



Team member

Judge

NATIONAL MINE RESCUE CONTEST DAY 2
JUDGES BRIEFING

Number 1 entry GT
Number 2 entry GT DI stopping
Number 3 entry GT DI stopping

Team Stop 1
Team will need to be on lifeline to enter smoke
Team check
Captain will RR & extinguish the fire & GT before team passes the fire
DI GT stopping between 1 & 2
GT DI at Barricade in #1
Teams will build between 1 & 2 RR & DI the team built & go through the stopping to team stop #2

Team Stop 2
RR GT DI unsafe roof outby
RR GT DI unsafe roof inby
GT between 2 & 3 & DI stopping not intact

Team Stop 3
GT DI stopping outby
GT inby

Team Stop 4
GT DI overcast wall
GT DI Barricade
Teams now have timbers they can do ventilation 1 & 2, make sure teams are getting permission for ventilation changes, if the team advances to team stop 5 it will be delay
Ventilation 1 got to remove explosive mixture in #2
Teams need to RR @ fire due to re-entering this area
Ventilation 2
Teams need to build to enter Barricade
Entering barricade GT
Patient Touch Assess DI
Captain can pass patient off to another team member & then RR DI GT @ caved airtight while team is getting patient ready for removal
Take patient to FAB
Teams do not have to build back an air lock before taking patient to the FAB

Team Stop 5
GT DI overcast wall between 1 & 2
GT RR DI outby at unsafe
GT inby
GT between 2 & 3

Team Stop 6
RR GT DI caved airtight outby
Inby GT

Team Stop 7
GT DI overcast wall between 1 & 2
Inby GT RR unsafe area with person in it

Team Stop 8
GT DI overcast wall between 2 & 3
GT outby
GT inby
GT between 2 & 3

Team Stop 9
GT DI Barricade
GT inby

Team Stop 10 o
RR DI GT inby @ face
GT between 2 & 3

Team Stop 11
GT between 1 &
GT outby
RR DI GT inby @ face

Team stop 12
GT outby
GT DI @ barricade
Teams can now ventilate for barricade in #1 @ located @ team stop 12
Ventilation 3, make sure teams are getting the required ventilation changes
Ventilation 4

Teams need to build to enter Barricade
Entering barricade GT
Patient Touch Assess DI
Captain can pass patient off to another team member & then RR DI GT @ face while team is getting patient ready for removal
The team can timber in to person outby in the unsafe area if the team does not have to make another team stop. Captain can timber in to patient Touch Assess DI, team can protect patient and remove fron unsafe area
Take patient/'s to FAB
Teams do not have to build back an air lock before taking patient to the FAB
If teams do not timber into unsafe to recover the patient they can do it on the way back in and take patient to the FAB

Ventilation 5

Teams need to build to enter Barricade in the #3 entry
Entering barricade GT
Touch body DI
Patient Touch Assess DI
Captain can pass patient off to another team member if he needs to
Protect patient load and take to the FAB
Team does not have to build back when they leave

Stop the clock!!

PATIENT 1

HELP

GET ME OUT!

PATIENT 2

HELP

GET ME OUT!