

MKS GE50A

pin 1 - power and signal common

pin 2 - +11-25 VDC power in

pin 3 - no connection

pin 4 - no connection

pin 5 - B/B+ (RS485+)

pin 6 - no connection

pin 7 - RS485 common

pin 8 - Shield

pin 9 - A/A+ (RS485-)

RS 485

black - GND

yellow - DATA B

red - power

brown - terminator 120R

orange - DATA A

green - terminator 120R