

Feld Architecture PLLC

315 West 36th Street, Suite 804, New York, NY 10018
(212) 555-0147 · office@feldarch.com

August 24, 2026

Eleanor Whitcomb
Whitcomb Holdings LLC
142 West 88th Street
New York, NY 10024

Re: Kitchen water repair, completion and sign-off

Dear Eleanor,

The leak under the kitchen sink came from a failed supply line. Our plumber replaced both supply lines and the shutoff valves, and our carpenter replaced the sink base cabinet and patched 6 sq ft of subfloor. Work finished on August 21.

We took moisture readings at the sink base, subfloor and adjoining wall on August 24. Every point read dry.

The repair is complete and we sign it off. No further work is needed.

Sincerely,

Daniel Feld, RA
Feld Architecture PLLC