Technical Operations
13th Floor – WHQEG
233 S. Wacker Dr.
Chicago IL 60606

May 18, 2026

Mr. Wayne Ha
Aviation Safety Engineer
FAA Seattle Aircraft Certification Office Branch
2200 South 216th St.
Des Moines, WA 98198

Subject: Comments to Docket No. FAA–2026–2730; Project Identifier AD–2025–01579–T

References:
/A/ Docket No. FAA–2026–2730; Project Identifier AD–2025–01579–T
/B/ Boeing Alert Requirements Service Bulletin (RB) 757-53A0122

United Airlines (UA) has reviewed Ref /A/ and /B/ notice of proposed rulemaking (NPRM) Docket to mandate certain maintenance actions for Boeing 757-300 Series airplanes.

UA requests changes Tables 2 to Ref /B/ as some steps note stringers S-13L and S-14L. Table 2, both for the Compliance and Actions Required for Compliance sections, is for the Right Side.

UA currently operates twenty-one (21) Boeing 757-300 airplanes affected by Ref /A/ and supports the proposed rulemaking Docket with no further comments.

Thank you for the opportunity to comment to the docket.

Sincerely,

Tiffany Little
Senior Engineer – Fleet Engineering Structures
United Airlines, Inc.
Mobile: 832-314-9169 e-mail: tiffany.little@united.com