## Experiment 6. Encapsulation and temperature testing of powdered PCM

First of all, the melting and freezing behavior of powder PCM will be examined as in experiment 1 and experiment 2. Then the powder PCM will be encapsulated and will be placed inside the server cabinet. Here, the phase change of the powder PCM will be examined by giving heat to the inside of the cabinet by means of a light bulb.