726063

Mercedes-Benz of Calabasas

WARRANTY

Authorized Mercedes-Benz Retaller

NATALIA TSEPENYUK 23777 MULHOLLAND HWY SPC 63 CALABASAS, CA 91302-3741

PAGE 1

24181 Calabasas Road Calabasas, CA 91302 (818) 223-3102

HOME:818-4	45-4	730	CONT: 747-	388-4090			B.A.R.# AC 25		# CAD 9824869	46			
BUS:			CELL:747-		SEF	RVICE ADVISOR:	: 1451 QI						
COLOR	YEAR		MAKE/MODEL			VIN	LICENSE	MILEAGE	EIN/OUT	TAG			
	23	MER	CEDES-BEN			J4GB7PN334174	1	38931,	/38940	T756			
DEL. DATE	PROD.	DATE	WARR. EXP.	PROMIS	ED	PO NO.	RATE	PAYMENT	INV. I	DATE			
20FEB24 DD				19:00 0	JAN25			CASH	11JAN	25			
R.O. OPEN	IED		READY	OPTIONS	S: DL	R:05179							
10:48 06JA								4		***************************************			
LINE OPCOD							LIST	r∥ ne:	r ro	ΓAL			
	5A00	7 FG				TRANS	Olla	Å					
			XMT 1.50	}				388.05	388	05			
1			01-09 TS		ER ELEI	MENT	17.50			.50			
						1211	5.00						
			3-014106 SEAL RING, VLRUB 5.00 5.00 5.00 36-20-00-16 WINDSHIELD CLEANING AGENT 5.75 5.75 5.75										
			10-08-19-			TITTO PIONIT	7.33			.17			
			OIL DISE		,		0.30			.10			
•			72-03 FIN		יודים ים:	מיזייז							
			56-05-09-				62.00			.00			
						ענו	29.34			.34			
			98-00 TS				58.00	58.00) 58	.00			
				FOR WINDS	SHIELD	LEFT & RIGHT	[
	SIDE												
	14	28 W	XMT 0.10	!				25.87	7 25	.87			
					146	03 22876	TPARTS						
					650	50 41392	? TLABOR						
,,,,38940	PREP	AID	40,000 MI	LE SERVI	CE AS	PER CUSTOMER	REOUEST.	•					
, PERFOR	MED	PREP	AID 40.00	0 MILE SH	ERVICE	. RESET SERVI	CE INDI	ATOR & TI	TRE.				
PRESSII	RE M	ONTT	ORS. CHAN	GED OTT. A	OTT	FILTER, CABIN	TETLTER	WIDER					
BLADES	. £	BRAK	E FLITTO	CORRECTE	TILITA (D LEVELS UNDE	י בבבבני, דם שעים סי						
, , , , , , , , , , , , , , , , , , , ,						*******							
					, .,								
******	****	****	******	*****	*****	*******	****						
ESTIMATE:						:48 SA: 1451							
				OPUAL	NZ5 10	:48 SA: 1451	_						
CONTACT			# # # # # # # # # # # # # # # # # # #	لا على مال مال مال مال مال مال مال	مداديات بالديات بالديات	*****	المراجع المستقدمات والمستقدمات والمستقدمات	la afa ala ala ala ala					
				11111		, , , , , , , , , , , , , , , , , , ,		* * * * * * * * * * * * * * * * * * *					
_		1-1/	111100	$\Delta \Pi \Pi \Lambda$									
Pans	\mathcal{N}	Y()Y	111440	2117									

Original Estimate (Parts & Labor)	Total Additional Cost Authorized	Approved By:	Date & Time	Authorization Obtained By:	*HAZARDOUS WASTE DISPOSAL COSTS: We have added this	220010111011	TOTALS
•				Telephone Fax (See Attached)	charge to cover costs associated	LABOR AMOUNT	
~				DE-mail (See Attached)	with the handling, management	PARTS AMOUNT	
Revised Estimate	\$			Telephone	and disposal of toxic wastes or	GAS, OIL, LUBE	
		<u> </u>		☐E-mail (See Attached)	hazardous substances under California and Federal Law.	SUBLET AMOUNT	
DE	sure check/inflation psi LF	nei DD	aniilii n	ei .	ALL PARTS ARE NEW	WASTE DISPOSAL COSTS*	
Customer	declined tire press	sure check/inflation	service.	Initials	UNLESS OTHERWISE	TOTAL CHARGES	
y signing be	llow, you acknow	/leage that you	were notified of	and authorized the	IMPICATED	LESS INSURANCE	
or had the opp	ortunity to inspect)	any replaced part	s as requested by	you.	Some Parts Not Returnable	SALES TAX	
DATE	CUSTO	MER SIGNATURE	UA	THORIZED DEALERSH	IIP REPRESENTATIVE SIGNATURE	PLEASE PAY THIS AMOUNT	, , , , , , , , , , , , , , , , , , , ,

726063

Mercedes-Benz of Calabasas

WARRANTY

Authorized Mercedes-Benz Retailer

NATALIA TSEPENYUK 23777 MULHOLLAND HWY SPC 63 CALABASAS, CA 91302-3741

PAGE 2

24181 Calabasas Road Calabasas, CA 91302 (818) 223-3102

HOME: 818-4	45-47	3.0	CONT: 747-	388	3-4090			B.A.R.# AC 250	333 E.P.A#	CAD 98248694	6
BUS:			CELL: 747-			SEF	RVICE ADVISOR:	1451 QU	INTERO JA	ZMIN	
COLOR	YEAR		MAKE/MODEL				VIN	LICENSE	MILEAGE	IN / OUT	TAG
	23	MER	CEDES-BEN	IZ C	CLA 25	W1K5	J4GB7PN334174	E .	38931/	38940	T756
DEL. DATE	PROD. [DATE	WARR. EXP.		PROMIS	ED	PO NO.	RATE	PAYMENT	INV. D	ATE
20FEB24 DD				19	9:00 06	JAN25			CASH	11JAN2	:5
R.O. OPEN	IED		READY		OPTIONS	3: DLI	R:05179				
10:48 06JA	M25	17:	17 11JAN2	25							
LINE OPCOL	E TEC	HT	YPE HOURS	;)				LIST	NET	TOT	'AL
CREATED	2024-	12-			PM C	ALABAS			DES-BENZ		
TAKEN BY	GAVI	м А	GUTTYK.		Si	SKVICE	HOURS MONDAY	(~FKIDAY	/:UUAM TU	' /:UUPM	l

EMERGENCY 24 HOUR SERVICE 1-800-367-6372 WE WILL NOT BE RESPONSIBLE FOR ITEMS LEFT IN CAR OR ANY AFTERMARKET PRODUCTS IN YOUR CAR.

SERVICE IS NOW OPEN SATURDAY 8:00AM TO 5:00PM

COST, SALE, & COMP TOTALS 21163 64478 HAZARDOUS WASTE DISPOSAL TOTALS Approved By: DESCRIPTION Date & Time Original Estimate (Parts & Labor) Total Additional Cost Authorized Authorization Obtained By: COSTS: We have added this LABOR AMOUNT <u>413.92</u> □Telephone □Fax (See Atlached) □E-mall (See Atlache charge to cover costs associated PARTS AMOUNT <u>228.76</u> with the handling, management Revised Estimate Telephone Fax (See Allached) E-mail (See Atlached and disposal of toxic wastes or 0.00 GAS, OIL, LUBE hazardous substances SUBLET AMOUNT 0.00 California and Federal Law. Tire pressure check/inflation service was performed. WASTE DISPOSAL COSTS * 2.10 RF___psi LF__psi RR__psi LR__ Customer declined tire pressure check/inflation service. **ALL PARTS ARE NEW** TOTAL CHARGES 644.78 Initials **UNLESS OTHERWISE** By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this Invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. LESS INSURANCE 0.00 INDICATED. Some Parts Not Returnable SALES TAX 21.73 AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE CUSTOMER SIGNATURE DATE PLEASE PAY THIS AMOUNT 666.51

NATALIA TSEPENYUK

726063

Mercedes-Benz of Calabasas

INVOICE

Authorized Mercedes-Benz Retailer

24181 Calabasas Road Calabasas, CA 91302 (818) 223-3102

23777 MULHOLLAND HWY SPC 63 CALABASAS, CA 91302-3741 PA

PAGE 3

HOME:818-4 BUS: COLOR	45-47		CONT:747- CELL:747- MAKE/MODEL	388		SER	VICE ADVISO		B.A.R.# AC 2 1451 QI LICENSE	UINTER	O JA	A# CAD 9824 ZMIN IN / OUT	186946 TAG
DEL. DATE			CEDES-BEN WARR. EXP.	IZ C	CLA 25 PROMISI		J4GB7PN3341 PO NO.	L74	RATE		931/	38940 INV. I	T756
20FEB24 DI			READY	19	0:00 06		R:05179			CASH		07JAN2	25
10:48 06JA LINE OPCOL	E TEC	СН Т	YPE HOURS)			*****		LIS'		NET	TOT	ΓΑΙ,
ESTIMATE: CONTACT	0.00 1:			er arenes 98800381	06JAN	J25 10	newser forms been annews about the State (1997)	151					
CUSTOMER CREATED	REQU 2024-	JEST -12-	ED A LOAN 2 4 12:46	I BI	DC TH	IANK YO	OU FOR VISI	ITIN	G MERC	EDES-B			
TAKEN BY	(GAV)	IN A	GUILAR		SI EM	ERVICE IERGENO	HOURS MOND IS NOW OPE CY 24 HOUR NOT BE RES	EN S SER	ATURDA VICE 1	Y 8:007 -800-3	AМ Т 67-6	0 5:001 372	PM
							ANY AFTERMA						
											501615151515151 501615515551		x())(0.000000000000000000000000000000000
	081030010000000000000000000000000000000	urisida kada	oces (1966) in the building of the	reteansi	prosposocioni del	kalokatoni kridiji.		8881884218888				90.000.000.000.000	

(Paris & Labor) Cost Authorized			COSTS: We have added this charge to cover costs associated	LABOR AMOUNT	0.00
\$,
In the second second		□E-mail (See Attached)	with the handling, management		0.00
Revised Estimate		☐Telephons ☐Fax (See Atteched)	and disposal of toxic wastes or hazardous substances under	GAS, OIL, LUBE	0.00
		☐E-mail (Sea Attached)	hazardous substances under California and Federal Law.	SUBLET AMOUNT	0.00
Tire pressure check/inflation service	pei IR pei		ALL DADTO ADE NEW	WASTE DISPOSAL COSTS *	0.00
Customer declined tire pressure che	ck/inflation service.	Initials	ALL PARTS ARE NEW UNLESS OTHERWISE	TOTAL CHARGES	0.00
By signing below, you acknowledge to Dealership to perform the services/repair	hat you were notified o	f and authorized the	INDICATED	LESS INSURANCE	0.00
(or had the opportunity to inspect) any re	eplaced parts as requested	by you.	Some Parts Not Returnable	SALES TAX	0.00
DATE CUSTOMES	SIGNATURE	AUTHORIZED DEALER	RSHIP REPRESENTATIVE SIGNATURE	PLEASE PAY THIS AMOUNT	0.00

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.

726063

Mercedes-Benz of Calabasas

INVOICE

Authorized Mercedes-Benz Retaller

NATALIA TSEPENYUK 23777 MULHOLLAND HWY SPC 63 CALABASAS. CA 91302-3741

PAGE 1

24181 Calabasas Road Calabasas, CA 91302 (818) 223-3102

HOME: 818-4		CONT: 747-	-388-4090	1		B.A.R.# AC 250)333 E.P	.A# CAD 9824	186946
BUS:		CELL:747-			RVICE ADVISOR:	1451 OU	INTERO JA	ZMIN	
COLOR	YEAR	MAKE/MODEL			VIN	LICENSE	MILEAGE		TAG
					5J4GB7PN334174			⁷ 38940	
DEL, DATE	PROD. DATE	WARR, EXP.	PROMI	SED	PO NO.	RATE	PAYMENT	INV. E	DATE
20FEB24 DI			<u> 19:00 0</u>				CASH	07JAN2	25
R.O. OPEN	IED	READY	OPTION	is: Di	LR:05179				
			_						
10:48 06JA									
LINE OPCOL						LIST			'AL
					E HAS LACK OF F				
		garante de la composição de la composição de la garante	engen, en ligigare percentar apareces	agreement the second of the second of the second	TANCE IN PEDAL		.,	dárováárások az etetet. Stol	mean our perouse
				PEDAL	PROVIDE CLIENT	MITH DI	4TAEK		
		ESTIMATE.		######################################		400 (844) 844, 387 (844) 84, 844 (84	Planthic of St. State (Sunanciar)	idurupalariaranan anamasan is	00000 RE 86.850000000000000
ENG E		_	cebarr					/ 5.7	/a\
20040	1428	IPS	N TINTENED C	ימות ימתי	DAL PROVIDED CI	TENTO LOTO	DII	(N)	
,,,,soggu	URLVER Vrr Ciic	MUMBD DEGI	TNIPO	ино гь.	DAM EKOATDED CT	I A. EMN A. WALL	l R	receivement in this element is	eachdeanachasaile c
,,,,EGIIME	****	**********	********	*****	*****	*****	.		180000004400402407
B CLIENT 9	ann annann in iomrafaithe is failt				LL GO INTO MANU	i itali matajat matusa mangtatigtisi	andaran na ngaran na mbayargaan naga naga magan		-00000000000000000000000000000000000000
FAMILIAN CONTRACTOR CO	VN. CHK	expression position removes being estimated that	LIAC ABILITO		BB OO INTO MANC	AL MODE	ON IID		
		PERFORMED	(arring p troceur, post naroders (coopers, toop	xicous noons noocospring		oongungngo (chu lon hannanga)	100001 W03 103 H118W11 W11 H10011	tropids attented passados, to	eevaaaaaaaa keakuun a
	1428							(N)	/C)
38940			CUSTOMER	CONC	ERN ATTACHED SD	S & BAT'	rery	a disabada an Nati A	:: ::
MAINTA	AINER. P	ERFORMED S	SHORT TES	T. NO	CODES FOUND. F	ERFORME	D TEST DE	RIVE	
					OUT 38,931, MIL			. 	ante mastruet e en acuera esper
,,,, UNABLE	TO VER	IFY CUSTON	MER CONCE	RN. N	O FURTHER REPAI	RS PERF	ORMED.		

C CLIENT S	STATES W	HILE DRIV	ING VEHIC	LE DR	IVE MODE WILL C	HANGE O	WO RTI V	1	
GC	DES FROM	COMFORT I	O ECO OR	ECO '	TO SPORT MODE.	CHK and	ADV		
NWP 1	10 WORK	PERFORMED		2000					
	1428	IPS						(N)	/C)
				IABLE	TO VERIFY CUSTO	MER CON	CERN. NO		
,,,,FURTHE	ER REPAI	RS PERFORN	MED.						
					******	****	***		
D 40,000 N			KED INTER	RVAL	tata esta de la colonida esta esta de la colonida d	udud sudaden uuraan udumutu sa	other and code obtains blood ball on the	doetoodesoovesooteon	eposocupa octooperna et
CAUSE: 21							108000000000000000000000000000000000000		561 1000 14 201 2000 1 . 300
04004		O MILE SER	RVICE - W	VITHOU	T TRANS	d 200 20 20 20 20 00 00 00 00 00 00 00 00	uscongousy) on connection of	000000000000000000000000000000000000000	
	SERVICE								/ ~~ \
50000000000000000000000000000000000000	1428		ATT TITE	n ara ya cara ara a	THE ATTENDATION	50864, by 1980816, Daniello 1900		(N)	
		-01-09 TS	11.1	,,,	EMENT			(N)	
		014106 SEA			E-7-34 (23 - 7) (21-3310)	energenegenegenegen.		(N _/	
4		.,			EANING AGENT		ruiterissi sisestissi saasiaasi	(N)	
Odeles Fester		-10-08-19- proved By: Date & 1			AZARDOUS WASTE DISPOSAI	DESCR	IDTION	(N) ATOT	
	Authorized App	proved By: Date & I	Obtained	11	STS: We have added this			IUIA	160
			Telephone Fax (See Attack E-mail (See Attack		arge to cover costs associated				
Revised Estimate			□Telephone	an	th the handling, management d disposal of toxic wastes of	·			
\$ \$			□Fax (See Attach □E-ma# (See Atta	sched) ha	zardous substances unde				
Tire pressure che				Ca	lifornia and Federal Law.	WASTE DISPO			
RFpsi LF	psi RR	psi LRps neck/inflation service,	si Initials		ALL PARTS ARE NEW	TOTAL CHAR			
By signing below, y	ou acknowledge	that you were notif	ied of and author		UNLESS OTHERWISEINDICATED.	LESS INSURA			
Dealership to perform	the services/repa	airs itemized in this Inv replaced parts as requ	voice and that you		Some Parts Not Returnable	SALES TAX			
DATE		R SIGNATURE		D DEALERSH	IP REPRESENTATIVE SIGNATURE	PLEASE PA	v l	.000.000.000.000.000.000	
						THIS AMOI		2400 CA 1400 CA 1500 CA 1600 CA	

NATALIA TSEPENYUK

726063

Mercedes-Benz of Calabasas

INVOICE

2

Authorized Mercedes-Benz Retailer

4.41

24181 Calabasas Road Calabasas, CA 91302 (818) 223-3102

142121111111111111111111111111111111111	
23777 MULHOLLAND HWY SPC 63	
CALABASAS, CA 91302-3741	PAGE
HOME:818-445-4730 CONT:747-388-4090	

HOME:81	18-4	45-4	730	CONT:	747-3	88-4090				B.A.R.# AC 25	0333 E.	P.A# CAD 9824	186946
BUS:						88-4090	SI	ERVICE A	DVISOR:	1451 OU	INTERO J	AZMIN	
COLOF	3	YEAR			MODEL			VIN		LICENSE		E IN / OUT	TAG
									N334174		38931		T756
DEL. DA	TE.	PROD.	DATE	WARR.	EXP.	PROMIS	ED	PO	NO.	RATE	PAYMENT	INV. I	DATE
20FEB24	.,,,,,		60 Bessel			19:00 00				<u> </u>	CASH	07JAN2	25
н.О.	OPENI	עפ		REAL	γ	OPTIONS); D	LR:0517	79				
10:48	ባ <i>ር</i> ፒክ	אזים בי	116.	EQ 07	7. Tス トス ア ニ								
LINE O						<u> </u>				LIST	NE	ייי ייי	ΓAL
DINE C.						SAL FEE					191:		/C)
5.44.66006000000000000000000000000000000						PARTIC		TTER	e suferiologica e edificade delibración de la composición del composición de la composición del composición de la compos	vade u tribusti tur e un triu tribito.	odiče Posesu I se pri Dostuski u popul D	(N)	
59,000,000,000,000,000,000,000,000,000,0						109 BRA							/č)
***************************************						IPER BL							/C)
82	2691	3 WI	PER	BLADE	B - F	OR WIND	SHIEL	D LEFT	& RIGHT				
		SIDE	, RE	PL.									
			28 W									(N)	/C)
,,,,389	940	PREP	AID	40,00	O MII	E SERVI	CE AS	PER CU	JSTOMER R	REQUEST,			
									ET SERVIC			'IRE	
,,,,PRI	ESSU	RE M	LINO	ORS.	CHANG	ED OIL	& OIL	. FILTER	R, CABIN	FILTER,	WIPER	: :::::::::::::::::::::::::::::::::::::	popped unitor total in
,,,,BL/	ADES								ELS UNDER				
<u></u>	55546556555								*****	*****	***	CONTRACTOR PROFESSIONAL CONSTRACT	TOTAL TENTANTANIAN SE
						ın and R	ecall	. ATN K€	eport				
ivi j	P MA	and the second of the second of the second of	11ANC 28	E PLA	7 77/		egaceauxeachae	200000000000000000000000000000000000000		isalautaeraasiataaanastora		7.87	/c)
250050050000000000000000000000000000000	600000000000000				*****	*****	****	*****	**** ***	****	***	(4N)	/. (-)
ษ *Tngı	nect								e Monitor				
									set Tire				200020000000000000000000000000000000000
800000000000000000000000000000000000000					stem								8211824183211431821
,			28	IPS								(N.	/C)
,,,,38	940	TIRE	S FF	RONTS	38PSI	, REARS	34PS	! I					
									*****	*****	* * *		
									74.95 Val	Lue			
M)									AND TIRE	Name and Administration	6		oorooten, aroa
3, 33, 33, 433, 33,								E MEASU	JREMENTS				
-565606060606060606060						CIFICAT				ansa luutara saataan ay ta ka ka ka ka	57/99/19/09/57/6/5/5/5/5/5/5/5/5/5/5/5/5/5/5/5/5/5/	50.17.18.88.88.88.88.87.191.86.00	nemice version nector.
550 54) 1 0000 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0						COURTES	Y CAF	WASH W	VHEN				0.40.000.0000000.000
	4900000000	er er egger er eger eger er eger	Contractor and the second	anno anno acceptante de la companya	COMPLE	TED.	5015051805188	g1999/110011985, 2001298:	000000000000000000000000000000000000000	4:600:140:07:1600:07:0800;0800;08	80.00088000000000000000000000000000000	::::::::::::::::::::::::::::::::::::::	/as
201	040		28 ECT 1		אם ריים כויי	MED INSP	·····································	NT.		.;000;100;000;100;100;100;100;100;100;10		(19)	/C)
,,,,,	34 0	* TNOL	****	. * * * * * *	*****	*******	****	. * * * * * * * * \TA	*****	*****	***		
H *Com	നിim			and a comment of the			hodelon, bod to cohis		ry en Troma eneseelledt fresta	urus i torki okersitotsi kestesi			
				WASI							g verteren gestietet. Die for Richtsteller wirden statisch	rs dina descripción teglo devir Talancia	
			28	IPS								(N,	/C)
Original Estimate	Total	Additional	Appro	oved By:	Đate & Timi	e Authorizat			WASTE DISPOSA		RIPTION	TOTA	ALS
(Parts & Labor)	Cost A	uthorized			·	Obtained Ortelephone			ave added this costs associated		TNUC		
\$	\$					□Fax (See Attache □E-mail (See Attac	hed) V	ith the handli	ing, managemen	t PARTS AMO	TNUC		
Revised Estimate	\$					☐Telephone ☐Fax (See Atlache	od)		toxic wastes o bstances unde		UBE		
		. l. 11 #1 #1 -				□E-mail (See Attac		alifornia and F		SUBLET AN	-		
Tire press	sure chec psi LF_		n service si RR	was perfor psi LR				ALL PART	S ARE NEW		OSAL COSTS *		
Custome	r decline	d tire pres	sure che	ck/inflation	service.	Initials			OTHERWISE	TOTAL CHA			
Dealership to	perform	the servic	ces/repair	s itemized	in this Invoi	l of and authorisce and that you i	zed the received I		CATED.	LESS INSUF			
(or had the op		to inspe	ct) any re	eplaced part	ts as reques	ted by you.			Not Returnable	SALES TAX	(C)		obero Perchebi Merci. Pa
DATE		CU	OIUNER	SIGNATURE	•	AUTHORIZEL	DEALERS!	III OCERESENTA	THE SIGNATURE	PLEASE PA			

NATALIA TSEPENYUK

726063 Mercedes-Benz of Calabasas

ACCOUNTING

Authorized Mercedes-Benz Retailer

24181 Calabasas Road

23777 MULHOLLAND HWY SPC 63 CALABASAS, CA 91302-3741

PAGE 1

Calabasas, CA 91302 (818) 223-3102

HOME:81	8-4	45-4	730	CONT:	747-	388-	-4090				В	.A.R.# AC 2	2503	33	E.P.A	# CAD 982	486946
BUS:		10 1	. , 5 0	CELL:				S	ERV	ICE ADVISOR	: 1	L451 O	IIU	VTERO	JAZ	MIN	
COLOR		YEAR	5,00,000,000	MAKE/						VIN				MILEA			TAG
•														,			
		23	MEF	CEDES	S-BEN	Z CI	JA 25	Wll	₹ 5₫	4GB7PN33417	4		13.5555			8940	
DEL, DA	TE	PROD	, DATE	WARR.	EXP.		PROMIS	ED		PO NO.	0.000000	RATE		PAYMENT		INV.	DATE
0077777700						10	00 0	C TD 310	۱, ا				١,	77.611		0 E T3 37	5.5
20FEB24	OPEN		880 - 8888088	l REA	nv l		ODTIONS			:05179				CASH		07JAN:	45
n.v.	OFEIN	עם		new	νı		OFFICIAL). I	אטנ	:051/9							
10:48) 6.TZ	N25	116.	58 05	7.TZNT2	5											
LINE OF							IRS				1	LIST		N	ET		TOTAL
								EHICI	jE, j	HAS LACK OF			ΤE				000000000000000000000000000000000000000
										NCE IN PEDA							
30.330, 500 000 000 000 0	WA	S PU	JSHEI	COM	PLETL	Y U	NDER .	PEDAI	L P)	ROVIDE CLIE	'NT'	WITH	DR.	IVER		Alleh den bedringset Andre San San Barri	eethaternaageneraans. Stootsprongeringenera
				ESTI													
El	IG E																
A0000000000000000000000000000000000000	550 550 V9661			IPS						0	2555561V4	. 1960 <u>. uze za senage</u> ez	<u> </u>		00	0	.00
			(EMI	°# 14!	51,07	JAN:	25 14	:24)	: 3	8940 PROVIL	ED	CLIEN	T	WITH			
,,,,EST	LTMY	ATE	/ range	SIL OH A A	5 A - A -	T-70 % T /	N ET CONTRACTOR	- A H-1	i i i i i i i i i i i i i i i i i i i	0040 DDTM	N 1845	A DT - 1.777.TN	(117 1)	O TANTONIO	Th	kripeliek kraipalakar	danakan Japanan
,,,,VEI	い い い し い に い に い に に い に い に り に り に り に り に り	אר <i>ב</i> ווע עדי		11 DED	28,07 CTTE	ידידאי ז ידידאי	SO LO	:4:0/ GCTT	יים אוא	8940 DRIVER E. CUSTOMER	C 1717	CONTRICT	GE.	שעמט כ	ĸ	1.000.000.000.000000	88. 1869 (C. 19. 1906)
DOTTEN	מייה כ	יחשעייי יחשרי	יטאק נוע פינ	ITTE I	TUTGO	MOLV	VIID VEUTO	LE M.	MAI. TT.T.	GO INTO MA	NIT I	T. MOD	ים ע	אר דייפ			
D. Charai				ind Al		TAKE	V 13 1 1 11 (\$	TO TENSON AND	- إينياء إينيان إشاد	GO THIC HE	TAOX		A. Propins	ATA COMPANS			380 800 0 800
NV	VP N	IO WC	DRK I	ERFO	RMED	25000000000	81831.781.88%										
70,000 (000 pg /g /g /g /g /g /g				IPS		0	.50	2050	0	2050			oran navana.	20.	50	20	.50
,,,,VEF	RSIC	N 1	(EMI)# 142	28,07	JAN:	25 13	:34)	: S	HORT TEST,	NO	CODES					
,,,,VE	RSIC	N 2	(EMI	P# 142	28,07	JAN:	25 13	:54)	: S	HORT TEST,	NO	CODES	•	TEST			
,,,,DR	CVE,	NO	ISSU	JES													
,,,,VE	RSIC	N 3	(EMI	P# 142	28,07	JAN:	25 14	:12)	: 3	8940 UNABLE	T(O VERI	FY		energia e	Nations objects along	eachtar an tacarra lea se
,,,,CUS	STOM	ER (CONCL	RN A	I'I'ACH	(ED 3	SDS &	BAT"	PER	Y MAINTAINE	SR.	PERFO	RM.	ED SHO	RT		00000000000000000000000000000000000000
,,,,TES	5'l',) OM		FOUL	ND, F	'ERF	OKMED OVER	LES.	ID.	RIVE (TIME	OU.	JMED C	E ONT	TIN' MIT	アドア		tokostovinos papavinių ir tili karnokas karnokas (1986)
,,,,ou.							<i>J</i>) , U.	NADL	Digital Control	O VERIFY CU) 12 T (JMEK C	OM	CEKN.	MO		
,,,,roi	OTP.	IN A	(EMI	0H 14'	28 N.7	TAN'	25 14	• 14)	• ্ব	8940 UNABLE	· ጥ	O WERT	FΥ				
CUS	STOM	IER (CONCI	RN A	ГТАСН	ED S	SDS &	BAT	· · ·	Y MAINTAINE	iR.	PERFO	RM	ED SHO	RT		055.000.0050000.5-0-0.0-
TES	3T'	NO (CODES	FOU	ND. E	ERF	ORMED	TEST	r D	RIVE (TIME	OU	Γ 1:34		TIME I	N		
,,,,1:5	54,	MILE	ES OU	JT 38	,931,	MI	LES I	N 38	,94	O), UNABLE	TO	VERIF	Y	CUSTOM	ER		
,,,,coi	NCER	2N. 1	ia of	JRTHEI	RREF	AIR:	S PER	FORM)	ED.								
C CLIE										E MODE WILI					WN		
						O E	CO OR	ECO	TO	SPORT MODE	; . (CHK an	d.	ADV			
NV	VP N			PERFO			0.0	838886.396386	A	Α	PESENSE	A. (876) (86) (10) (7)	1846910		00		0.0
ויסנז	OCT/		128 / ומיטו		0.00		.00		. o	0 8940 SEE LI	יאדני	ರ ಆಗಗ	τ.	O.	UU	V	.00
,,,,VEI	VDI E	TO TO	נויום / לים שונה	LAN CI	40,U/ 19TON	יינגאט. מישו	CONCE	ו מק יבי	. ⊃ N∩	FURTHER REF	- 1 N E- 2 D T 1	משם ס	DU T	EMED.	000000000	200000000000000000000000000000000000000	000000000000000000000000000000000000000
D 40,00					- FIX		INTER			1. OTC ETILLIC STUDE		· ~	·	* * * * * * * * * * * * * * * * * * *	0.00000000	x-90-14-000	90504-nn-60600neoc.250
Original Estimate (Parts & Labor)	Total	Additional		oved By:	Date & T	····	Authoriza	tion '		RDOUS WASTE DISP		DES	CRIP	TION		ТОТ	ALS
(Parts & Labor)	Cost /	Authorized	+				Obtained Telephone			: We have added to cover costs assoc		LABOR A	40U	TV			
\$	*					Ž	Fax (See Attache E-mail (See Attache	hed) \	with t	he handling, manage	ment	PARTS AN	NOU	VT .			
Revised Estimate	\$						Telephone Fax (See Attache	d)		sposal of toxic waste lous substances ε		GAS, OIL,	LUB	E			
☐ Tire press	ura aba	ok/jpfla*!	on eendaa	LWDD DOFFO	rmed	<u></u>	E-mail (See Altec			nia and Federal Law.	.,,,,,,,,,	SUBLET A					
RF	_psi LF		psi RR	psi LR	ps					ALL PARTS ARE NEW				AL COSTS *			
Customer By signing be						od of -	Initials	and the		UNLESS OTHERWISE		TOTAL CH					
Dealership to p	perform	the serv	ices/repai	rs itemized	in this inv	oice and	that you i	received	□ e.	INDICATED. ome Parts Not Returna	hla	LESS INSU		ICE .			
(or had the op	portunit			epiaced par SIGNATURI				DEALERS		PRESENTATIVE SIGNATU		PLEASE			- (100 mm) - (100 mm) - (100 mm)		
- · · · · · · · · · · · · · · · · · · ·												THIS AM					

NATALIA TSEPENYUK

23777 MULHOLLAND HWY SPC 63

CALABASAS, CA 91302-3741

726063

Mercedes-Benz of Calabasas

** PRE-INVOICE *ACCOUNTING*

Authorized Mercedes-Benz Retailer

24181 Calabasas Road Calabasas, CA 91302

PAGE 2

HOME: 818-445-4	730 CONT	:747-388	3-4090				B.A.R.# AC 25	0333	E.P.A#	CAD 9824	86946
BUS:		:747-388	3-4090	SE	RVICE ADVI	SOR:					
COLOR YEAR	MAKE	/MODEL			VIN		LICENSE	MILEA	GE IN	/ OUT	TAG
	MEDGER	G 73773777	~~ ~ ~ .	T.74 TF					. /		L
DEL, DATE PROD.	MERCEDE DATE WARF	S-BENZ (LA 25 PROMISE		5J4GB7PN33 PO NO.	34174	RATE	3893 PAYMENT		3940 INV. D	T756
DEE: DATE: 1110D.	DATE WAIII	ii LAI	THOMISE		FO NO:	.52 : 385 36 3 4863	DATE	A LIVIEIN I		HVV. L	AIR
20FEB24 DD	1	1 0	9:00 06	JAN2	5			CASH	1	7JAN2	5
R.O. OPENED	REA	ADY .	OPTIONS:		LR:05179					<i>,</i> , , , , , , , , , , , , , , , , , ,	<u> </u>
10:48 06JAN25			ļ								
LINE OPCODE TEC		A/HRS S,	/HRS	001/002000210000	3.623.033.033.033.033.033.033.033.033.033.0	koločnobskog s vodev	LIST	N	ΈT		TOTAI
CAUSE: 2175A00' 040041 40		r Croutt	יה היי	וזאנים	ייט אונים				6100200000000 6104060000000000000000000000000		
040041 40 SERV:		E DEKVI	~C - MT	ınou	I IKANS			. In Mile of the continuous too	5.006-01.14000-03 5.006-01.14000-03	90 (100 (100 (100 (100 (100 (100 (100 (1	alledon, luci i rei Siles i specialis
		1.30	1.50	6150	38805	94-9-43-90/9909/9909		388.	ი5	388.	ብ ና
	180-01-0					gungsvag uddou Ginto Haavistad					
	ELEMENT			1021	1750	0	17.50	17.	50	17.	50
	03-01410	6 SEAL									
RING, V			1509/079 1500/7900/7	300	500	0	5.00	5.	00	5.	00
	986-20-0 IELD CLE		Чтэки п	740				_	75		75
The service of the contract of	1610 CPF	e alternative allegation and alternative and a		340	575	0	5.75	5.	75	5.	75
5W30	2020 A O O	0 49 19191		3983	5117	0	7.31	7	31	51.	17
	ASTE OIL	DISPOSA			<u> </u>						- /
				0	210		0.30	0.	30	2.	10
	830-72-0										
	LE FILTE			3709	6200	0	62.00	62.	00	62.	00
	989-56-0	5-09-010		1000	2024		20 24	00			
BRAKE 1	820-98-0	O TS WI		1800	2934	0	29.34	29.	34 ******	29.	34
BLADE	5.2.VV	O SOLDO SOLDINA		3450	5800	0	58.00	58.	ሰሰ	58.	0 0
	PER BLAD	ES - FOI			D LEFT & F	_					
	, REPL.										
14:	TMXW 82	0.00 (0.10		2587			25.	87	25.	87
	titis, vitita rilas itisata katalas tasata	nda dagad dada desempeta era,	200000000000000000000000000000000000000				TPARTS	Maria de la composição de	0106116060696	Pagagaski sebabah dinias	<u> </u>
TEDOTON 1	/ TUNETAL 1 4	00 07 73	TOF 14.				TLABOR	MITT			
<pre>,,,,version 1 ,,,,service as</pre>									DTT	9 15	
,,,,RESET SERV										. فاد	
,,,,FILTER, CA											
,,,,LEVELS UND	ER THE H	OOD.									
E *Maintenance	Plan *C	ampaign	and Re	call:	VIN Repor	?t					
MP MAINTEI			grand garganian and	**************************************		douglas do processoros co	terresense stassense nasounes	5555/955/5055/5 <u>0</u> 27055	9 4 0449999	00000000000000000000000000000000000000	2 2 292235555555333
F *Inspect and	28 IPS			0		mitor	ina Cua		00	v,	00
	Approved By:	Date & Time	Authorizatio	n *1-	AZARDOUS WASTE			IPTION		TOTA	S
Original Estimate Total Additional (Parts & Labor) Cost Authorized	7,	Date 2 11110	Obtained By	<u></u>	osts: We have a	added this	I LABOR AMO		000000000000000000000000000000000000000		···
\$			Fax (See Attached) DE-mail (See Attache		narge to cover costs ith the handling, m			UNT			
Revised Estimate			Telephone Fax (See Attached)	111.	nd disposal of toxic azardous substanc			JBE			
☐ Tire pressure check/inflation	service was north	remed	□E-meil (See Attache		alifornia and Federal		SUBLET AMO	·····	ļ		
RF psiLF ps	iRR psiLF	t psi		_	ALL PARTS ARE	NEW	WASTE DISPO		ļ		
Customer declined tire press By signing below, you acknow	ure check/inflation	n service. were notified of	Initials and authorize	ed the	UNLESS OTHER		LESS INSUR				,
Dealership to perform the service (or had the opportunity to inspect	es/repairs itemized	l in this Invoice a	nd that you re-	ceived r	INDICATED Some Parts Not R		SALES TAX	TINGE			
	TOMER SIGNATUR		 	 	IP REPRESENTATIVE SI		PLEASE PA	Υ	000000000000000000000000000000000000000		
							THIS AMOU		000 10001 0		

726063 Mercedes-Benz of Calabasas

ACCOUNTING

24181 Calabasas Road Calabasas, CA 91302

NATALIA TSEPENYUK 23777 MULHOLLAND HWY SPC 63 CALABASAS, CA 91302-3741

PAGE 3

HOME: 818-4	45-4					051	3) // OF A D) // O D	B.A.R.# AC 250		P.A# CAD 982	486946
BUS:	YEAR			: 747-3 MODEL	88-4090	SEI	RVICE ADVISOR:	1451 QU. LICENSE		AZMIN EIN/OUT	
COLOR	YEAR		IVIANE/	MODEL			VIIN	LICENSE	IVILEAGI	E IIN / OUT	TAG
	22	MEG	ישרשיא	מואים פי	' CT.N 25	พานธ	J4GB7PN334174		30031	/38940	7756
DEL. DATE			WARR		PROMIS		PO NO.	RATE	PAYMENT	/ 36940 INV.	
BEEL BATE	inge.	Projection in the second		10.473 (0.700) (0.00	()10)1110	10 M			espectation.		H-14 N.L. W-
20FEB24 DI	1				19:00 0	6.TAN25			CASH	07JAN	25
R.O. OPEN			REA	DΥ	OPTIONS		R:05179		011011	0,011	
							•				
10:48 06JA	M25	16:	58 0	7JAN25	;						
LINE OPCOL								LIST	NE	T	TOTAL
CARB	Insp	ect	and i	Adjust	: Tire P	ressur	es Reset Tire				
	Moni	tori	ng S	ystem							
	14	28	IPS	0.00	0.00	0	0			0 0	.00
,,,,VERSIC)N 1	(EMI	P# 14:	28,07J	TAN25 14	:10):	38940 TIRES F	RONTS 381	PSI,		
,,,,REARS					_	000 00 1 000 000 0 100 00 00 00 00 00 00 00 00 00 00 00 00		w			
							. a \$74.95 Va			4: 55: 5. 1419 92195 (\$1: 50: 50: 54:	Should Choose to the oil the t
MBI							TION AND TIRE		rse los como destr		
	As and exercise						: MEASUREMENTS	- Jaka Terka na nankahu andiku s	hadilər bili Piliki i vəfi səliləri iz	Majorisi sungalaysa	i Kasifisisi mulay ji jamyosi.
					COUPERS		WASH WHEN				
				COMPLE		I CAR	MYOU MUDM			10000000000000000000000000000000000000	000000000000000000000000000000000000000
500000000000000000000000000000000000000		28			0.00	0	0	toru, soci (ruse, inspet) pediruktoo risebrisebr	0.0	Λ Λ	.00
VERSIO							38940 ÎNSPECT	TON PERF			.00
,,,,INSPEC			505(4 00000 75 00 31 07								butteruseerus betruter (+ ess
H *Complin			ar W	ash							
WASH											
	1.4	28	IPS	0.00	0.00	0	0		0.0	0 0	.00
									to energy therety is the control to the control of	Attivida esta e esta cata cata caraca, con a	
-5050000p000000000000000000000000	1440.44004446	(460660000000000	****	*****		054/410/04/04/04/05/04/05	******	und prouduct for the contract of the contract	****		
ESTIMATE:	and the second) 	a de la composition		06JA	N25 10):48 SA: 1451	usop as as sesses vespulausopalatop	contrate title to the old the abou	daybbi obayb wobyco obycocy	docear boso, code doceaso, s
CONTACT	Paragraphic and the second										
*****	****	****	·***	****	*****	****	****	*****	****	201100001000000000000000000000000000000	krejkokoerenkiekkrike krinkrije
CITCELONEIT	.	NI TO CO		T 🗥 N N T	DD4 M	የ የ ማ እየየደ	OU BOD VITOTET	NO MODORI	DEC DENIG	○ □	
CUSTOMER CREATED							OU FOR VISITI	NG MERCEI	JES-BENZ	OF	
TAKEN BY							HOURS MONDAY	י עמרודסים'	7 • በለ፮Μ ጥ	ነ 7.ሰለፔ	»M
IAKEN DI		, TIN E	7.GOTT1				IS NOW OPEN				
(3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4	400000000000000000000000000000000000000	10/000/10/00/10/00	5,000,000,000,000	000.00000000000000000000000000000000000			ICY 24 HOUR SE				(- 140 140 1 40 140 140 140 140 140 140 140 140 140 1
		M. 100, 100, 100, 100, 100, 100, 100, 100		00.000000000000000000000000000000000000			NOT BE RESPC				N
10.000000000000000000000000000000000000		14.40041 00401 P70001	201701700000000000000000000000000000000	oordaraadaaaa qaraa .ar			ANY AFTERMARK				
DATE	STA	ART	FINI	SH DU	JRATION	TYPE	TECH LINE	(S) CHG			
01-07-25	11:	80	12;	26	1.30	W	1428	D			
	12:	26	12:	34	0.14	DW	1428	В			
	Additional Authorized	Appr	oved By:	Date & Tim	e Authoriza Obtained		ZARDOUS WASTE DISPOS	Jo.		TOT	ALS
8 8					Telephone	11	rge to cover costs associat	ed LABOR AIVIO			
		-			DE-mail (See Atlan	wit	h the handling, manageme				
Revised Estimate \$					□Fex (See Attache □E-meil (See Attache	d) II.	l disposal of toxic wastes ardous substances und	ler 0,10, 012, 20			
☐ Tire pressure che	ock/inflatio	on service	was nerfn	rmed.			ifornia and Federal Law.	SUBLET AMO			
RFpsi LF	r	si RR	psiLR	psi			ALL PARTS ARE NEW	WASTE DISPO			
By signing below, y					Initials	zed the	UNLESS OTHERWISE	LESS INSURA			
Dealership to perform	the servi	ices/repai	rs itemized	in this Invoi	ce and that you	received	INDICATED. Some Parts Not Returnable		ANGE		
(or had the opportunit			epiaced pai SiGNATUR			D DEALERSHI	P REPRESENTATIVE SIGNATURE		v		
						,		PLEASE PA THIS AMOU			

NATALIA TSEPENYUK

23777 MULHOLLAND HWY SPC 63

CALABASAS, CA 91302-3741

Mercedes-Benz of Calabasas

** PRE-INVOICE *ACCOUNTING*

24181 Calabasas Road Calabasas, CA 91302

PAGE 4

HOME:818-445-4730 CC BUS: CE	ONT:747-388-4 ELL:747-388-4		SERVICE ADVISOR:	B.A.R.# AC 250	0333 E.P INTERO J <i>A</i>	A# CAD 982	486946
	AKE/MODEL		VIN	LICENSE	MILEAGE		TAG
	EDES-BENZ CLA VARR.EXP. PF	. 25 W1 ROMISED	K5J4GB7PN334174 PO NO.	L RATE	<u> 38931/</u> PAYMENT	/38940 INV	T756
<u> </u>	33110 HVI	TOMIGED	10000		O CHIVII N		MOUIH MARKET
20FEB24 DD		0 06JAN			CASH	07JAN	25
R.O. OPENED	READY OP	PTIONS:	DLR:05179				
10:48 06JAN25 16:58	07JAN25						
LINE OPCODE TECH TYP		S		LIST	NET	7	TOTAL
		15 D		В			
 Control of the control of the control	n nace regime, received an interest recovers an event was economic ex-	33 D 05 D		B B		10940 (1893 ST-1901 MC5+11881	Ng tag salabahasa sar .
T3; 5#	.a: a.	ע כט	W 1420	D			
ACCOUNT SALE C	COST CO	NTROL	ACCOUNT SAI	JE COS	ST	CONTRO	L)
14430 2050	2050	re to due to de tra e touget une telest			5560	di polionopposione negotapore.	era da a casa da Assa.
14700 17759 17333 210	10620			5117 2173	3983		
- The last of the control of the con	0 *****				0 ****	45.2000 \$460.	
4.4						A. N. M. C. 19999 144, 146 C.	2 (1) (1) (2) (2) (2) (2)
	Mark 1990, 1908, 1908, 1998, 1998, 1998, 1908, 1908	5.102.53.0500085000068		08 4080400401800188888041.88	kusos (500 e5 kessus 1991	descriptions and the	56 860 860 F F F F F F F F F F F F F F F F F F F
< 2000000000000000000000000000000000000	ganynapagg pag ng banas bassasan naasaag bel basaasaa	600500000, 5 00660000, 5006	popularia, volati orniki, mella katulokarnin kupima, thelia teknin	n. Province so servecime simple in sec	sperasesen representators side:	NOTE TO THE SECOND SECTION OF SECOND	r Decembe o medi demokra i
		0.0000.00000000000000000000000000000000		164 1650651 05001065106 164 16601065	000000000000000000000000000000000000000	0.0000000000000000000000000000000000000	
							- and topological processing and services
				19-5121-41219-1-15-51-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1	recent become the		
	COMP TOTALS	2321	3 66528 (*HAZARDOUS WASTE DISPO) 		***	
Original Estimate Total Additional Approved E (Parts & Labor) Cost Authorized		Authorization Obtained By:	COSTS: We have added	this LABOR AMO		TOT	.00
\$	□ Fox (: □ E·mai		charge to cover costs associa with the handling, managem	tea			.00
Revised Estimate	OTetap OFex ()	shone	and disposal of toxic wastes hazardous substances un	Of GAS, OIL, LU			.00
☐ Tire pressure check/inflation service was			California and Federal Law.	SUBLET AMO			.00
RFpsi LFpsi RR	psi LRpsi		ALL PARTS ARE NEW	TOTAL CHAP			.00
By signing below, you acknowledge that	you were notified of and	initials authorized the	UNLESS OTHERWISE INDICATED.	LESS INSURA			.00
Dealership to perform the services/repairs ite (or had the opportunity to inspect) any replace	ed parts as requested by you	ப .	Some Parts Not Returnab				,00
DATE CUSTOMER SIGN	NATURE AUT	HORIZED DEALER	SHIP REPRESENTATIVE SIGNATUR	PLEASE FA		_	
				THIS AMOU	719 1	0	.00

726063

Mercedes-Benz of Calabasas

INTERNAL

Authorized Mercedes-Benz Retailer

NATALIA TSEPENYUK 23777 MULHOLLAND HWY SPC 63 CALABASAS, CA 91302-3741

24181 Calabasas Road Calabasas, CA 91302 (818) 223-3102

PAGE 1

B.A.R.# AC 250333 E.P.A# CAD 982486946 HOME: 818-445-4730 CONT: 747-388-4090 CELL: 747-388-4090 SERVICE ADVISOR: 1451 QUINTERO JAZMIN BUS: COLOR YEAR MAKE/MODEL VIN LICENSE MILEAGE IN / OUT TAG <u>38931/389</u>40 23 MERCEDES-BENZ 25 W1K5J4GB7PN334174 T756 PROD. DATE WARR, EXP. PROMISED RATE PAYMENT INV. DATE DEL, DATE 20FEB24 DD 19:00 06JAN25 CASH 07JAN25 R.O. OPENED READY OPTIONS: DLR: 05179 10:48 06JAN25 16:58 07JAN25 LINE OPCODE TECH TYPE HOURS LIST NET TOTAL A CLIENT STATES WHEN ACCELERATING VEHICLE HAS LACK OF POWER, TEST DROVE WITH SHOP FOREMAN VERIFIED RESISTANCE IN PEDAL FOUND FLOOR MAT WAS PUSHED COMPLETLY UNDER PEDAL PROVIDE CLIENT WITH DRIVER FLOOR MAT ESTIMATE. ENG Engine Diagnosis/Repair IPS 0.00 1428 0.00 0.00 ,,,,38940 DRIVER MAT WEDGED UNDER GAS PEDAL PROVIDED CLIENT WITH ,,,,ESTIMATE. CUSTOMER DECLINED. **************** B CLIENT STATES WHILE DRIVING VEHICLE WILL GO INTO MANUAL MODE ON ITS OWN. CHK and ADV NWP NO WORK PERFORMED 1428 IPS 0.50 20.50 20.50 ,,,38940 UNABLE TO VERIFY CUSTOMER CONCERN ATTACHED SDS & BATTERY ,,,, MAINTAINER. PERFORMED SHORT TEST, NO CODES FOUND. PERFORMED TEST DRIVE ,,,,(TIME OUT 1:34, TIME IN 1:54, MILES OUT 38,931, MILES IN 38,940), ,,,, UNABLE TO VERIFY CUSTOMER CONCERN. NO FURTHER REPAIRS PERFORMED. ***************** C CLIENT STATES WHILE DRIVING VEHICLE DRIVE MODE WILL CHANGE ON ITS OWN GOES FROM COMFORT TO ECO OR ECO TO SPORT MODE. CHK and ADV NWP NO WORK PERFORMED 0.00 0.00 1428 IPS 0.00 ,,,,38940 SEE LINE B SEE LINE B. UNABLE TO VERIFY CUSTOMER CONCERN. NO ,,,, FURTHER REPAIRS PERFORMED. ******************** E *Maintenance Plan *Campaign and Recall VIN Report MP MAINTENANCE PLAN 0.00 1428 IPS 0.00 0.00 ********************** *Inspect and Adjust Tire Pressures Reset Tire Monitoring System CARB Inspect and Adjust Tire Pressures Reset Tire Monitoring System IPS 0.00 0.00 0.00 1428 ,38940 TIRES FRONTS 38PSI REARS 34PSI *HAZARDOUS WASTE DISPOSAL COSTS: We have added this Original Estimate (Parts & Labor) TOTALS Total Additional Cost Authorized DESCRIPTION Approved By: Date & Time Authorization Obtained By: LABOR AMOUNT Telephone Fax (See Allsched) charge to cover costs associated with the handling, management PARTS AMOUNT E-mail (See Attached) Revised Estimate and disposal of toxic wastes or GAS, OIL, LUBE hazardous substances under SUBLET AMOUNT California and Federal Law. Tire pressure check/inflation service was performed. WASTE DISPOSAL COSTS RF____psi LF___psi RR___psi LR___r
Customer declined tire pressure check/inflation service. ALL PARTS ARE NEW **TOTAL CHARGES** Initials **UNLESS OTHERWISE** By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this Invoice and that you received LESS INSURANCE INDICATED. Some Parts Not Returnable SALES TAX (or had the opportunity to inspect) any replaced parts as requested by you. CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE **PLEASE PAY** THIS AMOUNT

726063

Mercedes-Benz of Calabasas

INTERNAL

Authorized Mercedes-Benz Retailer

24181 Calabasas Road Calabasas, CA 91302 (818) 223-3102

NATALIA TSEPENYUK 23777 MULHOLLAND HWY SPC 63 CALABASAS, CA 91302-3741

HOME: 818-445-4730 CONT: 747-388-4090

PAGE 2

B.A.R.# AC 250333 E.P.A# CAD 982486946

<u>20.5</u>0

BUS:		CI	ELL:747-	388-4090	SE	RVICE ADVISOR:	1451 Qt	JINTERO	JAZMIN	
COLOR	YEAR	N	IAKE/MODEL			VIN	LICENSE		GE IN / OUT	TAG
	23	MERCI	EDES-BEN	Z CLA 25	W1K	5J4GB7PN334174	Ŀ	3893	1/38940	T756
DEL. DATE	PROD.	DATE V	/ARR, EXP.	PROMIS	ED	PO NO.	RATE	PAYMENT	INV.	DATE
20FEB24 DI	1			19:00 0	SJAN2	5		CASH	07JAN	25
R.O. OPEN	IED		READY	OPTIONS	6: D	LR:05179				
10:48 06JA	M25	16:58	3 07JAN2	5						
LINE OPCOL	E TE	CH TY	E HOURS				LIST	' N	ET TO	TAL
G *Complin	nenta	ry Mu	ltipoint	Inspect:	ion .	a \$74.95 Va	ılue			
						CTION AND TIRE				
	INFL	NOITA	SERVICE	. SET AL	L TIR	E MEASUREMENTS	}			
	TO M	ANUFA	CTURE SP	ECIFICAT:	ION					
	LF	RFLI	RRR	COURTES	Y CAR	WASH WHEN				1900 000 0000 000
	REPA	IRS A	RE COMPL	ETED.						
			9S 0.00					0.	00 0	.00
,,,,38940	INSP	ECTIO	N PERFOR	MED INSP	ECTIO	N				
	and the second section of the second	tra transfer i atribit. All it		****	****	*****	*****	***		
H *Complin	nenta	ry Car	c Wash							
WASH	COUR	TESY V	Vash							
	14	28 II	PS 0.00					0.	00 0	.00
	*	****	******	*****	****	******	******	***		
*****	****	****	******	*****	****	******	(*****	****		
ESTIMATE:	0.00			06JA	N25 1	0:48 SA: 1451	<u>L</u>			
CONTACT										
******	****	****	*****	****	****	*****	*****	****		
								34111381383133814631430 3.0038138138138		
CUSTOMER					HANK	YOU FOR VISIT	ING MERCI	EDES-BEN	Z OF	
CREATED					ALABA					
TAKEN BY	Z GAV	IN AGU	JILAR			E HOURS MONDAY	 10.00 (10.			
						E IS NOW OPEN				PM
						NCY 24 HOUR SE				o tanna ang malana ang ang ang ang
						L NOT BE RESPO				
201002000000000000000000000000000000000	100.000.000000000	50000000000000000000000000000000000000	000000000000000000000000000000000000000	C	AR OR	ANY AFTERMARI	CET PRODU	JCTS IN	YOUR CAR	• • 0000000000000000000000000000
prodebuteletoschole ecotolicite in	0.000.000.00.000.000.000.0000.0000.0000.0000		: ont 100 100 01 100 000 000 000 000 000 000	gnocco -not sessonit sitt eucocco in	1004x -00-00000000	uern roombong managnam usanni apagnaanni soomosa	10000000011000060000000000	c 55,560-41,050-55611115-665146	40-550 etti viitti vatti asaas saasi saas	00000 0000000 10000000 1100001
					851780765080					
\$1000000000000000000000000000000000000		teeconomic encuences	5,2140-46, 7581165,235523189556	egerayda sepera masayi ngaly ni sekile.	p to cortigo de couperous	Negovije og utilske grodik kalendarisk for medde for	KO 150 OBON JARSENSONA OBOU 1999A	PLUIDIS INNOTIUNIS INNOTIUNIS		niseokoloisuu totak cuuton.
100.000.000.000.000.000.000.000.000	50650,050,050	NASSAGE SET SEGS (SESSA)	866163518181818181151818185518181818	5.2518151818181818181818181818181818181	8888888888888888		ann ang sasahasan at saansaan ka saa	rouinser sonstweetingsteping		National Section Courts
~~~										
COST			COMP TO		2050		100000000000000000000000000000000000000		1 (000000000000000000000000000000000000	
	Additional Authorized	Approved	By: Date & Tir	ne Authorizat Obtained		AZARDOUS WASTE DISPOS DSTS: We have added to	L.J.a.	RIPTION	TOT	
, ,				Talsphone Test (See Allsohe	di ch	arge to cover costs associa	ted LABOR AIV			.50
	□ E-mail (Sae Attached)					th the handling, managem		······································		.00
Revised Estimate				Fex (See Attache	dì <b>ii</b> .	d disposal of toxic wastes zardous substances un	der CAO, OIL,			.00
☐ Tire pressure che	ack/inflatio	n service wa	s performed		117	ilifornia and Federal Law.	SUBLET AN			.00
RFpsi LF	:p	si RA	psi LRpsi			ALL PARTS ARE NEW	<u> </u>	OSAL COSTS *	<del>                                     </del>	.00
Customer decline				Initials		UNLESS OTHERWISE	TOTAL CHA			.50
By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this Invoice and that you received						eceived —		RANCE		.00
(or had the opportunity to inspect) any replaced parts as requested by you.					<u> </u>	Some Parts Not Returnab			1 0	.00
DATE	CU	STOMER SIGI	NA TURE	AUTHORIZED	DEALERSH	IP REPRESENTATIVE SIGNATURI	PLEASE P			
							THIS AMO	IWU	1 20	.50

726063

## Mercedes-Benz of Calabasas

*WARRANTY*

Authorized Mercedes-Benz Retailer

NATALIA TSEPENYUK 23777 MULHOLLAND HWY SPC 63 CALABASAS, CA 91302-3741

PAGE 1

24181 Calabasas Road Calabasas, CA 91302 (818) 223-3102

HOME:818-445-47	30 CONT	:747-388	3-4090			B.A.R.# AC 25	0333 E	E.P.A# CAD 9824	86946
BUS:		:747-388		SE	ERVICE ADVISOR:	1451 QU	INTERO S	JAZMIN	
COLOR YEAR	MAKE/	MÖDEL			VIN	LICENSE	MILEAC	SE IN / OUT	TAG
					<u>5J4GB7PN334174</u>				T756
DEL, DATE PROD. E	DATE WARR	EXP.	PROMISI	ŧD	PO NO:	RATE	PAYMENT	INV. C	AJE
0.000004 DD		1,	2.00.00	. TX NTO	ا سر		CASH	07JAN2	_
20FEB24 DD R.O. OPENED	l BEA	.DY	9:00 06		LR:05179		САБП	U/UAINZ	<u></u>
INO OF LIVED	1140	Uration in the second	OI HONG	• 1	VIK:05175				
10:48 06JAN25	16:58 0	7JAN25							
LINE OPCODE TEC			<del> </del>			LIST	' NI	ET TOI	'AL
D 40,000 MILE S	BERVICE	- FIXED	INTERV	/AL					
CAUSE: 2175A007	FG FG				nament as made made of the section (6.5). (6.5)		nor control of a recent of the second	ur rii i maa maar waxaan aan aan waxaan	
040041 40,	000 MIL)	E SERVI	CE ~ WI	THOU	T TRANS				
SERVI	<del> </del>								
	R WXMT						388.		
	80-01-0				EMENT	17.50			
	3-01410				DANIENG AGENTS	5.00			
					EANING AGENT	5.75 7.31	5.	75 5. 31 51.	75 4 <del>2</del>
	989-10-0: ASTE OIL			<i>)</i>		0.30			
	330-72-0:			.च च	מישית ז	62.00		00 62,	CONTRACTOR OF THE PLAN. THE ST.
	989-56-0					29.34			
	320-98-0					58.00			
					D LEFT & RIGHT				
	REPL.								
		0.10					25.	87 25.	87
					603 22876				
AMARIA ANTARA SANTA	000000000000000000000000000000000000000	551516066666666666666666666666666666666	450000000000000000000000000000000000000			2 TLABOR		000000000000000000000000000000000000000	909088889999999999999
,,,,38940 PREPA	AID 40,0	00 MILE	SERVI	CE AS	PER CUSTOMER	REQUEST,			
,,,,PERFORMED I	PREPAID	40,000 1	MILE SI	ERVIC	CE. RESET SERVI	CE INDIC	CATOR & '	PIRE	80008080808080
,,,, PRESSURE MO	ONITORS.	CHANGE	D OTT (	X OTT	FILTER, CABIT	V FILIER,	MTPEK		
,,,,BLADES, & F	SKAKE FL	01D, CO.	******* KKECTEI	) FLU	**************************************	********	/UD. :★★★		
							dejā aktūrēšeje saitus un tekst n		8.0000000000000000000000000000000000000
**********	*****	*****	*****	****	*****	·******	****		
ESTIMATE: 0.00		0.000,000,000,000,000,000,000,000,000,0		en in de la company de la comp	0:48 SA: 145				
CONTACT:									
******	*****	*****	****	****	*****	*****	****		
					nnannann eile eile eile eile eile eile eile ei		sanda daka dikacaka di Japac da Japac	es su turou una constituint de dos fois se	diference of the concepts
54444 (100 to 100 to	rentaeapaan, taat tat saantaan e		000000000000000000000000000000000000000	ekiserservaturais		444,000,000,000,000	entenytuknekinebikokintitabi k	008/02014/888886048888868486	9888635184584595545.56.1
				os jirskis sersest			5878/1088/1388/1880 A080		Sections of the sec
		D	Authorizat	- 1. ¥1	HAZARDOUS WASTE DISPO	SAI DECC	RIPTION	TOTA	ıç
Original Estimate Total Additional (Parts & Labor) Cost Authorized	Approved By:	Date & Time	Obtained E	3y: c	OSTS: We have added t	his LABOR AM		1.8.179	<b>"</b> .
\$ \$			Telephone  Fax (See Atteched  Fax (See Atteched	, c	harge to cover costs associa vith the handling, managem	ted			
Revised Estimate			□Telephone □Fax (See Atteches	а	nd disposal of toxic wastes	or GAS, OIL,			
8 8			DE-mail (See Attacl	hed) [N	azardous substances un alifornia and Federal Law.	der SUBLET AN	MOUNT		
Tire pressure check/inflation				F		WASTE DISI	OSAL COSTS *		
RFpsi LFpsi Customer declined tire press	i RRpsi LR :ure check/inflatior		Initials		ALL PARTS ARE NEW UNLESS OTHERWISE	TOTAL CH	ARGES		
By signing below, you acknow Dealership to perform the service	rledge that you	were notified of	and authorize	ed the	INDICATED.	LESS INSU	RANCE		
(or had the opportunity to inspec	t) any replaced pa	rts as requested	by you.		Some Parts Not Returnab		(		200000000000000000000000000000000000000
DATE CUS	TOMER SIGNATUR	ΙE	AUTHORIZED	DEALERS	HIP REPRESENTATIVE SIGNATUR	E PLEASE P			
						I IIIIS MIVIC	/ V   T		yanata utu utuf addiri 2006/2009/20 Nanata Indonesia Nata Cotu

#### 726063

## Mercedes-Benz of Calabasas

*WARRANTY*

Authorized Mercedes-Benz Retaller

24181 Calabasas Road Calabasas, CA 91302 (818) 223-3102

NATALIA TSEPENYUK 23777 MULHOLLAND HWY SPC 63 CALABASAS, CA 91302-3741

PAGE 2

HOME:81	18-44	15-47	30 (	CONT:74	7-388	8-4090				ı	3.A.R.# AC 2	25033	3 E.P.	.A# CAD 98:	2486946
BUS:				CELL: 74			SE	RVICE	<b>ADVISO</b>	)R:	1451 Q	UIN	TERO JA	ZMIN	
COLOR	1	YEAR		MAKE/MOD	EL			VI	N		LICENSE		MILEAGE	IN / OUT	TAG
		23	MERO	CEDES-B	ENZ (	CLA 25	W1K	5J4GB	7PN3341	.74			38931/	38940	T756
DEL, DA	ΤE			WARR, EXP		PROMIS			PO NO.		RATE	F	AYMENT		DATE
20FEB24	1 DD				1:	9:00 06	JAN2	5					'ASH	07JAN	125
	OPENE	D		READY		OPTIONS		LR:05	179						
10:48 0	)6:TAI	vi25	16:	58 07 ₀ TA	N25										
LINE OF											LIS'	T _	NET	TC	TAL
				ED A LO					OR VISI	LTIN	G MERC	EDE	S-BENZ	OF	
		e eur e europe europe eur autorité	Harana references to on	2 4 12: BUILAR	46:0		ALABA		RS MONE	ΑΥ-	PRIDAY	7,	OOAM TO	ን 7 • በሰፑ	Ν
	,	- WA W. Y	AN BURGERY	ga bar panjangan ayan wiji.	oprocessor recipients								:00AM T		
													0-367-6		
	s ex secolees (S Secolees )			dolf, dolffer fed. Med file Profes reported as a factor									R ITEMS PS IN YO		
***************	55-455-5155-5611	20110-200-20010-20	source rote, to	utoscocou ocu duc ruscusc						Some start at		910x 11x 10x	to be took economic and acres		
	eetrospeteetro 81,400,01985	y - 1931 1975 198 11 1831 1988 198										de 1000 100100			
					00,000,000,000							100000000 100000000		00.000	
												1000000000			
					4.4.4.684.63	353 82 5 12 13 13 13				90,803,30					
600000000000000000000000000000000000000		01 00 100 100 100 100 100 100 100 100 1			9000000 (110000 Sjiring (1860-1860)					eliteitusi seitti					
								1000.10.000.10.000							aditar partition
												30,00			
			- He - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -												
	801100000000000000000000000000000000000											1000 100			
200000000000000000000000000000000000000	55455551500000	950.000.000.000	udocustos vis	551555645551555555555	101110.001 x 0100		1200001 289022400		ander experience of the second		prija praca gradovnog.	noonnoogo	ornes repensiveser les societés	pus pagengring and commes	
(	COST	CΔT	·F'	& COMP	מידי∩ידי.	T.G '	21163	64	478	0		80000			
Original Estimate	Total A	dditional	Арргоч		& Time	Authorizati Obtained B	on *H	IAZARDOUS	WASTE DI	ISPOSAL	DES	CRIPT	ION	тот	ALS
(Parts & Labor)	\$	athonised	-			Telephone	n ch	arge to co	have adde ver costs ass	ociated	LABOR AN			<del></del>	3,92
Revised Estimate	, 					□E-meli (See Attaci	will will ar		ndling, mana I of toxic wa		GAS, OIL,				3.76 ).00
\$	\$				·	□Fax (See Attached □E-mail (See Attach	ha ha	zardous	substances	under	SUBLET A				).00
1 '				vas performed.	1				d Federal Law		WASTE DIS			······································	2.10
Customer	psi LF_ r declined	psi   tire pressu	ire chec	psi LR_ k/inflation servic	_psi e.	Initials			ARTS ARE NEV S OTHERWIS		TOTAL CH				.78
By signing be	low, you	u acknow!	edge th	at you were r itemized in this	otified of			IN	DICATED.		LESS INSU		CE		0.00
				laced parts as r			L	ے Some Pa	årts Not Retur	rnable	SALES TA	X		21	73

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

PLEASE PAY THIS AMOUNT

666.51

CUSTOMER SIGNATURE

DATE

LOANER

726063

### Mercedes-Benz of Calabasas

Authorized Mercedes-Benz Retailer

WORKORDER

24181 Calabasas Road Calabasas, CA 91302 (818) 223-3102

NATALIA TSEPENYUK 23777 MULHOLLAND HWY SPC 63 CALABASAS, CA 91302-3741

PAGE 1

HOME:818-4	45-4	730	CONT:747-	388-4090			B.A.R.# AC 2	50333 E.F	.A# CAD 9824	86946
BUS:			CELL:747-	388-4090	SER\	/ICE ADVISOR:	1451 JA			
COLOR	YEAR		MAKE/MODEL			VIN	LICENSE	MILEAG	E IN/ OUT	TAG
	22	NATE TO		7 01 7 05	T.71 TZC T /			20021	1789411	mn c c
DEL DATE	PROD		CEDES - BEN WARR, EXP.	Z CLA 25 PROMIS	<u> </u>	IGB7PN334174 PO NO.	RATE	38931 PAYMENT	INV. DA	T756
	111000							AND TOWN INICIA CO.	- In a sile of this	N.) 16.000 1.000 1.000
20FEB24 DD				19:00 06	JAN25			CASH		
R.O. OPEN	IED	e dixe	READY	OPTION	S: DLR:	05179				
0.5.7770.005										
06JAN2025 LINE OP CC		ष TECH	TYPE		TONG /TA	ISTRUCTIONS				
# A ENG	מעו	TECU	IPS			HEN ACCELER	ATING VE	HICLE HAS	TACK OF	7.0000000000000000000000000000000000000
nosassoneater so	A17117-115-116	HIPPI - 11 - 12-14-				OVE WITH SHO				e de tracellar basa que
						PEDAL FOUND				
			and the second of the second of			R PEDAL PROV	IDE CLIE	NT WITH D	RIVER	
	PAREL PA	4.1) 191		FLOOR MA	T ESTIM	ATE.				
	PSB HATA	ea Sepale			and the state of t		Beginskiperije			janya a ka
	to merkinin	1 8664 (2 ), 2 (1 2	BARRA TANDI		a madeki dalam				halan di iliba yang T	er slær i sette.
# B TRANS			W107	CLIENT S	TATES V	HILE DRIVING	G VEHICL	E WILL GO	INTO	
***************************************	noracouco accua	1.000.000000	un tagu utan uta utan ku ka ka ka ka	MANUAL M	ODE ON	ITS OWN. CH	K and AD	V	10	
									, , ,	)
	100014200140114	lacedostatata			Notale adecatos de	National construction of the state	Bado (1869) (1869) (1860) (186		<b>200</b> 0 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 -	
# C TRANS	ariaithith airdi L	iddindi kerdiki.	W107	CLIENT S	TATES V	HILE DRIVING	G VEHICI	E DRIVE M	ODE: WILI	
7 1 0 9			70	>CHANGE C	N ITS (	OWN GOES FROM	M COMFOR	T TO ECO	OR ECO 1	ro
100			30	SPORT MC	DE. CH	and ADV				e 1711,0111 111,
413 6:	5		#11 #159							
Consessor various construction	aBüta Hirak	g collection or	Parada da mendebag milatak di	anskrije sina langgara in	unsas. 1 cultura	n de gradajski i gregorije i 1900. godine. Stati	+ 15 E.S.d.:	dali Toldali vi inselan Satebere.	arta udeka tatu ikin	1111
# D 04004	n		WXM	40,000 M	ITIE CEL	RVICE - FIXE	D INTERV	Hadisə Gələriya TAT.	1 1965 A.S. 1995	
п D 01001		uebuteštuebute Score Societius	14771.1	40,000 F	TTE DET	(VICII - FIXE	D THIERA	Au Tijst Harris		
400000000000000000000000000000000000000	30 30 3 40 3 40 0 3 40 A	ontuc komo, tok		5-6765 #61755656#65715665 #646555	oners de preseue environde see. •	adada atu bau Prance e e Care e e e	Fill Records in All Presents	region for feed their place (60 LCDS) is	1709 S. 3400501 FN 19805	REPORT BUILDING GA
#E MP	378086000000000	6.1 40000066.UT	${\tt IPS}$	*Mainter	ance Pl	lan *Campaig	n and Re	call VIN	Report	n da sa
	idan siyalikan	ie viespiepie i							58.88.980.5-578.77	
BY LAW, YOU MAY	CHOOSE /	ANOTHER	LICENSED SMOG C	HECK FACILITY TO	PERFORM ANY	PARTS: All parts are new	unless otherwise	Indicated. Remanufac	tured and refurbis	shed parts that
NEEDED REPAIRS OR A	ADJUSTME MBLY: If	NTS WHI you auti	CH THE SMOG CHEC norize teardown of	K TEST INDICATES A the vehicle or cor	RE NECESSARY imencement of	PARTS: All parts are new meet manufacturer approve information is available up	ed source part request. You re	ulrements may be inst may inspect all parts	alled at our discret removed from the	tion. Additional e vehicle upon
repairs, but do not a teardown, reassembly	uthorize c	ompletion	of a repair or serv	/ice, a charge may	be imposed for	warranty arrangement and	they are not exem	ium the parts to the m	anutacturer or dist	tributor under a
It is necessary to disa teardown and reassen	ably chard	a linchudir	an narte and labort ic	4	. The estimated	returned to you upon reque		ble 🔲 Please Save Re	placed Parts	
The maximum time to	r reassemi	biy will be	• X			ESTIMATE: PLEASE CH INITIALING BESIDE ONE	OF THE FOLLOW	D OF ESTIMATE Y	OU WANT TO	RECEIVE BY
You understand that X						CONTACT YOU IF NECE	CCVBA	ORAL ESTIMATE		
SUBLET REPAIRS	: Some re sed upon r	epairs mu equest.	st be sublet due to	the type of service	e required. The	By Telephone at:		By Fax to	);	
PAYMENT TERMS: I (unless the Dealership	agree to	pay for a	all labor and materia	ils in <u>Cash</u> or appro	ved credit card	By E-Mail to:	DELIMINADO E	STIMATE \$		
delivery of the vehicle up. An express mecha	to me or	3 days af	ter receiving notice t	hat the vehicle is rea	dy to be picked	DESIGNATION	OF PERSON TO A	UTHORIZE ADDITIONA	L WORK OR PAR	TS.
materials, storage and will be assessed and s	/or towing hall accru	charges e daily if	. I underständ that a I fail to pick up the v	storage charge equi rehicle within 3 days	al to \$ from the date	I hereby designate the indi- not included in the original	vidual named below written estimated p	to authorize any addi price for parts and labor	tional work not sp	ecified or parts
am notified that the r	epairs hav	e been c	ompleted or after th	e communication of	an estimate if					
POWER-OF-ATTORNE sign my name upon	Y: I hereb	γ appoint	the Dealership as m	y attorney-in-fact an	d authorize it to	Name of Designee: Fax Number: Customer: Diginal Estimate Total Adv		E-Mail Address:		
Repair Order, X	uniy olista	uiaits	O OTHER TOTALS OF	payment issued in f	zavinent of this	Original Calimata Tatal Ad	ditional Acord	Date:	· · · · · · · · · · · · · · · · · · ·	

Original Estimate (Parts & Labor)

Revised Estimate

Total Additional Cost Authorized

Approved By:

acknowledge notice and oral approval of an increase in the original estimated price.

Date & Time

Authorization Obtained By: □ Telophons □ Fex (See Attached) □ E-me≩ (See Attached)

NATALIA TSEPENYUK

23777 MULHOLLAND HWY SPC 63

726063

## Mercedes-Benz of Calabasas

Authorized Mercedes-Benz Retailer

WORKORDER

24181 Calabasas Road Calabasas, CA 91302 (818) 223-3102

CALABASAS,	LABASAS, CA 91302-3741			P	AGE 2		(818) 223-3102				
HOME:818-4	45-4	1730	CONT • 747 -	388-4090			В.А.	R.# AC 25	60333 E.P.	A# CAD 9824	86946
BUS:	10 1		CELL: 747-		SER'	VICE ADV	'ISOR: 14!	51 JAZ	rning, mimz	ERO	
COLOR	YEAR		MAKE/MODEL			VIN		LICENSE		E IN/ OUT	TAG
			annea mmi			. ~				,	
DEL DATE	PROD		CEDES - BEN WARR, EXP.	Z CLA 25 PROMIS		4GB7PN33 PO NO		ATE I	38931/ PAYMENT	INV. DA	T756
	111,55			.,,,,,,	<del>. S</del> emmenta			78,10 Haydag ( a. 1 a.	E DALIMENS	1144	ente a compresso
20FEB24 DD				19:00 06					CASH		
R.O. OPEN	IED		READY	OPTION	s: DLR	:05179					
06JAN2025	10:4	ı g									
LINE OP CC		TECH	TYPE	DESCRIPT	IONS/I	NSTRUCT	CONS				
# F CARB			IPS	*Inspect	and A	djust T	lre Pres	sures	Reset Tir	e ·	
78844.088844.0888.0EF	8848 80 80 80 A	198998; 1441	Sekin Guig Catalan et	Monitori	ng Sys	tem		antei tuikin lääteesusti		47784.x0000xth (8.5x.)	
			Cillo selainisteiroi							ini magrapasa ayaga	
# G MBI	1590594948671	say waxaa sa	IPS		entary	Multipo	oint Insp	pectio	on a \$	74.95	Andrew States
	498498			Value	9 8 80 80 80 80 80						
										145748. G.K.S.	Anglia Jag
Lividuating tends to the section of	1901 4.54019-00		per a compliana cuerto e la comunicación		and continues there are					A CONTRACTOR OF THE CONTRACTOR	
# H WASH			IPS	*Complim	entary	Car Was	3h				
******	***	****	******	*****	*****	*****	*****	****	****		
wood (notice) manager.			radietrie de la redicta made	debendader in her buik 10kmb blank i i b	entra de la compansión de	ber in right frauens in	elel e melludeler	ng tinak na Italia Ingli	To TREASON ASSESS NO ANNESSYN	-ddgdau it easyjnyanjarja jir	
Preliminar	у Ея	stima	te : \$0.0	0							
*******	****	****	*******	*****	*****	******	*****		. 4 4 4 4		365308606-0404640
200.0000 00000 000000000000000000000000	.89509079.9.60	0.0000000000000000000000000000000000000	Rood seit til til seit och til til til sette sett och til til til sette sett och til til til sette sette sette	58 JB 51 (100 ) 8 686 6 Un AUG 60 646 6 656 7 107 1	1944-996611:07 :1661Mb				tranta (franche ffin die Radoadaan indic		
			Maria Maria, i e urana des cares se es		Jangara amerikkan	99001198644818944.		urteatika tubatea.	1949: Tuekoka Historikusiki	t kototo estas soci	og kjelog kjelog
7007000700070070000000000	48871 (304) 8025	otoriko uskul		3560 N 368 SASTA SSASSA - 1 1064 90		d wassessed a stack					
	gp-p-agentut	sangga ji ugawa	Na sudikida ni karanda		horback consistence	. 11. 33.40 38.31 19 kg :	9 6 9 21:	nu in Referense as	11 - 41 personal del 20 del 20 del 176 / 106	nter tederalinea in in itali	grown gargary
		, Chilerto Pro-			a Teate Mad			i. diskir			
BY LAW, YOU MAY O	CHOOSE	ANOTHER	LICENSED SMOG C	HECK FACILITY TO	PERFORM AN	y PARTS: All pa	rts are new unless	otherwise is	ndicated, Remanufactu rements may be instal	red and refurbis	hed parts that
TEARDOWN/REASSEI repairs, but do not a	ViBLY: If	you auth	norize teardown of	the vehicle or com	imencement o	of information is	available upon regi	uest. You ma	ay inspect all parts re rn the parts to the mai	emoved from the	vehicle unon
teardown, reassembly It is necessary to disa	or partial	lly complet	ted work and you ago	ree to pay the same.	•	warranty arrang	gement and they are	not exempt	due to their size, weig	tht or other factor	s, they will be
teardown and reassem The maximum time fo	ably charc	ne tincludir	or narts and lahor) is	s .	. The estimate		Some Parts N	ot Returnabl THE KIND	e Please Save Rep OF ESTIMATE YO	laced Parts	RECEIVE RY
You understand that	disassemi	bly may p	revent restoration of	the vehicle to its fo	rmer condition	INITIALING BE	SIDE ONE OF THE	E FOLLOWIN	NG CHOICES AND IN	IDICATE THE BE	EST WAY TO
SUBLET REPAIRS:	Some r	epairs mu	st be sublet due to	the type of service	e required. Th	WRI	TTEN ESTIMATE		ORAL ESTIMATE _ By Fax to:	ELECTI	RONIC EST.
location will be disclos PAYMENT TERMS: I	agree to	pay for a	all labor and materia	ils in <u>Cash</u> or appro	ved credit car	d By E-Mail to:	5 Q(1		IMATE \$		
(unless the Dealership delivery of the vehicle	to me or	3 days af	ter receiving notice t	hat the vehicle is rea	dy to be picke	d			TIMATE \$THORIZE ADDITIONAL		
up. An express mecha materials, storage and will be assessed and s	/or towin	ig chargès.	I understand that a	storage charge equa	l to \$	, 1			to authorize any additional to authorize any additional to a control and a control and to a control and to a control and to a control and a control		
am notified that the refail to authorize repairs	epairs har	ve been co	ompleted or after the	e communication of	an estimate if	Name of Design	nee:		Phone Number:_		
POWER-OF-ATTORNE sign my name upon a	Y: I herek	by appoint	the Dealership as my	y attorney-in-fact and	authorize it t	n Fax Number:			E-Mail Address: Date:		
Repair Order. X  By Signing Below: I ag				•	•	101111	Total Additional	Approve		ne Auth	orization
the services/repairs list Dealership is not respo	sted abov	ve in acco	ordance with the te	rms and conditions	herein: (2) th	e	Cost Authorized				ined By:
of fire, theft, hail, win vehicle on streets, hig	d or anv	other caus	e beyond its control:	: (3) the Dealershin n	nav operate th	أام	\$			CTS E-Mail (299 t	Attached)
vehicle; and (4) I auth and the sharing of that	norize the	e retrieval	of on-board data as	needed to facilitate	vehicle repair	S \$	\$			Telephone Fax (See Atti	eched) Attached)
_					, ,	]] acknowledg	e notice and ora	approval	of an increase in th	e original estin	nated price



# Vehicle Master Inquiry (VMI) FOR INTERNAL USE ONLY

Dealer : 05179

VIN:W1K5J4GB7PN334174

VIN:

W1K5J4GB7PN334174

Owner:

NONE

Engine No: 26092030459798

FIN:

W1K1183461N334174

**Transmission** 

72403302012042

Vehicle Info

Model/Year: CLA 250 2023

Upholstery: 651 -Black MB-Tex / Microfiber w/ Red

Paint:

696 -Night Black

Stitching

Warranty & Sale

Warranty Start:

11/29/2022

**Retail Date:** 

11/29/2022

Selling Dealer:

05146

**Production Info** 

Radio Code:

Serial No:

**Prod Date:** 

08/02/2022

Status: 0-NORMAL

Status Need Authorization Mileage Discrepancies

Warranty < 30 Days

Review History

#### Informational Status

Status Code	Status Description
	Vehicle eligible for extended emissions coverage based on the retail state, if an emission part is listed in the Serv & Warr booklet and shows not covered, open a OneTrac case.

Service Packages

Type	Description	Start Date	End Date	Miles Fm	Miles To	DLR or GEN	Contract #
MBFS	INTERIOR & EXTERIOR	12/30/2023	12/30/2030	0	999999		7392
MBFS	Paintless Dent Repair	12/29/2023	12/29/2027	0	999999		0057029911
MBFS	PLUS FIRST CLASS WHEEL & TIRE	12/29/2023	12/29/2027	0	999999		0057029912
MNT	STR PPMSC-3 Services - 3 Service Used Car PPM (For 2009 and later model years)	12/29/2023	03/28/2027	9129	44129	05146	6894092
MBFS	First Class Lease Protection	12/29/2023	12/29/2027	0	999999		PE12372768

Ontion Codes

Option			
Option	Description	Option	Description
-CA		A17	
AA5		B09	
B51	TIREFIT KIL	B59	DYNAMIC SELECT
D07	Wheel Locking Bolts	D16	LED Logo Projectors
D49	First Ald Kit	DA3	Parking Assistance Package
DC1	Night Package	DG3	AMG Line Package
DP1	Premium Package	F118 ·	
FC		G033	
GA		H45	Aluminum Linear Grain Trim
HA		K15	
K38		L,	
L5C	Multifunction Sport Steering Wheel	M20	
M260		P17	KEYLESS-GO Package
P47	Surround View System	P49	Mirror Package
P55	Night Package	PVH	
R01	High Performance Tires	R7K	
RVK	19" AMG Multispoke Wheels, Black	SAB	
U10	Passenger Seat Weight Sensing System	U22	4-Way Lumbar Support
U26	AMG Floor Mats	U55	Black Exterior:Spare Tire Carrier
U59	Seat comfort package	U62	Light & Sight Package
US3N		VL	
VR		12B	Owners Manual
132		14U	Smartphone Integration



# Vehicle Master Inquiry (VMI) FOR INTERNAL USE ONLY

Dealer: 05179 VIN:W1K5J4GB7PN334174

Option	Description	Option	Description
163		166	•
16U	Apple CarPlay™	17U	Android Auto
1B4		1S6	
1V8		213	Parameter Steering
232	Garage Door Opener	234	Blind Spot Assist
235	PARKTRONIC with Active Parking Assist	242	Passenger Seat Memory
249	Auto-dimming Driver and Rearview Mirrors	258	Active Brake Assist
264	License Plate Holder	270	GPS Antenna
273	Vehicle Exit Warning	275	Power Driver Seats with Memory
286	Luggage nets on back of front seats	287	Split-Folding Rear Seats
294	Driver Knee Airbag	310	Twin Cupholders
342B		345	Rain Sensor Wipers
34U	Remote Services Premium	351	eCall-Emergency System
355	Extended MBUX functions"	362	HERMES Communications module LTE
367	Live Traffic	37U	Remote Services Advanced
3U7		400	Rear Center Arm Rest
413	Panorama Sunroof	429	7-Speed DCT
431	Galvanized Shift Paddles	440	Cruise Control w/o speed limiter
446	Touchpad	458	10.25" Instrument Cluster Display
461	English Inscriptions	475	Tire Pressure Monitoring System
494	USA specification	4B8	USB adapter cable
500	Power Folding Mirrors	501	Surround View Camera
517	HD Radio	51U	Black Headliner
536	SiriusXM Radio with Free Trial Period	543	Double Sun Visors
548	MBUX Multimedia System	551	Anti-Theft Alarm System
581	Dual Zone Climate Control	632	LED Headlamps
634	Omission of first-aid kit	636	Omission of Warning Triangle
650A		651A	
668	Sea Packing & Dispatch	677	Lowered Comfort Suspension
696U		6P5	
6U0		705L	
763	Remote Key with Panic Button	772	AMG Body Styling
7U3	Sport Seats	7XXL	
803	Technical modifications	859	10.25" Center Display
871	HANDS FREE ACCESS	873	Heated Front Seats
877	Multi-Color Ambient Lighting	889	KEYLESS-GO®
897	Inductive wireless charging and NFC pairing	8U6	
916	Large Capacity Fuel Tank	950	AMG Line
986	Identification label with VIN number	989	VIN Code

**Damage History** 

Damage Code	10 (20 Little of Carlos Alba Anna Anna Anna Anna Anna Anna Anna An	Dealer Code	RO No	Line No	asset to the company of the company	RO Open Date	RO Close Date		Service Type Desc	Seq No
0 32558 73 7	Switch, tranmission modes Electrical fault	05146	1192614	С	074510882	12/03/2024	12/05/2024	36321	03-Warranty	
1 2174A 00 0	PPMSC - 1st Maintenance Service of Package	05179	721330	A	109051072	09/19/2024	09/23/2024	31002	RAPS	
1 21852 ZZ 0	Dealer Pre- Delivery (PDI)	05146	136196	А	107272190	10/21/2022	10/21/2022		RAPS	

**Customer Pay Data** 

Dealer Code	RO Number		Repair Close Date	RO Mileage	OP Code/Part #	Description
05179	725632	12/24/2024	12/24/2024	0037792	055	Inspect & Adjust Tire Pressures Reset Tire Monitoring System
05179	725632	12/24/2024	12/24/2024	0037792	056	MOUNT BALANCE ONE TIRE
05179	725632	12/24/2024	12/24/2024	0037792	097	PERFORM COURTESY 27 POINT INSPECTION AND TIRE INFLATION SERVICE. SET ALL TIRE MEASUREMENTS TO MANUFACTURE SPECIFICATION LFRFLRRR, COURTESY CAR WASH WHEN REPAIRS ARE COMPLE
05179	725632	12/24/2024	12/24/2024	0037792	098	MISC, SHOP CHARGES
05179	725632	12/24/2024	12/24/2024	0037792	098	MISC, SHOP CHARGES
05179	725632	12/24/2024	12/24/2024	0037792	098	NO INTERVAL DUE BASIC
05179	725632	12/24/2024	12/24/2024	0037792	098	MISC, SHOP CHARGES
05179	725632	12/24/2024	12/24/2024	0037792	BQ8402816	BRIDGESTONE 225/40R19 SKU



# Vehicle Master Inquiry (VMI) FOR INTERNAL USE ONLY

Dealer: 05179 VIN:W1K5J4GB7PN334174

Dealer	RO	Repair	Repair	RO	OP Code/Part#	Description
Code	Number	Open Date	Close Date			
05146	1192614	12/03/2024	12/05/2024	0036321	014	CHECK AND ADJUST TIRE PRESSURE PER CARB REG #95550. INCLUDES ONLY VISUALLY INSPECTING THE OUTSIDE AND TREAD FOR NAILS, CUTS & VISIBLE DAMAGE TO TIRE.
05146	1192614	12/03/2024	12/05/2024	0036321	020	COMPLIMENTARY CAR WASH INCLUDED AFTER REPAIRS/MAINTENANCE IS COMPLETED.
05146	1192614	12/03/2024	12/05/2024	0036321	073	PERFORM COURTESY MULTI-POINT INSPECTION-PLEASE REMOVE ALL VALUABLES FROMYOUR VEHICLE- MERCEDES-BENZ OF BEVERLY HILLS IS NOT RESPONSIBLE FOR LOST OR STOLEN ITEMS-ALL INSURANCE CLAIM
05146	1192614	12/03/2024	12/05/2024	0036321	073	COMPLIMENTARY LOANER VEHICLE. MUST BE RETURNED UPON FOUR HOURS OF COMPLETION
05146	1192614	12/03/2024	12/05/2024	0036321	098	UNABLE TO VERIFY AT THIS TIME
05179	721330	09/19/2024	09/23/2024	0031002	020	COURTESY WASH
05179	721330	09/19/2024	09/23/2024	0031002	028	MAINTENANCE PLAN
05179	721330	09/19/2024	09/23/2024	0031002	055	Inspect & Adjust Tire Pressures Reset Tire
05179	721330	09/19/2024	09/23/2024	0031002	097	Monitoring System  PERFORM COURTESY 27 POINT INSPECTION AND TIRE INFLATION SERVICE. SET ALL TIRE MEASUREMENTS TO MANUFACTURE SPECIFICATION LFRFLRRR COURTESY CAR WASH WHEN REPAIRS ARE COMPLE
05321	331531	07/17/2024	08/30/2024	0026537	020	COMPLIMENTARY AUTOMATED CAR WASH- EXTERIOR WASH, VACUUM INTERIOR LESS TRUNK, CLEAN OUTSIDE OF WINDOWS- DTLA MOTORS IS NOT RESPONSIBLE FOR LOOSE / DAMAGED/ OR PREVIOUSLY REPAIRED B
05321	331531	07/17/2024	08/30/2024	0026537	055	WHEELS & TIRES
05321	331531	07/17/2024	08/30/2024	0026537	055	CHECK AND ADJUST TIRE PRESSURE TO FACTORY SPECIFICATIONS PER ARB REGULATION 17 CA ADC 95550
05321	331531	07/17/2024	08/30/2024	0026537	062	ELEC INSTRUMENTS
05321	331531	07/17/2024	08/30/2024	0026537	062	ELEC INSTRUMENTS
05321	331531	07/17/2024	08/30/2024	0026537	069	CLIMATE CONTROL
05321	331531	07/17/2024	08/30/2024	0026537	097	PERFORM COMPLIMENTARY MULTI- POINT INSPECTION - COPY PROVIDED UPON REQUESTUSE LINK TO PAY FOR CONTACTLESS TRANSACTION-WE DO NOT TEST DRIVE VEHICLES WITH TINTED WINDSHILEDS
05321	331531	07/17/2024	08/30/2024	0026537	098	ATTENTION; VEHICLE HAS RETURNED WITH IN A 90 DAY TIME PERIOD. SHOP FORMAN INVOLVEMENT REQUIRED.
05321	331531	07/17/2024	08/30/2024	0026537	098	PLEASE DOUBLE CHECK TO MAKE SURE ANY PERSONAL BELONGINGS HAVE BEEN REMOVED FROM YOUR VEHICLE. MERCEDES BENZ OF LOS ANGELES IS NOT RESPONSIBLE FOR ANY BELONGINGS LEFT IN YOUR VEHIC
05321	331531	07/17/2024	08/30/2024	0026537	098	PLEASE BE AWARE INSURANCE CLAIMS MUST BE PAID IN FULL BEFORE A VEHICLE CAN BE RELEASED.
05321	331531	07/17/2024	08/30/2024	0026537	098	-My signature on the repair order consents to receive auto dialed, pre-recorded and artificial voice marketing and text messages on behalf of thedealer. Also consents to future ma
05321	331531	07/17/2024	08/30/2024	0026537	A0008176203	COMPANY SIGN
05321	331531	07/17/2024	08/30/2024	0026537	A1188800902	RADIATOR TRIM
05321	331531	07/17/2024	08/30/2024	0026537	A1188807501	LICENSE PLATE HOLDER
05321	331531	07/17/2024	08/30/2024	0026537	A1188808700 9999	TRIM, BUMPER
05321	331531	07/17/2024	08/30/2024	0026537	A1188854102	SUPPORT
05321	331531	07/17/2024	08/30/2024	0026537	A1188855301	COVER, BUMPER AREA
05321	331531	07/17/2024	08/30/2024	0026537	A1188855401	COVER, BUMPER AREA
05321	331531	07/17/2024	08/30/2024	0026537	A1188881100 9040	TRIM STRIP
05321	331531	07/17/2024	08/30/2024	0026537	A1778854302	ORNAMENTAL TRIM
05321	331531	07/17/2024	08/30/2024	0026537	A1778854302	ORNAMENTAL TRIM
05321	331531	07/17/2024	08/30/2024	0026537	A1778859100	COVER BUMPER AREA
05321	331531	07/17/2024	08/30/2024	0026537	A1778881300	ORNAMENTAL TRIM
05321	331531	07/17/2024	08/30/2024	0026537	A1778881400 64	TRIM STRIP
05321	331531	07/17/2024	08/30/2024	0026537	A1778884200 64	CARRIER
05321	331351	07/15/2024	07/16/2024	0026355	055	CHECK AND ADJUST TIRE PRESSURE TO FACTORY SPECIFICATIONS PER ARB REGULATION 17 CA ADC 95550



#### Vehicle Master Inquiry (VMI) FOR INTERNAL USE ONLY

Dealer: 05179 VIN:W1K5J4GB7PN334174

Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
05321	331351	07/15/2024	07/16/2024	0026355	056	CUSTOMER REQUEST ONE TIRE REPLACEMENT- ELIGIBLE FOR FREE TIRE ROTATION EVERY 5,000 MILES FOR THE LIFE OF THE REPLACED TIRE(S) ONLY AT DTLA MOTORS
05321	331351	07/15/2024	07/16/2024	0026355	097	EXPRESS- PERFORM MULTI POINT INSPECTION
05321	331351	07/15/2024	07/16/2024	0026355	098	PLEASE BE AWARE INSURANCE CLAIMS MUST BE PAID IN FULL BEFORE A VEHICLE CAN BE RELEASED.
05321	331351	07/15/2024	07/16/2024	0026355	098	MISC, SHOP CHARGES
05321	331351	07/15/2024	07/16/2024	0026355	098	PLEASE DOUBLE CHECK TO MAKE SURE ANY PERSONAL BELONGINGS HAVE BEEN REMOVED FROM YOUR VEHICLE. MERCEDES BENZ OF LOS ANGELES IS NOT RESPONSIBLE FOR ANY BELONGINGS LEFT IN YOUR VEHIC
05321	331351	07/15/2024	07/16/2024 ,	0026355	098	<ul> <li>-My signature on the repair order consents to receive auto dialed, pre-recorded and artificial voice marketing and text messages on behalf of thedeater. Also consents to future ma</li> </ul>
05321	331351	07/15/2024	07/16/2024	0026355	098	MISC. SHOP CHARGES
05321	331351	07/15/2024	07/16/2024	0026355	098	PLEASE DO NOT WASH CAR AS PER CLIENT REQUEST
05321	331351	07/15/2024	07/16/2024	0026355	098	MISC. SHOP CHARGES
05321	331351	07/15/2024	07/16/2024	0026355	BQ8402816	BRIDGESTONE 225/40R19 SKU
05179	711276	02/20/2024	03/06/2024	0012474	007	MOUNT AND BALANCE ONE TIRE
05179	711276	02/20/2024	03/06/2024	0012474	055	Inspect & Adjust Tire Pressures Reset Tire Monitoring System
05179	711276	02/20/2024	03/06/2024	0012474	097	PERFORM COURTESY 27 POINT INSPECTION AND TIRE INFLATION SERVICE. SET ALL TIRE MEASUREMENTS TO MANUFACTURE SPECIFICATION LFRFLRRR, COURTESY CAR WASH WHEN REPAIRS ARE COMPLE
05179	711276	02/20/2024	03/06/2024	0012474	098	NO INTERVAL DUE BASIC
05179	711276	02/20/2024	03/06/2024	0012474	098	MISC. SHOP CHARGES
05179	711276	02/20/2024	03/06/2024	0012474	098	MISC. SHOP CHARGES
05179	711276	02/20/2024	03/06/2024	0012474	098	MISC. SHOP CHARGES
05179	711276	02/20/2024	03/06/2024	0012474	BQ8402816	BRIDGESTONE 225/40R19 SKU
05146	1164495	12/22/2023	12/22/2023	0009133	073	Loaner safety inspection to include synthetic oil and filter change
05146	1164495	12/22/2023	12/22/2023	0009133	A0009862000 16	WINDSHIELD CLEANING AGENT
05146	1164495	12/22/2023	12/22/2023	0009133	A0019893701 USA9	MB Genuine Engine Oil 5W-
05146	1164495	12/22/2023	12/22/2023	0009133	A2701800109	TS OIL FILTER ELEMENT
05146	1164495	12/22/2023	12/22/2023	0009133	N007603014106	SEAL RING, VLRUB
05146	1154827	08/18/2023	08/23/2023	0005032	098	CUSTOMER STATES:
05146	1154827	08/18/2023	08/23/2023	0005032	098	SUBLET REPAIRS
05146	1145940	04/29/2023	05/01/2023	0003165	098	CUSTOMER STATES:
05146	1145940	04/29/2023	05/01/2023	0003165	098	SUBLET REPAIRS
05146	1130242	10/21/2022	10/21/2022	8000000	072	PERFORM NEW CAR DETAIL
05146	1130242	10/21/2022	10/21/2022	8000000	090	SUPPLY LICENSE PLATE FRAMES FOR VEHICLE



AP00.20-U-1208EK

SERVICE SHEET for Mercedes-Benz Maintenance System (USA)

# Model Year 2023 USA

# Model 118



Customer:			Repair order nun	nber:
Tire Rotation (non-staggered width wheel setup only)	Tire rotation is recommend or 10,000 miles.	led every 1-year	Tires rotated	YES NO
Note: For any c	ondition found while performi	ng the checks or inspec	ctions included in this m	naintenance sheet, determine
·	ding:	·	Oil grade/viscosity:_	
Additional notes:				
	animination Andrew Survey .			
N. Control Manda Address		Name and the second		
National Control of the Control of t				
Service work to be p service advisor:	performed as advised by	Completion date:	Confirm work has below:	been performed by signing

Required Service Work miles (thousands)  Performed years  (check if performed)	2	10	20 2	30 3	40 4	50 5	60 6	70 7	80 8	90 9	100 10	110 11		130 13	140 14	150 15	Not OK	
Reset maintenance service indicator in instrument cluster Except CODE 521/525 (Connect 20 mid/high (NTG7))		•	*	•	•	•	•	•	•		•	•	•	•	•	•		AP00,20-P-0043F
With CODE 521/525 (Connect 20 mid/high (NTG7))		•	*	•	*		•	•	•	•	•	•	•	•	•	•		AP00,20-P-0043L
☐ Replace engine oil and filter Engine 260		•	•	•	•		•		•		•	•	•	•	•	•		AP18.00-P-0101MFA
Engine 139	<u> </u>	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•		AP18.00-P-0101MFC
Replace activated charcoal combination filter			•		•		•	3300	•		٠	1000	•		•			AP83.00-P-8350MFA
□ Replace brake fluid ■ Every 2 years			•		•		•		•		•		*		•			AP42.00-P-4280E
□Perform brake test			•		•		•			#365 9355	٠		•		•			AP42.00-P-4290BA
☐ Check brake system fluid level and correct if necessary			٠	•	•	•	•	•	•	•	•	•		•	•			AP42.10-P-4210D
☐Check thickness of brake pads, front and rear		•	•	•	٠	•	٠	•	•	•	•	•	•	•	•	•		AP42.10-P-4252CLA
□ Correct tire inflation pressure including spare (where applicable) and enter in the table at the end of the service sheet		•	•	•	•		•		•	•	•	•	•	•	•			AP40,15-P-4061A
Check main circuit coolant fluid level and correct if necessary										10000								
Observe correct coolant composition     Engine 139			_															AP20.30-P-2050T
Engine 260					Ţ			J										AP20,30-P-2050R
☐ Check low-temperature coolant fluid level and correct if necessary	-		-		-		Ī		H		-	1966	<del>-</del>	100 to 10	Ť			
Engine 139			•					•		•	٠			•				AP20.30-P-2052P
Check windshield washer system fluid level and correct if necessary	t				•				•	•		•	•	•	•	•		AP82.35-P-8210D
☐ Check catch, safety catch and hinges on engine hood for proper operation			•		•		•		•	•	•	•	•	•	٠	•		
□Check first ald kit	Γ	•	•	•	•		•	•			٠	•		•		•		AP68,00-P-6850EW
Check vehicle underside for damage and leakage		2000		1000	•	- 1000 1000 1000 1000 1000 1000 1000 100	•		•		•		•		•			AP00.20-P-0054N
☐ Check condition of poly-V-belt	1	100				# 15 m												
Engine 260		199	•	941	•		•		•		•		•		•			AP13,22-P-1352EW
Engine 139		100	•		•	1	•				•		•					AP13,22-P-1352C
Check all visible parts in engine compartment for damage and leaks	ļ	100	•		•		•	30.00	•	100	•		•	(3200 (3200	•	1900 S		AP00.20-P-0055I
Check condition of steering mechanical components, rubber boots	L		•	333	•	•	٠		•		•		•		•	101/02		AP46.00-P-4651G
☐ Check condition of front axle and front axle ball joints			•	33	•	100	•	100	•		•		•		•			AP33,10-P-3358G
☐ Check condition of rear axle and rear axle ball joints												373					 	
With CODE U54 (compound-link axle)			*		•	•	•		•		•		•		•			AP35.20-P-3552G
With CODE U55 (multi-link axle)	-		•	38	•		•		•		•		•		1			AP35.20-P-3552H
Check seal of tank filler recess	+	188	-	163	-		•	1 486 548	-		•		•	(3) (3)	•			AP47.10-P-4752A AP41.10-P-4152C
☐ Check condition of propeller shaft and flex disks. With CODE M005 (4MATIC)		100	•		•		•		•		•		•		•		لسا	AF 41.10-F-41320
☐ Check condition of suspension struts or shock absorbers and springs.			•		•		•		•		•		•	5000 5000 5000 5000	•	100 mg		AP32.25-P-3255P
Reset maintenance service indicator in instrument cluster  Reminder - if not yet performed												1000 1000 1000 1000 1000 1000 1000 100						
Except CODE 521/525 (Connect 20 mid/high (NTG7))					•						•		•	•	•			AP00.20-P-0043F
With CODE 521/525 (Connect 20 mid/high (NTG7))					•	,									•			AP00.20-P-0043L
Required Additional Work miles (thousands)  Performed years (check if performed)	2	10	20 2					70 7	80		100 10	110 11		130 13		150 15		
☐ Replace engine air filter	+	110					·	100		•			•					AP09.10-P-0980W
Engine 139  Replace engine air filter Engine 260				7/1 7/1 100 100 100 100 100 100 100 100 100 1		•		1483 2483 2483 2483 2483 2483 2483 2483 2			•			303.0		•		AP09.10-P-0980N
☐ Replace automatic transmission oll and filter Engine 139	T					120	•			•		9875 9875 9875 9875 9875 9875 9875	•			•		AP27.00-P-2707MFA

Required Additional Work miles (thousands)  Performed years  (check if performed)	2	10 1	20 2	30 3	40 4	50 5	60 6	70 7	80 8	90 9	100 10	110 11	120 12	130 13	140 14	150 15	Not OK	
Replace automatic transmission oil and filter Engine 260										7000 7000 7000 7000 7000								
Transmission 724.0		2000 2000 2000 2000 2000					•											AP27.00-P-2707NK
Transmission 724.1							٠						*					AP27.00-P-2707MFA
☐ Replace rear axle oil Engine 139 with CODE M005 (4MATIC)				•			•			•			•			•		AP35,00-P-3501E
Replace rear axle oil													•					
Engline 260 with CODE M005 (4MATIC)  Except AMG model (118.351)																		AP35.00-P-3501MFA
Model 118.351 (AMG)											•					•		AP35,00-P-3501I
☐ Replace spark plugs Engine 139		1000 1000 1000 1000 1000		3.00	•			1000	•	VAN			•					AP15.10-P-1580J
□ Replace spark plugs Engine 260						•					٠					•		AP15.10-P-1580F
☐ Replace fuel filter																		AP47,20-P-0780G
Replace low temperature circuit coolant Engine 139													•					AP20.00-P-2083M
Dobserve correct coolant composition				\$33 333 333	_	2000 2000 2000	L	33	ļ	100 100 100 100 100 100 100 100 100 100						500 M		
Replace main circuit coolant		1000 1000 1000 1000 1000 1000 1000 100											•					AP20.00-P-2082R
Observe correct coolant composition  Recommended Service Work miles (thousands)	2	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150		
Performed years (check if performed)	-	1	2		4	5	6	7	8	9			12			15	Not OK <b>↓</b>	
☐Replace wiper blades		•	•	•		•	٠	•	٠	•	٠	•	٠	•	٠	•		
☐ Check windshield wiper, washer and headlamp washer system operation		•	•	•	•	•	•	•	•	•	•	•	•	•	•	•		AP82.35-P-8252H
☐ Inspect tires for damage, measure tread depth and enter table at the end of the service sheet	е	•	٠		•	•	•	•	•	•	•	•	•		•	•		AP40.10-P-4051EW
☐ Tire rotation (where applicable)		•	٠		•	•	•	•	•	•	٠	•	•	•	•	•	ļ	
☐ Activate Tire Pressure Monitoring System  ☐ Refer to vehicle Operator's Manual		•	٠		•	•	•		•		•	•	•	•	•	•		
☐ Check TIREFIT sealant expiration date (where applicable)		•			•		٠	٠	•	٠		•	•	•	•	٠		
☐ Check thickness of brake pads and discs, front and rear wheels removed												0.000 0.000 0.000 0.000 0.000 0.000 0.000					_	
Pads		•	•	•	•	•	*	•	•	•	•	•	•		•	•		AP42.10-P-4252CLA
Discs		•	•		•	•	•	•	•	•	•		•		•			AP42.10-P-4256EW
☐ Check TIREFIT tire sealant expiration date (where applicable)		•	•	•	•	•	•	•	•	•	•	•	•	•	•			AP40.10-P-4054R
☐ Check brake system components, lines, hoses, calipers		•	٠	•	•	•	•	•	•	•	•	•	•		•	•		
☐ Check headlamp settings, correct if necessary	_		•	•	•		•	136	•		•	3000	•	20000	•	100 A		AP82,10-P-8260Y
Check operation of headlamp range adjustment	-	32	•	)	•	•	•	1000 1000 1000	•		•		•	- 100 - 100	•	30000		AP82.10-P-8250EW
Check all exterior lights		•	•	•	•		•		-	•	•				•			AP82,10-P-8252EW
☐ Check warning/indicator lamps		•	•	•	•		•	•	-	•	•	•	•	•	•	•		AP54,30-P-5451F AP54,30-P-5453F
Check illumination and interior lighting	-		•		•		•	*	•		•		•		•			AP54.3U-P-5453F
☐ Check trunk/cargo compartment lighting			•	•	•				•		•	•	•		•	•		
☐ Replace battery for KEYLESS-GO key With CODE 889 (KEYLESS-GO)  ☐ After consultation with customer		•	•	•	•		•		•		•	•	•	•	•			
Check horn	$\dashv$		•	•			•		•		•	•	•		•			
Check battery condition. Attach printout to sheet	$\dashv$		•		•		•		•		•		•		•	•		
☐ Check, clean and lubricate mechanism of panaroma roof with power till/silding panel (where applicable)  With CODE 413 (panoramic sliding sunroof/glassroof)	er		•	•	•	,	•	18.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50 10.50	•	100   100	•	7000 7000 7000 7000 7000 7000 7000 700	•		٠			AP77.20-P-7732A
☐ Check seat belts and buckles for damage and proper function			•	<b>)</b>			•	· T	•		•	1000	•		•			
☐ Check for body paint damage			•		•		•		•	. AS		1000	•	8000 2000	•			AP60.00-P-0050Q

Recommended Service Work miles (thousands)  ☑ Performed years	2	10	20 2		30 4 3 4	0 5 1 8		0 70 5 7	80		100 10	110 11	120 12		140 14	150 15	Not OK	
(check if performed)																	Ψ	
☐ Check chassis and load-bearing body components for damage and corrosion			•		•	• 3000000	•	•	•	•	•		٠		•			
☐ Check traller hitch condition and function With CODE 550 (trailer hitch)		777 777 777 777 777 777	•	500000 mm	•	2000	•	•	•		٠		•		•			AP31,11-P-3152B
High Mileage Required Service Work at 160,000 miles or 16	yea	ars	; th	er	1 ev	ery	20,	000	ml	les d	or 2 y	year	S					
I Plus any applicable additional work listed at the end of the service sheet																		
☑ Performed (check if performed)																	Not OK	
																	Ψ_	
Reset maintenance service indicator in instrument cluster																		AP00,20-P-0043F
Except CODE 521/525 (Connect 20 mid/high (NTG7)) With CODE 521/525 (Connect 20 mid/high (NTG7))																		AP00.20-P-0043L
□Replace engine oil and filter																		
Engine 260																		AP18,00-P-0101MFA
Engine 139																		AP18.00-P-0101MFC
Replace activated charcoal combination filter																		AP83.00-P-8350MFA
□ Replace brake fluid ■ Every 2 years														<u> </u>				AP42.00-P-4280E
□ Perform brake test												t						AP42.00-P-4290BA
☐ Check brake system fluid level and correct if necessary												-						AP42.10-P-4210D
Check thickness of brake pads, front and rear																		AP42.10-P-4252CLA
☐ Correct tire inflation pressure including spare (where application)	able)	) a	nd e	 nt	er in	the	e ta	ble a	t th	ne er	ıd of	the	serv	ice s	hee	t		AP40.15-P-4061A
Check main circuit coolant fluid level and correct if necessar						•												
Observe correct coolant composition	,																	
Engine 139																		AP20.30-P-2050T
Engine 260																		AP20.30-P-2050R
☐ Check low-temperature coolant fluid level and correct if nece	essa	ary															_	
Engine 139				_														AP20.30-P-2052P
Check windshield washer system fluid level and correct if ne	eces	sa	ry						•									AP82.35-P-8210D
Check catch, safety catch and hinges on engine hood for pr	ope	ro	pera	tic	on													ABAA AA B ABEAE!A!
☐ Check first aid kit																		AP68.00-P-6850EW
☐ Check vehicle underside for damage and leakage																	<u></u>	AP00.20-P-0054N
☐ Check condition of poly-V-belt																		
Engine 260																		AP13.22-P-1352EW
Engine 139											***************************************							AP13.22-P-1352C AP00.20-P-0055I
Check all visible parts in engine compartment for damage a				_														AP46.00-P-4651G
Check condition of steering mechanical components, rubbe	r bo	ots	3															AP33,10-P-3358G
Check condition of front axle and front axle ball joints													·				Committee Commit	AF 33, 10-F-3338G
Check condition of rear axle and rear axle ball joints																		ADOL OO D OECOO
With CODE U54 (compound-link axle) With CODE U55 (multi-link axle)																		AP35,20-P-3552G AP35,20-P-3552H
Check seal of tank filler recess																		AP47.10-P-4752A
										············								AP41.10-P-4152C
Check condition of propeller shaft and flex disks.  With CODE M005 (4MATIC)																		
Check condition of suspension struts or shock absorbers ar	nd s	prii	ngs.															AP32.25-P-3255P
Reset maintenance service indicator in instrument cluster																		
☑ Reminder - if not yet performed Except CODE 521/525 (Connect 20 mid/high (NTG7))																		AP00.20-P-0043F

With CODE 521/525 (Connect 20 mid/high (NTG7))		AP00,20-P-0043L
High Mileage Recommended Service Work at 160,000 miles or 16 years; then every 20,000 miles or 2 years		
II Plus any applicable additional work listed at the end of the service sheet		
Performed	Not OK	
(check if performed)	Ψ	
Replace wiper blades		
Check windshield wiper, washer and headlamp washer system operation		AP82.35-P-8252H
☐ Inspect tires for damage, measure tread depth and enter table at the end of the service sheet		AP40.10-P-4051EW
☐ Tire rotation (where applicable)		
☐ Activate Tire Pressure Monitoring System		
Refer to vehicle Operator's Manual		
Check TIREFIT sealant expiration date (where applicable)		
$\square$ Check thickness of brake pads and discs, front and rear wheels removed		
Pads		AP42.10-P-4252CLA
Discs		AP42,10-P-4256EW AP40.10-P-4054R
Check TIREFIT tire sealant expiration date (where applicable)		AP40.10-P-4054K
Check brake system components, lines, hoses, calipers		4505 (0 B 0000)
Check headlamp settings, correct if necessary		AP82.10-P-8260Y
Check operation of headlamp range adjustment		AP82.10-P-8250EW
☐ Check all exterior lights		AP82.10-P-8252EW
☐ Check warning/indicator lamps		AP54,30-P-5451F
☐ Check illumination and interior lighting		AP54,30-P-5453F
☐ Check trunk/cargo compartment lighting		
☐ Replace battery for KEYLESS-GO key With CODE 889 (KEYLESS-GO)  ☐ After consultation with customer		
□ Check horn		
Check battery condition. Attach printout to sheet		AP77.20-P-7732A
Check, clean and lubricate mechanism of panaroma roof with power tilt/sliding panel (where applicable) With CODE 413 (panoramic sliding sunroof/glassroof)		71177.20-1-11027
Check seat belts and buckles for damage and proper function		
☐ Check for body paint damage		AP60.00-P-0050Q
Check chassis and load-bearing body components for damage and corrosion		
☐ Check trailer hitch condition and function With CODE 550 (trailer hitch)		AP31.11-P-3152B
High Mileage Required Service Work at 170,000 miles or 17 years; then every 20,000 miles or 2 years		
II Plus any applicable additional work listed at the end of the service sheet		_
☐ Performed (check if performed)	Not Oi	(
	Ψ	
Reset maintenance service indicator in instrument cluster		4 B00 00 B 0040F
Except CODE 521/525 (Connect 20 mid/high (NTG7)) With CODE 521/525 (Connect 20 mid/high (NTG7))		AP00,20-P-0043F AP00,20-P-0043L
Replace engine oil and filter		74 00,201 00,700
Engine 260		AP18.00-P-0101MFA
Engine 139		AP18.00-P-0101MFC
☐ Check brake system fluid level and correct if necessary		AP42.10-P-4210D
☐ Check thickness of brake pads, front and rear		AP42,10-P-4252CLA
Correct tire inflation pressure including spare (where applicable) and enter in the table at the end of the service sheet		AP40.15-P-4061A
Check main circuit coolant fluid level and correct if necessary	***************************************	
Observe correct coolant composition		
Engine 139		AP20,30-P-2050T
Engline 260		AP20.30-P-2050R

$\square$ Check low-temperature coolant fluid level and correct if	necessary		
Engine 139			AP20,30-P-2052P
Check windshield washer system fluid level and correct	if necessary		AP82.35-P-8210D
Check catch, safety catch and hinges on engine hood f	or proper operation		
☐ Check first aid kit			AP68,00-P-6850EW
☐ Reset maintenance service indicator in instrument clust ☐ Reminder - if not yet performed Except CODE 521/525 (Connect 20 mid/high (NTG7)) With CODE 521/525 (Connect 20 mid/high (NTG7))	ler		AP00.20-P-0043F AP00.20-P-0043L
High Mileage Recommended Service Work at 170,000	miles or 17 years; then every 20,000 miles or 2 years		
Plus any applicable additional work listed at the en	d of the service sheet		
☑ Performed		Not OK	
(check if performed)		Ψ	
Replace wiper blades			
Check windshield wiper, washer and headlamp washer	system operation		AP82.35-P-8252H
$\square$ Inspect tires for damage, measure tread depth and ente	er table at the end of the service sheet		AP40.10-P-4051EW
☐ Tire rotation (where applicable)			
☐ Activate Tire Pressure Monitoring System ☐ Refer to vehicle Operator's Manual			
☐ Check TIREFIT sealant expiration date (where applicat	ole)		
☐ Check thickness of brake pads and discs, front and rea			
Pads			AP42.10-P-4252CLA
Discs			AP42.10-P-4256EW
☐ Check TIREFIT tire sealant expiration date (where app	licable)	<u></u>	AP40.10-P-4054R
☐ Check brake system components, lines, hoses, caliper	S		
☐ Check all exterior lights	AND 10-10-10-10-10-10-10-10-10-10-10-10-10-1		AP82.10-P-8252EW
☐ Check warning/indicator lamps			AP54.30-P-5451F
☐ Check illumination and interior lighting			AP54.30-P-5453F
☐ Check trunk/cargo compartment lighting			
☐ Replace battery for KEYLESS-GO key With CODE 889 (KEYLESS-GO) ☐ After consultation with customer			
☐ Check horn			
☐ Check battery condition. Attach printout to sheet			
High Mileage Additional Work  ☑ Performed (check if performed)	•		
Replace engine air filter Engine 139	If more than 30,000 miles or 3 years since last replacement		AP09.10-P-0980W
Replace engine air filter Engine 260	If more than 50,000 miles or 5 years since last replacement		AP09.10-P-0980N
Replace automatic transmission oil and filter Engine 139	If more than 30,000 miles or 3 years since last replacement		AP27,00-P-2707MFA
Replace automatic transmission oil and filter Engine 260			
Transmission 724.0	If more than 60,000 miles or 6 years since last replacement		AP27,00-P-2707NK
Transmission 724.1	If more than 60,000 miles or 6 years since last replacement  If more than 30,000 miles or 3 years since last replacement		AP27.00-P-2707MFA AP35,00-P-3501E
Engine 139 with CODE M005 (4MATIC)			<del>.</del>
☐ Replace rear axle oil Engine 260 with CODE M005 (4MATIC)			
Except AMG model (118.351)	If more than 50,000 miles or 5 years since last replacement		AP35.00-P-3501MFA
Model 118.351 (AMG)	If more than 50,000 miles or 5 years since last replacement  If more than 40,000 miles or 4 years since last replacement		AP35.00-P-35011 AP15.10-P-1580J
└── Replace spark plugs Engine 139	n more than to,000 miles of 4 years since last replacement		71 10.10°F= (UOUU

Replace spark plugs Engine 260	If more than 50,000 miles or 5 years since last replacement	AP15.10-P-1580F
☐ Replace fuel filter	If more than 120,000 miles or 12 years since last replacement	AP47.20-P-0780G
Replace low temperature circuit coolant Engine 139  Dobserve correct coolant composition	If more than 120,000 miles or 12 years since last replacement	AP20.00-P-2083M
Replace main circuit coolant  Observe correct coolant composition	If more than 120,000 miles or 12 years since last replacement	AP20.00-P-2082R

Tire infla	tion press	ure (bar/	psi)	
LF	RF	LR	RR	Spare

Tire trea	d depth	(mm)		
	LF	RF	LR	RR
outside				
center				
inside				

726063

## Mercedes-Benz of Calabasas

Authorized Mercedes-Benz Retailer

24181 Calabasas Road Calabasas, CA 91302

WORKORDER NATALIA TSEPENYUK 23777 MULHOLLAND HWY SPC 63 CALABASAS, CA 91302-3741 PAGE 1

VIIII   VIII   V	,		<u>.</u>				(010) 223-3	102	
HOME:818-445-4730	CONT • 747 =	388-4090				B.A.R.# AC 25	50333 E.P	.A# CAD 9824	186946
BUS:	CELL: 747-		SER	VICE ADV	/ISOR	1451 .TA!	ZMIN, QUIN		
COLOR YEAR	MAKE/MODEL	- 0 - 0 - 0 - 0	<u> </u>	VIN		LICENSE		E IN/ OUT	TAG
23 MEI	RCEDES-BEN						38931,		T756
DEL DATE PROD. DATE	WARR, EXP.	PROMISI	ED	PO NO	),	RATE	PAYMENT	INV. D.	ATE
20FEB24 DD		10.00 06	TANOR				GR GII		
R.O. OPENED	READY	19:00 06		:05179			CASH		
	<u> </u>	0, 11010	o. Duk	.03113					
06JAN2025 10:48									
LINE OP CODE TECH	H TYPE	DESCRIPT	IONS/I	NSTRUCT:	IONS				
# A ENG	IPS	CLIENT S	TATES	WHEN AC	CELERA	TING VE	HICLE HAS	LACK O	P .
		POWER, T	EST DR	OVE WIT	H SHOP	FOREMAI	VERIFIEI		
		RESISTAN	CE IN	PEDAL FO	OUND FI	LOOR MA	r was pusi	IED	
		FLOOR MA			PROVII	DE CLIEI	NT WITH DE	₹T VER	\$155055079659161617566
		I LIOOK MA		MAIE.					
			6-6-303103031061010 210-0110-100303031						
				ex 58/55/54/51 / 55/50/61 / 6			, der star retur, er kult by et til somer kilg einer flege f	va. 16.16.16.16.16.16.16.16.16.16.16.16.16.1	
# B TRANS	W107	CLIENT S	TATES	WHILE D	RIVING	VEHICLE	E WILL GO	INTO	
1081: 008 00001 ATM 1000 (1000 ) Published ARM 1000 (1000 ) Published ARM 1000 (1000 )	1980 (1888) sekireken ilang pada da kanas	MANUAL M	ODE ON	ITS OW	N. CHK	and ADV	J		
	avlasiosius es es suscituta			Nederlands (1980)		(919709301103), (44,64,44,1	es de san antans de lamba e anten e	::::::::::::::::::::::::::::::::::::::	ecoconomica campo de
# C TRANS	W107	CLTENT S	ጥሿጥፑር '	ות ס.דעוג	DT1/TNIC	VEUTALI	E DRIVE MO	י דידוא יהרו	
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						TO ECO (		
	191791111111111111111111111111111111111	SPORT MO	DE. CH	K and Al	OV	COMP ON	L TO DCO (	A BCO.	r Asserting (s)
000100000000000000000000000000000000000	ubb. tonos, ocosopcionononononos vuo	Att veet veese too too oo oo oo oo oo oo oo							
" D 040040	<i>-</i>								
# D 040040	MXM	40,000 M	ILE SE	RVICE -	FIXED	INTERV	/L	Note that is to concentration to our	
									x253145,551555 40515155-1
# E MP	IPS	*Mainten	ance P	lan *Car	npaign	and Rec	all VIN F	Report	
BY LAW, YOU MAY CHOOSE ANOTHE NEEDED REPAIRS OR ADJUSTMENTS WH	R LICENSED SMOG CH IICH THE SMOG CHECK	HECK FACILITY TO TEST INDICATES A	PERFORM AN RE NECESSARY	y PARTS: All pa meet manufact	rts are new ur turer approved	nless otherwise i source part requi	ndicated. Remanufacti rements may be instal	ured and refurbis led at our discre	thed parts that
repairs, but do not authorize completion	on of a repair or servi	ine venicie or com ice, a charge may l		request. If our	Dealership does	request. You m s not have to retu	ay inspect all parts re	emoved from th	e vehicle upon
teardown, reassembly or partially complete is necessary to disassemble the vehic	eted work and you agre	ee to pay the same.	· ·	warranty arran	ı upon request.		due to their size, weig		rs, they will be
teardown and reassembly charge (includ The maximum time for reassembly will be	ing parts and labor) is:	\$	. The estimate	1	Some Par	ts Not Returnabl	e Please Save Rep OF ESTIMATE YO	laced Parts	DECENT DV
You understand that disassembly may		the vehicle to its fo	rmer condition	INITIALING BE	SIDE ONE OF	THE FOLLOW!	NG CHOICES AND IN	DICATE THE B	EST WAY TO
SUBLET REPAIRS: Some repairs m	Ust be sublet due to	the type of service	required Th	WRI	ITTEN ESTIM	IATE	ORAL ESTIMATE _	ELECT	RONIC EST.
location will be disclosed upon request. PAYMENT TERMS: I agree to pay for				Let Letebison	e at:		By Fax to:		
(unless the Dealership agrees to other delivery of the vehicle to me or 3 days a	navment arrangement	lumie (anneuhe ni e	tangousely wit	hl		LIMINARY EST	TIMATE \$		
up. An express mechanics lien is hereby materials, storage and/or towing charges	acknowledged on the	vehicle to secure the	a cost of labor	. J DE	SIGNATION OF	PERSON TO AU	THORIZE ADDITIONAL	WORK OR PAR	
will be assessed and shall accrue daily if	I fail to pick up the ve	hicle within 3 days	from the date	not included in	ate the individu the original wri	iał named below i tten estłmated pri	to authorize any additi ice for parts and labor:	onal work not sp	ecified or parts
am notified that the repairs have been a fail to authorize repairs.									
POWER-OF-ATTORNEY: I hereby appoint sign my name upon any checks, drafts	t the Dealership as my s or other forms of p	attorney-in-fact and avment issued in or	l authorize it t avment of thi	o Fax Number: S Customer:			E-Mail Address:_ Date:		
Repair Order, X  By Signing Below: I agree that: (1) I hav			•		Total Addition	nal Approve		ne Auth	orization
the services/repairs listed above in acc Dealership is not responsible for loss or of	ordance with the ter	me and acaditions	haraine 191 sh	.	Cost Authoriz	zeo		Obt	ained By:
IOT TIPE, THEST, HAII, WING OF ANY OTHER CAL	ise hevand its control:	13) the Deslerchin m	sass amarata th	~11	\$			☐ Telephone ☐ Fax (See At ☐ E-mail (See	tached) Attached)
vehicle on streets, highways or public revehicle; and (4) I authorize the retrieva	l of on-board data as	needed to facilitate	vehicle renair	Revised Estimate	4			□ Talephone □ Fax (See At □ E-meil (See	(sched)
and the sharing of that data with the vel Customer	licie manufacturer for d	lagnostic or researd	h purposes.	acknowledg	e notice and	oral approval	of an increase in th	e original esti	mated price.
DESIGNATION TO THE CONTROL OF THE CO	R TYPE 2 - SW2C - Limited Werren	LY - CALIFORNIA - 9694522				(eignaturg er kritisk)		-	efel:
*107	IAC TO CONO								

NATALIA TSEPENYUK

Customer _

726063

# Mercedes-Benz of Calabasas

Authorized Mercedes-Benz Retaller

WORKORDER

24181 Calabasas Road

23777 MULHOLLAND HWY SPC 63 CALABASAS, CA 91302-3741	PAGE 2	Calabasas, CA 91302 (818) 223-3102				
HOME:818-445-4730 CONT:747-388-4090 BUS: CELL:747-388-4090	SERVICE ADVISOR: 1	1451 JAZMIN,QUINT				
COLOR YEAR MAKE/MODEL	VIN	LICENSE MILEAGE	IN/ OUT TAG			
	V1K5J4GB7PN334174	38931/	T756			
DEL DATE PROD. DATE WARR. EXP. PROMISED	PO NO.	RATE PAYMENT	INV. DATE			
20FEB24 DD 19:00 06JA		CASH				
R.O. OPENED READY OPTIONS:	DLR:05179		_ :			
06JAN2025 10:48 LINE OP CODE TECH TYPE DESCRIPTION	DNS/INSTRUCTIONS					
# F CARB IPS *Inspect ar	and Adjust Tire Pre	essures Reset Tir	е			
Monitoring	System					
# G MBI IPS *Compliment	ntary Multipoint Ir	nspection a \$'	74.95			
Value						
	itary Car Wash					
*************************	*******	*****				
Preliminary Estimate : \$0.00						
**************	******	*****				
BY LAW, YOU MAY CHOOSE ANOTHER LICENSED SMOG CHECK FACILITY TO PERFORMEDED REPAIRS OR ADJUSTMENTS WHICH THE SMOG CHECK TEST INDICATES ARE NE	IFCESSARY I meet manufacturer approved	uniess otherwise indicated. Remanufacture I source part requirements may be installed	red and refurbished parts tha			
TEARDOWN/REASSEMBLY: If you authorize teardown of the vehicle or commence repairs, but do not authorize completion of a repair or service, a charge may be impleaded work and you agree to pay the same.	ncement of information is available upon managed for request. If our Dealership does	r source pair requirements may be installed or request. You may inspect all parts rem as not have to return the parts to the manu ney are not exempt due to their size, weight	moved from the vehicle upor			
It is necessary to disassemble the vehicle to provide an estimated price for repairs. The teardown and reassembly charge (including parts and labor) is \$	e estimated returned to you upon request.  Some Part	irts Not Returnable 🗖 Please Save Repla	aced Parts			
The maximum time for reassembly will be X  You understand that disassembly may prevent restoration of the vehicle to its former	ESTIMATE: PLEASE CHOC	OSE THE KIND OF ESTIMATE YOU F THE FOLLOWING CHOICES AND IND	I WANT TO RECEIVE BY			
X SUBLET REPAIRS: Some repairs must be sublet due to the type of service requirements will be disclosed upon request.	WRITTEN ESTIM	MATE ORAL ESTIMATE By Fax to:	ELECTRONIC EST.			
PAYMENT TERMS: I agree to pay for all labor and materials in Cash or approved conclusions the Dealership agrees to other payment arrangements in advance) simultaneous	credit card By E-Mail to:	ELIMINARY ESTIMATE \$				
delivery of the vehicle to me or 3 days after receiving notice that the vehicle is ready to lup. An express mechanics lien is hereby acknowledged on the vehicle to secure the cost materials, storage and/or towing charges. I understand that a storage charge equal to \$	o be picked ost of labor, s DESIGNATION OF	F PERSON TO AUTHORIZE ADDITIONAL V	WORK OR PARTS.			
will be assessed and shall accrue daily if I fail to pick up the vehicle within 3 days from am notified that the repairs have been completed or after the communication of an est fail to authorize repairs.	n the date I not included in the original wri	ritten estimated price for parts and labor:	•			
POWER-OF-ATTORNEY: I hereby appoint the Dealership as my attorney-in-fact and auth sign my name upon any checks, drafts or other forms of payment issued in payment	thorize it to Fax Number:	Phone Number: E-Mail Address: Date:				
Repair Order, X  By Signing Below: I scree that: (1) I have read this Repair Order and I sutherize the com	Original Estimate Total Addition	onal Approved By: Date & Time	e Authorization Obtained By:			
the services/repairs listed above in accordance with the terms and conditions herein Dealership is not responsible for loss or damage to the vehicle or article set in the vehicle of fire, theft, hail, wind or any other cause beyond its control; (3) the Dealership may on	pin; (2) the sicle in case s		☐ Telephone ☐ Fax (See Attached) ☐ E-mail (See Attached)			
vehicle on streets, highways or public roadways for the purpose of testing and/or inspevehicle; and (4) I authorize the retrieval of on-board data as needed to facilitate vehicle and the sharing of that data with the vehicle manufacturer for diagnostic or research purpose.	pecting the Revised Estimate since repairs s		Telephone  Fax (See Attached)  E-mail (See Attached)			
,	l cokpositedos potico and	d man   managed   1   1   1   1   1   1   1   1   1				

I acknowledge notice and oral approval of an increase in the original estimated price.