
Operating temperature changes the calibrated output
Temperature
0 °C
15 °C
30 °C
45 °C
60 °C
Corrected output (model units)
0.2
0.4
0.6
0.8
0.0
0.2
0.4
0.6
0.8
1.0
Normalized sensor input x