
Computed uncertainty and conservative quality margin
0.001
0.000
−0.001
−0.002
−0.003
−0.004
−0.005
Calculated value (model units)
Standard uncertainty (illustrative)
Acceptance margin
0.0
0.2
0.4
0.6
0.8
1.0
Normalized sensor input x