
V2 at 110°C: feasible current vectors under both physical limits
3,000 rpm
9,000 rpm
q-axis current (A peak)
0
50
100
150
200
−200
−150
−100
−50
0
d-axis current (A peak)
d-axis current (A peak)