

Vicenza Campus

Facility Condition Assessment Report



CAMPUS SUMMARY

Year Built ¹	2011
GSF ²	267,825
Date of Assessment	13-Jan-2020

¹ Indicates range of dates of construction present on campus

² Only permanent and semi permanent facilities are included

SCHOOL SUMMARY

School	Assessed Condition		Annual Condition Report (June 2019)		2009 Congressional	Starting Grade	Ending Grade	Students
	Q-Rating	FCI	Q-Rating	FCI	Q-Rating			
Vicenza Elementary School	Q 1	100	Q 1	100	Q 4	Sure Start	Fifth	584
Vicenza Middle School	Q 1	100	Q 1	100	N/A	Sixth	Eighth	259

BUILDING SUMMARY

Building/School	Year Built	GSF	Vicenza ES (% Occupied)	Vicenza MS (% Occupied)	Type
Vicenza ES/MS Bldg 700	2011	267,825	50%	50%	PERM

I. INTRODUCTION

The Vicenza Campus is part of Vicenza Family Housing, U.S. Army Garrison Italy. This report provides a summary of findings for the physical condition assessment of the building at this campus. The physical condition assessment includes a general description of typical building systems found and includes conditions present at the time of the site visit.

II. SCHOOL PHYSICAL DESCRIPTION

The summary below provides a physical description of the campus. When multiple systems or materials are present, the predominant system or material observed during the facility condition assessment is shown.

a. STRUCTURAL/EXTERIOR ENCLOSURE: The building exterior is an exterior insulation and finish system (E.I.F.S). Roof coverings are clay tile. Exterior doors are pre-finished aluminum with glazing. Window systems are pre-finished aluminum with double-glazing.

b. INTERIORS: Floor finishes used include ceramic tile and resilient sheeting. Walls are painted hard surfaces. Ceilings are acoustical lay-in tiles.

c. MECHANICAL: Building 700 has heating, which is provided by a central plant. The facility has air conditioning, which is provided by a central plant. Building 700 has two elevators.

d. ELECTRICAL: No electrical upgrades have been completed, and most wiring appears to be original. Lighting is typically lay-in fixtures with fluorescent lamps. Ground-fault circuit interrupter (GFCI) receptacles appear to be present in required locations. Building 700 has an intercom system. There is no security system, and security cameras are present.

e. PLUMBING: Plumbing fixtures and piping are original. Domestic hot water is provided by point of use (tankless) water heaters.

f. SITE: The campus has parking for approximately 158 privately owned vehicles. In addition, Vicenza Elementary School has six playgrounds.

g. LIFE SAFETY: A fire safety inspection report was not available for review.

"Identification only"

III. OBSERVATIONS

The following observations were made: Exterior door security was not observed or reported to be a problem. The clay tile roofing system on Building 700 was reported to have several leaks throughout the facility. Evidence of water intrusion was observed in various areas throughout the building. Additionally, the exterior enclosure wall trim of Building 700, which is composed of synthetic stucco over rigid foam, was observed to be consistently damaged and deteriorated throughout; as well as the wall base finish with exposed metal lathe which is beginning to show indicators of rust and corrosion. The interior finishes were generally in good condition with no major issues observed.

It appears that outside air is being introduced into the HVAC system. Hot and chilled water at Building 700 is supplied by the base. The air handling units throughout the building were observed to be in good condition. There is an HVAC duct above the ceiling in Room 1222, in Building 700 that has standing water inside due to an apparent water leak, source unknown. Additionally, the motion sensors that control the lights throughout Building 700 do not always function.

The Facility Utilization Survey (FUS) drawings to include the site plan have been updated to reflect the following: X-Building (X700C) was renamed as "WALK-IN COOLER 1". Room-use changes were observed throughout the building. Further, Building 700 was identified as a shared facility between Vicenza Elementary School, Vicenza Middle School, and the DoDEA Europe South DSO. Additionally, the Maintenance contractor, SKE, occupies space in the building. Vicenza Elementary School and Vicenza Middle School share Building 700 equally, and utilize approximately 98% of Building 700 (266,617 SF), the DoDEA Europe South DSO utilizes approximately <1% of Building 700 (741 SF), and SKE utilizes approximately <1% of Building 700, specifically Rooms E0129, E0122, and E0123 (467 SF) for a GSF total of 267,825 SF.

Building 700 remained a Q-1.

"Identification only"

IV. QUALITY / CONDITION RATINGS

Table 1 shows building-specific information to include Real Property Unique Identifier (RPUID), type of construction, year built, gross area, Facility Condition Index (FCI), and Q-Rating. Table 2 shows buildings that are classified as temporary (TEMP) or relocatable (RELO) and therefore, by definition, are not included in Quality/Condition calculations.

TABLE 1: QUALITY / CONDITION RATINGS								
Photo	Building	RPUID	Type	Year Built	GSF	Assessed		Plant Replacement Value ³
						FCI	Q-Rating	
	700	1064995	PERM	2011	267,825	100	Q 1	

³ The Plant Replacement Value is calculated according to the DoD Facility Pricing Guide

TABLE 2: TEMPORARY / RELOCATABLE BUILDINGS					
Photo	Building	Type	Year Built	GSF	Current Use
	X700A	RELO	2011	24	Storage Shed
	X700B	RELO	2011	24	Storage Shed
	X700C	RELO	2011	24	Storage Shed
	X700D	RELO	2011	24	Storage Shed
	X700E	RELO	2011	24	Storage Shed
	X700F	RELO	2011	24	Storage Shed

Appendix A

Site Plan

"identification only"

SYMBOL LEGEND

BASKETBALL GOAL

AREA LIGHT

STADIUM LIGHT

FLAG POLE

OPEN

MONUMENT

FEDERAL GOAL

DOCKING GOAL

BASEBALL BACKSTOP

MAIN ENTRY

PARKING AREA

CONCRETE

FLAT ROOF

PLAYGROUND

GRAVEL SLOPE

PERIMETER

CONCRETE WALKWAY

CONCRETE ROOF

SLOPING ROOF

PROPERTY LINE

APPROX. PLANTING

APPROX. PLANTING

FENCE LINE

LEGEND

PLAYGROUND SURFACES

MC-VIDEODISCS PR-FOUR-REBER K-BULCH

SPT-SHOCKED/SHOCKED K-SHOCK

PG-PEA GRAVEL RT-RUBBER TILES

BUILDING LABEL

BLDG L B OF FLOOR

KEY PLAN

MS

NORTH

PROPERTY

MS

01 MAY 2020

NOT TO SCALE

dodea

FACILITY UTILIZATION SURVEY

VICENZA ELEMENTARY SCHOOL

VICENZA MIDDLE SCHOOL

COUNTY: ITALY

CITY: VICENZA

REGION: VENETO


REGION DISTRICT: VICENZA EUROPE SOUTH

HE5420

HE5420

JANUARY 2020

1 of 1



Appendix B

Overview of Sustainment Management System (SMS) and
BUILDER™ Engineered Management System (EMS)

"identification only"

Overview of Sustainment Management System (SMS) and BUILDER™ Engineered Management System (EMS)

Sustainment Management System (SMS)

The Sustainment Management System (SMS) is a suite of web-based software applications developed by the United States Army Corps of Engineers - Engineer Research Development Center - Construction Engineering Research Laboratory (USACE-ERDC-CERL) to help facility engineers, technicians, and managers decide when, where, and how to best maintain the built environment. The SMS modules include BUILDER™ and ROOFER™ for assessing building conditions, PAVER™ for pavements, and RAILER™ for railroad infrastructure.

Because real property assets are so vast and diverse, a "knowledge-based" philosophy drives the SMS process. The process starts with the automated download of real property data, and then more detailed system inventory is modeled and/or collected which identifies components and their key life cycle attributes such as the age and material.

From this inventory, Condition Index (CI) measures for each component are predicted based on its expected stage in the life cycle. Objective and repeatable inspections can then be performed on various components to verify their condition with respect to the expected life cycle deterioration. The level of detail and frequency of these inspections are not fixed like other processes; they are dependent on knowledge of component criticality, the expected and measured condition and rate of deterioration, and remaining maintenance and service life. This "knowledge-based" inspection focuses attention to the most critical components at the time. In addition to these condition assessments, functionality assessments can be performed to evaluate user requirement changes, compliance and obsolescence issues. This provides a comprehensive picture of the overall performance of real property assets and their key components.

BUILDER Engineered Management System (EMS)

In September 2013, the Under Secretary of Defense, Frank Kendall, issued a memo indicating the Department of Defense requires a standardized process for facility condition assessments to ensure consistent and reliable data necessary for sound strategic investment decisions in managing the Department's built environment.

Establishing a DoD-wide facility condition assessment process will contribute to a more credible DoD asset management program and will support better buying power by allowing Department leadership to better target fiscal resources to those facilities most in need of investment. Further, adopting a standard process will help ensure that condition data will be audit-ready in accordance with the Under Secretary of Defense (Comptroller)'s "Financial Improvement and Readiness Guidance" issued in March 2013.

The facility condition assessment process used to generate this report is based on BUILDER Engineered Management System (EMS) Version 3. BUILDER EMS was developed by the Engineer Research and Development Center.

The facility condition assessment process addresses the requirements necessary for routine building facility management activities, including long range budgeting and sustainment/restoration/modernization (SRM) planning. This assessment approach provides an objective and generalized framework to help to identify problem areas that will require more investigation through detailed or specialized assessments. There may be times when detailed engineering assessments may be required to diagnose specific problems.

BUILDER is a software application for building asset life cycle management. The primary focus of BUILDER is work plan development. BUILDER stores real property building information and more detailed system inventory is modeled and/or collected which identifies building components and their key life cycle attributes such as the age, material and capacity. Inspections are then performed on the various components to

determine an objective and repeatable Condition Index (CI) measure, which relates the general physical health of the asset.

With information about condition and remaining service life, BUILDER guides the development of short- and long-range work plans based on sound investment strategies, prioritization criteria, and budget constraints. BUILDER consolidates a variety of building-related management issues into a single decision-support package.

The system gives functional managers and decision-makers instant access to building inventory, current building condition indices, and probabilities condition prediction models. It also employs a patented knowledge-based inspection scheduling process. BUILDER improves the allocation process and return of building life cycle investments by directing resources to the most condition critical components to avoid costly repair penalty costs, as well as, the most mission critical components to manage risks of failure.

BUILDER Facility Condition Assessment Process

Facility Condition Assessment (FCA) is one of the primary processes of a facility life cycle asset management program. The FCA process results in a better understanding of the physical condition and readiness of an organization's buildings along with the reliability of its systems and components. It also facilitates the identification of work candidates for facility SRM repair projects. It is a critical aspect of the shift towards a proactive versus reactive facility management strategy. Instead of keeping facilities operational by relying primarily on corrective repairs (after a system or component has failed due to significant loss of function), it focuses on condition-based repairs which can be planned prior to failure. A condition-based approach can result in higher performing facilities at lower life cycle costs.

Prior to an assessment, knowledge of the building systems and components present is necessary, since assessments are done against these components, not against the building as a whole. This information about the systems and components that make up a building is called the BUILDER Inventory. BUILDER has a vast library of predefined components which all assessors will select from, and the inventory collection process involves identifying the type, quantity, and year installed for all pertinent components. These components are also organized into systems and sub-systems according to the UNIFORMAT classification hierarchy. When a specific instance of a component is recorded, this is called a component-section in BUILDER, and represents a single component assembly or collection of like components to be managed as a single unit. The BUILDER facility condition assessment process directly supports the computation of a condition index for building component-sections, known as the Component-Section Condition Index (CSCI), which is the fundamental metric used in BUILDER. The CSCI is aggregated to compute a condition index metric at the system (SCI), building (BCI), and site/organizational level.

A condition-based facility repair strategy requires condition information be collected at a component level, and that this condition information relate to loss of component function. Every component of a building has a primary function that it performs. This function is the reason that the component was constructed or installed in the building. It may also serve a number of secondary or tertiary functions. For example, for a door component, the primary function is to provide safe entry/egress of authorized movements while limiting unwanted movements of people (security), or other objects (water or moisture). The secondary functions would relate to aesthetics and thermal and air control, among others.

The condition assessment process in BUILDER uses the Direct Rating method.

1. The **Direct Rating** method uses a single qualitative rating for each component based on condition observations. This also results in a condition index metric, which relates to the level of deterioration and the loss of function. This abbreviated Direct Rating approach is often better suited to initial baseline assessments where the components are inventoried, and data is initially loaded into BUILDER.

The following figure illustrates the Direct Rating criteria used in this assessment.

RATING	SRM NEEDS	RATING DEFINITION
Green (+)	Sustainment consisting of possible preventive maintenance (where applicable)	Entire component-section or component-section sample is free of observable or known distress.
Green	Sustainment consisting of possible preventive maintenance (where applicable) and minor repairs (corrective maintenance) to possibly few or some subcomponents.	No component-section or sample serviceability* or reliability* reduction. Some, but not all minor (non-critical) subcomponents may suffer from slight degradation or few major (critical) subcomponents may suffer from slight degradation.
Green (-)		Slight or no serviceability or reliability or reliability reduction overall to the component-section or sample. Some, but not all minor (non-critical) subcomponents may suffer from slight degradation or more than one major (critical) subcomponents may suffer from slight degradation.
Amber (+)	Sustainment or restoration to any of the following: Minor repairs to several sub-components; or Significant repair, rehabilitation or replacement of one or more subcomponents, but not enough to encompass the component-section as a whole; or Combinations thereof.	Component-section or sample serviceability or reliability is degraded, but adequate. A very few major (critical) subcomponents may suffer from moderate deterioration with perhaps a few minor (non-critical) subcomponents suffering from severe deterioration.
Amber		Component-section or sample serviceability or reliability is definitely impaired. Some, but not a majority of major (critical) subcomponents may suffer from moderate deterioration with perhaps many minor (non-critical) subcomponents suffering from severe deterioration.
Amber (-)		Component-section or sample has significant serviceability or reliability loss. Most subcomponents may suffer from moderate degradation or a few major (critical) subcomponents may suffer from severe degradation.
Red (+)	Sustainment or restoration required consisting of major repair, rehabilitation or replacement to the component-section as a whole.	Significant serviceability or reliability reduction in component-section or sample. A majority of subcomponents are severely degraded, and others may have varying degrees of degradation.
Red		Severe serviceability or reliability reduction to the component-section or sample such that it is barely able to perform. Most subcomponents are severely degraded.
Red (-)		Overall component-section degradation is total. Few, if any subcomponents are salvageable. Complete loss of component-section or sample serviceability.

Once the component-sections have been rated with a Direct Rating, BUILDER calculates the Component-Section Condition Index (CSCI) of the component-section. The next step in the process is to create a work plan, which will list the component-sections that need repair or replacement and the estimated cost of the repair or replacement.

To create a work plan, condition standards, policies and a policy sequence are created. The standards serve as thresholds for CSCI and remaining service life. Policies link standards to component-sections and policy sequences link standards and policies together.

The table below summarizes the DoDEA standards and how they are applied to the component-sections for this assessment.

Standard and Component-section Cross-Reference		
Standard	CI Threshold	Component-section
Amber +	80	D4010 FIRE ALARM AND DETECTION SYSTEMS
Amber	71	B3010 ROOF COVERINGS D1010 ELEVATORS AND LIFTS D2010 PLUMBING FIXTURES D3020 HEAT GENERATING SYSTEMS D3030 COOLING GENERATING SYSTEMS D3040 DISTRIBUTION SYSTEMS (A) D3050 TERMINAL & PACKAGE UNITS D3060 CONTROLS & INSTRUMENTATION D3090 OTHER HVAC SYSTEMS AND EQUIPMENT D4020 FIRE SUPP WATER SUPPLY / EQUIP D4030 STANDPIPE SYSTEMS D4040 SPRINKLERS D4050 FIRE PROTECTION SPECIALTIES D4090 OTHER FIRE PROTECTION SYSTEMS D5010 ELECTRICAL SERVICE & DISTRIBUTION D5020 LIGHTING & BRANCH WIRING D5030 COMMUNICATIONS & SECURITY D5090 OTHER ELECTRICAL SERVICES
Amber -	61	B2030 EXTERIOR DOORS C1020 INTERIOR DOORS C3010 WALL FINISHES C3020 FLOOR FINISHES C3030 CEILING FINISHES C3040 INT COATINGS / SPECIAL FINISHES D3010 ENERGY SUPPLY
Red +	50	B2010 EXTERIOR WALLS B2020 EXTERIOR WINDOWS C1030 SPECIALTIES D1020 WEIGHT HANDLING EQUIPMENT D1030 ESCALATORS AND MOVING WALKS D1090 OTHER CONVEYING SYSTEMS D2020 DOMESTIC WATER DISTRIBUTION D2030 SANITARY WASTE D2040 RAIN WATER DRAINAGE D2090 OTHER PLUMBING SYSTEMS D3070 SYSTEMS TESTING & BALANCING
Service Life	40	Paint

For this project, the following building components are not included in the BUILDER Inventory and are not evaluated during the assessment unless significant damage or deterioration was observed or reported.

- A1010 STANDARD FOUNDATIONS
- A1020 SPECIAL FOUNDATIONS
- A1030 SLAB ON GRADE
- A2010 BASEMENT EXCAVATION
- A2020 BASEMENT WALLS
- B1010 FLOOR CONSTRUCTION
- B1020 ROOF CONSTRUCTION
- B2010 EXTERIOR WALLS
- C1010 PARTITIONS
- C2010 STAIR CONSTRUCTION

Damage that is not visible or that is unknown will not be reflected in facility condition index calculations. It is anticipated that unknown damage or deterioration is more likely to be present in older facilities than more modern facilities.

In addition, some building components are concealed or inaccessible. In accordance with BUILDER guidelines, quantities for concealed and inaccessible components have been estimated and recorded in the BUILDER Inventory but have not been rated. When concealed or inaccessible components are encountered, life cycle data contained within BUILDER is used to predict renewal requirements, which are included in facility condition index calculations. Components that are often concealed or inaccessible include:

- D2020 DOMESTIC WATER PIPING
- D2030 SANITARY WASTE PIPING
- D3040 HVAC DISTRIBUTION
- D4010 FIRE ALARM DISTRIBUTION
- D5020 ELECTRICAL BRANCH WIRING

In addition to the building components noted above, if a building component is concealed or inaccessible, life cycle data contained within BUILDER is used to predict renewal requirements.

When a work plan is created, the CSCI of a component-section is compared to its associated standard. If the CSCI is less than or equal to the threshold in the standard, the remaining service life is evaluated. If the service life is less than the standard's remaining service life, BUILDER will add this section to the work plan and generate dollars to estimate a cost for the replacement.

If the CSCI is less than or equal to the threshold in the standard and the service life is greater than the standard's remaining service life, BUILDER will conduct a cost benefit analysis. The cost benefit analysis will determine whether the component-section should be repaired or left to expire at the end of its service life. When BUILDER determines a repair is the correct action, BUILDER will add this section to the work plan and generate dollars to estimate a cost for the repair.

When BUILDER determines taking no action is more cost effective, BUILDER will not add the component-section to the work plan. For example, if the CSCI for an external door component-section is 50 with a remaining service life of five years, BUILDER will compare the CSCI of 50 to the CI Threshold set by DoDEA and determine that 50 is less than the threshold of 61. BUILDER will compare the five years of remaining services life against the zero years of the threshold and determine a cost benefit analysis is required. The results of the cost benefit analysis will typically suggest to take no action and let the component-section run until the end of its service life before generating an item in the work plan.

A typical life cycle of a component-section is explained below.

Condition	Work Plan
CSCI > threshold	Work plan does not generate an item for the component-section
CSCI = threshold or just below it	Work plan will generate a repair item for the component-section
CSCI < threshold and the remaining service life > service life threshold	Work plan will remove the repair item for the component-section. It is too costly to repair so it is better to wait to replace it.
Remaining service life < service life threshold	Work plan will generate a replace item for the component-section

Facility Condition Assessment Data Analysis

In multiple building portfolios and especially with widespread geographic portfolios, it is important to know how building conditions compare. The Condition Index (CI) and Quality Ratings (Q-Ratings) are determined for each building assessed using guidelines shown below.

Condition Index (CI) – A measure of the constructed asset's condition at a specific point in time with respect to physical condition and ability to support the current occupant or mission. CI is calculated as the ratio of estimated cost of maintenance and repair requirements to Plant Replacement Value (PRV). Maintenance and repair requirements consist of that work necessary to ensure that a constructed asset is restored to a condition substantially equivalent to the originally intended and designed capacity, efficiency or capability. The formula for Condition Index is:

$$CI = 1 - \left(\frac{\text{Requirements}}{\text{PRV}} \right) \times 100$$

Q-Rating Bands – Bands allow OSD, Military Services, and Defense Agencies/Activities to group facilities by condition for the purposes of developing investment strategies.

TABLE 1: Q-RATING DESCRIPTIONS		
Rating Band	Calculated Rating (Condition Index)	General Description
Q-1	100 to 90	Facility is new or well-maintained (Good Condition)
Q-2	89 to 80	Facility is satisfactorily maintained (Fair Condition)
Q-3	79 to 60	Facility is under maintained (Poor Condition)
Q-4	59 to 0	Facility should be considered for replacement (Failing Condition)

Requirements – Sum of the work items from BUILDER.

Plant Replacement Value – Cost to design and construct a notional facility to current standards to replace an existing facility on the same site, (reference United Facilities Criteria UFC 3-701-01 23 May 2018, Change 3, 29 July 2019).

BUILDER Report Overview

Outlined below is a summary and description of the reports that are included.

Appendix C - Facility Summary Report – Provides a summation of FCA results. A Building Summary Report is included for each building that is considered permanent or semi-permanent construction and receives a Q-Rating. The purpose of this report is to provide a general overview of the building including key performance indicators. This report was generated using DoDEA's calculated Replacement Cost overwriting the data populated from real property records. This provides a more accurate Replacement Cost due to the inconsistencies with real property reconciliation between DoDEA and the Services. The DoD Facility Pricing Guide and DoDEA measurements for building square footage were used to calculate the Replacement Cost.

Appendix D - System Summary Report – Provides an overview of inspected systems and their condition index rating. A Building System Condition Index (SCI) By System Report is included for each building that is considered permanent or semi-permanent construction and receives a Q-Rating.

Appendix E - Work Items By Building – Provides a list of work items requiring repair or replacement of system/components, including budgets, for project planning purposes. A Work Plan Detail by Year Report is included for each building that is considered permanent or semi-permanent construction and receives a Q-Rating.

Appendix F - Remaining Service Life (RSL) Detail Report – Provides a detailed overview of systems/components, including descriptions, and their respective age, remaining service life and remaining paint life.

Appendix G - Direct Condition Rating Inspection By Section Report – Provides a summary of direct condition ratings for each component-section collected within each facility.

Appendix H - System Inventory Report – Provides a list of details for each component-section collected within each facility.

Appendix I - Fire Inspection Safety Report – This appendix is only applicable when a Fire Inspection Safety Report is provided at the time of the assessment for inclusion in the Facility Condition Assessment Report. The report provides a summary of the recent Fire Inspection to include any deficiencies.

Note: All reports are generated from the DoDEA BUILDER database. In the event line items within a report are compressed and difficult to read, this is a result of how BUILDER generates the report. It is our understanding that CERL is working to update the report format.

Summary of Terms

Acronyms	Description
BCI	Building Condition Index - Measures the condition of the building as a whole. The higher the BCI, the better.
BFI	Building Functionality Index - Measures the functionality of a building as a whole. The higher the BFI, the better.
BPI	Building Performance Index - Measures the overall performance of a building. The higher the BPI, the better.
EA	Each
ESC	Emergency Service Call
FCI	Facility Condition Index - The current maintenance, repair, and replacement deficiencies of the facility divided by the current replacement value of the facility, derives the FCI of a facility. The higher the FCI, the better.
GSF	Gross Square Foot
ISR	Installation Status Report - Measures installation condition against Army-wide standards.
LF	Linear Feet
MBH	Thousands of BTU per hour.
MDI	Mission Dependency Index - Measures how critical a facility is to the overall mission of its owner. The higher the MDI, the more critical.
PERM	Permanent
RELO	Relocatable
RPL	Remaining Paint Life - Displays the remaining paint life, in years, of a section.
RPUID	Real Property Unique Identifier - The unique identification number assigned to each asset.
RSL	Remaining Service Life - Displays the remaining service life, in years, of a section.
SCI	System Condition Index - Measures the condition of a system as a whole. The higher the SCI, the better.
SF	Square Foot
TEMP	Temporary
UM	Unit of Measure

Appendix C

Facility Summary Report

"identification only"

700 - Vicenza Bldg ES/MS 700

Vicenza FAM HSG - Unassigned



YEAR BUILT: 2011

AREA (SF): 267,825

PLANT REPLACEMENT COST: [REDACTED]

SURVEY DATE: January 2020

TOTAL DEFICIENCIES: \$0

BUILDER(TM) METRIC		SCORE
Facility Condition Index	FCI:	100

Appendix D

System Summary Report

"identification only"

DoDEA SYSTEM SUMMARY

Vicenza FAM HSG

Complex	Building #	Building Name	A10	A20	B10	B20	B30	C10	C20	C30	D10	D20	D30	D40	D50	E10	E20	F10	F20	G10	G20	G30	G40	G90
Unassigned	700	Vicenza Bldg ES/MS 700				77	66	80	86	85	87	96	89	95	90	94								

A10 - Foundations

A20 -Basement Construction

B10 - Superstructure

B20 - Exterior Enclosure

B30 - Roofing

C10 - Interior Construction

C20 - Stairs

C30 - Interior Finishes

D10 - Conveying

D20 - Plumbing

D30 - HVAC

D40 - Fire Protection

D50 - Electrical

E10 - Equipment

E20 - Furnishings

F10 - Special Construction

F20 - Selective Building Demo

G10 - Site Preparations

G20 - Site Improvements

G30 - Site Civil / Mech Utilities

G40 - Site Electrical Utilities

G50 - Other Site Construction

Appendix E

Work Items By Building

"identification only"

Vicenza FAM HSG

Cost Book: Reference

700 - Vicenza Bldg ES/MS 700

Unassigned

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
2015	C30	INTERIOR FINISHES						
	C3020	FLOOR FINISHES	5,663 (SF)	Replace				0.00
	2011 C302005	CARPETING General						
	-- Replace C3020 FLOOR FINISHES 2011 C302005 CARPETING General							
	C3020	FLOOR FINISHES	5,663 (SF)	Replace				0.00
	2011 C302005	CARPETING General						
	-- Replace C3020 FLOOR FINISHES 2011 C302005 CARPETING General							
2017	B30	ROOFING						
	B3010	ROOF COVERINGS	6,000 (SF)	Repair				0.00
	2011 B301002	LOW SLOPE ROOF SYSTEMS Built-Up						
	-- Repair B3010 ROOF COVERINGS 2011 B301002 LOW SLOPE ROOF SYSTEMS Built-Up							
2017	C30	INTERIOR FINISHES						
	C3020	FLOOR FINISHES	5,663 (SF)	Replace				0.00
	2011 C302005	CARPETING General						
	-- Replace C3020 FLOOR FINISHES 2011 C302005 CARPETING General							
2018	D50	ELECTRICAL						
	D5030	COMMUNICATIONS & SECURITY	1 (EA)	Replace				0.00
	2011 A D503003	INTERCOMMUNICATIONS SYSTEMS 100 stations						
	-- Replace D5030 COMMUNICATIONS & SECURITY 2011 A D503003 INTERCOMMUNICATIONS SYSTEMS 100 stations							
2019	C30	INTERIOR FINISHES						
	C3020	FLOOR FINISHES	5,800 (SF)	Replace				0.00
	2011 C302005	CARPETING General						
	-- Replace C3020 FLOOR FINISHES 2011 C302005 CARPETING General							



Vicenza FAM HSG

Cost Book: Reference

700 - Vicenza Bldg ES/MS 700

Unassigned

Year	System	Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score	Completion Date
-- Description										
2019	D50	ELECTRICAL								
	D5030	COMMUNICATIONS & SECURITY	1 EA	Replace						0.00
	2011 A	D503003 INTERCOMMUNICATIONS SYSTEMS	100 stations							
		-- Replace D5030 COMMUNICATIONS & SECURITY 2011 A D503003 INTERCOMMUNICATIONS SYSTEMS 100 stations								

"Identification only"

Appendix F

Remaining Service Life (RSL) Detail Report

"identification only"

Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	2011 B201001 EXTERIOR CLOSURE E.I.F.S.	9	15	
	B2010 EXTERIOR WALLS	2011 B201004 PARAPETS General	9	8	
	B2010 EXTERIOR WALLS	2011 B201005 EXTERIOR LOUVERS & SCREENS General	9	10	
	B2010 EXTERIOR WALLS	2011 B201006 BALCONY WALLS & HANDRAILS Ladder	9	8	
	B2010 EXTERIOR WALLS	2011 B201007 EXTERIOR SOFFITS General	9	8	
	B2010 EXTERIOR WALLS	2011 B201010 EXTERIOR JOINT SEALANT General	9	8	
	B2020 EXTERIOR WINDOWS	2011 B202001 WINDOWS Aluminum Windows	9	39	
	B2020 EXTERIOR WINDOWS	2011 B202002 STOREFRONTS General	9	10	
	B2020 EXTERIOR WINDOWS	2011 B202003 CURTAIN WALLS General	9	39	
	B2030 EXTERIOR DOORS	2011 B203001 SOLID DOORS Aluminum	9	10	
	B2030 EXTERIOR DOORS	2011 B203002 GLAZED DOORS General	9	21	
	B2030 EXTERIOR DOORS	2011 B203007 GATES General	9	10	Unknown
	B2030 EXTERIOR DOORS	2011 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress	9	10	
B30 ROOFING	B3010 ROOF COVERINGS	2011 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	9	7	
	B3010 ROOF COVERINGS	2011 B301002 LOW SLOPE ROOF SYSTEMS Built-Up	9	4	
	B3010 ROOF COVERINGS	2011 B301003 ROOF INSULATION & FILL General	9	11	
	B3010 ROOF COVERINGS	2011 B301004 FLASHINGS & TRIM Flashings - Base	9	10	
	B3010 ROOF COVERINGS	2011 B301004 FLASHINGS & TRIM Flashings - Valley	9	10	
	B3010 ROOF COVERINGS	2011 B301005 GUTTERS & DOWNSPOUTS Downspouts	9	10	
	B3010 ROOF COVERINGS	2011 B301005 GUTTERS & DOWNSPOUTS Gutters	9	10	
	B3010 ROOF COVERINGS	2011 B301006 ROOF OPENINGS AND SUPPORTS Gravity Ventilator - 48" x 60"	9	10	
	B3010 ROOF COVERINGS	2011 B301006 ROOF OPENINGS AND SUPPORTS Gravity Ventilator - 6"	9	10	
	B3010 ROOF COVERINGS	2011 A B301004 FLASHINGS & TRIM Flashings - Cap	9	10	
	B3010 ROOF COVERINGS	2011 B B301004 FLASHINGS & TRIM Flashings - Cap	9	10	
C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	2011 C101001 FIXED PARTITIONS Wall - Drywall w/Stud Framing	9	26	27
	C1010 PARTITIONS	2011 C101005 INTERIOR WINDOWS Interior Windows	9	26	
	C1020 INTERIOR DOORS	2011 C102001 STANDARD INTERIOR DOORS Wood Door/Wood Frame	9	16	
	C1020 INTERIOR DOORS	2011 C102002 GLAZED INTERIOR DOORS General	9	12	
	C1030 SPECIALTIES	2011 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Shower	9	8	
	C1030 SPECIALTIES	2011 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet	9	10	
	C1030 SPECIALTIES	2011 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Urinal	9	10	



Remaining Service Life (RSL) Detail Report



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	C1030 SPECIALTIES	2011 C103002 TOILET & BATH ACCESSORIES General	9	8	
	C1030 SPECIALTIES	2011 C103003 MARKER BOARDS & TACK BOARDS General	9	8	
	C1030 SPECIALTIES	2011 C103005 LOCKERS General	9	12	
	C1030 SPECIALTIES	2011 C103008 COUNTERS Laminated Plastic	9	12	
	C1030 SPECIALTIES	2011 C103009 CABINETS Other	9	8	
C20 STAIRS	C2010 STAIR CONSTRUCTION	2011 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	9	41	
	C2010 STAIR CONSTRUCTION	2011 C201001 INTERIOR AND EXTERIOR STAIRS Interior Steps	9	10	Unknown
	C2010 STAIR CONSTRUCTION	2011 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General	9	10	
C30 INTERIOR FINISHES	C3010 WALL FINISHES	2011 C301004 TILE & TERRAZZO WALL FINISHES Tile	9	39	
	C3020 FLOOR FINISHES	2011 C302001 TILE FLOOR FINISHES Ceramic Tile	9	39	
	C3020 FLOOR FINISHES	2011 C302001 WOOD FLOORING General	9	16	
	C3020 FLOOR FINISHES	2011 C302004 RESILIENT FLOOR FINISHES Composition Sheet	9	7	
	C3020 FLOOR FINISHES	2011 C302005 CARPETING General	9	2	
	C3030 CEILING FINISHES	2011 C303001 ACOUSTICAL CEILING TILES & PANELS General	9	29	
	C3030 CEILING FINISHES	2011 C303003 PLASTER CEILING FINISHES General	9	65	Unknown
	C3030 CEILING FINISHES	2011 C303005 SUSPENSION SYSTEMS General	9	8	
D10 CONVEYING	D1010 ELEVATORS AND LIFTS	2011 D101002 PASSENGER ELEVATORS Hydraulic Elevators - 2000 lb, 2 floors	9	13	
D20 PLUMBING	D2010 PLUMBING FIXTURES	2011 D201001 WATERCLOSETS General	9	10	
	D2010 PLUMBING FIXTURES	2011 D201002 URINALS General	9	10	
	D2010 PLUMBING FIXTURES	2011 D201004 SINKS General	9	10	
	D2010 PLUMBING FIXTURES	2011 D201004 SINKS Kitchen Sink	9	18	
	D2010 PLUMBING FIXTURES	2011 D201004 SINKS Service Sink	9	10	
	D2010 PLUMBING FIXTURES	2011 D201005 SHOWERS/TUBS Shower	9	10	
	D2010 PLUMBING FIXTURES	2011 D201006 DRINKING FOUNTAINS AND COOLERS Drinking Fountain	9	10	
	D2010 PLUMBING FIXTURES	2011 D201090 OTHER PLUMBING FIXTURES Emergency Eye Wash	9	13	
	D2010 PLUMBING FIXTURES	2011 D201090 OTHER PLUMBING FIXTURES Emergency Shower	9	13	
	D2020 DOMESTIC WATER	2011 D202001 PIPES & FITTINGS General	9	41	
	D2020 DOMESTIC WATER	2011 D202003 DOMESTIC WATER EQUIPMENT Storage Tank - Galvanized	4	15	
	D2020 DOMESTIC WATER	2011 D202003 DOMESTIC WATER EQUIPMENT Water Heaters, Residential,	9	10	
	D2020 DOMESTIC WATER	2011 M0302 D202003 DOMESTIC WATER EQUIPMENT Water Heaters,	9	4	

Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D2020 DOMESTIC WATER DISTRIBUTION	2011 M3010 D202003 DOMESTIC WATER EQUIPMENT Booster Pump - 1 HP	9	10	
	D2020 DOMESTIC WATER DISTRIBUTION	2011 M3010 D202003 DOMESTIC WATER EQUIPMENT Water Heaters, General	9	5	
	D2020 DOMESTIC WATER DISTRIBUTION	2011 M3020 D202003 DOMESTIC WATER EQUIPMENT Booster Pump - 1 HP	9	8	
	D2030 SANITARY WASTE DISTRIBUTION	2011 D203001 WASTE PIPE & FITTINGS General	9	41	
	D2030 SANITARY WASTE DISTRIBUTION	2011 D203002 VENT PIPE & FITTINGS General	9	11	
	D2030 SANITARY WASTE DISTRIBUTION	2011 D203003 FLOOR DRAINS General	9	10	
D30 HVAC	D3020 HEAT GENERATING SYSTEMS	2011 D302004 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	9	15	
	D3020 HEAT GENERATING SYSTEMS	2011 D302004 AUXILIARY EQUIPMENT Expansion Tank - 80 gal	4	15	
	D3020 HEAT GENERATING SYSTEMS	2011 D302005 EQUIPMENT THERMAL INSULATION General	9	10	
	D3040 DISTRIBUTION SYSTEMS	2011 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	9	31	
	D3040 DISTRIBUTION SYSTEMS	2011 D304001 AIR DISTRIBUTION, HEATING & COOLING Smoke Vents	9	10	
	D3040 DISTRIBUTION SYSTEMS	2011 D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating Pump, End	9	10	
	D3040 DISTRIBUTION SYSTEMS	2011 D304003 HOT WATER DISTRIBUTION SYSTEMS General	9	11	
	D3040 DISTRIBUTION SYSTEMS	2011 D304006 CHILLED WATER DISTRIBUTION SYSTEMS Circulating Pump, End	9	10	
	D3040 DISTRIBUTION SYSTEMS	2011 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	9	11	
	D3040 DISTRIBUTION SYSTEMS	2011 D304007 EXHAUST SYSTEMS Fume Hood Exhaust System - 6', 5000 CFM	9	5	
	D3040 DISTRIBUTION SYSTEMS	2011 D304007 EXHAUST SYSTEMS Kitchen Exhaust/Make-Up Air - 5000 CFM	9	10	
	D3040 DISTRIBUTION SYSTEMS	2011 M0301 AHU/2E D304008 AIR HANDLING UNITS Central Station - 30000 CFM	9	18	
	D3040 DISTRIBUTION SYSTEMS	2011 M0301 AHU/3E D304008 AIR HANDLING UNITS Central Station - 30000 CFM	9	18	
	D3040 DISTRIBUTION SYSTEMS	2011 M0301 EF/10E D304007 EXHAUST SYSTEMS Fan System, Wall Exhaust	9	5	
	D3040 DISTRIBUTION SYSTEMS	2011 M0301 EF/11E D304007 EXHAUST SYSTEMS Fan System, Wall Exhaust	9	5	
	D3040 DISTRIBUTION SYSTEMS	2011 M0301 EF/13E D304007 EXHAUST SYSTEMS Fan System, Wall Exhaust	9	5	
	D3040 DISTRIBUTION SYSTEMS	2011 M0301 EF/14E D304007 EXHAUST SYSTEMS Fan System, Wall Exhaust	9	5	
	D3040 DISTRIBUTION SYSTEMS	2011 M0301 EF/15E D304007 EXHAUST SYSTEMS Fan System, Wall Exhaust	9	5	
	D3040 DISTRIBUTION SYSTEMS	2011 M0301 EF/9E D304007 EXHAUST SYSTEMS Fan System, Wall Exhaust	9	5	
	D3040 DISTRIBUTION SYSTEMS	2011 M0301 ERU/2E D304008 AIR HANDLING UNITS Central Station - 10000 CFM	9	8	
	D3040 DISTRIBUTION SYSTEMS	2011 M0302 AHU/4E D304008 AIR HANDLING UNITS Central Station - 20000 CFM	9	8	
	D3040 DISTRIBUTION SYSTEMS	2011 M0302 AHU/5E D304008 AIR HANDLING UNITS Central Station - 30000 CFM	9	14	
	D3040 DISTRIBUTION SYSTEMS	2011 M0302 EF/12E D304008 AIR HANDLING UNITS Central Station - 30000 CFM	9	18	
	D3040 DISTRIBUTION SYSTEMS	2011 M0302 EF/5E D304008 AIR HANDLING UNITS Central Station - 30000 CFM	9	18	
	D3040 DISTRIBUTION SYSTEMS	2011 M0302 ERU/3E D304008 AIR HANDLING UNITS Central Station - 30000 CFM	9	18	
	D3040 DISTRIBUTION SYSTEMS	2011 M0302 ERU/4E D304008 AIR HANDLING UNITS Central Station - 30000 CFM	9	18	



Remaining Service Life (RSL) Detail Report



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D3040 DISTRIBUTION SYSTEMS	2011 M1090 AHU/1E D304008 AIR HANDLING UNITS Central Station - 30000	9	18	
	D3040 DISTRIBUTION SYSTEMS	2011 M1090 AHU/7E D304008 AIR HANDLING UNITS Central Station - 30000	9	18	
	D3040 DISTRIBUTION SYSTEMS	2011 M1090 EF/3E D304007 EXHAUST SYSTEMS Fan System, Wall Exhaust	9	5	
	D3040 DISTRIBUTION SYSTEMS	2011 M1090 EF/4E D304007 EXHAUST SYSTEMS Fan System, Wall Exhaust	9	5	
	D3040 DISTRIBUTION SYSTEMS	2011 M1090 ERU/1E D304008 AIR HANDLING UNITS Central Station - 30000	9	14	
	D3040 DISTRIBUTION SYSTEMS	2011 M1255 AHU/6E D304008 AIR HANDLING UNITS Central Station - 30000	9	18	
	D3050 TERMINAL & PACKAGE UNITS	2011 D305001 UNIT VENTILATORS Air Curtain	9	10	
	D3050 TERMINAL & PACKAGE UNITS	2011 D305002 UNIT HEATERS Hydronic - 200 MBH	9	15	
	D3050 TERMINAL & PACKAGE UNITS	2011 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	9	8	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION	2011 D401001 FIRE ALARM DISTRIBUTION Other	9	11	
	D4020 FIRE SUPP WATER SUPPLY / EQUIPMENT	2011 D402001 FIRE PROTECTION WATER PIPING AND EQUIPMENT Backflow	9	21	
	D4030 STANDPIPE SYSTEMS	2011 D403001 STANDPIPE EQUIPMENT & PIPING Riser - 4" diam	9	10	
	D4040 SPRINKLERS	2011 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	9	66	
	D4090 OTHER FIRE PROTECTION	2011 D409004 HOOD & DUCT FIRE PROTECTION General	9	13	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & EQUIPMENT	2011 D501004 PANELBOARDS Main lugs, 120/208 V, 100 amp, NQOD	9	15	
	D5010 ELECTRICAL SERVICE & EQUIPMENT	2011 D501004 PANELBOARDS Main lugs, 120/208 V, 225 amp, NQOD	9	15	
	D5010 ELECTRICAL SERVICE & EQUIPMENT	2011 D501004 PANELBOARDS Switchgear - 2000 Amp	9	26	
	D5010 ELECTRICAL SERVICE & EQUIPMENT	2011 D501004 PANELBOARDS Switchgear - 100 Amp	9	26	
	D5010 ELECTRICAL SERVICE & EQUIPMENT	2011 D501004 PANELBOARDS Switchgear - 800 Amp	9	26	
	D5010 ELECTRICAL SERVICE & EQUIPMENT	2011 D501005 ENCLOSED CIRCUIT BREAKERS Main circuit breaker, 120/208	9	26	
	D5010 ELECTRICAL SERVICE & EQUIPMENT	2011 D501006 MOTOR CONTROL CENTERS Motor Control Center - Size 3, 50	9	21	
	D5010 ELECTRICAL SERVICE & EQUIPMENT	2011 D501006 MOTOR CONTROL CENTERS Motor Control Center - Size 4, 100	9	21	
	D5020 LIGHTING & BRANCH WIRING	2011 D502001 BRANCH WIRING General	9	51	
	D5020 LIGHTING & BRANCH WIRING	2011 D502002 LIGHTING EQUIPMENT Exit Lighting	9	10	
	D5020 LIGHTING & BRANCH WIRING	2011 D502002 LIGHTING EQUIPMENT General	9	10	
	D5030 COMMUNICATIONS & EQUIPMENT	2011 D503005 SECURITY SYSTEMS General	9	10	
	D5030 COMMUNICATIONS & EQUIPMENT	2011 D503007 CLOCK & PROGRAM SYSTEMS General	9	10	
	D5030 COMMUNICATIONS & EQUIPMENT	2011 A D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	9	10	
	D5030 COMMUNICATIONS & EQUIPMENT	2011 A D503003 INTERCOMMUNICATIONS SYSTEMS 100 stations	9	8	
	D5030 COMMUNICATIONS & EQUIPMENT	2011 B D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	9	10	
	D5030 COMMUNICATIONS & EQUIPMENT	2011 B D503003 INTERCOMMUNICATIONS SYSTEMS 100 stations	9	8	

Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D5090 OTHER ELECTRICAL	2011 D509002 EMERGENCY LIGHTING & POWER General	9	10	
	D5090 OTHER ELECTRICAL	2011 D509003 GROUNDING SYSTEMS General	9	41	
	D5090 OTHER ELECTRICAL	2011 D509004 LIGHTNING PROTECTION Unknown	9	26	
	D5090 OTHER ELECTRICAL	2011 D509006 ENERGY MANAGEMENT CONTROL SYSTEM General	9	10	
E10 EQUIPMENT	E1090 OTHER EQUIPMENT	*DEEP FRYER E109002 FOOD SERVICE EQUIPMENT General	9	13	
	E1090 OTHER EQUIPMENT	*DISH MACHINE E109002 FOOD SERVICE EQUIPMENT General	9	13	
	E1090 OTHER EQUIPMENT	*FIRE SUPPRESSION SYSTEM E109002 FOOD SERVICE EQUIPMENT	9	13	
	E1090 OTHER EQUIPMENT	*FREEZER REACH IN 2 DR E109002 FOOD SERVICE EQUIPMENT General	9	13	
	E1090 OTHER EQUIPMENT	*HOT CABINET REACH IN 1 DR A E109002 FOOD SERVICE EQUIPMENT	9	13	
	E1090 OTHER EQUIPMENT	*HOT CABINET REACH IN 1 DR B E109002 FOOD SERVICE EQUIPMENT	9	13	
	E1090 OTHER EQUIPMENT	*HOT CABINET REACH IN 1 DR C E109002 FOOD SERVICE EQUIPMENT	9	13	
	E1090 OTHER EQUIPMENT	*HOT CABINET REACH IN 1 DR D E109002 FOOD SERVICE EQUIPMENT	9	13	
	E1090 OTHER EQUIPMENT	*ICE MACHINE E109002 FOOD SERVICE EQUIPMENT General	9	13	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR PASS THRU 4 DR A E109002 FOOD SERVICE EQUIPMENT	9	13	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR PASS THRU 4 DR B E109002 FOOD SERVICE EQUIPMENT	9	13	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR PASS THRU 4 DR C E109002 FOOD SERVICE EQUIPMENT	9	13	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR PASS THRU 4 DR D E109002 FOOD SERVICE EQUIPMENT	9	13	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR PASS THRU 4 DR E E109002 FOOD SERVICE EQUIPMENT	9	13	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2 DR A E109002 FOOD SERVICE EQUIPMENT	9	13	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2 DR B E109002 FOOD SERVICE EQUIPMENT	9	13	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2 DR C E109002 FOOD SERVICE EQUIPMENT	9	13	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2 DR D E109002 FOOD SERVICE EQUIPMENT	9	13	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2 DR E E109002 FOOD SERVICE EQUIPMENT	9	13	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2 DR F E109002 FOOD SERVICE EQUIPMENT	9	13	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2 DR G E109002 FOOD SERVICE EQUIPMENT	9	13	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN A E109002 FOOD SERVICE EQUIPMENT	9	13	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN B E109002 FOOD SERVICE EQUIPMENT	9	13	
	E1090 OTHER EQUIPMENT	*STEAMER 1 DOOR A E109002 FOOD SERVICE EQUIPMENT General	9	13	
	E1090 OTHER EQUIPMENT	*TILT KETTLE E109002 FOOD SERVICE EQUIPMENT General	9	13	
	E1090 OTHER EQUIPMENT	*WALK IN COOLER E109002 FOOD SERVICE EQUIPMENT General	9	13	
	E1090 OTHER EQUIPMENT	*WALK IN FREEZER E109002 FOOD SERVICE EQUIPMENT General	9	13	

Appendix G

Direct Condition Rating Inspection By Section Report

"identification only"



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
*DEEP FRYER E109002 FOOD SERVICE EQUIPMENT General	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: G Used Sampling? No Inspection Source: Inspection			
*DISH MACHINE E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: G Used Sampling? No Inspection Source: Inspection			
*FIRE SUPPRESSION SYSTEM E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: G Used Sampling? No Inspection Source: Inspection			
*FREEZER REACH IN 2 DR E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: G Used Sampling? No Inspection Source: Inspection			
*HOT CABINET REACH IN 1 DR A E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: G Used Sampling? No Inspection Source: Inspection			
*HOT CABINET REACH IN 1 DR B E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: G Used Sampling? No Inspection Source: Inspection			
*HOT CABINET REACH IN 1 DR C E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
*HOT CABINET REACH IN 1 DR D E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
*ICE MACHINE E109002 FOOD SERVICE EQUIPMENT General	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
*REFRIGERATOR PASS THRU 4 DR A E109002 FOOD	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
*REFRIGERATOR PASS THRU 4 DR B E109002 FOOD	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
*REFRIGERATOR PASS THRU 4 DR C E109002 FOOD	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
*REFRIGERATOR PASS THRU 4 DR D E109002 FOOD	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
*REFRIGERATOR PASS THRU 4 DR E E109002 FOOD	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
*REFRIGERATOR REACH IN 2 DR A E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
*REFRIGERATOR REACH IN 2 DR B E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
*REFRIGERATOR REACH IN 2 DR C E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
*REFRIGERATOR REACH IN 2 DR D E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
*REFRIGERATOR REACH IN 2 DR E E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
*REFRIGERATOR REACH IN 2 DR F E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
*REFRIGERATOR REACH IN 2 DR G E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
*STEAM COUNTER ELECTRIC MULTI BASIN A E109002 FOOD	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
*STEAM COUNTER ELECTRIC MULTI BASIN B E109002 FOOD	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
*STEAMER 1 DOOR A E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
*TILT KETTLE E109002 FOOD SERVICE EQUIPMENT General	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
*WALK IN COOLER E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
*WALK IN FREEZER E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 B201001 EXTERIOR CLOSURE E.I.F.S.	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	88,000 (SF)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i> The exterior wall trim composed of synthetic stone over rigid foam was consistently damaged and deteriorated as was the wall base finish with exposed metal lath beginning to rust. Numerous hairline cracks were also observed.	<i>Condition Rating:</i> A	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 B201004 PARAPETS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	196 (LF)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> A+	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 B201005 EXTERIOR LOUVERS & SCREENS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	5,822 (SF)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 B201006 BALCONY WALLS & HANDRAILS Ladder	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	57 (LF)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 B201007 EXTERIOR SOFFITS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	7,167 (SF)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> A+	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	7,310 (LF)



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2011 B202001 WINDOWS Aluminum Windows	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	384 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 B202002 STOREFRONTS General	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	612 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 B202003 CURTAIN WALLS General	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	1,339 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 B203001 SOLID DOORS Aluminum	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	10 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 B203002 GLAZED DOORS General	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	11 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 B203007 GATES General	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	147 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: G-	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
2011 B203090 OTHER EXTERIOR SPECIALTY DOORS	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	57 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 B301001 STEEP SLOPE ROOF SYSTEMS Clay Tile	B30 ROOFING	B3010 ROOF COVERINGS	148,000 (SF)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i> The clay tile roofing system was reported to have numerous leaks throughout the school. A detailed report based on crane lift investigations was provided. Assessor observations above ceiling tiles confirmed evidence of the known water leaks.	<i>Condition Rating:</i> R+	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 B301002 LOW SLOPE ROOF SYSTEMS Built-Up	B30 ROOFING	B3010 ROOF COVERINGS	6,000 (SF)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> A+	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 B301003 ROOF INSULATION & FILL General	B30 ROOFING	B3010 ROOF COVERINGS	154,000 (SF)
<i>Last Inspection Date:</i> 01-Jan-2011 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i> Original Inspection	<i>Condition Rating:</i> G+	<i>Used Sampling?</i> No <i>Inspection Source:</i> InstallDate	
2011 B301004 FLASHINGS & TRIM Flashings - Base	B30 ROOFING	B3010 ROOF COVERINGS	7,629 (LF)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> A+	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 B301004 FLASHINGS & TRIM Flashings - Valley	B30 ROOFING	B3010 ROOF COVERINGS	325 (LF)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> A+	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 B301005 GUTTERS & DOWNSPOUTS Downspouts	B30 ROOFING	B3010 ROOF COVERINGS	2,640 (LF)



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 B301005 GUTTERS & DOWNSPOUTS Gutters	B30 ROOFING	B3010 ROOF COVERINGS	4,336 (LF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 B301006 ROOF OPENINGS AND SUPPORTS Gravity	B30 ROOFING	B3010 ROOF COVERINGS	7 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 B301006 ROOF OPENINGS AND SUPPORTS Gravity	B30 ROOFING	B3010 ROOF COVERINGS	46 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 C101001 FIXED PARTITIONS Wall - Drywall w/Stud	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	260,000 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
2011 C101005 INTERIOR WINDOWS Interior Windows	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	60 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 C102001 STANDARD INTERIOR DOORS Wood	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	192 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
2011 C102002 GLAZED INTERIOR DOORS General	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	291 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> A	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	6 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> A+	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	95 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	29 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 C103002 TOILET & BATH ACCESSORIES General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	345 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> A+	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 C103003 MARKER BOARDS & TACK BOARDS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	250 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> A+	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 C103005 LOCKERS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	300 (EA)



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2011 C103008 COUNTERS Laminated Plastic	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	1,500 (LF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2011 C103009 CABINETS Other	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	3,500 (LF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2011 C201001 INTERIOR AND EXTERIOR STAIRS Interior	C20 STAIRS	C2010 STAIR CONSTRUCTION	8 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2011 C201001 INTERIOR AND EXTERIOR STAIRS Interior	C20 STAIRS	C2010 STAIR CONSTRUCTION	6 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
2011 C201090 STAIR HANDRAILS, GUARDRAILS AND	C20 STAIRS	C2010 STAIR CONSTRUCTION	1,099 (LF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 C301004 TILE & TERRAZZO WALL FINISHES Tile	C30 INTERIOR FINISHES	C3010 WALL FINISHES	51,000 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
2011 C302001 TILE FLOOR FINISHES Ceramic Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	165,000 (SF)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 C302003 WOOD FLOORING General	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	13,000 (SF)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> A+	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 C302004 RESILIENT FLOOR FINISHES Composition	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	26,000 (SF)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> A+	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 C302005 CARPETING General	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	5,800 (SF)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> A	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 C303001 ACOUSTICAL CEILING TILES & PANELS	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	174,000 (SF)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> A+	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 C303003 PLASTER CEILING FINISHES General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	23,000 (SF)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G- <i>Paint Rating:</i> G	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 C303005 SUSPENSION SYSTEMS General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	174,000 (SF)



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2011 D101002 PASSENGER ELEVATORS Hydraulic Elevators -	D10 CONVEYING	D1010 ELEVATORS AND LIFTS	2 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 D201001 WATERCLOSETS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	126 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 D201002 URINALS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	37 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 D201004 SINKS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	289 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 D201004 SINKS Kitchen Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	4 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 D201004 SINKS Service Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	12 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
2011 D201005 SHOWERS/TUBS Shower	D20 PLUMBING	D2010 PLUMBING FIXTURES	7 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 D201006 DRINKING FOUNTAINS AND COOLERS Drinking	D20 PLUMBING	D2010 PLUMBING FIXTURES	34 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 D201090 OTHER PLUMBING FIXTURES Emergency Eye	D20 PLUMBING	D2010 PLUMBING FIXTURES	3 (EA)
<i>Last Inspection Date:</i> 13-Jan- [REDACTED] <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 D201090 OTHER PLUMBING FIXTURES Emergency	D20 PLUMBING	D2010 PLUMBING FIXTURES	3 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 D202001 PIPES & FITTINGS General	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	62,976 (LF)
<i>Last Inspection Date:</i> 01-Jan-2011 <i>Inspector:</i> <i>Inspection Comments:</i> Original Inspection	<i>Condition Rating:</i> G+	<i>Used Sampling?</i> No <i>Inspection Source:</i> InstallDate	
2011 D202003 DOMESTIC WATER EQUIPMENT Storage Tank -	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 D202003 DOMESTIC WATER EQUIPMENT Water Heaters,	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	289 (EA)



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 D203001 WASTE PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	31,488 (LF)
Last Inspection Date: 01-Jan-2011 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2011 D203002 VENT PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	7,659 (EA)
Last Inspection Date: 01-Jan-2011 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2011 D203003 FLOOR DRAINS General	D20 PLUMBING	D2030 SANITARY WASTE	48 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 D302004 AUXILIARY EQUIPMENT Expansion Tank - 15	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	3 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 D302004 AUXILIARY EQUIPMENT Expansion Tank - 80	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 D302005 EQUIPMENT THERMAL INSULATION General	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	3,500 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
2011 D304001 AIR DISTRIBUTION, HEATING & COOLING	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	49,890 (LF)
<i>Last Inspection Date:</i> 01-Jan-2011 <i>Condition Rating:</i> G+ <i>Used Sampling?</i> No <i>Inspector:</i> <i>Inspection Source:</i> InstallDate <i>Inspection Comments:</i> Original Inspection			
2011 D304001 AIR DISTRIBUTION, HEATING & COOLING	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	10 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Condition Rating:</i> G- <i>Used Sampling?</i> No <i>Inspector:</i> <i>Inspection Source:</i> Inspection <i>Inspection Comments:</i>			
2011 D304003 HOT WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	3 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Condition Rating:</i> G- <i>Used Sampling?</i> No <i>Inspector:</i> <i>Inspection Source:</i> Inspection <i>Inspection Comments:</i>			
2011 D304003 HOT WATER DISTRIBUTION SYSTEMS General	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	6,696 (MBH)
<i>Last Inspection Date:</i> 01-Jan-2011 <i>Condition Rating:</i> G+ <i>Used Sampling?</i> No <i>Inspector:</i> <i>Inspection Source:</i> InstallDate <i>Inspection Comments:</i> Original Inspection			
2011 D304006 CHILLED WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	5 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Condition Rating:</i> G- <i>Used Sampling?</i> No <i>Inspector:</i> <i>Inspection Source:</i> Inspection <i>Inspection Comments:</i>			
2011 D304006 CHILLED WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	670 (TON)
<i>Last Inspection Date:</i> 01-Jan-2011 <i>Condition Rating:</i> G+ <i>Used Sampling?</i> No <i>Inspector:</i> <i>Inspection Source:</i> InstallDate <i>Inspection Comments:</i> Original Inspection			
2011 D304007 EXHAUST SYSTEMS Fume Hood Exhaust	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	3 (EA)



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 D304007 EXHAUST SYSTEMS Kitchen Exhaust/Make-Up	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	4 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 D305001 UNIT VENTILATORS Air Curtain	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	24 (LF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 D305002 UNIT HEATERS Hydronic - 200 MBH	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	52 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 D401001 FIRE ALARM DISTRIBUTION Other	D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYSTEMS	267,825 (SF)
Last Inspection Date: 01-Jan-2011 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2011 D402001 FIRE PROTECTION WATER PIPING AND	D40 FIRE PROTECTION	D4020 FIRE SUPP WATER SUPPLY / EQUIPMENT	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
2011 D403001 STANDPIPE EQUIPMENT & PIPING Riser - 4"	D40 FIRE PROTECTION	D4030 STANDPIPE SYSTEMS	28 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: G- Used Sampling? No Inspection Source: Inspection			
2011 D404001 SPRINKLERS AND RELEASING DEVICES Wet	D40 FIRE PROTECTION	D4040 SPRINKLERS	267,825 (SF)
Last Inspection Date: 01-Jan-2011 Inspector: Inspection Comments: Original Inspection Condition Rating: G+ Used Sampling? No Inspection Source: InstallDate			
2011 D409004 HOOD & DUCT FIRE PROTECTION General	D40 FIRE PROTECTION	D4090 OTHER FIRE PROTECTION SYSTEMS	4 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: G- Used Sampling? No Inspection Source: Inspection			
2011 D501004 PANELBOARDS Main lugs, 120/208 V, 100 amp,	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	35 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: G- Used Sampling? No Inspection Source: Inspection			
2011 D501004 PANELBOARDS Main lugs, 120/208 V, 225 amp,	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	6 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: G- Used Sampling? No Inspection Source: Inspection			
2011 D501004 PANELBOARDS Switchgear - 2000 Amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: G- Used Sampling? No Inspection Source: Inspection			
2011 D501004 PANELBOARDS Switchgear - 400 Amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	7 (EA)



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 D501004 PANELBOARDS Switchgear - 800 Amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)
Last Inspection Date: 13-Jan- [REDACTED] Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 D501005 ENCLOSED CIRCUIT BREAKERS Main circuit	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	36 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 D501006 MOTOR CONTROL CENTERS Motor Control	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	33 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 D501006 MOTOR CONTROL CENTERS Motor Control	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	17 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 D502001 BRANCH WIRING General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	267,825 (SF)
Last Inspection Date: 01-Jan-2011 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
2011 D502002 LIGHTING EQUIPMENT Exit Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	228 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
2011 D502002 LIGHTING EQUIPMENT General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	267,825 (SF)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 D503005 SECURITY SYSTEMS General	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	2 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 D503007 CLOCK & PROGRAM SYSTEMS General	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	2 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 D509002 EMERGENCY LIGHTING & POWER General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	267,825 (SF)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 D509003 GROUNDING SYSTEMS General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	1 (EA)
<i>Last Inspection Date:</i> 01-Jan-2011 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i> Original Inspection	<i>Condition Rating:</i> G+	<i>Used Sampling?</i> No <i>Inspection Source:</i> InstallDate	
2011 D509004 LIGHTNING PROTECTION Unknown	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	267,825 (SF)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 D509006 ENERGY MANAGEMENT CONTROL SYSTEM	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	267,825 (SF)



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 A B301004 FLASHINGS & TRIM Flashings - Cap	B30 ROOFING	B3010 ROOF COVERINGS	98 (LF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2011 A D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 A D503003 INTERCOMMUNICATIONS SYSTEMS 100	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 B B301004 FLASHINGS & TRIM Flashings - Cap	B30 ROOFING	B3010 ROOF COVERINGS	2,415 (LF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2011 B D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 B D503003 INTERCOMMUNICATIONS SYSTEMS 100	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
2011 M0301 AHU/2E D304008 AIR HANDLING UNITS Central	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i>  <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 M0301 AHU/3E D304008 AIR HANDLING UNITS Central	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i>  <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 M0301 EF/10E D304007 EXHAUST SYSTEMS Fan System,	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i>  <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 M0301 EF/11E D304007 EXHAUST SYSTEMS Fan System,	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i>  <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 M0301 EF/13E D304007 EXHAUST SYSTEMS Fan System,	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i>  <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 M0301 EF/14E D304007 EXHAUST SYSTEMS Fan System,	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i>  <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 M0301 EF/15E D304007 EXHAUST SYSTEMS Fan System,	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 M0301 EF/9E D304007 EXHAUST SYSTEMS Fan System,	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 M0301 ERU/2E D304008 AIR HANDLING UNITS Central	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 M0302 D202003 DOMESTIC WATER EQUIPMENT Water	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2011 M0302 AHU/4E D304008 AIR HANDLING UNITS Central	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 M0302 AHU/5E D304008 AIR HANDLING UNITS Central	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2011 M0302 EF/12E D304008 AIR HANDLING UNITS Central	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
2011 M0302 EF/5E D304008 AIR HANDLING UNITS Central	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 M0302 ERU/3E D304008 AIR HANDLING UNITS Central	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 M0302 ERU/4E D304008 AIR HANDLING UNITS Central	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 M1090 AHU/1E D304008 AIR HANDLING UNITS Central	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 M1090 AHU/7E D304008 AIR HANDLING UNITS Central	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 M1090 EF/3E D304007 EXHAUST SYSTEMS Fan System,	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
<i>Last Inspection Date:</i> 13-Jan-2020 <i>Inspector:</i> [REDACTED] <i>Inspection Comments:</i>	<i>Condition Rating:</i> G-	<i>Used Sampling?</i> No <i>Inspection Source:</i> Inspection	
2011 M1090 EF/4E D304007 EXHAUST SYSTEMS Fan System,	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)



Direct Condition Rating Inspection Report by Section



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 M1090 ERU/1E D304008 AIR HANDLING UNITS Central	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
2011 M1255 AHU/6E D304008 AIR HANDLING UNITS Central	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 M3010 D202003 DOMESTIC WATER EQUIPMENT Booster	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 M3010 D202003 DOMESTIC WATER EQUIPMENT Water	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
2011 M3020 D202003 DOMESTIC WATER EQUIPMENT Booster	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	

Appendix H

System Inventory Report

"identification only"



System Inventory Report



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	2011 B201001 EXTERIOR CLOSURE E.I.F.S.	88,000 (SF)	2011	
	B2010 EXTERIOR WALLS	2011 B201004 PARAPETS General	196 (LF)	2011	
	B2010 EXTERIOR WALLS	2011 B201005 EXTERIOR LOUVERS & SCREENS General	5,822 (SF)	2011	
	B2010 EXTERIOR WALLS	2011 B201006 BALCONY WALLS & HANDRAILS Ladder	57 (LF)	2011	
	B2010 EXTERIOR WALLS	2011 B201007 EXTERIOR SOFFITS General	7,167 (SF)	2011	
	B2010 EXTERIOR WALLS	2011 B201010 EXTERIOR JOINT SEALANT General	7,310 (LF)	2011	
	B2020 EXTERIOR WINDOWS	2011 B202001 WINDOWS Aluminum Windows	384 (EA)	2011	
	B2020 EXTERIOR WINDOWS	2011 B202002 STOREFRONTS General	612 (SF)	2011	
	B2020 EXTERIOR WINDOWS	2011 B202003 CURTAIN WALLS General	1,339 (SF)	2011	
	B2030 EXTERIOR DOORS	2011 B203001 SOLID DOORS Aluminum	10 (EA)	2011	
	B2030 EXTERIOR DOORS	2011 B203002 GLAZED DOORS General	11 (EA)	2011	
	B2030 EXTERIOR DOORS	2011 B203003 GATES General	147 (SF)	2011	2011
	B2030 EXTERIOR DOORS	2011 B203004 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door	57 (EA)	2011	
B30 ROOFING	B3010 ROOF COVERINGS	2011 B301001 STEEL SLOPE ROOF SYSTEMS Clay Tile	148,000 (SF)	2011	
	B3010 ROOF COVERINGS	2011 B301002 LOW SLOPE ROOF SYSTEMS Built-Up	6,000 (SF)	2011	
	B3010 ROOF COVERINGS	2011 B301003 ROOF INSULATION & FILL General	154,000 (SF)	2011	
	B3010 ROOF COVERINGS	2011 B301004 FLASHINGS & TRIM Flashings - Base	7,629 (LF)	2011	
	B3010 ROOF COVERINGS	2011 B301004 FLASHINGS & TRIM Flashings - Valley	325 (LF)	2011	
	B3010 ROOF COVERINGS	2011 B301005 GUTTERS & DOWNSPOUTS Downspouts	2,640 (LF)	2011	
	B3010 ROOF COVERINGS	2011 B301005 GUTTERS & DOWNSPOUTS Gutters	4,336 (LF)	2011	
	B3010 ROOF COVERINGS	2011 B301006 ROOF OPENINGS AND SUPPORTS Gravity Ventilator - 48" x 60"	7 (EA)	2011	
	B3010 ROOF COVERINGS	2011 B301006 ROOF OPENINGS AND SUPPORTS Gravity Ventilator - 6" Diameter	46 (EA)	2011	
	B3010 ROOF COVERINGS	2011 A B301004 FLASHINGS & TRIM Flashings - Cap	98 (LF)	2011	
C10 INTERIOR CONSTRUCTION	B3010 ROOF COVERINGS	2011 B B301004 FLASHINGS & TRIM Flashings - Cap	2,415 (LF)	2011	
	C1010 PARTITIONS	2011 C101001 FIXED PARTITIONS Wall - Drywall w/Stud Framing	260,000 (SF)	2011	2011
	C1010 PARTITIONS	2011 C101005 INTERIOR WINDOWS Interior Windows	60 (EA)	2011	
	C1020 INTERIOR DOORS	2011 C102001 STANDARD INTERIOR DOORS Wood Door/Wood Frame	192 (EA)	2011	
	C1020 INTERIOR DOORS	2011 C102002 GLAZED INTERIOR DOORS General	291 (EA)	2011	
	C1030 SPECIALTIES	2011 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Shower Compartment	6 (EA)	2011	
	C1030 SPECIALTIES	2011 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions	95 (EA)	2011	
	C1030 SPECIALTIES	2011 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Urinal Screen	29 (EA)	2011	



System Inventory Report



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	C1030 SPECIALTIES	2011 C103002 TOILET & BATH ACCESSORIES General	345 (EA)	2011	
	C1030 SPECIALTIES	2011 C103003 MARKER BOARDS & TACK BOARDS General	250 (EA)	2011	
	C1030 SPECIALTIES	2011 C103005 LOCKERS General	300 (EA)	2011	
	C1030 SPECIALTIES	2011 C103008 COUNTERS Laminated Plastic	1,500 (LF)	2011	
	C1030 SPECIALTIES	2011 C103009 CABINETS Other	3,500 (LF)	2011	
C20 STAIRS	C2010 STAIR CONSTRUCTION	2011 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	8 (EA)	2011	
	C2010 STAIR CONSTRUCTION	2011 C201001 INTERIOR AND EXTERIOR STAIRS Interior Steps	6 (EA)	2011	2011
	C2010 STAIR CONSTRUCTION	2011 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General	1,099 (LF)	2011	
C30 INTERIOR FINISHES	C3010 WALL FINISHES	2011 C301004 TILE & TERRAZZO WALL FINISHES Tile	51,000 (SF)	2011	
	C3020 FLOOR FINISHES	2011 C302001 TILE FLOOR FINISHES Ceramic Tile	165,000 (SF)	2011	
	C3020 FLOOR FINISHES	2011 C302003 WOOD FLOORING General	13,000 (SF)	2011	
	C3020 FLOOR FINISHES	2011 C302004 RESILIENT FLOOR FINISHES Composition Sheet	26,000 (SF)	2011	
	C3020 FLOOR FINISHES	2011 C302005 CARPETING General	5,800 (SF)	2011	
	C3030 CEILING FINISHES	2011 C303001 ACUSTICAL CEILING TILES & PANELS General	174,000 (SF)	2011	
	C3030 CEILING FINISHES	2011 C303003 PLASTER CEILING FINISHES General	23,000 (SF)	2011	2018
	C3030 CEILING FINISHES	2011 C303005 SUSPENSION SYSTEMS General	174,000 (SF)	2011	
D10 CONVEYING	D1010 ELEVATORS AND LIFTS	2011 D101002 PASSENGER ELEVATORS Hydraulic Elevators - 2000 lb, 2 floors	2 (EA)	2011	
D20 PLUMBING	D2010 PLUMBING FIXTURES	2011 D201001 WATERCLOSETS General	126 (EA)	2011	
	D2010 PLUMBING FIXTURES	2011 D201002 URINALS General	37 (EA)	2011	
	D2010 PLUMBING FIXTURES	2011 D201004 SINKS General	289 (EA)	2011	
	D2010 PLUMBING FIXTURES	2011 D201004 SINKS Kitchen Sink	4 (EA)	2011	
	D2010 PLUMBING FIXTURES	2011 D201004 SINKS Service Sink	12 (EA)	2011	
	D2010 PLUMBING FIXTURES	2011 D201005 SHOWERS/TUBS Shower	7 (EA)	2011	
	D2010 PLUMBING FIXTURES	2011 D201006 DRINKING FOUNTAINS AND COOLERS Drinking Fountain	34 (EA)	2011	
	D2010 PLUMBING FIXTURES	2011 D201090 OTHER PLUMBING FIXTURES Emergency Eye Wash	3 (EA)	2011	
	D2010 PLUMBING FIXTURES	2011 D201090 OTHER PLUMBING FIXTURES Emergency Shower	3 (EA)	2011	
	D2020 DOMESTIC WATER DISTRIBUTION	2011 D202001 PIPES & FITTINGS General	62,976 (LF)	2011	
	D2020 DOMESTIC WATER DISTRIBUTION	2011 D202003 DOMESTIC WATER EQUIPMENT Storage Tank - Galvanized steel, 400 gallon, 36" diameter, 100" L.O.A.	1 (EA)	2016	
	D2020 DOMESTIC WATER DISTRIBUTION	2011 D202003 DOMESTIC WATER EQUIPMENT Water Heaters, Residential, Electric	289 (EA)	2011	

Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D2020 DOMESTIC WATER DISTRIBUTION	2011 M0302 D202003 DOMESTIC WATER EQUIPMENT Water Heaters, Commercial, Electric - 80 gal, 36 KW, 147 GPH	1 (EA)	2011	
	D2020 DOMESTIC WATER DISTRIBUTION	2011 M3010 D202003 DOMESTIC WATER EQUIPMENT Booster Pump - 1 HP	1 (EA)	2011	
	D2020 DOMESTIC WATER DISTRIBUTION	2011 M3010 D202003 DOMESTIC WATER EQUIPMENT Water Heaters, Commercial, Electric - 80 gal, 12 KW, 49 GPH	1 (EA)	2011	
	D2020 DOMESTIC WATER DISTRIBUTION	2011 M3020 D202003 DOMESTIC WATER EQUIPMENT Booster Pump - 1 HP	1 (EA)	2011	
	D2030 SANITARY WASTE	2011 D203001 WASTE PIPE & FITTINGS General	31,488 (LF)	2011	
	D2030 SANITARY WASTE	2011 D203002 VENT PIPE & FITTINGS General	7,659 (EA)	2011	
	D2030 SANITARY WASTE	2011 D203003 FLOOR DRAINS General	48 (EA)	2011	
D30 HVAC	D3020 HEAT GENERATING SYSTEMS	2011 D302001 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	3 (EA)	2011	
	D3020 HEAT GENERATING SYSTEMS	2011 D302001 AUXILIARY EQUIPMENT Expansion Tank - 80 gal	1 (EA)	2016	
	D3020 HEAT GENERATING SYSTEMS	2011 D302005 EQUIPMENT THERMAL INSULATION General	3,500 (SF)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	49,890 (LF)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 D304001 AIR DISTRIBUTION, HEATING & COOLING Smoke Vents	10 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 2-1/2" size, 3 HP, to 150 GPM	3 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 D304003 HOT WATER DISTRIBUTION SYSTEMS General	6,696 (MBH)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 D304006 CHILLED WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 5" size, 15 HP, to 1000 GPM	5 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	670 (TON)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 D304007 EXHAUST SYSTEMS Fume Hood Exhaust System - 6", 5000 CFM	3 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 D304007 EXHAUST SYSTEMS Kitchen Exhaust/Make Up Air - 5000 CFM	4 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 M0301 AHU/2E D304008 AIR HANDLING UNITS Central Station - 30000 CFM, VAV	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 M0301 AHU/3E D304008 AIR HANDLING UNITS Central Station - 30000 CFM, VAV	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 M0301 EF/10E D304007 EXHAUST SYSTEMS Fan System, Wall Exhaust	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 M0301 EF/11E D304007 EXHAUST SYSTEMS Fan System, Wall Exhaust	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 M0301 EF/13E D304007 EXHAUST SYSTEMS Fan System, Wall Exhaust	1 (EA)	2011	



System Inventory Report



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D3040 DISTRIBUTION SYSTEMS	2011 M0301 EF/14E D304007 EXHAUST SYSTEMS Fan System, Wall Exhaust	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 M0301 EF/15E D304007 EXHAUST SYSTEMS Fan System, Wall Exhaust	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 M0301 EF/9E D304007 EXHAUST SYSTEMS Fan System, Wall Exhaust	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 M0301 ERU/2E D304008 AIR HANDLING UNITS Central Station - 10000 CFM, VAV	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 M0302 AHU/4E D304008 AIR HANDLING UNITS Central Station - 20000 CFM, VAV	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 M0302 AHU/5E D304008 AIR HANDLING UNITS Central Station - 30000 CFM, VAV	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 M0302 EF/12E D304008 AIR HANDLING UNITS Central Station - 30000 CFM, VAV	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 M0302 EF/5E D304008 AIR HANDLING UNITS Central Station - 30000 CFM, VAV	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 M0302 ERU/3E D304008 AIR HANDLING UNITS Central Station - 30000 CFM, VAV	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 M0302 ERU/4E D304008 AIR HANDLING UNITS Central Station - 30000 CFM, VAV	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 M1090 AHU/1E D304008 AIR HANDLING UNITS Central Station - 30000 CFM, VAV	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 M1090 AHU/7E D304008 AIR HANDLING UNITS Central Station - 30000 CFM, VAV	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 M1090 EF/3E D304007 EXHAUST SYSTEMS Fan System, Wall Exhaust	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 M1090 EF/4E D304007 EXHAUST SYSTEMS Fan System, Wall Exhaust	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 M1090 ERU/1E D304008 AIR HANDLING UNITS Central Station - 30000 CFM, VAV	1 (EA)	2011	
	D3040 DISTRIBUTION SYSTEMS	2011 M1255 AHU/6E D304008 AIR HANDLING UNITS Central Station - 30000 CFM, VAV	1 (EA)	2011	
	D3050 TERMINAL & PACKAGE UNITS	2011 D305001 UNIT VENTILATORS Air Curtain	24 (LF)	2011	
	D3050 TERMINAL & PACKAGE UNITS	2011 D305002 UNIT HEATERS Hydronic - 200 MBH	1 (EA)	2011	
	D3050 TERMINAL & PACKAGE UNITS	2011 D305003 FAN COIL UNITS Cab Mount, Two Pipe - 1 ton	52 (EA)	2011	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYSTEMS	2011 D401001 FIRE ALARM DISTRIBUTION Other	267,825 (SF)	2011	
	D4020 FIRE SUPP WATER SUPPLY / EQUIP	2011 D402001 FIRE PROTECTION WATER PIPING AND EQUIPMENT Backflow Preventer - 8"	1 (EA)	2011	
	D4030 STANDPIPE SYSTEMS	2011 D403001 STANDPIPE EQUIPMENT & PIPING Riser - 4" diam	28 (EA)	2011	



System Inventory Report



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D4040 SPRINKLERS	2011 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	267,825 (SF)	2011	
	D4090 OTHER FIRE PROTECTION SYSTEMS	2011 D409004 HOOD & DUCT FIRE PROTECTION General	4 (EA)	2011	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2011 D501004 PANELBOARDS Main lugs, 120/208 V, 100 amp, NQOD	35 (EA)	2011	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2011 D501004 PANELBOARDS Main lugs, 120/208 V, 225 amp, NQOD	6 (EA)	2011	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2011 D501004 PANELBOARDS Switchgear - 2000 Amp	1 (EA)	2011	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2011 D501004 PANELBOARDS Switchgear - 400 Amp	7 (EA)	2011	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2011 D501004 PANELBOARDS Switchgear - 800 Amp	1 (EA)	2011	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2011 D501005 ENCLOSED CIRCUIT BREAKERS Main circuit breaker, 120/208 V, 400 amp, NQOD	36 (EA)	2011	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2011 D501006 MOTOR CONTROL CENTERS Motor Control Center - Size 3, 50 HP, 24" high	33 (EA)	2011	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	2011 D501006 MOTOR CONTROL CENTERS Motor Control Center - Size 4, 100 HP, 30" high	17 (EA)	2011	
	D5020 LIGHTING & BRANCH WIRING	2011 D502001 BRANCH WIRING General	267,825 (SF)	2011	
	D5020 LIGHTING & BRANCH WIRING	2011 D502002 LIGHTING EQUIPMENT Exit Lighting	228 (EA)	2011	
	D5020 LIGHTING & BRANCH WIRING	2011 D502002 LIGHTING EQUIPMENT General	267,825 (SF)	2011	
	D5030 COMMUNICATIONS & SECURITY	2011 D503005 SECURITY SYSTEMS General	2 (EA)	2011	
	D5030 COMMUNICATIONS & SECURITY	2011 D503007 CLOCK & PROGRAM SYSTEMS General	2 (EA)	2011	
	D5030 COMMUNICATIONS & SECURITY	2011 A D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	1 (EA)	2011	
	D5030 COMMUNICATIONS & SECURITY	2011 A D503003 INTERCOMMUNICATIONS SYSTEMS 100 stations	1 (EA)	2011	
	D5030 COMMUNICATIONS & SECURITY	2011 B D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	1 (EA)	2011	
	D5030 COMMUNICATIONS & SECURITY	2011 B D503003 INTERCOMMUNICATIONS SYSTEMS 100 stations	1 (EA)	2011	
	D5090 OTHER ELECTRICAL SERVICES	2011 D509002 EMERGENCY LIGHTING & POWER General	267,825 (SF)	2011	
	D5090 OTHER ELECTRICAL SERVICES	2011 D509003 GROUNDING SYSTEMS General	1 (EA)	2011	
	D5090 OTHER ELECTRICAL SERVICES	2011 D509004 LIGHTNING PROTECTION Unknown	267,825 (SF)	2011	

Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D5090 OTHER ELECTRICAL SERVICES	2011 D509006 ENERGY MANAGEMENT CONTROL SYSTEM General	267,825 (SF)	2011	
E10 EQUIPMENT	E1090 OTHER EQUIPMENT	*DEEP FRYER E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*DISH MACHINE E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*FIRE SUPPRESSION SYSTEM E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*FREEZER REACH IN 2 DR E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*HOT CABINET REACH IN 1 DR A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*HOT CABINET REACH IN 1 DR B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*HOT CABINET REACH IN 1 DR C E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*HOT CABINET REACH IN 1 DR D E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*ICE MACHINE E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR PASS THRU 4 DR A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR PASS THRU 4 DR B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR PASS THRU 4 DR C E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR PASS THRU 4 DR D E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR PASS THRU 4 DR E E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2 DR A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2 DR B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2 DR C E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2 DR D E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2 DR E E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2 DR F E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2 DR G E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	



System Inventory Report



Vicenza FAM HSG

700 - Vicenza Bldg ES/MS 700

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*STEAMER 1 DOOR A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*TILT KETTLE E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*WALK IN COOLER E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	
	E1090 OTHER EQUIPMENT	*WALK IN FREEZER E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2011	