

Vicenza High School/DoDEA Europe South District Superintendent's Office

Facility Condition Assessment Report



CAMPUS SUMMARY

Year Built ¹	1958-1995
GSF ²	123,895
Date of Assessment	09-Jan-2020

¹ Indicates range of dates of construction present on campus

² Only permanent and semi-permanent facilities are included

SCHOOL SUMMARY

School	Assessed Condition		Annual Condition Report (June 2019)		2009 Congressional	Starting Grade	Ending Grade	Students
	Q-Rating	FCI	Q-Rating	FCI	Q-Rating			
DoDEA Europe South District Superintendent's Office	Q-3	77	Q-3	74	N/A	N/A	N/A	0
Vicenza High School	Q-2	82	Q-2	82	Q-4	Ninth	Twelfth	302

BUILDING SUMMARY

Building/School	Year Built	GSF	DoDEA Europe South DSO (%Occupied)	Vicenza HS (%Occupied)	Type
DoDEA Europe South DSO Bldg 307	1958	11,193	100%	0%	PERM
Vicenza HS Bldg 309	1958-1983	111,867	5%	95%	PERM
DoDEA Europe South DSO Bldg 358	1995	835	100%	0%	PERM

I. INTRODUCTION

The Vicenza High School/DoDEA Europe South District Superintendent's Office is part of Camp Ederle, U.S. Army Garrison Italy. This report provides a summary of findings for the physical condition assessment of buildings at this campus. The physical condition assessment includes a general description of typical building systems found and includes conditions present at the time of the site visit.

II. SCHOOL PHYSICAL DESCRIPTION

The summary below provides a physical description of the Vicenza High School and the DoDEA Europe South District Superintendent's Office. When multiple systems or materials are present, the predominant system or material observed during the facility condition assessment is shown.

a. STRUCTURAL/EXTERIOR ENCLOSURE: The building exterior is an exterior insulation and finish system (E.I.F.S). Roof coverings are modified bitumen. Exterior doors are pre-finished aluminum with glazing. Window systems are pre-finished aluminum with double-glazing.

b. INTERIORS: Floor finishes used include ceramic tile and resilient sheeting. Walls are painted hard surfaces. Ceilings are acoustical lay-in tiles.

c. MECHANICAL: Vicenza High School/DoDEA Europe South DSO facilities have heating, which is provided by a boiler. All facilities have air conditioning, which is provided by chillers. Building 309 has one elevator.

d. ELECTRICAL: Major electrical upgrades have been completed to support the additions to Building 309, but most wiring appears to be original. Lighting is typically lay-in fixtures with fluorescent lamps. Ground-fault circuit interrupter (GFCI) receptacles appear to be present but are not properly labeled. Building 309 has an intercom system. There is no security system; however, security cameras are present.

e. PLUMBING: Plumbing fixtures have been partially upgraded, but most piping appears to be original. Domestic hot water is provided by indirect water heaters.

f. SITE: The Vicenza High School/DoDEA Europe South DSO site has parking for approximately 34 privately owned vehicles. In addition, the campus has no playgrounds on-site.

g. LIFE SAFETY: A fire safety inspection report was not available for review.

"Identification only"

III. OBSERVATIONS

The following observations were made: Exterior door security was not observed or reported to be a problem. However, egress doors at the Cafeteria and Weight Room were observed to operate with difficulty or do not secure properly. At Vicenza High School, the windows gasket seals are deteriorating, and various units were observed to be inoperable or operate with some difficulty. Additionally, at Vicenza High School, the roof covering system was in poor condition with extensive blistering and membrane deterioration observed throughout. However, no roof leaks were observed. At Building 307, the exterior enclosure stone facing at the base of the exterior walls is dislodged and damaged at the Southside of the building, and minor wall discoloration was observed. Overall, the interior construction finishes were observed to be in good to fair condition and are aging as designed.

It appears that outside air is being introduced into the HVAC system. At Building 309 the exhaust fans and make-up air units appear to be in poor condition, and the make-up air units contained an estimated half of an inch of standing water at the bottom of the enclosure. The roof-mounted package unit above the Kitchen appeared to be moderately deteriorated. Additionally, at Building 309, the radiant heaters appeared to be in poor condition, and some were observed to be nonfunctioning at the time of the assessment. The two condensing units located at Building 358, which were installed in 2010, are showing signs of significant deterioration. At Building 309, most plumbing fixtures were observed to be in fair condition with moderate corrosion observed. The electrical distribution panels and enclosed circuit breakers were observed to be generally in fair condition.

The Facility Utilization Survey (FUS) drawings to include the site plan have been updated to reflect the following: X-Building (X309A) was renamed as "WALK-IN COOLER 1" and X-Building (X309C) was renamed as "WALK-IN COOLER 2". The X-Building (X309F) now known as "WALK-IN COOLER 3" was turned over to AAFES and is no longer part of the portfolio. Room-use changes were observed throughout the site. Additionally, per DoDEA HQ guidance Vicenza High School Building CMU Shed is now part of Table 2 (page 4). Building 309 was identified as a shared facility between Vicenza High School and the DoDEA Europe South DSO. Additionally, the Maintenance contractor, SKE, occupies space in Building 309. Vicenza High School utilizes approximately 93% of Building 309 (103,960 SF), the DoDEA Europe South DSO utilizes approximately 5% of Building 309 (5,707 SF), and SKE utilizes approximately 2% of Building 309, specifically Rooms 63, 63A, 63B, 63C, 65, 65A, 65B, and 65C (2,200 SF) for a GSF total of 111,867 SF.

Building 307 remained a Q-3.

Building 309 remained a Q-2.

Building 358 remained a Q-1.

IV. QUALITY / CONDITION RATINGS

Table 1 shows building-specific information to include Real Property Unique Identifier (RPUID), type of construction, year built, gross area, Facility Condition Index (FCI), and Q-Rating. Table 2 shows buildings that are classified as temporary (TEMP) or relocatable (RELO) and therefore, by definition, are not included in Quality/Condition calculations.

TABLE 1: QUALITY / CONDITION RATINGS								
Photo	Building	RPUID	Type	Year Built	GSF	Assessed		Plant Replacement Value ³
						FCI	Q-Rating	
	307	253374	PERM	1958	11,193	74	Q-3	██████████
	309	253375	PERM	1958	111,867	82	Q-2	██████████
	358	253345	PERM	1995	835	95	Q-1	██████████


³ The Plant Replacement Value is calculated according to the DOE Facility Pricing Guide.


TABLE 2: TEMPORARY / RELOCATABLE BUILDINGS					
Photo	Building	Type	Year Built	GSF	Current Use
	CMU Shed	TEMP	1983	412	Permanent
	R0309	RELO	1995	759	Temp Storage
	X309B	RELO	2005	25	Storage Shed
	X309E	RELO	2010	189	Storage Shed

Appendix A

Site Plan

"identification only"





Appendix B

Overview of Sustainment Management System (SMS) and
BUILDER™ Engineered Management System (EMS)

"identification only"

Overview of Sustainment Management System (SMS) and BUILDER™ Engineered Management System (EMS)

Sustainment Management System (SMS)

The Sustainment Management System (SMS) is a suite of web-based software applications developed by the United States Army Corps of Engineers - Engineer Research Development Center - Construction Engineering Research Laboratory (USACE-ERDC-CERL) to help facility engineers, technicians, and managers decide when, where, and how to best maintain the built environment. The SMS modules include BUILDER™ and ROOFER™ for assessing building conditions, PAVER™ for pavements, and RAILER™ for railroad infrastructure.

Because real property assets are so vast and diverse, a "knowledge-based" philosophy drives the SMS process. The process starts with the automated download of real property data, and then more detailed system inventory is modeled and/or collected which identifies components and their key life cycle attributes such as the age and material.

From this inventory, Condition Index (CI) measures for each component are predicted based on its expected stage in the life cycle. Objective and repeatable inspections can then be performed on various components to verify their condition with respect to the expected life cycle deterioration. The level of detail and frequency of these inspections are not fixed like other processes; they are dependent on knowledge of component criticality, the expected and measured condition and rate of deterioration, and remaining maintenance and service life. This "knowledge-based" inspection focuses attention to the most critical components at the time. In addition to these condition assessments, functionality assessments can be performed to evaluate user requirement changes, compliance and obsolescence issues. This provides a comprehensive picture of the overall performance of real property assets and their key components.

BUILDER Engineered Management System (EMS)

In September 2013, the Under Secretary of Defense, Frank Kendall, issued a memo indicating the Department of Defense requires a standardized process for facility condition assessments to ensure consistent and reliable data necessary for sound strategic investment decisions in managing the Department's built environment.

Establishing a DoD-wide facility condition assessment process will contribute to a more credible DoD asset management program and will support better buying power by allowing Department leadership to better target fiscal resources to those facilities most in need of investment. Further, adopting a standard process will help ensure that condition data will be audit-ready in accordance with the Under Secretary of Defense (Comptroller)'s "Financial Improvement and Readiness Guidance" issued in March 2013.

The facility condition assessment process used to generate this report is based on BUILDER Engineered Management System (EMS) Version 3. BUILDER EMS was developed by the Engineer Research and Development Center.

The facility condition assessment process addresses the requirements necessary for routine building facility management activities, including long range budgeting and sustainment/restoration/modernization (SRM) planning. This assessment approach provides an objective and generalized framework to help to identify problem areas that will require more investigation through detailed or specialized assessments. There may be times when detailed engineering assessments may be required to diagnose specific problems.

BUILDER is a software application for building asset life cycle management. The primary focus of BUILDER is work plan development. BUILDER stores real property building information and more detailed system inventory is modeled and/or collected which identifies building components and their key life cycle attributes such as the age, material and capacity. Inspections are then performed on the various components to

determine an objective and repeatable Condition Index (CI) measure, which relates the general physical health of the asset.

With information about condition and remaining service life, BUILDER guides the development of short- and long-range work plans based on sound investment strategies, prioritization criteria, and budget constraints. BUILDER consolidates a variety of building-related management issues into a single decision-support package.

The system gives functional managers and decision-makers instant access to building inventory, current building condition indices, and probabilities condition prediction models. It also employs a patented knowledge-based inspection scheduling process. BUILDER improves the allocation process and return of building life cycle investments by directing resources to the most condition critical components to avoid costly repair penalty costs, as well as, the most mission critical components to manage risks of failure.

BUILDER Facility Condition Assessment Process

Facility Condition Assessment (FCA) is one of the primary processes of a facility life cycle asset management program. The FCA process results in a better understanding of the physical condition and readiness of an organization's buildings along with the reliability of its systems and components. It also facilitates the identification of work candidates for facility SRM repair projects. It is a critical aspect of the shift towards a proactive versus reactive facility management strategy. Instead of keeping facilities operational by relying primarily on corrective repairs (after a system or component has failed due to significant loss of function), it focuses on condition-based repairs which can be planned prior to failure. A condition-based approach can result in higher performing facilities at lower life cycle costs.

Prior to an assessment, knowledge of the building systems and components present is necessary, since assessments are done against these components, not against the building as a whole. This information about the systems and components that make up a building is called the BUILDER Inventory. BUILDER has a vast library of predefined components which all assessors will select from, and the inventory collection process involves identifying the type, quantity, and year installed for all pertinent components. These components are also organized into systems and sub-systems according to the UNIFORMAT classification hierarchy. When a specific instance of a component is recorded, this is called a component-section in BUILDER, and represents a single component assembly or collection of like components to be managed as a single unit. The BUILDER facility condition assessment process directly supports the computation of a condition index for building component-sections, known as the Component-Section Condition Index (CSCI), which is the fundamental metric used in BUILDER. The CSCI is aggregated to compute a condition index metric at the system (SCI), building (BCI), and site/organizational level.

A condition-based facility repair strategy requires condition information be collected at a component level, and that this condition information relate to loss of component function. Every component of a building has a primary function that it performs. This function is the reason that the component was constructed or installed in the building. It may also serve a number of secondary or tertiary functions. For example, for a door component, the primary function is to provide safe entry/egress of authorized movements while limiting unwanted movements of people (security), or other objects (water or moisture). The secondary functions would relate to aesthetics and thermal and air control, among others.

The condition assessment process in BUILDER uses the Direct Rating method.

1. The **Direct Rating** method uses a single qualitative rating for each component based on condition observations. This also results in a condition index metric, which relates to the level of deterioration and the loss of function. This abbreviated Direct Rating approach is often better suited to initial baseline assessments where the components are inventoried, and data is initially loaded into BUILDER.

The following figure illustrates the Direct Rating criteria used in this assessment.

RATING	SRM NEEDS	RATING DEFINITION
Green (+)	Sustainment consisting of possible preventive maintenance (where applicable)	Entire component-section or component-section sample is free of observable or known distress.
Green	Sustainment consisting of possible preventive maintenance (where applicable) and minor repairs (corrective maintenance) to possibly few or some subcomponents.	No component-section or sample serviceability* or reliability* reduction. Some, but not all minor (non-critical) subcomponents may suffer from slight degradation or few major (critical) subcomponents may suffer from slight degradation.
Green (-)		Slight or no serviceability or reliability or reliability reduction overall to the component-section or sample. Some, but not all minor (non-critical) subcomponents may suffer from slight degradation or more than one major (critical) subcomponents may suffer from slight degradation.
Amber (+)	Sustainment or restoration to any of the following: Minor repairs to several sub-components; or Significant repair, rehabilitation or replacement of one or more subcomponents, but not enough to encompass the component-section as a whole; or Combinations thereof.	Component-section or sample serviceability or reliability is degraded, but adequate. A very few major (critical) subcomponents may suffer from moderate deterioration with perhaps a few minor (non-critical) subcomponents suffering from severe deterioration.
Amber		Component-section or sample serviceability or reliability is definitely impaired. Some, but not a majority of major (critical) subcomponents may suffer from moderate deterioration with perhaps many minor (non-critical) subcomponents suffering from severe deterioration.
Amber (-)		Component-section or sample has significant serviceability or reliability loss. Most subcomponents may suffer from moderate degradation or a few major (critical) subcomponents may suffer from severe degradation.
Red (+)	Sustainment or restoration required consisting of major repair, rehabilitation or replacement to the component-section as a whole.	Significant serviceability or reliability reduction in component-section or sample. A majority of subcomponents are severely degraded, and others may have varying degrees of degradation.
Red		Severe serviceability or reliability reduction to the component-section or sample such that it is barely able to perform. Most subcomponents are severely degraded.
Red (-)		Overall component-section degradation is total. Few, if any subcomponents are salvageable. Complete loss of component-section or sample serviceability.

Once the component-sections have been rated with a Direct Rating, BUILDER calculates the Component-Section Condition Index (CSCI) of the component-section. The next step in the process is to create a work plan, which will list the component-sections that need repair or replacement and the estimated cost of the repair or replacement.

To create a work plan, condition standards, policies and a policy sequence are created. The standards serve as thresholds for CSCI and remaining service life. Policies link standards to component-sections and policy sequences link standards and policies together.

The table below summarizes the DoDEA standards and how they are applied to the component-sections for this assessment.

Standard and Component-section Cross-Reference		
Standard	CI Threshold	Component-section
Amber +	80	D4010 FIRE ALARM AND DETECTION SYSTEMS
Amber	71	B3010 ROOF COVERINGS D1010 ELEVATORS AND LIFTS D2010 PLUMBING FIXTURES D3020 HEAT GENERATING SYSTEMS D3030 COOLING GENERATING SYSTEMS D3040 DISTRIBUTION SYSTEMS (A) D3050 TERMINAL & PACKAGE UNITS D3060 CONTROLS & INSTRUMENTATION D3090 OTHER HVAC SYSTEMS AND EQUIPMENT D4020 FIRE SUPP WATER SUPPLY / EQUIP D4030 STANDPIPE SYSTEMS D4040 SPRINKLERS D4050 FIRE PROTECTION SPECIALTIES D4090 OTHER FIRE PROTECTION SYSTEMS D5010 ELECTRICAL SERVICE & DISTRIBUTION D5020 LIGHTING & BRANCH WIRING D5030 COMMUNICATIONS & SECURITY D5090 OTHER ELECTRICAL SERVICES
Amber -	61	B2030 EXTERIOR DOORS C1020 INTERIOR DOORS C3010 WALL FINISHES C3020 FLOOR FINISHES C3030 CEILING FINISHES C3040 INT COATINGS / SPECIAL FINISHES D3010 ENERGY SUPPLY
Red +	50	B2010 EXTERIOR WALLS B2020 EXTERIOR WINDOWS C1030 SPECIALTIES D1020 WEIGHT HANDLING EQUIPMENT D1030 ESCALATORS AND MOVING WALKS D1090 OTHER CONVEYING SYSTEMS D2020 DOMESTIC WATER DISTRIBUTION D2030 SANITARY WASTE D2040 RAIN WATER DRAINAGE D2090 OTHER PLUMBING SYSTEMS D3070 SYSTEMS TESTING & BALANCING
Service Life	40	Paint

For this project, the following building components are not included in the BUILDER Inventory and are not evaluated during the assessment unless significant damage or deterioration was observed or reported.

- A1010 STANDARD FOUNDATIONS
- A1020 SPECIAL FOUNDATIONS
- A1030 SLAB ON GRADE
- A2010 BASEMENT EXCAVATION
- A2020 BASEMENT WALLS
- B1010 FLOOR CONSTRUCTION
- B1020 ROOF CONSTRUCTION
- B2010 EXTERIOR WALLS
- C1010 PARTITIONS
- C2010 STAIR CONSTRUCTION

Damage that is not visible or that is unknown will not be reflected in facility condition index calculations. It is anticipated that unknown damage or deterioration is more likely to be present in older facilities than more modern facilities.

In addition, some building components are concealed or inaccessible. In accordance with BUILDER guidelines, quantities for concealed and inaccessible components have been estimated and recorded in the BUILDER Inventory but have not been rated. When concealed or inaccessible components are encountered, life cycle data contained within BUILDER is used to predict renewal requirements, which are included in facility condition index calculations. Components that are often concealed or inaccessible include:

- D2020 DOMESTIC WATER PIPING
- D2030 SANITARY WASTE PIPING
- D3040 HVAC DISTRIBUTION
- D4010 FIRE ALARM DISTRIBUTION
- D5020 ELECTRICAL BRANCH WIRING

In addition to the building components noted above, if a building component is concealed or inaccessible, life cycle data contained within BUILDER is used to predict renewal requirements.

When a work plan is created, the CSCI of a component-section is compared to its associated standard. If the CSCI is less than or equal to the threshold in the standard, the remaining service life is evaluated. If the service life is less than the standard's remaining service life, BUILDER will add this section to the work plan and generate dollars to estimate a cost for the replacement.

If the CSCI is less than or equal to the threshold in the standard and the service life is greater than the standard's remaining service life, BUILDER will conduct a cost benefit analysis. The cost benefit analysis will determine whether the component-section should be repaired or left to expire at the end of its service life. When BUILDER determines a repair is the correct action, BUILDER will add this section to the work plan and generate dollars to estimate a cost for the repair.

When BUILDER determines taking no action is more cost effective, BUILDER will not add the component-section to the work plan. For example, if the CSCI for an external door component-section is 50 with a remaining service life of five years, BUILDER will compare the CSCI of 50 to the CI Threshold set by DoDEA and determine that 50 is less than the threshold of 61. BUILDER will compare the five years of remaining services life against the zero years of the threshold and determine a cost benefit analysis is required. The results of the cost benefit analysis will typically suggest to take no action and let the component-section run until the end of its service life before generating an item in the work plan.

A typical life cycle of a component-section is explained below.

Condition	Work Plan
CSCI > threshold	Work plan does not generate an item for the component-section
CSCI = threshold or just below it	Work plan will generate a repair item for the component-section

CSCI < threshold and the remaining service life > service life threshold	Work plan will remove the repair item for the component-section. It is too costly to repair so it is better to wait to replace it.
Remaining service life < service life threshold	Work plan will generate a replace item for the component-section

Facility Condition Assessment Data Analysis

In multiple building portfolios and especially with widespread geographic portfolios, it is important to know how building conditions compare. The Condition Index (CI) and Quality Ratings (Q-Ratings) are determined for each building assessed using guidelines shown below.

Condition Index (CI) – A measure of the constructed asset's condition at a specific point in time with respect to physical condition and ability to support the current occupant or mission. CI is calculated as the ratio of estimated cost of maintenance and repair requirements to Plant Replacement Value (PRV). Maintenance and repair requirements consist of that work necessary to ensure that a constructed asset is restored to a condition substantially equivalent to the originally intended and designed capacity, efficiency or capability. The formula for Condition Index is:

$$CI = 1 - \left(\frac{\text{Requirements}}{\text{PRV}} \right) \times 100$$

Q-Rating Bands – Bands allow OSD, Military Services, and Defense Agencies/Activities to group facilities by condition for the purposes of developing investment strategies.

TABLE 1: Q-RATING DESCRIPTIONS		
Rating Band	Calculated Rating (Condition Index)	General Description
Q-1	100 to 90	Facility new or well maintained (Good Condition)
Q-2	89 to 80	Facility is satisfactorily maintained (Fair Condition)
Q-3	79 to 60	Facility is under maintained (Poor Condition)
Q-4	59 to 0	Facility should be considered for replacement (Failing Condition)

Requirements – Sum of the work items from BUILDER.

Plant Replacement Value – Cost to design and construct a notional facility to current standards to replace an existing facility on the same site, (reference United Facilities Criteria UFC 3-701-01 23 May 2018, Change 3, 29 July 2019).

BUILDER Report Overview

Outlined below is a summary and description of the reports that are included.

Appendix C - Facility Summary Report – Provides a summation of FCA results. A Building Summary Report is included for each building that is considered permanent or semi-permanent construction and receives a Q-Rating. The purpose of this report is to provide a general overview of the building including key performance indicators. This report was generated using DoDEA's calculated Replacement Cost overwriting the data populated from real property records. This provides a more accurate Replacement Cost due to the inconsistencies with real property reconciliation between DoDEA and the Services. The DoD Facility Pricing Guide and DoDEA measurements for building square footage were used to calculate the Replacement Cost.

Appendix D - System Summary Report – Provides an overview of inspected systems and their condition index rating. A Building System Condition Index (SCI) By System Report is included for each building that is considered permanent or semi-permanent construction and receives a Q-Rating.

Appendix E - Work Items By Building – Provides a list of work items requiring repair or replacement of system/components, including budgets, for project planning purposes. A Work Plan Detail by Year Report is included for each building that is considered permanent or semi-permanent construction and receives a Q-Rating.

Appendix F - Remaining Service Life (RSL) Detail Report – Provides a detailed overview of systems/components, including descriptions, and their respective age, remaining service life and remaining paint life.

Appendix G - Direct Condition Rating Inspection By Section Report – Provides a summary of direct condition ratings for each component-section collected within each facility.

Appendix H - System Inventory Report – Provides a list of details for each component-section collected within each facility.

Appendix I - Fire Inspection Safety Report – This appendix is only applicable when a Fire Inspection Safety Report is provided at the time of the assessment for inclusion in the Facility Condition Assessment Report. The report provides a summary of the recent Fire Inspection to include any deficiencies.

Note: All reports are generated from the DoDEA BUILDER database. In the event line items within a report are compressed and difficult to read, this is a result of how BUILDER generates the report. It is our understanding that CERL is working to update the report format.

Summary of Terms

Acronyms	Description
BCI	Building Condition Index - Measures the condition of the building as a whole. The higher the BCI, the better.
BFI	Building Functionality Index - Measures the functionality of a building as a whole. The higher the BFI, the better.
BPI	Building Performance Index - Measures the overall performance of a building. The higher the BPI, the better.
EA	Each
ESC	Emergency Service Call
FCI	Facility Condition Index - The current maintenance, repair, and replacement deficiencies of the facility divided by the current replacement value of the facility, derives the FCI of a facility. The higher the FCI, the better.
GSF	Gross Square Foot
ISR	Installation Status Report - Measures installation condition against Army-wide standards.
LF	Linear Feet
MBH	Thousands of BTU per hour.
MDI	Mission Dependency Index - Measures how critical a facility is to the overall mission of its owner. The higher the MDI, the more critical.
PERM	Permanent
RELO	Relocatable
RPL	Remaining Paint Life - Displays the remaining paint life, in years, of a section.
RPUID	Real Property Unique Identifier - The unique identification number assigned to each asset.
RSL	Remaining Service Life - Displays the remaining service life, in years, of a section.
SCI	System Condition Index - Measures the condition of a system as a whole. The higher the SCI, the better.
SF	Square Foot
TEMP	Temporary
UM	Unit of Measure

Appendix C

Facility Summary Report

"identification only"

307 - DoDEA Europe South DSO Bldg 307

Camp Ederle - DoDEA Europe South DSO



YEAR BUILT: 1958

AREA (SF): 11,193

PLANT REPLACEMENT COST: [REDACTED]

SURVEY DATE: January 2020

TOTAL DEFICIENCIES: [REDACTED]

BUILDER(TM) METRIC		SCORE
Facility Condition Index	FCI:	74

358 - DoDEA Europe South DSO Bldg 358

Camp Ederle - DoDEA Europe South DSO



YEAR BUILT: 1995

AREA (SF): 835

PLANT REPLACEMENT COST: [REDACTED]

SURVEY DATE: January 2020

TOTAL DEFICIENCIES: [REDACTED]

BUILDER(TM) METRIC		SCORE
Facility Condition Index	FCI:	95

309 - Vicenza HS Bldg 309

Camp Ederle - Unassigned



YEAR BUILT: 1958

AREA (SF): 111,867

PLANT REPLACEMENT COST: [REDACTED]

SURVEY DATE: January 2020

TOTAL DEFICIENCIES: [REDACTED]

BUILDER(TM) METRIC		SCORE
Facility Condition Index	FCI:	82

Appendix D

System Summary Report

"identification only"

DoDEA SYSTEM SUMMARY

Camp Ederle

Complex	Building #	Building Name	A10	A20	B10	B20	B30	C10	C20	C30	D10	D20	D30	D40	D50	E10	E20	F10	F20	G10	G20	G30	G40	G90
DoDEA Europe South DSO	307	DoDEA Europe South DSO Bldg 307				89	67	82	82	83		28	43	22	88									
DoDEA Europe South DSO	358	DoDEA Europe South DSO Bldg 358				84	71	88		86			70	18	88									

A10 - Foundations

A20 -Basement Construction

B10 - Superstructure

B20 - Exterior Enclosure

B30 - Roofing

C10 - Interior Construction

C20 - Stairs

C30 - Interior Finishes

D10 - Conveying

D20 - Plumbing

D30 - HVAC

D40 - Fire Protection

D50 - Electrical

E10 - Equipment

E20 - Furnishings

F10 - Special Construction

F20 - Selective Building Demo

G10 - Site Preparations

G20 - Site Improvements

G30 - Site Civil / Mech Utilities

G40 - Site Electrical Utilities

G50 - Other Site Construction

DoDEA SYSTEM SUMMARY

Camp Ederle

Complex	Building #	Building Name	A10	A20	B10	B20	B30	C10	C20	C30	D10	D20	D30	D40	D50	E10	E20	F10	F20	G10	G20	G30	G40	G90
Unassigned	309	Vicenza HS Bldg 309				79	52	76	77	77	87	31	62	16	66	95								

- A10 - Foundations

A20 -Basement Construction

B10 - Superstructure

B20 - Exterior Enclosure

B30 - Roofing

C10 - Interior Construction
- C20 - Stairs

C30 - Interior Finishes

D10 - Conveying

D20 - Plumbing

D30 - HVAC

D40 - Fire Protection
- D50 - Electrical

E10 - Equipment

E20 - Furnishings

F10 - Special Construction

F20 - Selective Building Demo
- G10 - Site Preparations

G20 - Site Improvements

G30 - Site Civil / Mech Utilities

G40 - Site Electrical Utilities

G50 - Other Site Construction

"identification only"

Appendix E

Work Items By Building

"identification only"



Work Items by Building Report



Camp Ederle

Cost Book: Reference

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description							
2015	D20 PLUMBING						
	D2020 DOMESTIC WATER DISTRIBUTION	1612 (LF)	Replace				0.00
	1958 D202001 PIPES & FITTINGS General						
	-- Replace D2020 DOMESTIC WATER DISTRIBUTION D202001 PIPES & FITTINGS General						
	D2030 SANITARY WASTE	266 (LF)	Replace				0.00
	1958 D203001 WASTE PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE D203001 WASTE PIPE & FITTINGS General						
	D2030 SANITARY WASTE	134 (EA)	Replace				0.00
	1958 D203002 VENT PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE D203002 VENT PIPE & FITTINGS General						
	D2030 SANITARY WASTE	4 (EA)	Replace				0.00
	1958 D203003 FLOOR DRAINS General						
	-- Replace D2030 SANITARY WASTE D203003 FLOOR DRAINS General						
2015	D30 HVAC						
	D3040 DISTRIBUTION SYSTEMS	200 (MBH)	Replace				0.00
	1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS D304003 HOT WATER DISTRIBUTION SYSTEMS General						
2015	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS	11 (SF)	Repair				0.00
	1958 D401001 FIRE ALARM DISTRIBUTION Other						
	-- Repair D4010 FIRE ALARM AND DETECTION SYSTEMS D401001 FIRE ALARM DISTRIBUTION Fire detection systems, 50 detectors						
2015	D50 ELECTRICAL						
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)	Replace				0.00
	1958 D501002 SERVICE ENTRANCE EQUIPMENT Electrical Service - 3 Phase, 120/208 V, 1200 A						
	-- Replace D5010 ELECTRICAL SERVICE & DISTRIBUTION D501002 SERVICE ENTRANCE EQUIPMENT General						

Camp Ederle

Cost Book: Reference

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

Year	System	Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score	Completion Date
-- Description										
2016	D20	PLUMBING								
	D2020	DOMESTIC WATER DISTRIBUTION	1612 (LF)	Replace					0.00	
	1958	D202001 PIPES & FITTINGS General								
		-- Replace D2020 DOMESTIC WATER DISTRIBUTION D202001 PIPES & FITTINGS General								
	D2030	SANITARY WASTE	266 (LF)	Replace					0.00	
	1958	D203001 WASTE PIPE & FITTINGS General								
		-- Replace D2030 SANITARY WASTE D203001 WASTE PIPE & FITTINGS General								
	D2030	SANITARY WASTE	134 (EA)	Replace					0.00	
	1958	D203002 VENT PIPE & FITTINGS General								
		-- Replace D2030 SANITARY WASTE D203002 VENT PIPE & FITTINGS General								
	D2030	SANITARY WASTE	4 (EA)	Replace					0.00	
	1958	D203003 FLOOR DRAINS General								
		-- Replace D2030 SANITARY WASTE D203003 FLOOR DRAINS General								
2016	D30	HVAC								
	D3040	DISTRIBUTION SYSTEMS	200 (MBH)	Replace					0.00	
	1958	D304003 HOT WATER DISTRIBUTION SYSTEMS General								
		-- Replace D3040 DISTRIBUTION SYSTEMS D304003 HOT WATER DISTRIBUTION SYSTEMS General								
2016	D40	FIRE PROTECTION								
	D4010	FIRE ALARM AND DETECTION SYSTEMS	11 (SF)	Repair					0.00	
	1958	D401001 FIRE ALARM DISTRIBUTION Other								
		-- Repair D4010 FIRE ALARM AND DETECTION SYSTEMS D401001 FIRE ALARM DISTRIBUTION Fire detection systems, 50 detectors								
2016	D50	ELECTRICAL								
	D5010	ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)	Replace					0.00	
	1958	D501002 SERVICE ENTRANCE EQUIPMENT Electrical Service - 3 Phase, 120/208 V, 1200 A								
		-- Replace D5010 ELECTRICAL SERVICE & DISTRIBUTION D501002 SERVICE ENTRANCE EQUIPMENT General								

Camp Ederle

Cost Book: Reference

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

Year	System	Component	Qty (UM)	Activity	Project	Cost	Status	Score
Section Description								
-- Description								
2017	C10 INTERIOR CONSTRUCTION							
	C1010 PARTITIONS	20,501 (SF)	Paint					0.00
	1958 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing							
	-- Paint C1010 PARTITIONS 1958 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing							
2017	D20 PLUMBING							
	D2020 DOMESTIC WATER DISTRIBUTION	1,642 (LF)	Replace					0.00
	1958 D202001 PIPES & FITTINGS General							
	-- Replace D2020 DOMESTIC WATER DISTRIBUTION D202001 PIPES & FITTINGS General							
	D2030 SANITARY WASTE	266 (LF)	Replace					0.00
	1958 D203001 WASTE PIPE & FITTINGS General							
	-- Replace D2030 SANITARY WASTE D203001 WASTE PIPE & FITTINGS General							
	D2030 SANITARY WASTE	134 (EA)	Replace					0.00
	1958 D203002 VENT PIPE & FITTINGS General							
	-- Replace D2030 SANITARY WASTE D203002 VENT PIPE & FITTINGS General							
	D2030 SANITARY WASTE	4 (EA)	Replace					0.00
	1958 D203003 FLOOR DRAINS General							
	-- Replace D2030 SANITARY WASTE D203003 FLOOR DRAINS General							
2017	D30 HVAC							
	D3040 DISTRIBUTION SYSTEMS	200 (MBH)	Replace					0.00
	1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General							
	-- Replace D3040 DISTRIBUTION SYSTEMS D304003 HOT WATER DISTRIBUTION SYSTEMS General							
2017	D50 ELECTRICAL							
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1 (EA)	Replace					0.00
	1958 D501002 SERVICE ENTRANCE EQUIPMENT Electrical Service - 3 Phase, 120/208 V, 1200 A							
	-- Replace D5010 ELECTRICAL SERVICE & DISTRIBUTION D501002 SERVICE ENTRANCE EQUIPMENT General							

Camp Ederle

Cost Book: Reference

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
2018	B30 ROOFING							
	B3010 ROOF COVERINGS		1,698 (SF)	Replace				0.00
	1958 B301003 ROOF INSULATION & FILL General							
	-- Replace B3010 ROOF COVERINGS 1958 B301003 ROOF INSULATION & FILL General							
2018	D20 PLUMBING							
	D2020 DOMESTIC WATER DISTRIBUTION		3,304 (LF)	Replace				0.00
	1958 D202001 PIPES & FITTINGS General							
	-- Replace D2020 DOMESTIC WATER DISTRIBUTION 1958 D202001 PIPES & FITTINGS General							
	D2030 SANITARY WASTE		1,652 (LF)	Replace				0.00
	1958 D203001 WASTE PIPE & FITTINGS General							
	-- Replace D2030 SANITARY WASTE 1958 D203001 WASTE PIPE & FITTINGS General							
	D2030 SANITARY WASTE		402 (EA)	Replace				0.00
	1958 D203002 VENT PIPE & FITTINGS General							
	-- Replace D2030 SANITARY WASTE 1958 D203002 VENT PIPE & FITTINGS General							
2018	D30 HVAC							
	D3040 DISTRIBUTION SYSTEMS		280 (MBH)	Replace				0.00
	1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General							
	-- Replace D3040 DISTRIBUTION SYSTEMS 1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General							
	D3050 TERMINAL & PACKAGE UNITS		58 (EA)	Replace				0.00
	1958 D305002 UNIT HEATERS Hydronic - 300 MBH							
	-- Replace D3050 TERMINAL & PACKAGE UNITS 1958 D305002 UNIT HEATERS Hydronic - 300 MBH							
2018	D40 FIRE PROTECTION							
	D4010 FIRE ALARM AND DETECTION SYSTEMS		11,193 (SF)	Replace				0.00
	1958 D401001 FIRE ALARM DISTRIBUTION Other							
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1958 D401001 FIRE ALARM DISTRIBUTION Other							

Camp Ederle

Cost Book: Reference

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
2018	D50 ELECTRICAL							
	D5020 LIGHTING & BRANCH WIRING	1 (EA)	Replace					0.00
	1958 D502002 LIGHTING EQUIPMENT Exit Lighting							
	-- Replace D5020 LIGHTING & BRANCH WIRING 1958 D502002 LIGHTING EQUIPMENT Exit Lighting							
	D5090 OTHER ELECTRICAL SERVICES	1 (EA)	Replace					0.00
	1958 D509003 GROUNDING SYSTEMS General							
	-- Replace D5090 OTHER ELECTRICAL SERVICES 1958 D509003 GROUNDING SYSTEMS General							
2019	B30 ROOFING							
	B3010 ROOF COVERINGS	5,688 (SF)	Replace					0.00
	1958 B301003 ROOF INSULATION & FILL General							
	-- Replace B3010 ROOF COVERINGS 1958 B301003 ROOF INSULATION & FILL General							
2019	D20 PLUMBING							
	D2020 DOMESTIC WATER DISTRIBUTION	3,304 (LF)	Replace					0.00
	1958 D202001 PIPES & FITTINGS General							
	-- Replace D2020 DOMESTIC WATER DISTRIBUTION 1958 D202001 PIPES & FITTINGS General							
	D2030 SANITARY WASTE	1,652 (LF)	Replace					0.00
	1958 D203001 WASTE PIPE & FITTINGS General							
	-- Replace D2030 SANITARY WASTE 1958 D203001 WASTE PIPE & FITTINGS General							
	D2030 SANITARY WASTE	402 (EA)	Replace					0.00
	1958 D203002 VENT PIPE & FITTINGS General							
	-- Replace D2030 SANITARY WASTE 1958 D203002 VENT PIPE & FITTINGS General							
2019	D30 HVAC							
	D3040 DISTRIBUTION SYSTEMS	280 (MBH)	Replace					0.00
	1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General							
	-- Replace D3040 DISTRIBUTION SYSTEMS 1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General							



Work Items by Building Report



Camp Ederle

Cost Book: Reference

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description							
	D3050 TERMINAL & PACKAGE UNITS	5 (EA)	Replace				0.00
	1958 D305002 UNIT HEATERS Hydronic - 300 MBH						
	-- Replace D3050 TERMINAL & PACKAGE UNITS 1958 D305002 UNIT HEATERS Hydronic - 300 MBH						
2019	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS	11,193 (SF)	Replace				0.00
	1958 D401001 FIRE ALARM DISTRIBUTION Other						
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1958 D401001 FIRE ALARM DISTRIBUTION Other						
2019	D50 ELECTRICAL						
	D5020 LIGHTING & BRANCH WIRING	10 (EA)	Replace				0.00
	1958 D502002 LIGHTING EQUIPMENT Exit Lighting						
	-- Replace D5020 LIGHTING & BRANCH WIRING 1958 D502002 LIGHTING EQUIPMENT Exit Lighting						
	D5090 OTHER ELECTRICAL SERVICES	1 (EA)	Replace				0.00
	1958 D509003 GROUNDING SYSTEMS General						
	-- Replace D5090 OTHER ELECTRICAL SERVICES 1958 D509003 GROUNDING SYSTEMS General						
2020	B30 ROOFING						
	B3010 ROOF COVERINGS	5,688 (SF)	Replace				0.00
	1958 B301003 ROOF INSULATION & FILL General						
	-- Replace B3010 ROOF COVERINGS 1958 B301003 ROOF INSULATION & FILL General						
2020	D20 PLUMBING						
	D2020 DOMESTIC WATER DISTRIBUTION	3,304 (LF)	Replace				0.00
	1958 D202001 PIPES & FITTINGS General						
	-- Replace D2020 DOMESTIC WATER DISTRIBUTION 1958 D202001 PIPES & FITTINGS General						
	D2030 SANITARY WASTE	1,652 (LF)	Replace				0.00
	1958 D203001 WASTE PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE 1958 D203001 WASTE PIPE & FITTINGS General						

Camp Ederle

Cost Book: Reference

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
Section Description							
-- Description							
	D2030 SANITARY WASTE	402 (EA)	Replace				0.00
	1958 D203002 VENT PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE 1958 D203002 VENT PIPE & FITTINGS General						
2020	D30 HVAC						
	D3040 DISTRIBUTION SYSTEMS	280 (MBH)	Replace				0.00
	1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	D3050 TERMINAL & PACKAGE UNITS	58 (EA)	Replace				0.00
	1958 D305002 UNIT HEATERS Hydronic - 300 MBH						
	-- Replace D3050 TERMINAL & PACKAGE UNITS 1958 D305002 UNIT HEATERS Hydronic - 300 MBH						
2020	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS	11,193 (SF)	Replace				0.00
	1958 D401001 FIRE ALARM DISTRIBUTION Other						
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1958 D401001 FIRE ALARM DISTRIBUTION Other						
2020	D50 ELECTRICAL						
	D5090 OTHER ELECTRICAL SERVICES	1 (EA)	Replace				0.00
	1958 D509003 GROUNDING SYSTEMS General						
	-- Replace D5090 OTHER ELECTRICAL SERVICES 1958 D509003 GROUNDING SYSTEMS General						

Camp Ederle

Cost Book: Reference

358 - DoDEA Europe South DSO Bldg 358

DoDEA Europe South DSO (HE5468)

Year	System	Component	Qty (UM)	Activity	Project	Cost	Status	Score
Section Description								
-- Description								
2015	B20 EXTERIOR ENCLOSURE							
	B2010 EXTERIOR WALLS	1,200 (SF)	Paint					0.00
	1995 B201001 EXTERIOR CLOSURE E.I.F.S.							
	-- Paint B2010 EXTERIOR WALLS 1995 B201001 EXTERIOR CLOSURE Stucco							
2015	B30 ROOFING							
	B3010 ROOF COVERINGS	840 (SF)	Repair					0.00
	1995 B301001 STEEP SLOPE ROOF SYSTEMS Preformed Metal - Metal Panel							
	-- Repair B3010 ROOF COVERINGS 1995 B301001 STEEP SLOPE ROOF SYSTEMS Preformed Metal - Metal Panel							
2015	D40 FIRE PROTECTION							
	D4010 FIRE ALARM AND DETECTION SYSTEMS	22 (SF)	Repair					0.00
	1995 D401001 FIRE ALARM DISTRIBUTION Other							
	-- Repair D4010 FIRE ALARM AND DETECTION SYSTEMS D401002 FIRE ALARM DEVICES Detectors with brackets, ion detector (smoke) detector							
2016	B20 EXTERIOR ENCLOSURE							
	B2010 EXTERIOR WALLS	1,200 (SF)	Paint					0.00
	1995 B201001 EXTERIOR CLOSURE E.I.F.S.							
	-- Paint B2010 EXTERIOR WALLS 1995 B201001 EXTERIOR CLOSURE Stucco							
2016	D40 FIRE PROTECTION							
	D4010 FIRE ALARM AND DETECTION SYSTEMS	22 (SF)	Repair					0.00
	1995 D401001 FIRE ALARM DISTRIBUTION Other							
	-- Repair D4010 FIRE ALARM AND DETECTION SYSTEMS D401002 FIRE ALARM DEVICES Detectors with brackets, ion detector (smoke) detector							
2018	B30 ROOFING							

Camp Ederle

Cost Book: Reference

358 - DoDEA Europe South DSO Bldg 358

DoDEA Europe South DSO (HE5468)

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
	B3010 ROOF COVERINGS	1995 B301001 STEEP SLOPE ROOF SYSTEMS Preformed Metal - Metal Panel	840 (SF)	Repair				0.00
	-- Repair B3010 ROOF COVERINGS 1995 B301001 STEEP SLOPE ROOF SYSTEMS Preformed Metal - Metal Panel							
	B3010 ROOF COVERINGS	1995 B301003 ROOF INSULATION & FILL General	840 (SF)	Replace				0.00
	-- Replace B3010 ROOF COVERINGS 1995 B301003 ROOF INSULATION & FILL General							
2018	D40 FIRE PROTECTION							
	D4010 FIRE ALARM AND DETECTION SYSTEMS	1995 D401001 FIRE ALARM DISTRIBUTION Other	835 (SF)	Replace				0.00
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1995 D401001 FIRE ALARM DISTRIBUTION Other							
2019	B30 ROOFING							
	B3010 ROOF COVERINGS	1995 B301003 ROOF INSULATION & FILL General	840 (SF)	Replace				0.00
	-- Replace B3010 ROOF COVERINGS 1995 B301003 ROOF INSULATION & FILL General							
2019	D40 FIRE PROTECTION							
	D4010 FIRE ALARM AND DETECTION SYSTEMS	1995 D401001 FIRE ALARM DISTRIBUTION Other	835 (SF)	Replace				0.00
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1995 D401001 FIRE ALARM DISTRIBUTION Other							
2020	B30 ROOFING							
	B3010 ROOF COVERINGS	1995 B301003 ROOF INSULATION & FILL General	840 (SF)	Replace				0.00
	-- Replace B3010 ROOF COVERINGS 1995 B301003 ROOF INSULATION & FILL General							
2020	D40 FIRE PROTECTION							

358 - DoDEA Europe South DSO Bldg 358

DoDEA Europe South DSO (HE5468)

Year	System	Component	Qty (UM)	Activity	Project	Cost	Status	Score
Section Description								
-- Description						Completion Date		
	D4010	FIRE ALARM AND DETECTION SYSTEMS	828 (SF)	Replace				0.00
	1995	D401001 FIRE ALARM DISTRIBUTION Other						
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1995 D401001 FIRE ALARM DISTRIBUTION Other							

"Identification only"

Camp Ederle

Cost Book: Reference

309 - Vicenza HS Bldg 309

Unassigned

Year	System	Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score
			-- Description				Completion Date		
2015	B20 EXTERIOR ENCLOSURE								
	B2010	EXTERIOR WALLS	14,250 (SF)	Paint					0.00
	1958 B201001	EXTERIOR CLOSURE CIP Concrete							
	-- Paint B2010 EXTERIOR WALLS B201001 EXTERIOR CLOSURE CIP Concrete								
	B2010	EXTERIOR WALLS	74 (SF)	Paint					0.00
	1958 B201001	EXTERIOR CLOSURE Wall Louver							
	-- Paint B2010 EXTERIOR WALLS 1958 B201001 EXTERIOR CLOSURE Wall Louver								
	B2010	EXTERIOR WALLS	3,068 (SF)	Paint					0.00
	1958 B201007	EXTERIOR SOFFITS General							
	-- Paint B2010 EXTERIOR WALLS 1980 Stucco B201007 EXTERIOR SOFFITS General								
	B2010	EXTERIOR WALLS	40 (LF)	Paint					0.00
	1958 A B201006	BALCONY WALLS & HANDRAILS Handrailing							
	-- Paint B2010 EXTERIOR WALLS B201006 BALCONY WALLS & HANDRAILS General								
	B2010	EXTERIOR WALLS	50,665 (SF)	Paint					0.00
	1983 B201001	EXTERIOR CLOSURE E.I.F.S.							
	-- Paint B2010 EXTERIOR WALLS 1983 B201001 EXTERIOR CLOSURE E.I.F.S.								
	B2010	EXTERIOR WALLS	138 (LF)	Paint					0.00
	1983 B201006	BALCONY WALLS & HANDRAILS Handrailing							
	-- Paint B2010 EXTERIOR WALLS 1983 B201006 BALCONY WALLS & HANDRAILS Handrailing								
	B2010	EXTERIOR WALLS	1,188 (SF)	Paint					0.00
	1983 B201007	EXTERIOR SOFFITS General							
	-- Paint B2010 EXTERIOR WALLS 1983 Stucco B201007 EXTERIOR SOFFITS General								
2015	B30 ROOFING								
	B3010	ROOF COVERINGS	91,000 (SF)	Replace					0.00
	1958 B301002	LOW SLOPE ROOF SYSTEMS Modified Bitumen							
	-- Replace B3010 ROOF COVERINGS 1958 & 1983 B301002 LOW SLOPE ROOF SYSTEMS Built-Up, including critical distresses								

Camp Ederle

Cost Book: Reference

309 - Vicenza HS Bldg 309

Unassigned

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
	B3010	ROOF COVERINGS	91,000 (SF)	Replace				0.00
	1958 B301003	ROOF INSULATION & FILL General						
	-- Replace B3010 ROOF COVERINGS 1958 & 1983 B301003 ROOF INSULATION & FILL Unknown							
2015	C30	INTERIOR FINISHES						
	C3020	FLOOR FINISHES	3,827 (SF)	Replace				0.00
	1983 C302005	CARPETING General						
	-- Replace C3020 FLOOR FINISHES 1983 C302005 CARPETING General							
	C3030	CEILING FINISHES	6,995 (SF)	Paint				0.00
	1958 C303003	PLASTER CEILING FINISHES General						
	-- Paint C3030 CEILING FINISHES 1958 C303003 PLASTER CEILING FINISHES General							
2015	D10	CONVEYING						
	D1010	ELEVATORS AND LIFTS	1 (EA)	Replace				0.00
	1983 EL101 D101002	PASSENGER ELEVATORS Hydraulic Elevators - 1500 lb, 2 floors						
	-- Replace D1010 ELEVATORS AND LIFTS D101002 PASSENGER ELEVATORS Hydraulic Elevators - 1500 lb, 2 floors							
2015	D20	PLUMBING						
	D2020	DOMESTIC WATER DISTRIBUTION	21,540 (LF)	Replace				0.00
	1958 D202001	PIPES & FITTINGS General						
	-- Replace D2020 DOMESTIC WATER DISTRIBUTION 1958 D202001 PIPES & FITTINGS General							
	D2030	SANITARY WASTE	1,061 (LF)	Replace				0.00
	1958 D203001	WASTE PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE 1958 D203001 WASTE PIPE & FITTINGS General							
	D2030	SANITARY WASTE	1,756 (EA)	Replace				0.00
	1958 D203002	VENT PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE 1958 D203002 VENT PIPE & FITTINGS General							



Work Items by Building Report



Camp Ederle

Cost Book: Reference

309 - Vicenza HS Bldg 309

Unassigned

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description							
	D2030 SANITARY WASTE	4 (EA)	Replace				0.00
	1958 D203003 FLOOR DRAINS General						
	-- Replace D2030 SANITARY WASTE 1958 D203003 FLOOR DRAINS General						
	D2030 SANITARY WASTE	391 (EA)	Replace				0.00
	1983 D203002 VENT PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE 1983 D203002 VENT PIPE & FITTINGS General						
	D2030 SANITARY WASTE	4 (EA)	Replace				0.00
	1983 D203003 FLOOR DRAINS General						
	-- Replace D2030 SANITARY WASTE 1983 D203003 FLOOR DRAINS General						
2015	D30 HVAC						
	D3040 DISTRIBUTION SYSTEMS	2,744 (MBH)	Replace				0.00
	1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1958 D304003 HOT WATER DISTRIBUTION SYSTEMS Unknown						
	D3040 DISTRIBUTION SYSTEMS	600 (MBH)	Replace				0.00
	1983 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1983 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
2015	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS	111,867 (SF)	Replace				0.00
	1958 D401001 FIRE ALARM DISTRIBUTION Other						
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1958 & 1983 D401001 FIRE ALARM DISTRIBUTION General						
2015	D50 ELECTRICAL						
	D5030 COMMUNICATIONS & SECURITY	10,393 (EA)	Replace				0.00
	1958 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets						
	-- Replace D5030 COMMUNICATIONS & SECURITY 1958 & 1983 D503002 PUBLIC ADDRESS SYSTEMS General						

Camp Ederle

Cost Book: Reference

309 - Vicenza HS Bldg 309

Unassigned

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
	D5030	COMMUNICATIONS & SECURITY	2 (EA)	Replace				0.00
	1958 D503007	CLOCK & PROGRAM SYSTEMS General						
	-- Replace D5030 COMMUNICATIONS & SECURITY D503007 CLOCK & PROGRAM SYSTEMS General							
2016	B20 EXTERIOR ENCLOSURE							
	B2010	EXTERIOR WALLS	11,200 (SF)	Paint				0.00
	1958 B201001	EXTERIOR CLOSURE CIP Concrete						
	-- Paint B2010 EXTERIOR WALLS B201001 EXTERIOR CLOSURE CIP Concrete							
	B2010	EXTERIOR WALLS	74 (SF)	Paint				0.00
	1958 B201001	EXTERIOR CLOSURE Wall Louver						
	-- Paint B2010 EXTERIOR WALLS 1958 B201001 EXTERIOR CLOSURE Wall Louver							
	B2010	EXTERIOR WALLS	3,068 (SF)	Paint				0.00
	1958 B201007	EXTERIOR SOFFITS General						
	-- Paint B2010 EXTERIOR WALLS 1980 Stucco B201007 EXTERIOR SOFFITS General							
	B2010	EXTERIOR WALLS	40 (LF)	Paint				0.00
	1958 A B201006	BALCONY WALLS & HANDRAILS Handrailing						
	-- Paint B2010 EXTERIOR WALLS B201006 BALCONY WALLS & HANDRAILS General							
	B2010	EXTERIOR WALLS	50,665 (SF)	Paint				0.00
	1983 B201001	EXTERIOR CLOSURE E.I.F.S.						
	-- Paint B2010 EXTERIOR WALLS 1983 B201001 EXTERIOR CLOSURE E.I.F.S.							
	B2010	EXTERIOR WALLS	138 (LF)	Paint				0.00
	1983 B201006	BALCONY WALLS & HANDRAILS Handrailing						
	-- Paint B2010 EXTERIOR WALLS 1983 B201006 BALCONY WALLS & HANDRAILS Handrailing							
	B2010	EXTERIOR WALLS	1,188 (SF)	Paint				0.00
	1983 B201007	EXTERIOR SOFFITS General						
	-- Paint B2010 EXTERIOR WALLS 1983 Stucco B201007 EXTERIOR SOFFITS General							
2016	B30 ROOFING							

Camp Ederle

Cost Book: Reference

309 - Vicenza HS Bldg 309

Unassigned

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
Section Description							
-- Description							
B3010	ROOF COVERINGS	91,000 (SF)	Replace				0.00
1958	B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen						
-- Replace B3010 ROOF COVERINGS 1958 & 1983 B301002 LOW SLOPE ROOF SYSTEMS Built-Up							
B3010	ROOF COVERINGS	91,000 (SF)	Replace				0.00
1958	B301003 ROOF INSULATION & FILL General						
-- Replace B3010 ROOF COVERINGS 1958 & 1983 B301003 ROOF INSULATION & FILL Unknown							
2016	C30 INTERIOR FINISHES						
C3020	FLOOR FINISHES	3,827 (SF)	Replace				0.00
1983	C302005 CARPETING General						
-- Replace C3020 FLOOR FINISHES 1983 C302005 CARPETING General							
C3030	CEILING FINISHES	6,995 (SF)	Paint				0.00
1958	C303003 PLASTER CEILING FINISHES General						
-- Paint C3030 CEILING FINISHES 1958 C303003 PLASTER CEILING FINISHES General							
2016	D10 CONVEYING						
D1010	ELEVATORS AND LIFTS	1 (EA)	Replace				0.00
1983	EL101 D101002 PASSENGER ELEVATORS Hydraulic Elevators - 1500 lb, 2 floors						
-- Replace D1010 ELEVATORS AND LIFTS D101002 PASSENGER ELEVATORS Hydraulic Elevators - 1500 lb, 2 floors							
2016	D20 PLUMBING						
D2020	DOMESTIC WATER DISTRIBUTION	21,540 (LF)	Replace				0.00
1958	D202001 PIPES & FITTINGS General						
-- Replace D2020 DOMESTIC WATER DISTRIBUTION 1958 D202001 PIPES & FITTINGS General							
D2030	SANITARY WASTE	1,061 (LF)	Replace				0.00
1958	D203001 WASTE PIPE & FITTINGS General						
-- Replace D2030 SANITARY WASTE 1958 D203001 WASTE PIPE & FITTINGS General							



Camp Ederle

Cost Book: Reference

309 - Vicenza HS Bldg 309

Unassigned

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
Section Description							
-- Description							
	D2030 SANITARY WASTE	1,706 (EA)	Replace				0.00
	1958 D203002 VENT PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE 1958 D203002 VENT PIPE & FITTINGS General						
	D2030 SANITARY WASTE	46 (EA)	Replace				0.00
	1958 D203003 FLOOR DRAINS General						
	-- Replace D2030 SANITARY WASTE 1958 D203003 FLOOR DRAINS General						
	D2030 SANITARY WASTE	391 (EA)	Replace				0.00
	1983 D203002 VENT PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE 1983 D203002 VENT PIPE & FITTINGS General						
	D2030 SANITARY WASTE	4 (EA)	Replace				0.00
	1983 D203003 FLOOR DRAINS General						
	-- Replace D2030 SANITARY WASTE 1983 D203003 FLOOR DRAINS General						
2016	D30 HVAC						
	D3040 DISTRIBUTION SYSTEMS	2,744 (MBH)	Replace				0.00
	1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1958 D304003 HOT WATER DISTRIBUTION SYSTEMS Unknown						
	D3040 DISTRIBUTION SYSTEMS	600 (MBH)	Replace				0.00
	1983 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1983 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
2016	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS	111,867 (SF)	Replace				0.00
	1958 D401001 FIRE ALARM DISTRIBUTION Other						
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1958 & 1983 D401001 FIRE ALARM DISTRIBUTION General						
2016	D50 ELECTRICAL						

Camp Ederle

Cost Book: Reference

309 - Vicenza HS Bldg 309

Unassigned

Year	System	Component	Qty (UM)	Activity	Project	Cost	Status	Score
Section Description								
– Description						Completion Date		
	D5030	COMMUNICATIONS & SECURITY	10,293 (EA)	Replace				0.00
	1958	D503002 PUBLIC ADDRESS SYSTEMS 100 outlets						
		– Replace D5030 COMMUNICATIONS & SECURITY 1958 & 1983 D503002 PUBLIC ADDRESS SYSTEMS General						
	D5030	COMMUNICATIONS & SECURITY	1 (EA)	Replace				0.00
	1958	D503007 CLOCK & PROGRAM SYSTEMS General						
		– Replace D5030 COMMUNICATIONS & SECURITY D503007 CLOCK & PROGRAM SYSTEMS General						
2017	B20 EXTERIOR ENCLOSURE							
	B2010	EXTERIOR WALLS	11,200 (SF)	Paint				0.00
	1958	B201001 EXTERIOR CLOSURE CIP Concrete						
		– Paint B2010 EXTERIOR WALLS B201001 EXTERIOR CLOSURE CIP Concrete						
	B2010	EXTERIOR WALLS	74 (SF)	Paint				0.00
	1958	B201001 EXTERIOR CLOSURE Wall Louver						
		– Paint B2010 EXTERIOR WALLS 1958 B201001 EXTERIOR CLOSURE Wall Louver						
	B2010	EXTERIOR WALLS	3,068 (SF)	Paint				0.00
	1958	B201007 EXTERIOR SOFFITS General						
		– Paint B2010 EXTERIOR WALLS 1980 Stucco B201007 EXTERIOR SOFFITS General						
	B2010	EXTERIOR WALLS	40 (LF)	Paint				0.00
	1958	A B201006 BALCONY WALLS & HANDRAILS Handrailing						
		– Paint B2010 EXTERIOR WALLS B201006 BALCONY WALLS & HANDRAILS General						
	B2010	EXTERIOR WALLS	50,665 (SF)	Paint				0.00
	1983	B201001 EXTERIOR CLOSURE E.I.F.S.						
		– Paint B2010 EXTERIOR WALLS 1983 B201001 EXTERIOR CLOSURE E.I.F.S.						
	B2010	EXTERIOR WALLS	138 (LF)	Paint				0.00
	1983	B201006 BALCONY WALLS & HANDRAILS Handrailing						
		– Paint B2010 EXTERIOR WALLS 1983 B201006 BALCONY WALLS & HANDRAILS Handrailing						

Camp Ederle

Cost Book: Reference

309 - Vicenza HS Bldg 309

Unassigned

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
Section Description -- Description							
	B2010 EXTERIOR WALLS	1,168 (SF)	Paint				0.00
	1983 B201007 EXTERIOR SOFFITS General						
	-- Paint B2010 EXTERIOR WALLS 1983 Stucco B201007 EXTERIOR SOFFITS General						
2017	B30 ROOFING						
	B3010 ROOF COVERINGS	91,000 (SF)	Replace				0.00
	1958 B301003 ROOF INSULATION & FILL General						
	-- Replace B3010 ROOF COVERINGS 1958 & 1983 B301003 ROOF INSULATION & FILL Unknown						
2017	C10 INTERIOR CONSTRUCTION						
	C1010 PARTITIONS	121,886 (SF)	Paint				0.00
	1958 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing						
	-- Paint C1010 PARTITIONS 1958 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing						
	C1010 PARTITIONS	28,708 (SF)	Paint				0.00
	1983 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing						
	-- Paint C1010 PARTITIONS 1983 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing						
	C1030 SPECIALTIES	43 (EA)	Replace				0.00
	1958 A C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions						
	-- Replace C1030 SPECIALTIES 1958 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS General						
	C1030 SPECIALTIES	95 (EA)	Replace				0.00
	1958 A C103002 TOILET & BATH ACCESSORIES General						
	-- Replace C1030 SPECIALTIES 1958 C103002 TOILET & BATH ACCESSORIES General						
	C1030 SPECIALTIES	17 (EA)	Replace				0.00
	1983 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions						
	-- Replace C1030 SPECIALTIES 1983 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions						
	C1030 SPECIALTIES	29 (EA)	Replace				0.00
	1983 C103002 TOILET & BATH ACCESSORIES General						
	-- Replace C1030 SPECIALTIES 1983 C103002 TOILET & BATH ACCESSORIES General						

Camp Ederle

Cost Book: Reference

309 - Vicenza HS Bldg 309

Unassigned

Year	System	Component	Qty (UM)	Activity	Project	Cost	Status	Score
Section Description								Completion Date
-- Description								
2017	C30 INTERIOR FINISHES							
	C3020 FLOOR FINISHES	1,877 (SF)	Replace					0.00
	1983 C302005 CARPETING General							
	-- Replace C3020 FLOOR FINISHES 1983 C302005 CARPETING General							
	C3030 CEILING FINISHES	6,995 (SF)	Paint					0.00
	1958 C303003 PLASTER CEILING FINISHES General							
	-- Paint C3030 CEILING FINISHES 1958 C303003 PLASTER CEILING FINISHES General							
2017	D10 CONVEYING							
	D1010 ELEVATORS AND LIFTS	1 (EA)	Replace					0.00
	1983 EL101 D101002 PASSENGER ELEVATORS Hydraulic Elevators - 1500 lb, 2 floors							
	-- Replace D1010 ELEVATORS AND LIFTS D101002 PASSENGER ELEVATORS Hydraulic Elevators - 1500 lb, 2 floors							
2017	D20 PLUMBING							
	D2020 DOMESTIC WATER DISTRIBUTION	21,540 (LF)	Replace					0.00
	1958 D202001 PIPES & FITTINGS General							
	-- Replace D2020 DOMESTIC WATER DISTRIBUTION 1958 D202001 PIPES & FITTINGS General							
	D2030 SANITARY WASTE	1,061 (LF)	Replace					0.00
	1958 D203001 WASTE PIPE & FITTINGS General							
	-- Replace D2030 SANITARY WASTE 1958 D203001 WASTE PIPE & FITTINGS General							
	D2030 SANITARY WASTE	1,756 (EA)	Replace					0.00
	1958 D203002 VENT PIPE & FITTINGS General							
	-- Replace D2030 SANITARY WASTE 1958 D203002 VENT PIPE & FITTINGS General							
	D2030 SANITARY WASTE	46 (EA)	Replace					0.00
	1958 D203003 FLOOR DRAINS General							
	-- Replace D2030 SANITARY WASTE 1958 D203003 FLOOR DRAINS General							

Camp Ederle

Cost Book: Reference

309 - Vicenza HS Bldg 309

Unassigned

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
– Description								
	D2030 SANITARY WASTE	1983 D203002 VENT PIPE & FITTINGS General	301 (EA)	Replace				0.00
– Replace D2030 SANITARY WASTE 1983 D203002 VENT PIPE & FITTINGS General								
	D2030 SANITARY WASTE	1983 D203003 FLOOR DRAINS General	4 (EA)	Replace				0.00
– Replace D2030 SANITARY WASTE 1983 D203003 FLOOR DRAINS General								
2017 D30 HVAC								
	D3040 DISTRIBUTION SYSTEMS	1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General	2,744 (MBH)	Replace				0.00
– Replace D3040 DISTRIBUTION SYSTEMS 1958 D304003 HOT WATER DISTRIBUTION SYSTEMS Unknown								
	D3040 DISTRIBUTION SYSTEMS	1983 D304003 HOT WATER DISTRIBUTION SYSTEMS General	600 (MBH)	Replace				0.00
– Replace D3040 DISTRIBUTION SYSTEMS 1983 D304003 HOT WATER DISTRIBUTION SYSTEMS General								
2017 D40 FIRE PROTECTION								
	D4010 FIRE ALARM AND DETECTION SYSTEMS	1958 D401001 FIRE ALARM DISTRIBUTION Other	111,867 (SF)	Replace				0.00
– Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1958 & 1983 D401001 FIRE ALARM DISTRIBUTION General								
2017 D50 ELECTRICAL								
	D5020 LIGHTING & BRANCH WIRING	1958 D502001 BRANCH WIRING General	91,475 (SF)	Replace				0.00
– Replace D5020 LIGHTING & BRANCH WIRING 1958 D502001 BRANCH WIRING General								
	D5030 COMMUNICATIONS & SECURITY	1958 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	10,393 (EA)	Replace				0.00
– Replace D5030 COMMUNICATIONS & SECURITY 1958 & 1983 D503002 PUBLIC ADDRESS SYSTEMS General								



Camp Ederle

Cost Book: Reference

309 - Vicenza HS Bldg 309

Unassigned

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description							
	D5030 COMMUNICATIONS & SECURITY	2 (EA)	Replace				0.00
	1958 D503007 CLOCK & PROGRAM SYSTEMS General						
	-- Replace D5030 COMMUNICATIONS & SECURITY 1958 D503007 CLOCK & PROGRAM SYSTEMS General						
2018	B20 EXTERIOR ENCLOSURE						
	B2010 EXTERIOR WALLS	3,068 (SF)	Paint				0.00
	1958 B201007 EXTERIOR SOFFITS General						
	-- Paint B2010 EXTERIOR WALLS 1958 B201007 EXTERIOR SOFFITS General						
2018	B30 ROOFING						
	B3010 ROOF COVERINGS	91,000 (SF)	Replace				0.00
	1958 B301003 ROOF INSULATION & FILL General						
	-- Replace B3010 ROOF COVERINGS 1958 B301003 ROOF INSULATION & FILL General						
2018	D20 PLUMBING						
	D2020 DOMESTIC WATER DISTRIBUTION	27,079 (LF)	Replace				0.00
	1958 D202001 PIPES & FITTINGS General						
	-- Replace D2020 DOMESTIC WATER DISTRIBUTION 1958 D202001 PIPES & FITTINGS General						
	D2030 SANITARY WASTE	13,540 (LF)	Replace				0.00
	1958 D203001 WASTE PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE 1958 D203001 WASTE PIPE & FITTINGS General						
	D2030 SANITARY WASTE	3,293 (EA)	Replace				0.00
	1958 D203002 VENT PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE 1958 D203002 VENT PIPE & FITTINGS General						
	D2030 SANITARY WASTE	723 (EA)	Replace				0.00
	1983 D203002 VENT PIPE & FITTINGS General						
	-- Replace D2030 SANITARY WASTE 1983 D203002 VENT PIPE & FITTINGS General						
2018	D30 HVAC						



Work Items by Building Report



Camp Ederle

Cost Book: Reference

309 - Vicenza HS Bldg 309

Unassigned

Year	System Component	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description							
	D3040 DISTRIBUTION SYSTEMS	17,243 (LF)	Replace				0.00
	1958 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1958 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork						
	D3040 DISTRIBUTION SYSTEMS	2,287 (MBH)	Replace				0.00
	1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	D3040 DISTRIBUTION SYSTEMS	3,799 (LF)	Replace				0.00
	1983 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1983 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork						
	D3040 DISTRIBUTION SYSTEMS	510 (MBH)	Replace				0.00
	1983 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1983 D304003 HOT WATER DISTRIBUTION SYSTEMS General						
	D3040 DISTRIBUTION SYSTEMS	51 (TON)	Replace				0.00
	1983 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
	-- Replace D3040 DISTRIBUTION SYSTEMS 1983 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General						
2018	D40 FIRE PROTECTION						
	D4010 FIRE ALARM AND DETECTION SYSTEMS	91,475 (SF)	Replace				0.00
	1958 D401001 FIRE ALARM DISTRIBUTION Other						
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1958 D401001 FIRE ALARM DISTRIBUTION Other						
	D4010 FIRE ALARM AND DETECTION SYSTEMS	20,392 (SF)	Replace				0.00
	1983 D401001 FIRE ALARM DISTRIBUTION Other						
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1983 D401001 FIRE ALARM DISTRIBUTION Other						
2018	D50 ELECTRICAL						
	D5020 LIGHTING & BRANCH WIRING	91,475 (SF)	Replace				0.00
	1958 D502001 BRANCH WIRING General						
	-- Replace D5020 LIGHTING & BRANCH WIRING 1958 D502001 BRANCH WIRING General						



Camp Ederle

Cost Book: Reference

309 - Vicenza HS Bldg 309

Unassigned

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score	Completion Date
-- Description									
	D5030	COMMUNICATIONS & SECURITY	2 (EA)	Replace				0.00	
	1958 D503002	PUBLIC ADDRESS SYSTEMS 100 outlets							
	-- Replace D5030 COMMUNICATIONS & SECURITY 1958 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets								
2019	B30	ROOFING							
	B3010	ROOF COVERINGS	91,000 (SF)	Replace				0.00	
	1958 B301003	ROOF INSULATION & FILL General							
	-- Replace B3010 ROOF COVERINGS 1958 B301003 ROOF INSULATION & FILL General								
2019	C30	INTERIOR FINISHES							
	C3020	FLOOR FINISHES	4,400 (SF)	Replace				0.00	
	1983 C302005	CARPETING General							
	-- Replace C3020 FLOOR FINISHES 1983 C302005 CARPETING General								
2019	D20	PLUMBING							
	D2020	DOMESTIC WATER DISTRIBUTION	27,079 (LF)	Replace				0.00	
	1958 D202001	PIPES & FITTINGS General							
	-- Replace D2020 DOMESTIC WATER DISTRIBUTION 1958 D202001 PIPES & FITTINGS General								
	D2030	SANITARY WASTE	13,540 (LF)	Replace				0.00	
	1958 D203001	WASTE PIPE & FITTINGS General							
	-- Replace D2030 SANITARY WASTE 1958 D203001 WASTE PIPE & FITTINGS General								
	D2030	SANITARY WASTE	3,293 (EA)	Replace				0.00	
	1958 D203002	VENT PIPE & FITTINGS General							
	-- Replace D2030 SANITARY WASTE 1958 D203002 VENT PIPE & FITTINGS General								
	D2030	SANITARY WASTE	723 (EA)	Replace				0.00	
	1983 D203002	VENT PIPE & FITTINGS General							
	-- Replace D2030 SANITARY WASTE 1983 D203002 VENT PIPE & FITTINGS General								
2019	D30	HVAC							

Camp Ederle

Cost Book: Reference

309 - Vicenza HS Bldg 309

Unassigned

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
	D3040 DISTRIBUTION SYSTEMS	17,243 (LF)	Replace					0.00
	1958 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork							
	-- Replace D3040 DISTRIBUTION SYSTEMS 1958 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork							
	D3040 DISTRIBUTION SYSTEMS	2,287 (MBH)	Replace					0.00
	1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General							
	-- Replace D3040 DISTRIBUTION SYSTEMS 1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General							
	D3040 DISTRIBUTION SYSTEMS	3,799 (LF)	Replace					0.00
	1983 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork							
	-- Replace D3040 DISTRIBUTION SYSTEMS 1983 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork							
	D3040 DISTRIBUTION SYSTEMS	510 (MBH)	Replace					0.00
	1983 D304003 HOT WATER DISTRIBUTION SYSTEMS General							
	-- Replace D3040 DISTRIBUTION SYSTEMS 1983 D304003 HOT WATER DISTRIBUTION SYSTEMS General							
	D3040 DISTRIBUTION SYSTEMS	51 (TON)	Replace					0.00
	1983 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General							
	-- Replace D3040 DISTRIBUTION SYSTEMS 1983 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General							
2019	D40 FIRE PROTECTION							
	D4010 FIRE ALARM AND DETECTION SYSTEMS	91,475 (SF)	Replace					0.00
	1958 D401001 FIRE ALARM DISTRIBUTION Other							
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1958 D401001 FIRE ALARM DISTRIBUTION Other							
	D4010 FIRE ALARM AND DETECTION SYSTEMS	20,392 (SF)	Replace					0.00
	1983 D401001 FIRE ALARM DISTRIBUTION Other							
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1983 D401001 FIRE ALARM DISTRIBUTION Other							
2019	D50 ELECTRICAL							
	D5020 LIGHTING & BRANCH WIRING	91,475 (SF)	Replace					0.00
	1958 D502001 BRANCH WIRING General							
	-- Replace D5020 LIGHTING & BRANCH WIRING 1958 D502001 BRANCH WIRING General							

Camp Ederle

Cost Book: Reference

309 - Vicenza HS Bldg 309

Unassigned

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
	D5030 COMMUNICATIONS & SECURITY	1958 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	2 (EA)	Replace				0.00
-- Replace D5030 COMMUNICATIONS & SECURITY 1958 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets								
2020	B30 ROOFING							
	B3010 ROOF COVERINGS	1958 B301003 ROOF INSULATION & FILL General	91,000 (SF)	Replace				0.00
-- Replace B3010 ROOF COVERINGS 1958 B301003 ROOF INSULATION & FILL General								
2020	D20 PLUMBING							
	D2020 DOMESTIC WATER DISTRIBUTION	1958 D202001 PIPES & FITTINGS General	27,083 (LF)	Replace				0.00
-- Replace D2020 DOMESTIC WATER DISTRIBUTION 1958 D202001 PIPES & FITTINGS General								
	D2030 SANITARY WASTE	1958 D203001 WASTE PIPE & FITTINGS General	13,540 (LF)	Replace				0.00
-- Replace D2030 SANITARY WASTE 1958 D203001 WASTE PIPE & FITTINGS General								
	D2030 SANITARY WASTE	1958 D203002 VENT PIPE & FITTINGS General	3,293 (EA)	Replace				0.00
-- Replace D2030 SANITARY WASTE 1958 D203002 VENT PIPE & FITTINGS General								
	D2030 SANITARY WASTE	1983 D203002 VENT PIPE & FITTINGS General	723 (EA)	Replace				0.00
-- Replace D2030 SANITARY WASTE 1983 D203002 VENT PIPE & FITTINGS General								
2020	D30 HVAC							
	D3040 DISTRIBUTION SYSTEMS	1958 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	17,043 (LF)	Replace				0.00
-- Replace D3040 DISTRIBUTION SYSTEMS 1958 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork								



Camp Ederle

Cost Book: Reference

309 - Vicenza HS Bldg 309

Unassigned

Year	System Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score Completion Date
-- Description								
	D3040 DISTRIBUTION SYSTEMS	1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General	2,287 (MBH)	Replace				0.00
	-- Replace D3040 DISTRIBUTION SYSTEMS 1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General							
	D3040 DISTRIBUTION SYSTEMS	1983 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	3,799 (LF)	Replace				0.00
	-- Replace D3040 DISTRIBUTION SYSTEMS 1983 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork							
	D3040 DISTRIBUTION SYSTEMS	1983 D304003 HOT WATER DISTRIBUTION SYSTEMS General	510 (MBH)	Replace				0.00
	-- Replace D3040 DISTRIBUTION SYSTEMS 1983 D304003 HOT WATER DISTRIBUTION SYSTEMS General							
	D3040 DISTRIBUTION SYSTEMS	1983 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	51 (TON)	Replace				0.00
	-- Replace D3040 DISTRIBUTION SYSTEMS 1983 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General							
2020	D40 FIRE PROTECTION							
	D4010 FIRE ALARM AND DETECTION SYSTEMS	1958 D401001 FIRE ALARM DISTRIBUTION Other	91,475 (SF)	Replace		\$		0.00
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1958 D401001 FIRE ALARM DISTRIBUTION Other							
	D4010 FIRE ALARM AND DETECTION SYSTEMS	1983 D401001 FIRE ALARM DISTRIBUTION Other	20,392 (SF)	Replace				0.00
	-- Replace D4010 FIRE ALARM AND DETECTION SYSTEMS 1983 D401001 FIRE ALARM DISTRIBUTION Other							
2020	D50 ELECTRICAL							
	D5020 LIGHTING & BRANCH WIRING	1958 D502001 BRANCH WIRING General	91,475 (SF)	Replace				0.00
	-- Replace D5020 LIGHTING & BRANCH WIRING 1958 D502001 BRANCH WIRING General							

Appendix F

Remaining Service Life (RSL) Detail Report

"identification only"

Camp Ederle

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1958 B201001 EXTERIOR CLOSURE E.I.F.S.	20	33	Unknown
	B2010 EXTERIOR WALLS	1958 B201001 EXTERIOR CLOSURE Stone Veneer w/CMU Backup	20	31	
	B2010 EXTERIOR WALLS	1958 B201006 BALCONY WALLS & HANDRAILS Handrailing	32	6	
	B2010 EXTERIOR WALLS	1958 B201007 EXTERIOR SOFFITS General	20	8	Unknown
	B2010 EXTERIOR WALLS	1958 B201010 EXTERIOR JOINT SEALANT General	20	8	
	B2020 EXTERIOR WINDOWS	1958 B202001 WINDOWS Aluminum Windows	30	39	
	B2030 EXTERIOR DOORS	1958 B203001 SOLID DOORS Aluminum	20	8	
	B2030 EXTERIOR DOORS	1958 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress	20	8	
B30 ROOFING	B3010 ROOF COVERINGS	1958 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	10	8	
	B3010 ROOF COVERINGS	1958 B301003 ROOF INSULATION & FILL General	62	0	
	B3010 ROOF COVERINGS	1958 B301004 FLASHINGS & TRIM Flashings - Base	24	10	
	B3010 ROOF COVERINGS	1958 B301004 FLASHINGS & TRIM Flashings - Cap	24	10	
	B3010 ROOF COVERINGS	1958 B301004 FLASHINGS & TRIM Flashings - Embedded Edge Metal	24	10	
	B3010 ROOF COVERINGS	1958 B301005 GUTTERS & DOWNSPOUTS Downspouts	24	8	
	B3010 ROOF COVERINGS	1958 B301005 GUTTERS & DOWNSPOUTS Gutters	14	8	
	B3010 ROOF COVERINGS	1958 B301006 ROOF OPENINGS AND SUPPORTS Gravity Ventilator - 12" x 12"	14	8	
	B3010 ROOF COVERINGS	1958 B301006 ROOF OPENINGS AND SUPPORTS Gravity Ventilator - 6"	62	8	
	B3010 ROOF COVERINGS	1958 B301090 OTHER ROOFING Walkway Protection	14	4	
	B3010 ROOF COVERINGS	1958 A B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	24	8	
C10 INTERIOR	C1010 PARTITIONS	1958 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	62	52	28
	C1010 PARTITIONS	1958 C101005 INTERIOR WINDOWS Interior Windows	12	20	
	C1010 PARTITIONS	1958 A C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	4	52	5
	C1020 INTERIOR DOORS	1958 C102001 STANDARD INTERIOR DOORS Wood Door/Metal Frame	4	21	
	C1020 INTERIOR DOORS	1958 C102001 STANDARD INTERIOR DOORS Wood Door/Wood Frame	12	21	
	C1020 INTERIOR DOORS	1958 C102002 GLAZED INTERIOR DOORS General	12	16	
	C1020 INTERIOR DOORS	1958 A C102002 GLAZED INTERIOR DOORS General	4	21	
	C1030 SPECIALTIES	1958 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet	22	10	
	C1030 SPECIALTIES	1958 C103002 TOILET & BATH ACCESSORIES General	19	6	
	C1030 SPECIALTIES	1958 C103003 MARKER BOARDS & TACK BOARDS General	12	10	
	C1030 SPECIALTIES	1958 C103008 COUNTERS Laminated Plastic	32	12	
	C1030 SPECIALTIES	1958 C103009 CABINETS Other	12	8	

Camp Ederle

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	C1030 SPECIALTIES	1958 A C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet	4	10	
	C1030 SPECIALTIES	1958 A C103002 TOILET & BATH ACCESSORIES General	4	10	
C20 STAIRS	C2010 STAIR CONSTRUCTION	1958 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete	62	52	
	C2010 STAIR CONSTRUCTION	1958 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete	62	52	
	C2010 STAIR CONSTRUCTION	1958 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	12	41	
	C2010 STAIR CONSTRUCTION	1958 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES	20	10	
C30 INTERIOR FINISHES	C3010 WALL FINISHES	1958 C301004 TILE & TERRAZZO WALL FINISHES Tile	12	31	
	C3010 WALL FINISHES	1958 A C301004 TILE & TERRAZZO WALL FINISHES Tile	4	39	
	C3020 FLOOR FINISHES	1958 C302001 TILE FLOOR FINISHES Ceramic Tile	12	31	
	C3020 FLOOR FINISHES	1958 A C302001 TILE FLOOR FINISHES Ceramic Tile	4	39	
	C3030 CEILING FINISHES	1958 C303001 ACOUSTICAL CEILING TILES & PANELS General	24	29	
	C3030 CEILING FINISHES	1958 C303005 SUSPENSION SYSTEMS General	24	8	
	C3030 CEILING FINISHES	1958 A C303001 ACOUSTICAL CEILING TILES & PANELS General	4	37	
	C3030 CEILING FINISHES	1958 A C303005 SUSPENSION SYSTEMS General	4	10	
D20 PLUMBING	D2010 PLUMBING FIXTURES	1958 D201001 WATERCLOSERS General	22	10	
	D2010 PLUMBING FIXTURES	1958 D201002 URINALS General	22	10	
	D2010 PLUMBING FIXTURES	1958 D201004 SINKS General	22	10	
	D2010 PLUMBING FIXTURES	1958 D201004 SINKS Stainless	22	10	
	D2020 DOMESTIC WATER	1958 D202001 PIPES & FITTINGS General	62	0	
	D2020 DOMESTIC WATER	1958 M101 D202003 DOMESTIC WATER EQUIPMENT Storage Tank -	20	15	
	D2030 SANITARY WASTE	1958 D203001 WASTE PIPE & FITTINGS General	62	0	
	D2030 SANITARY WASTE	1958 D203002 VENT PIPE & FITTINGS General	62	0	
	D2030 SANITARY WASTE	1958 D203003 FLOOR DRAINS General	62	6	
D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General	43	0	
	D3040 DISTRIBUTION SYSTEMS	1958 M101 D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating Pump,	20	6	
	D3040 DISTRIBUTION SYSTEMS	1958 M101 D304003 HOT WATER DISTRIBUTION SYSTEMS Heat Exchanger,	10	8	
	D3050 TERMINAL & PACKAGE UNITS	1958 D305002 UNIT HEATERS Hydronic - 300 MBH	40	0	
	D3050 TERMINAL & PACKAGE UNITS	1958 ROOFTOP D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air	5	10	
	D3050 TERMINAL & PACKAGE UNITS	1958 ROOFTOP A D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air	11	6	
	D3050 TERMINAL & PACKAGE UNITS	1958 ROOFTOP B D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air	4	10	

Camp Ederle

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D3050 TERMINAL & PACKAGE UNITS	1958 ROOFTOP C D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air	15	4	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION	1958 D401001 FIRE ALARM DISTRIBUTION Other	24	0	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1958 D501002 SERVICE ENTRANCE EQUIPMENT Electrical Service - 3 Phase,	24	10	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1958 D501004 PANELBOARDS Main lugs, 120/208 V, 225 amp, NQOD	24	15	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1958 D501004 PANELBOARDS Main lugs, 400 amp	5	10	
	D5020 LIGHTING & BRANCH WIRING	1958 D502001 BRANCH WIRING General	24	36	
	D5020 LIGHTING & BRANCH WIRING	1958 D502002 LIGHTING EQUIPMENT Exit Lighting	40	10	
	D5020 LIGHTING & BRANCH WIRING	1958 D502002 LIGHTING EQUIPMENT General	5	10	
	D5030 COMMUNICATIONS & EQUIPMENT	1958 D503002 PUBLIC ADDRESS SYSTEMS 30 outlets	5	10	
	D5090 OTHER ELECTRICAL	1958 D509002 EMERGENCY LIGHTING & POWER General	5	10	
	D5090 OTHER ELECTRICAL	1958 D509001 GROUNDING SYSTEMS General	62	0	

"Identification only"

Camp Ederle

358 - DoDEA Europe South DSO Bldg 358

DoDEA Europe South DSO (HE5468)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1995 B201001 EXTERIOR CLOSURE E.I.F.S.	25	26	8
	B2010 EXTERIOR WALLS	1995 B201010 EXTERIOR JOINT SEALANT General	21	8	
	B2020 EXTERIOR WINDOWS	1995 B202001 WINDOWS Aluminum Windows	25	31	
	B2030 EXTERIOR DOORS	1995 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress	25	8	
B30 ROOFING	B3010 ROOF COVERINGS	1995 B301001 STEEP SLOPE ROOF SYSTEMS Preformed Metal - Metal Panel	25	12	
	B3010 ROOF COVERINGS	1995 B301003 ROOF INSULATION & FILL General	25	0	
	B3010 ROOF COVERINGS	1995 B301004 FLASHINGS & TRIM Flashings - Cap	25	10	
	B3010 ROOF COVERINGS	1995 B301004 FLASHINGS & TRIM Flashings - Embedded Edge Metal	25	10	
	B3010 ROOF COVERINGS	1995 B301005 GUTTERS & DOWNSPOUTS Downspouts	25	8	
	B3010 ROOF COVERINGS	1995 B301005 GUTTERS & DOWNSPOUTS Gutters	25	8	
C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	1995 C101001 FIXED PARTITIONS Wall - Drywall w/Stud Framing	25	26	Unknown
C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	1995 C302001 TILE FLOOR FINISHES Ceramic Tile	25	39	
	C3030 CEILING FINISHES	1995 C303001 ACOUSTICAL CEILING TILES & PANELS General	25	29	
	C3030 CEILING FINISHES	1995 C303005 SUSPENSION SYSTEMS General	25	8	
D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1995 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled	10	6	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYSTEMS	1995 D401001 FIRE ALARM DISTRIBUTION Other	25	0	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1995 D501004 PANELBOARDS Main lugs, 120 am	25	10	
	D5020 LIGHTING & BRANCH WIRING	1995 D502001 BRANCH WIRING General	25	35	
	D5020 LIGHTING & BRANCH WIRING	1995 D502002 LIGHTING EQUIPMENT General	25	10	
	D5090 OTHER ELECTRICAL	1995 D509002 EMERGENCY LIGHTING & POWER General	25	10	
	D5090 OTHER ELECTRICAL	1995 D509003 GROUNDING SYSTEMS General	25	25	

Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1958 B201001 EXTERIOR CLOSURE Brick Veneer w/CMU Backup	62	39	
	B2010 EXTERIOR WALLS	1958 B201001 EXTERIOR CLOSURE CIP Concrete	62	31	0
	B2010 EXTERIOR WALLS	1958 B201001 EXTERIOR CLOSURE Glass Block	62	20	
	B2010 EXTERIOR WALLS	1958 B201001 EXTERIOR CLOSURE Wall Louver	40	12	0
	B2010 EXTERIOR WALLS	1958 B201004 PARAPETS General	25	8	
	B2010 EXTERIOR WALLS	1958 B201007 EXTERIOR SOFFITS General	40	8	8
	B2010 EXTERIOR WALLS	1958 B201010 EXTERIOR JOINT SEALANT General	26	8	
	B2010 EXTERIOR WALLS	1958 B201006 BALCONY WALLS & HANDRAILS Handrailing	40	6	20
	B2010 EXTERIOR WALLS	1983 B201001 EXTERIOR CLOSURE E.I.F.S.	37	20	0
	B2010 EXTERIOR WALLS	1983 B201001 EXTERIOR CLOSURE Metal Panel	32	12	
	B2010 EXTERIOR WALLS	1983 B201001 EXTERIOR CLOSURE Stone	37	39	
	B2010 EXTERIOR WALLS	1983 B201007 EXTERIOR LOUVERS & SCREENS General	37	8	
	B2010 EXTERIOR WALLS	1983 B201006 BALCONY WALLS & HANDRAILS Handrailing	37	8	0
	B2010 EXTERIOR WALLS	1983 B201006 BALCONY WALLS & HANDRAILS Ladder	32	6	
	B2010 EXTERIOR WALLS	1983 B201007 EXTERIOR SOFFITS General	37	8	8
	B2010 EXTERIOR WALLS	1983 B201010 EXTERIOR JOINT SEALANT General	37	8	
	B2020 EXTERIOR WINDOWS	1958 B202001 WINDOWS Aluminum Windows	29	23	
	B2020 EXTERIOR WINDOWS	1958 B202002 STOREFRONTS General	26	8	
	B2020 EXTERIOR WINDOWS	1958 B202003 CURTAIN WALLS General	29	39	
	B2020 EXTERIOR WINDOWS	1983 B202001 WINDOWS Aluminum Windows	37	39	
	B2030 EXTERIOR DOORS	1958 B203001 SOLID DOORS Aluminum	22	8	
	B2030 EXTERIOR DOORS	1958 B203001 SOLID DOORS Steel	22	6	
	B2030 EXTERIOR DOORS	1958 B203002 GLAZED DOORS General	26	16	
	B2030 EXTERIOR DOORS	1958 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress	22	8	
B30 ROOFING	B3010 ROOF COVERINGS	1958 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	25	2	
	B3010 ROOF COVERINGS	1958 B301003 ROOF INSULATION & FILL General	25	0	
	B3010 ROOF COVERINGS	1958 B301004 FLASHINGS & TRIM Flashings - Cap	25	10	
	B3010 ROOF COVERINGS	1958 B301004 FLASHINGS & TRIM Flashings - Embedded Edge Metal	25	10	
	B3010 ROOF COVERINGS	1958 B301004 FLASHINGS & TRIM General	25	10	
	B3010 ROOF COVERINGS	1958 B301005 GUTTERS & DOWNSPOUTS Downspouts	25	8	
	B3010 ROOF COVERINGS	1958 B301005 GUTTERS & DOWNSPOUTS Gutters	25	8	
	B3010 ROOF COVERINGS	1958 B301006 ROOF OPENINGS AND SUPPORTS Gravity Ventilator - 36"	25	8	

Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	B3010 ROOF COVERINGS	1958 B301006 ROOF OPENINGS AND SUPPORTS Gravity Ventilator - 6"	25	8	
	B3010 ROOF COVERINGS	1958 B301006 ROOF OPENINGS AND SUPPORTS Skylights	25	31	
	B3010 ROOF COVERINGS	1983 B301002 LOW SLOPE ROOF SYSTEMS Built-Up	14	4	
	B3010 ROOF COVERINGS	1983 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	14	8	
	B3010 ROOF COVERINGS	1983 B301003 ROOF INSULATION & FILL General	14	6	
	B3010 ROOF COVERINGS	1983 B301004 FLASHINGS & TRIM Flashings - Cap	14	10	
	B3010 ROOF COVERINGS	1983 B301006 ROOF OPENINGS AND SUPPORTS Skylights	37	23	
C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	1958 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	62	51	19
	C1010 PARTITIONS	1958 A C101005 INTERIOR WINDOWS Interior Windows	22	15	
	C1010 PARTITIONS	1958 B C101005 INTERIOR WINDOWS Interior Windows	4	20	
	C1010 PARTITIONS	1983 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	37	65	19
	C1010 PARTITIONS	1983 C101005 INTERIOR WINDOWS Interior Windows	37	15	
	C1020 INTERIOR DOORS	1958 C102001 STANDARD INTERIOR DOORS Wood Door/Wood Frame	14	12	
	C1020 INTERIOR DOORS	1958 C102006 INTERIOR GATES General	22	8	
	C1020 INTERIOR DOORS	1958 A C102002 GLAZED INTERIOR DOORS General	20	12	
	C1020 INTERIOR DOORS	1958 B C102002 GLAZED INTERIOR DOORS General	4	16	
	C1020 INTERIOR DOORS	1983 C102001 STANDARD INTERIOR DOORS Wood Door/Metal Frame	34	12	
	C1020 INTERIOR DOORS	1983 C102002 GLAZED INTERIOR DOORS General	34	12	
	C1030 SPECIALTIES	1958 C103003 MARKER BOARDS & TASK BOARDS General	21	6	
	C1030 SPECIALTIES	1958 C103005 LOCKERS General	21	12	
	C1030 SPECIALTIES	1958 A C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet	22	6	
	C1030 SPECIALTIES	1958 A C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Urinal	22	6	
	C1030 SPECIALTIES	1958 A C103002 TOILET & BATH ACCESSORIES General	22	6	
	C1030 SPECIALTIES	1958 A C103008 COUNTERS Laminated Plastic	20	9	
	C1030 SPECIALTIES	1958 A C103009 CABINETS Other	20	6	
	C1030 SPECIALTIES	1958 B C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet	4	8	
	C1030 SPECIALTIES	1958 B C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Urinal	4	8	
	C1030 SPECIALTIES	1958 B C103002 TOILET & BATH ACCESSORIES General	4	8	
	C1030 SPECIALTIES	1958 B C103008 COUNTERS Stone	4	12	
	C1030 SPECIALTIES	1958 B C103009 CABINETS Other	4	8	
	C1030 SPECIALTIES	1983 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet	37	6	
	C1030 SPECIALTIES	1983 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Urinal	22	6	

Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	C1030 SPECIALTIES	1983 C103002 TOILET & BATH ACCESSORIES General	37	6	
C20 STAIRS	C2010 STAIR CONSTRUCTION	1958 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Steps - Concrete	22	8	
	C2010 STAIR CONSTRUCTION	1958 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	62	41	
	C2010 STAIR CONSTRUCTION	1958 C201001 INTERIOR AND EXTERIOR STAIRS Interior Steps	14	8	
	C2010 STAIR CONSTRUCTION	1958 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES	14	6	
	C2010 STAIR CONSTRUCTION	1983 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete	22	39	
	C2010 STAIR CONSTRUCTION	1983 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete	62	39	
C30 INTERIOR FINISHES	C3010 WALL FINISHES	1958 A C301004 TILE & TERRAZZO WALL FINISHES Tile	17	23	
	C3010 WALL FINISHES	1958 B C301004 TILE & TERRAZZO WALL FINISHES Tile	4	31	
	C3010 WALL FINISHES	1983 C301004 TILE & TERRAZZO WALL FINISHES Tile	17	31	
	C3020 FLOOR FINISHES	1958 C302001 WOOD FLOORING General	13	12	
	C3020 FLOOR FINISHES	1958 C302004 RESILIENT FLOOR FINISHES Composition Sheet	13	5	
	C3020 FLOOR FINISHES	1958 C302005 CARPETING Carpet Tile	13	3	
	C3020 FLOOR FINISHES	1958 A C302001 TILE FLOOR FINISHES Ceramic Tile	13	31	
	C3020 FLOOR FINISHES	1958 B C302001 TILE FLOOR FINISHES Ceramic Tile	4	31	
	C3020 FLOOR FINISHES	1983 C302001 TILE FLOOR FINISHES Ceramic Tile	37	31	
	C3020 FLOOR FINISHES	1983 C302004 RESILIENT FLOOR FINISHES Composition Sheet	37	5	
	C3020 FLOOR FINISHES	1983 C302005 CARPETING General	37	2	
	C3030 CEILING FINISHES	1958 C303003 PLASTER CEILING FINISHES General	62	51	0
	C3030 CEILING FINISHES	1958 C303090 OTHER CEILING & CEILING FINISHES Other	62	12	
	C3030 CEILING FINISHES	1958 A C303001 ACOUSTICAL CEILING TILES & PANELS General	12	21	
	C3030 CEILING FINISHES	1958 A C303005 SUSPENSION SYSTEMS General	12	6	
	C3030 CEILING FINISHES	1958 B C303001 ACOUSTICAL CEILING TILES & PANELS General	4	36	
	C3030 CEILING FINISHES	1958 B C303005 SUSPENSION SYSTEMS General	4	10	
	C3030 CEILING FINISHES	1983 C303001 ACOUSTICAL CEILING TILES & PANELS General	37	21	
	C3030 CEILING FINISHES	1983 C303003 PLASTER CEILING FINISHES General	37	39	
	C3030 CEILING FINISHES	1983 C303005 SUSPENSION SYSTEMS General	37	6	
D10 CONVEYING	D1010 ELEVATORS AND LIFTS	1983 EL101 D101002 PASSENGER ELEVATORS Hydraulic Elevators - 1500 b,	37	13	
D20 PLUMBING	D2010 PLUMBING FIXTURES	1958 D201001 WATERCLOSETS General	26	6	
	D2010 PLUMBING FIXTURES	1958 D201002 URINALS General	26	10	

Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D2010 PLUMBING FIXTURES	1958 D201004 SINKS General	26	10	
	D2010 PLUMBING FIXTURES	1958 D201004 SINKS Kitchen Sink	26	18	
	D2010 PLUMBING FIXTURES	1958 D201004 SINKS Laboratory Sink	26	10	
	D2010 PLUMBING FIXTURES	1958 D201090 OTHER PLUMBING FIXTURES Emergency Eye Wash	22	13	
	D2010 PLUMBING FIXTURES	1958 D201090 OTHER PLUMBING FIXTURES Emergency Shower	22	13	
	D2010 PLUMBING FIXTURES	1983 D201001 WATERCLOSETS General	37	10	
	D2010 PLUMBING FIXTURES	1983 D201002 URINALS General	37	10	
	D2010 PLUMBING FIXTURES	1983 D201003 LAVATORIES General	37	10	
	D2010 PLUMBING FIXTURES	1983 D201004 SINKS Service Sink	37	10	
	D2020 DOMESTIC WATER	1958 D202001 PIPES & FITTINGS General	62	0	
	D2020 DOMESTIC WATER	1958 D202003 DOMESTIC WATER EQUIPMENT Water Heaters, Commercial,	20	3	
	D2020 DOMESTIC WATER	1958 M201 D202003 DOMESTIC WATER EQUIPMENT Storage Tank -	20	9	
	D2020 DOMESTIC WATER	1958 M201 D202003 DOMESTIC WATER EQUIPMENT Storage Tank - Glass	20	9	
	D2020 DOMESTIC WATER	1983 D202001 PIPES & FITTINGS General	37	13	
	D2030 SANITARY WASTE	1958 D203001 WASTE PIPE & FITTINGS General	62	0	
	D2030 SANITARY WASTE	1958 D203002 VENT PIPE & FITTINGS General	62	0	
	D2030 SANITARY WASTE	1958 D203003 FLOOR DRAINS General	62	10	
	D2030 SANITARY WASTE	1983 D203001 WASTE PIPE & FITTINGS General	37	13	
	D2030 SANITARY WASTE	1983 D203002 VENT PIPE & FITTINGS General	37	0	
	D2030 SANITARY WASTE	1983 D203003 FLOOR DRAINS General	37	10	
D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1958 D302001 BOILERS Gas/Oil, Hot Water - 3,500-4,250 MBH	19	15	
	D3020 HEAT GENERATING SYSTEMS	1958 D302004 AUXILIARY EQUIPMENT Expansion Tank - 10 gal	20	15	
	D3020 HEAT GENERATING SYSTEMS	1983 D302004 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	37	15	
	D3020 HEAT GENERATING SYSTEMS	1983 D302004 AUXILIARY EQUIPMENT Expansion Tank - 220 gal	5	15	
	D3030 COOLING GENERATING	1958 A D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled	3	10	
	D3030 COOLING GENERATING	1958 B D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled	10	6	
	D3040 DISTRIBUTION SYSTEMS	1958 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	62	0	
	D3040 DISTRIBUTION SYSTEMS	1958 D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating Pump, End	20	10	
	D3040 DISTRIBUTION SYSTEMS	1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General	62	0	
	D3040 DISTRIBUTION SYSTEMS	1958 D304003 HOT WATER DISTRIBUTION SYSTEMS Heat Exchanger, Shell &	19	10	
	D3040 DISTRIBUTION SYSTEMS	1958 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	10	10	
	D3040 DISTRIBUTION SYSTEMS	1958 D304007 EXHAUST SYSTEMS Fume Hood Exhaust System - 4', 2000	25	5	

Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D3040 DISTRIBUTION SYSTEMS	1958 D304008 AIR HANDLING UNITS Central Station - 10000 CFM	10	8	
	D3040 DISTRIBUTION SYSTEMS	1983 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	62	0	
	D3040 DISTRIBUTION SYSTEMS	1983 D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating Pump, End	5	10	
	D3040 DISTRIBUTION SYSTEMS	1983 D304003 HOT WATER DISTRIBUTION SYSTEMS General	37	0	
	D3040 DISTRIBUTION SYSTEMS	1983 D304003 HOT WATER DISTRIBUTION SYSTEMS Heat Exchanger, Shell &	5	10	
	D3040 DISTRIBUTION SYSTEMS	1983 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	62	0	
	D3050 TERMINAL & PACKAGE UNITS	1958 D305001 UNIT VENTILATORS Air Curtain	20	10	
	D3050 TERMINAL & PACKAGE UNITS	1958 D305002 UNIT HEATERS Hydronic - 150 MBH	15	15	
	D3050 TERMINAL & PACKAGE UNITS	1958 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled	17	10	
	D3050 TERMINAL & PACKAGE UNITS	1958 D305007 PACKAGE UNITS Packaged A/C, Air Cooled, Elec Heat - 5 ton	7	10	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION	1958 D401001 FIRE ALARM DISTRIBUTION Other	37	0	
	D4010 FIRE ALARM AND DETECTION	1983 D401001 FIRE ALARM DISTRIBUTION Other	22	0	
	D4030 STANDPIPE SYSTEMS	1958 D403001 STANDPIPE EQUIPMENT & PIPING Riser - 4" diam	62	10	
	D4090 OTHER FIRE PROTECTION	1958 D409004 HOOD & DUCT FIRE PROTECTION General	20	13	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE &	1958 D501004 PANELBOARDS Main lugs, 120/208 V, 225 amp, NQOD	37	9	
	D5010 ELECTRICAL SERVICE &	1958 D501004 PANELBOARDS Main lugs, 400 amp	20	10	
	D5010 ELECTRICAL SERVICE &	1958 D501004 PANELBOARDS Switchgear - 800 Amp	20	26	
	D5010 ELECTRICAL SERVICE &	1958 D501005 ENCLOSED CIRCUIT BREAKERS Main circuit breaker, 120/208	20	26	
	D5010 ELECTRICAL SERVICE &	1983 D501004 PANELBOARDS Main lugs, 120/208 V, 225 amp, NQOD	37	15	
	D5010 ELECTRICAL SERVICE &	1983 D501004 PANELBOARDS Main lugs, 400 amp	20	10	
	D5010 ELECTRICAL SERVICE &	1983 D501004 PANELBOARDS Switchgear - 800 Amp	20	26	
	D5020 LIGHTING & BRANCH WIRING	1958 D502001 BRANCH WIRING General	62	0	
	D5020 LIGHTING & BRANCH WIRING	1958 D502002 LIGHTING EQUIPMENT Exit Lighting	37	6	
	D5020 LIGHTING & BRANCH WIRING	1958 D502002 LIGHTING EQUIPMENT General	37	6	
	D5020 LIGHTING & BRANCH WIRING	1983 D502001 BRANCH WIRING General	37	23	
	D5020 LIGHTING & BRANCH WIRING	1983 D502002 LIGHTING EQUIPMENT Exit Lighting	37	6	
	D5020 LIGHTING & BRANCH WIRING	1983 D502002 LIGHTING EQUIPMENT General	37	6	
	D5030 COMMUNICATIONS &	1958 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	37	10	
	D5030 COMMUNICATIONS &	1958 D503003 INTERCOMMUNICATIONS SYSTEMS 100 stations	22	6	
	D5030 COMMUNICATIONS &	1958 D503007 CLOCK & PROGRAM SYSTEMS General	37	10	
	D5030 COMMUNICATIONS &	1983 D503002 PUBLIC ADDRESS SYSTEMS 30 outlets	22	8	

Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D5030 COMMUNICATIONS & SECURITY	1983 D503003 INTERCOMMUNICATIONS SYSTEMS 25 stations	22	6	
	D5090 OTHER ELECTRICAL	1958 D509002 EMERGENCY LIGHTING & POWER General	37	6	
	D5090 OTHER ELECTRICAL	1958 D509003 GROUNDING SYSTEMS General	22	28	
	D5090 OTHER ELECTRICAL	1958 D509006 ENERGY MANAGEMENT CONTROL SYSTEM General	20	10	
	D5090 OTHER ELECTRICAL	1983 D509002 EMERGENCY LIGHTING & POWER General	20	10	
	D5090 OTHER ELECTRICAL	1983 D509006 ENERGY MANAGEMENT CONTROL SYSTEM General	37	10	
E10 EQUIPMENT	E1090 OTHER EQUIPMENT	*CONVECTION OVEN DOUBLE A E109002 FOOD SERVICE EQUIPMENT	15	13	
	E1090 OTHER EQUIPMENT	*CONVECTION OVEN DOUBLE B E109002 FOOD SERVICE EQUIPMENT	15	13	
	E1090 OTHER EQUIPMENT	*CONVECTION OVEN SINGLE A E109002 FOOD SERVICE EQUIPMENT	15	13	
	E1090 OTHER EQUIPMENT	*CONVECTION OVEN SINGLE B E109002 FOOD SERVICE EQUIPMENT	15	13	
	E1090 OTHER EQUIPMENT	*DEEP FRYER E109002 FOOD SERVICE EQUIPMENT General	15	13	
	E1090 OTHER EQUIPMENT	*DISH MACHINE E109002 FOOD SERVICE EQUIPMENT General	15	13	
	E1090 OTHER EQUIPMENT	*FIRE SUPPRESSION SYSTEM E109002 FOOD SERVICE EQUIPMENT	15	13	
	E1090 OTHER EQUIPMENT	*FREEZER REACH IN 1 DR E109002 FOOD SERVICE EQUIPMENT General	15	13	
	E1090 OTHER EQUIPMENT	*MIXER FLOOR MOUNTED E109002 FOOD SERVICE EQUIPMENT General	15	13	
	E1090 OTHER EQUIPMENT	*RANGE 12 INCH ELECTRIC E109002 FOOD SERVICE EQUIPMENT General	15	13	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2 DR A E109002 FOOD SERVICE EQUIPMENT	15	13	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2 DR B E109002 FOOD SERVICE EQUIPMENT	15	13	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 6 DR E109002 FOOD SERVICE EQUIPMENT	15	13	
	E1090 OTHER EQUIPMENT	*SERVING LINE COOLER E109002 FOOD SERVICE EQUIPMENT General	15	13	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN A E109002 FOOD SERVICE EQUIPMENT	15	13	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN B E109002 FOOD SERVICE EQUIPMENT	15	13	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN C E109002 FOOD SERVICE EQUIPMENT	15	13	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN D E109002 FOOD SERVICE EQUIPMENT	15	13	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN E E109002 FOOD SERVICE EQUIPMENT	15	13	

Appendix G

Direct Condition Rating Inspection By Section Report

"identification only"



Direct Condition Rating Inspection Report by Section



Camp Ederle

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

Section Description	System	Component	Quantity (UM)
1958 B201001 EXTERIOR CLOSURE E.I.F.S.	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	9,280 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G Paint Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 B201001 EXTERIOR CLOSURE Stone Veneer w/CMU	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	538 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments: The stone facing and trim have cracked and dislodged.	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 B201006 BALCONY WALLS & HANDRAILS Handrailing	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	60 (LF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 B201007 EXTERIOR SOFFITS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	874 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+ Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1,500 (LF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 B202001 WINDOWS Aluminum Windows	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	74 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 B203001 SOLID DOORS Aluminum	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	2 (EA)



Direct Condition Rating Inspection Report by Section



Camp Ederle

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 B203090 OTHER EXTERIOR SPECIALTY DOORS	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	8 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments: The egress doors are beginning to show their age and are mildly deteriorated with surface damage, to include damage to the integral blinds.	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	B30 ROOFING	B3010 ROOF COVERINGS	5,268 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 B301003 ROOF INSULATION & FILL General	B30 ROOFING	B3010 ROOF COVERINGS	5,688 (SF)
Last Inspection Date: 01-Jan-1958 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1958 B301004 FLASHINGS & TRIM Flashings - Base	B30 ROOFING	B3010 ROOF COVERINGS	30 (LF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 B301004 FLASHINGS & TRIM Flashings - Cap	B30 ROOFING	B3010 ROOF COVERINGS	80 (LF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 B301004 FLASHINGS & TRIM Flashings - Embedded	B30 ROOFING	B3010 ROOF COVERINGS	550 (LF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED]	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Camp Ederle

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

Section Description	System	Component	Quantity (UM)
Inspection Comments:			
1958 B301005 GUTTERS & DOWNSPOUTS Downspouts	B30 ROOFING	B3010 ROOF COVERINGS	270 (LF)
Last Inspection Date: 13-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1958 B301005 GUTTERS & DOWNSPOUTS Gutters	B30 ROOFING	B3010 ROOF COVERINGS	530 (LF)
Last Inspection Date: 13-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1958 B301006 ROOF OPENINGS AND SUPPORTS Gravity	B30 ROOFING	B3010 ROOF COVERINGS	1 (EA)
Last Inspection Date: 13-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1958 B301006 ROOF OPENINGS AND SUPPORTS Gravity	B30 ROOFING	B3010 ROOF COVERINGS	20 (EA)
Last Inspection Date: 13-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1958 B301090 OTHER ROOFING Walkway Protection	B30 ROOFING	B3010 ROOF COVERINGS	32 (SF)
Last Inspection Date: 13-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1958 C101001 FIXED PARTITIONS Wall - Plaster w/Stud	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	25,000 (SF)
Last Inspection Date: 13-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]	Paint Rating: A+		
Inspection Comments:			
1958 C101005 INTERIOR WINDOWS Interior Windows	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	39 (EA)



Direct Condition Rating Inspection Report by Section



Camp Ederle

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 13-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 C102001 STANDARD INTERIOR DOORS Wood	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 C102001 STANDARD INTERIOR DOORS Wood	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	6 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 C102002 GLAZED INTERIOR DOORS General	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	35 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	6 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 C103002 TOILET & BATH ACCESSORIES General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	17 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 C103003 MARKER BOARDS & TACK BOARDS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	23 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Camp Ederle

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

Section Description	System	Component	Quantity (UM)
1958 C103008 COUNTERS Laminated Plastic	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	30 (LF)
Last Inspection Date: 13-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 C103009 CABINETS Other	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	75 (LF)
Last Inspection Date: 13-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 C201001 INTERIOR AND EXTERIOR STAIRS Exterior	C20 STAIRS	C2010 STAIR CONSTRUCTION	2 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 C201001 INTERIOR AND EXTERIOR STAIRS Exterior	C20 STAIRS	C2010 STAIR CONSTRUCTION	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 C201001 INTERIOR AND EXTERIOR STAIRS Interior	C20 STAIRS	C2010 STAIR CONSTRUCTION	2 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 C201090 STAIR HANDRAILS, GUARDRAILS AND	C20 STAIRS	C2010 STAIR CONSTRUCTION	169 (LF)
Last Inspection Date: 13-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 C301004 TILE & TERRAZZO WALL FINISHES Tile	C30 INTERIOR FINISHES	C3010 WALL FINISHES	1,400 (SF)



Direct Condition Rating Inspection Report by Section



Camp Ederle

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 C302001 TILE FLOOR FINISHES Ceramic Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	7,000 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 C303001 ACOUSTICAL CEILING TILES & PANELS	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	7,000 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 C303005 SUSPENSION SYSTEMS General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	7,000 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 D201001 WATERCLOSETS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	11 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D201002 URINALS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	5 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D201004 SINKS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	9 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Camp Ederle

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

Section Description	System	Component	Quantity (UM)
1958 D201004 SINKS Stainless	D20 PLUMBING	D2010 PLUMBING FIXTURES	2 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D202001 PIPES & FITTINGS General	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	3,304 (LF)
Last Inspection Date: 01-Jan-1958 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1958 D203001 WASTE PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	1,652 (LF)
Last Inspection Date: 01-Jan-1958 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1958 D203002 VENT PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	402 (EA)
Last Inspection Date: 01-Jan-1958 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1958 D203003 FLOOR DRAINS General	D20 PLUMBING	D2030 SANITARY WASTE	6 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	280 (MBH)
Last Inspection Date: 01-Jan-1977 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1958 D305002 UNIT HEATERS Hydronic - 300 MBH	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	58 (EA)



Direct Condition Rating Inspection Report by Section



Camp Ederle

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments: The hydronic heaters are heavily deteriorated. Condition Rating: R Used Sampling? No Inspection Source: Inspection			
1958 D401001 FIRE ALARM DISTRIBUTION Other	D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SY\$	11,193 (SF)
Last Inspection Date: 01-Jan-1996 Inspector: [REDACTED] Inspection Comments: Original Inspection Condition Rating: G+ Used Sampling? No Inspection Source: InstallDate			
1958 D501002 SERVICE ENTRANCE EQUIPMENT Electrical	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: G- Used Sampling? No Inspection Source: Inspection			
1958 D501004 PANELBOARDS Main lugs, 120/208 V, 225 amp,	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	6 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: G- Used Sampling? No Inspection Source: Inspection			
1958 D501004 PANELBOARDS Main lugs, 400 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: G- Used Sampling? No Inspection Source: Inspection			
1958 D502001 BRANCH WIRING General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	11,193 (SF)
Last Inspection Date: 01-Jan-1996 Inspector: [REDACTED] Inspection Comments: Original Inspection Condition Rating: G+ Used Sampling? No Inspection Source: InstallDate			
1958 D502002 LIGHTING EQUIPMENT Exit Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	10 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments: Condition Rating: G- Used Sampling? No Inspection Source: Inspection			



Direct Condition Rating Inspection Report by Section



Camp Ederle

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

Section Description	System	Component	Quantity (UM)
1958 D502002 LIGHTING EQUIPMENT General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	11,193 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D503002 PUBLIC ADDRESS SYSTEMS 30 outlets	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D509002 EMERGENCY LIGHTING & POWER General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	11,193 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D509003 GROUNDING SYSTEMS General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	1 (EA)
Last Inspection Date: 01-Jan-1958 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1958 A B301002 LOW SLOPE ROOF SYSTEMS Modified	B30 ROOFING	B3010 ROOF COVERINGS	420 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 A C101001 FIXED PARTITIONS Wall - Plaster w/Stud	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	5,800 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+ Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 A C102002 GLAZED INTERIOR DOORS General	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	12 (EA)



Direct Condition Rating Inspection Report by Section



Camp Ederle

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 A C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	6 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 A C103002 TOILET & BATH ACCESSORIES General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	12 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 A C301004 TILE & TERRAZZO WALL FINISHES Tile	C30 INTERIOR FINISHES	C3010 WALL FINISHES	500 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 A C302001 TILE FLOOR FINISHES Ceramic Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	3,000 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 A C303001 ACOUSTICAL CEILING TILES & PANELS	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	2,000 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 A C303005 SUSPENSION SYSTEMS General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	2,000 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Camp Ederle

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

Section Description	System	Component	Quantity (UM)
1958 M101 D202003 DOMESTIC WATER EQUIPMENT Storage	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)
Last Inspection Date: 13-Jan-2020	Condition Rating: G-	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1958 M101 D304003 HOT WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 13-Jan-2020	Condition Rating: A	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1958 M101 D304003 HOT WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 13-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1958 ROOFTOP D305006 PACKAGE UNITS A/C Unit, Split	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	4 (EA)
Last Inspection Date: 13-Jan-2020	Condition Rating: G-	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1958 ROOFTOP A D305006 PACKAGE UNITS A/C Unit, Split	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1 (EA)
Last Inspection Date: 13-Jan-2020	Condition Rating: A	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1958 ROOFTOP B D305006 PACKAGE UNITS A/C Unit, Split	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	2 (EA)
Last Inspection Date: 13-Jan-2020	Condition Rating: G-	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1958 ROOFTOP C D305006 PACKAGE UNITS A/C Unit, Split	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	2 (EA)



Camp Ederle

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

Section Description	System	Component	Quantity (UM)
---------------------	--------	-----------	---------------

Last Inspection Date: 13-Jan-2020

Condition Rating: ☐

Used Sampling? ☐

Inspector:

Inspection Comments: split units are deteriorated with some fading of the outer casing due to exposure and surface damage.

"identification only"



Direct Condition Rating Inspection Report by Section



Camp Ederle

358 - DoDEA Europe South DSO Bldg 358

DoDEA Europe South DSO (HE5468)

Section Description	System	Component	Quantity (UM)
1995 B201001 EXTERIOR CLOSURE E.I.F.S.	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1,200 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
1995 B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	140 (LF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1995 B202001 WINDOWS Aluminum Windows	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	6 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1995 B203090 OTHER EXTERIOR SPECIALTY DOORS	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	2 (EA)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1995 B301001 STEEP SLOPE ROOF SYSTEMS Preformed	B30 ROOFING	B3010 ROOF COVERINGS	840 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1995 B301003 ROOF INSULATION & FILL General	B30 ROOFING	B3010 ROOF COVERINGS	840 (SF)
Last Inspection Date: 01-Jan-1995 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1995 B301004 FLASHINGS & TRIM Flashings - Cap	B30 ROOFING	B3010 ROOF COVERINGS	36 (LF)



Direct Condition Rating Inspection Report by Section



Camp Ederle

358 - DoDEA Europe South DSO Bldg 358

DoDEA Europe South DSO (HE5468)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1995 B301004 FLASHINGS & TRIM Flashings - Embedded	B30 ROOFING	B3010 ROOF COVERINGS	85 (LF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1995 B301005 GUTTERS & DOWNSPOUTS Downspouts	B30 ROOFING	B3010 ROOF COVERINGS	30 (LF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1995 B301005 GUTTERS & DOWNSPOUTS Gutters	B30 ROOFING	B3010 ROOF COVERINGS	85 (LF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1995 C101001 FIXED PARTITIONS Wall - Drywall w/Stud	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	1,000 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G- Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
1995 C302001 TILE FLOOR FINISHES Ceramic Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	808 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1995 C303001 ACOUSTICAL CEILING TILES & PANELS	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	808 (SF)
Last Inspection Date: 13-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Camp Ederle

358 - DoDEA Europe South DSO Bldg 358

DoDEA Europe South DSO (HE5468)

Section Description	System	Component	Quantity (UM)
1995 C303005 SUSPENSION SYSTEMS General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	808 (SF)
Last Inspection Date: 13-Jan-2020	Condition Rating: A+	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1995 D305006 PACKAGE UNITS A/C Unit, Split Systems	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	2 (EA)
Last Inspection Date: 13-Jan-2020	Condition Rating: A	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1995 D401001 FIRE ALARM DISTRIBUTION Other	D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYS	835 (SF)
Last Inspection Date: 01-Jan-1995	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
Inspector: [REDACTED]			
Inspection Comments: Original Inspection			
1995 D501004 PANELBOARDS Main lugs, 125 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	1 (EA)
Last Inspection Date: 13-Jan-2020	Condition Rating: G-	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1995 D502001 BRANCH WIRING General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	835 (SF)
Last Inspection Date: 01-Jan-1995	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
Inspector: [REDACTED]			
Inspection Comments: Original Inspection			
1995 D502002 LIGHTING EQUIPMENT General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	835 (SF)
Last Inspection Date: 13-Jan-2020	Condition Rating: G-	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1995 D509002 EMERGENCY LIGHTING & POWER General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	835 (SF)



Camp Ederle

358 - DoDEA Europe South DSO Bldg 358	DoDEA Europe South DSO (HE5468)
---------------------------------------	---------------------------------

Section Description	System	Component	Quantity (UM)
---------------------	--------	-----------	---------------

Last Inspection Date: 13-Jan-2020
 Inspector: [REDACTED]
 Inspection Comments:

Condition Rating: G-

Used Sampling? No
 Inspection Source: Inspection

1995 D509003 GROUNDING SYSTEMS General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	1 (EA)
--	----------------	---------------------------------	--------

Last Inspection Date: 01-Jan-1995
 Inspector:
 Inspection Comments: Original Inspection

Condition Rating: G+

Used Sampling? No
 Inspection Source: InstallDate

"Identification only"



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
*CONVECTION OVEN DOUBLE A E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 09-Jan-2020 Condition Rating: G Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
*CONVECTION OVEN DOUBLE B E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 09-Jan-2020 Condition Rating: G Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
*CONVECTION OVEN SINGLE A E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 09-Jan-2020 Condition Rating: G Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
*CONVECTION OVEN SINGLE B E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 09-Jan-2020 Condition Rating: G Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
*DEEP FRYER E109002 FOOD SERVICE EQUIPMENT General	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 09-Jan-2020 Condition Rating: G Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
*DISH MACHINE E109002 FOOD SERVICE EQUIPMENT	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 09-Jan-2020 Condition Rating: G Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
*FIRE SUPPRESSION SYSTEM E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
*FREEZER REACH IN 1 DR E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
*MIXER FLOOR MOUNTED E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
*RANGE 12 INCH ELECTRIC E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
*REFRIGERATOR REACH IN 2 DR A E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
*REFRIGERATOR REACH IN 2 DR B E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
*REFRIGERATOR REACH IN 6 DR E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
*SERVING LINE COOLER E109002 FOOD SERVICE	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
*STEAM COUNTER ELECTRIC MULTI BASIN A E109002 FOOD	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
*STEAM COUNTER ELECTRIC MULTI BASIN B E109002 FOOD	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
*STEAM COUNTER ELECTRIC MULTI BASIN C E109002 FOOD	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
*STEAM COUNTER ELECTRIC MULTI BASIN D E109002 FOOD	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
*STEAM COUNTER ELECTRIC MULTI BASIN E E109002 FOOD	E10 EQUIPMENT	E1090 OTHER EQUIPMENT	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1958 B201001 EXTERIOR CLOSURE Brick Veneer w/CMU	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	525 (SF)



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 B201001 EXTERIOR CLOSURE CIP Concrete	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	11,200 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+ Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 B201001 EXTERIOR CLOSURE Glass Block	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	72 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 B201001 EXTERIOR CLOSURE Wall Louver	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	74 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+ Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 B201004 PARAPETS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	645 (LF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 B201007 EXTERIOR SOFFITS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	3,068 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+ Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	6,100 (LF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
1958 B202001 WINDOWS Aluminum Windows	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	259 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments: The replacement windows are generally in operable condition with acceptable exterior finishes. However, gasket seals are deteriorating and various units were observed to be inoperable or to operate with some difficulty.	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 B202002 STOREFRONTS General	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	260 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 B202003 CURTAIN WALLS General	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	319 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 B203001 SOLID DOORS Aluminum	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	8 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 B203001 SOLID DOORS Steel	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	6 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments: The steel doors have rusting present.	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 B203002 GLAZED DOORS General	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	3 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 B203090 OTHER EXTERIOR SPECIALTY DOORS	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	34 (EA)



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	B30 ROOFING	B3010 ROOF COVERINGS	91,000 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments: The roof covering is significantly deteriorated with extensive blistering and in overall poor condition. However, no leaks were reported or observed.	Condition Rating: R+	Used Sampling? No Inspection Source: Inspection	
1958 B301003 ROOF INSULATION & FILL General	B30 ROOFING	B3010 ROOF COVERINGS	91,000 (SF)
Last Inspection Date: 01-Jan-1995 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1958 B301004 FLASHINGS & TRIM Flashings - Cap	B30 ROOFING	B3010 ROOF COVERINGS	560 (LF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 B301004 FLASHINGS & TRIM Flashings - Embedded	B30 ROOFING	B3010 ROOF COVERINGS	2,428 (LF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 B301004 FLASHINGS & TRIM General	B30 ROOFING	B3010 ROOF COVERINGS	763 (LF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 B301005 GUTTERS & DOWNSPOUTS Downspouts	B30 ROOFING	B3010 ROOF COVERINGS	970 (LF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED]	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
Inspection Comments:			
1958 B301005 GUTTERS & DOWNSPOUTS Gutters	B30 ROOFING	B3010 ROOF COVERINGS	2,292 (LF)
Last Inspection Date: 09-Jan-2020	Condition Rating: A+	Used Sampling? No	
Inspector: [REDACTED]		Inspection Source: Inspection	
Inspection Comments:			
1958 B301006 ROOF OPENINGS AND SUPPORTS Gravity	B30 ROOFING	B3010 ROOF COVERINGS	12 (EA)
Last Inspection Date: 09-Jan-2020	Condition Rating: A+	Used Sampling? No	
Inspector: [REDACTED]		Inspection Source: Inspection	
Inspection Comments:			
1958 B301006 ROOF OPENINGS AND SUPPORTS Gravity	B30 ROOFING	B3010 ROOF COVERINGS	49 (EA)
Last Inspection Date: 09-Jan-2020	Condition Rating: A+	Used Sampling? No	
Inspector: [REDACTED]		Inspection Source: Inspection	
Inspection Comments:			
1958 B301006 ROOF OPENINGS AND SUPPORTS Skylights	B30 ROOFING	B3010 ROOF COVERINGS	130 (SF)
Last Inspection Date: 09-Jan-2020	Condition Rating: A+	Used Sampling? No	
Inspector: [REDACTED]		Inspection Source: Inspection	
Inspection Comments:			
1958 C101001 FIXED PARTITIONS Wall - Plaster w/Stud	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	140,000 (SF)
Last Inspection Date: 09-Jan-2020	Condition Rating: A+	Used Sampling? No	
Inspector: [REDACTED]	Paint Rating: A	Inspection Source: Inspection	
Inspection Comments:			
1958 C102001 STANDARD INTERIOR DOORS Wood	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	67 (EA)
Last Inspection Date: 09-Jan-2020	Condition Rating: A	Used Sampling? No	
Inspector: [REDACTED]		Inspection Source: Inspection	
Inspection Comments:			
1958 C102006 INTERIOR GATES General	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	2 (EA)



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 C103003 MARKER BOARDS & TACK BOARDS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	150 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 C103005 LOCKERS General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	530 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 C201001 INTERIOR AND EXTERIOR STAIRS Exterior	C20 STAIRS	C2010 STAIR CONSTRUCTION	6 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 C201001 INTERIOR AND EXTERIOR STAIRS Interior	C20 STAIRS	C2010 STAIR CONSTRUCTION	17 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 C201001 INTERIOR AND EXTERIOR STAIRS Interior	C20 STAIRS	C2010 STAIR CONSTRUCTION	13 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 C201090 STAIR HANDRAILS, GUARDRAILS AND	C20 STAIRS	C2010 STAIR CONSTRUCTION	770 (LF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
1958 C302003 WOOD FLOORING General	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	6,200 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 C302004 RESILIENT FLOOR FINISHES Composition	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	8,100 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 C302005 CARPETING Carpet Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	700 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 C303003 PLASTER CEILING FINISHES General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	600 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A+ Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 C303090 OTHER CEILING & CEILING FINISHES Other	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	2,800 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 D201001 WATERCLOSETS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	59 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 D201002 URINALS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	24 (EA)



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D201004 SINKS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	46 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D201004 SINKS Kitchen Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	8 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D201004 SINKS Laboratory Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	25 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D201090 OTHER PLUMBING FIXTURES Emergency Eye	D20 PLUMBING	D2010 PLUMBING FIXTURES	2 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D201090 OTHER PLUMBING FIXTURES Emergency	D20 PLUMBING	D2010 PLUMBING FIXTURES	2 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D202001 PIPES & FITTINGS General	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	27,083 (LF)
Last Inspection Date: 01-Jan-1958 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
1958 D202003 DOMESTIC WATER EQUIPMENT Water Heaters,	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	2 (EA)
Last Inspection Date: 09-Jan-2020	Condition Rating: A	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1958 D203001 WASTE PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	13,540 (LF)
Last Inspection Date: 01-Jan-1958	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
Inspector:			
Inspection Comments: Original Inspection			
1958 D203002 VENT PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	3,293 (EA)
Last Inspection Date: 01-Jan-1958	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
Inspector:			
Inspection Comments: Original Inspection			
1958 D203003 FLOOR DRAINS General	D20 PLUMBING	D2030 SANITARY WASTE	46 (EA)
Last Inspection Date: 09-Jan-2020	Condition Rating: G-	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1958 D302001 BOILERS Gas/Oil, Hot Water - 3,500-4,250 MBH	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 09-Jan-2020	Condition Rating: G-	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1958 D302004 AUXILIARY EQUIPMENT Expansion Tank - 15	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	2 (EA)
Last Inspection Date: 09-Jan-2020	Condition Rating: G-	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1958 D304001 AIR DISTRIBUTION, HEATING & COOLING	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	17,043 (LF)



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 01-Jan-1958 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? Inspection Source:	No InstallDate
1958 D304003 HOT WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	6 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G-	Used Sampling? Inspection Source:	No Inspection
1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2,287 (MBH)
Last Inspection Date: 01-Jan-1958 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? Inspection Source:	No InstallDate
1958 D304003 HOT WATER DISTRIBUTION SYSTEMS Heat	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G-	Used Sampling? Inspection Source:	No Inspection
1958 D304006 CHILLED WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	229 (TON)
Last Inspection Date: 01-Jan-2010 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? Inspection Source:	No InstallDate
1958 D304007 EXHAUST SYSTEMS Fume Hood Exhaust	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G-	Used Sampling? Inspection Source:	No Inspection
1958 D304008 AIR HANDLING UNITS Central Station - 10000	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G-	Used Sampling? Inspection Source:	No Inspection



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
1958 D305001 UNIT VENTILATORS Air Curtain	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	10 (LF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D305002 UNIT HEATERS Hydronic - 150 MBH	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	9 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	104 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D305006 PACKAGE UNITS Packaged A/C, Air Cooled,	D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	3 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D401001 FIRE ALARM DISTRIBUTION Other	D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYSE	91,475 (SF)
Last Inspection Date: 01-Jan-1983 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1958 D403001 STANDPIPE EQUIPMENT & PIPING Riser - 4"	D40 FIRE PROTECTION	D4030 STANDPIPE SYSTEMS	9 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D409004 HOOD & DUCT FIRE PROTECTION General	D40 FIRE PROTECTION	D4090 OTHER FIRE PROTECTION SYSTEI	2 (EA)



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D501004 PANELBOARDS Main lugs, 120/208 V, 225 amp,	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	13 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 D501004 PANELBOARDS Main lugs, 400 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	3 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D501004 PANELBOARDS Switchgear - 800 Amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	5 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D501005 ENCLOSED CIRCUIT BREAKERS Main circuit	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	4 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D502001 BRANCH WIRING General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	91,475 (SF)
Last Inspection Date: 01-Jan-1958 Inspector: [REDACTED] Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1958 D502002 LIGHTING EQUIPMENT Exit Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	42 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
1958 D502002 LIGHTING EQUIPMENT General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	91,475 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D503003 INTERCOMMUNICATIONS SYSTEMS 100	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 D503007 CLOCK & PROGRAM SYSTEMS General	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 D509002 EMERGENCY LIGHTING & POWER General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	91,475 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 D509003 GROUNDING SYSTEMS General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	1 (EA)
Last Inspection Date: 01-Jan-1998 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1958 D509006 ENERGY MANAGEMENT CONTROL SYSTEM	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	91,475 (SF)



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1958 A B201006 BALCONY WALLS & HANDRAILS Handrailing	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	40 (LF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+ Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 A C101005 INTERIOR WINDOWS Interior Windows	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	100 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 A C102002 GLAZED INTERIOR DOORS General	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	48 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 A C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	50 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 A C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	17 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 A C103002 TOILET & BATH ACCESSORIES General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	160 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
1958 A C103008 COUNTERS Laminated Plastic	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	780 (LF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 A C103009 CABINETS Other	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	500 (LF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 A C301004 TILE & TERRAZZO WALL FINISHES Tile	C30 INTERIOR FINISHES	C3010 WALL FINISHES	10,000 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 A C302001 TILE FLOOR FINISHES Ceramic Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	64,000 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1958 A C303001 ACOUSTICAL CEILING TILES & PANELS	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	75,000 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 A C303005 SUSPENSION SYSTEMS General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	75,000 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 A D303001 CHILLED WATER SYSTEMS Chiller,	D30 HVAC	D3030 COOLING GENERATING SYSTEMS	1 (EA)



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 09-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? Inspection Source:	No Inspection
1958 B C101005 INTERIOR WINDOWS Interior Windows	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	16 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection
1958 B C102002 GLAZED INTERIOR DOORS General	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	16 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection
1958 B C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	7 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection
1958 B C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	4 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection
1958 B C103002 TOILET & BATH ACCESSORIES General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	20 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection
1958 B C103008 COUNTERS Stone	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	15 (LF)
Last Inspection Date: 09-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
1958 B C103009 CABINETS Other	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	30 (LF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection
1958 B C301004 TILE & TERRAZZO WALL FINISHES Tile	C30 INTERIOR FINISHES	C3010 WALL FINISHES	1,000 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection
1958 B C302001 TILE FLOOR FINISHES Ceramic Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	5,500 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? Inspection Source:	No Inspection
1958 B C303001 ACOUSTICAL CEILING TILES & PANELS	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	5,500 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? Inspection Source:	No Inspection
1958 B C303005 SUSPENSION SYSTEMS General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	5,500 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? Inspection Source:	No Inspection
1958 B D303001 CHILLED WATER SYSTEMS Chiller,	D30 HVAC	D3030 COOLING GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? Inspection Source:	No Inspection
1958 M201 D202003 DOMESTIC WATER EQUIPMENT Storage	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	1 (EA)



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 09-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1958 M201 D202003 DOMESTIC WATER EQUIPMENT Storage	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	2 (EA)
Last Inspection Date: 09-Jan- XXXX Inspector: XXXXXX Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1983 B201001 EXTERIOR CLOSURE E.I.F.S.	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	50,665 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+ Paint Rating: A	Used Sampling? No Inspection Source: Inspection	
1983 B201001 EXTERIOR CLOSURE Metal Panel	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	480 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1983 B201001 EXTERIOR CLOSURE Stone	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1,700 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1983 B201005 EXTERIOR LOUVERS & SCREENS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	12 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1983 B201006 BALCONY WALLS & HANDRAILS Handrailing	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	138 (LF)
Last Inspection Date: 09-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G- Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
1983 B201006 BALCONY WALLS & HANDRAILS Ladder	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	10 (LF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1983 B201007 EXTERIOR SOFFITS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1,188 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+ Paint Rating: A+	Used Sampling? No Inspection Source: Inspection	
1983 B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	69 (LF)
Last Inspection Date: [REDACTED] Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1983 B202001 WINDOWS Aluminum Windows	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	33 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1983 B301002 LOW SLOPE ROOF SYSTEMS Built-Up	B30 ROOFING	B3010 ROOF COVERINGS	7,200 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1983 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	B30 ROOFING	B3010 ROOF COVERINGS	1,925 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1983 B301003 ROOF INSULATION & FILL General	B30 ROOFING	B3010 ROOF COVERINGS	9,125 (SF)



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 01-Jan-2006 Inspector: Inspection Comments: Original Inspection Condition Rating: G+ Used Sampling? No Inspection Source: InstallDate			
1983 B301004 FLASHINGS & TRIM Flashings - Cap	B30 ROOFING	B3010 ROOF COVERINGS	580 (LF)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments: Condition Rating: A+ Used Sampling? No Inspection Source: Inspection			
1983 B301006 ROOF OPENINGS AND SUPPORTS Skylights	B30 ROOFING	B3010 ROOF COVERINGS	192 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments: Some units have been patched. Condition Rating: A Used Sampling? No Inspection Source: Inspection			
1983 C101001 FIXED PARTITIONS Wall - Plaster w/Stud	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	20,000 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments: Condition Rating: G- Paint Rating: A Used Sampling? No Inspection Source: Inspection			
1983 C101005 INTERIOR WINDOWS Interior Windows	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	2 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments: Condition Rating: A Used Sampling? No Inspection Source: Inspection			
1983 C102001 STANDARD INTERIOR DOORS Wood	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	14 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments: Condition Rating: A Used Sampling? No Inspection Source: Inspection			
1983 C102002 GLAZED INTERIOR DOORS General	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	23 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments: Condition Rating: A Used Sampling? No Inspection Source: Inspection			



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
1983 C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	8 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1983 C103001 COMPARTMENTS, CUBICLES & TOILET	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	3 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1983 C103002 TOILET & BATH ACCESSORIES General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	29 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1983 C201001 INTERIOR AND EXTERIOR STAIRS Exterior	C20 STAIRS	C2010 STAIR CONSTRUCTION	4 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1983 C201001 INTERIOR AND EXTERIOR STAIRS Exterior	C20 STAIRS	C2010 STAIR CONSTRUCTION	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1983 C301004 TILE & TERRAZZO WALL FINISHES Tile	C30 INTERIOR FINISHES	C3010 WALL FINISHES	2,400 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1983 C302001 TILE FLOOR FINISHES Ceramic Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	9,200 (SF)



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1983 C302004 RESILIENT FLOOR FINISHES Composition	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	2,376 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1983 C302005 CARPETING General	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	4,400 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1983 C303001 ACOUSTICAL CEILING TILES & PANELS	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	13,000 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1983 C303003 PLASTER CEILING FINISHES General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	1,300 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1983 C303005 SUSPENSION SYSTEMS General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	13,000 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1983 D201001 WATERCLOSETS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	13 (EA)
Last Inspection Date: 09-Jan- Inspector: Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
1983 D201002 URINALS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	4 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1983 D201003 LAVATORIES General	D20 PLUMBING	D2010 PLUMBING FIXTURES	18 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1983 D201004 SINKS Service Sink	D20 PLUMBING	D2010 PLUMBING FIXTURES	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1983 D202001 PIPES & FITTINGS General	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	5,944 (LF)
Last Inspection Date: 01-Jan-1983 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1983 D203001 WASTE PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	2,972 (LF)
Last Inspection Date: 01-Jan-1983 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1983 D203002 VENT PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	723 (EA)
Last Inspection Date: 01-Jan-1983 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1983 D203003 FLOOR DRAINS General	D20 PLUMBING	D2030 SANITARY WASTE	4 (EA)



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1983 D302004 AUXILIARY EQUIPMENT Expansion Tank - 15	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1983 D302004 AUXILIARY EQUIPMENT Expansion Tank - 220	D30 HVAC	D3020 HEAT GENERATING SYSTEMS	2 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1983 D304001 AIR DISTRIBUTION, HEATING & COOLING	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	3,799 (LF)
Last Inspection Date: 01-Jan-1958 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1983 D304003 HOT WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	4 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1983 D304003 HOT WATER DISTRIBUTION SYSTEMS General	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	510 (MBH)
Last Inspection Date: 01-Jan-1983 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1983 D304003 HOT WATER DISTRIBUTION SYSTEMS Heat	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1 (EA)
Last Inspection Date: 09-Jan- [REDACTED] Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
1983 D304006 CHILLED WATER DISTRIBUTION SYSTEMS	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	51 (TON)
Last Inspection Date: 01-Jan-1958	Condition Rating: G+	Used Sampling? No	Inspector: InstallDate
Inspection Comments: Original Inspection			
1983 D401001 FIRE ALARM DISTRIBUTION Other	D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYS	20,392 (SF)
Last Inspection Date: 01-Jan-1998	Condition Rating: G+	Used Sampling? No	Inspector: InstallDate
Inspection Comments: Original Inspection			
1983 D501004 PANELBOARDS Main lugs, 120/208 V, 225 amp,	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	10 (EA)
Last Inspection Date: 09-Jan-2020	Condition Rating: G-	Used Sampling? No	Inspector: Inspection
Inspection Comments:			
1983 D501004 PANELBOARDS Main lugs, 400 amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	3 (EA)
Last Inspection Date: 09-Jan-2020	Condition Rating: G-	Used Sampling? No	Inspector: Inspection
Inspection Comments:			
1983 D501004 PANELBOARDS Switchgear - 800 Amp	D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBL	3 (EA)
Last Inspection Date: 09-Jan-2020	Condition Rating: G-	Used Sampling? No	Inspector: Inspection
Inspection Comments:			
1983 D502001 BRANCH WIRING General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	20,392 (SF)
Last Inspection Date: 01-Jan-1983	Condition Rating: G+	Used Sampling? No	Inspector: InstallDate
Inspection Comments: Original Inspection			
1983 D502002 LIGHTING EQUIPMENT Exit Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	20 (EA)



Direct Condition Rating Inspection Report by Section



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1983 D502002 LIGHTING EQUIPMENT General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	20,392 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A	Used Sampling? No Inspection Source: Inspection	
1983 D503002 PUBLIC ADDRESS SYSTEMS 30 outlets	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1983 D503003 INTERCOMMUNICATIONS SYSTEMS 25 stations	D50 ELECTRICAL	D5030 COMMUNICATIONS & SECURITY	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: A+	Used Sampling? No Inspection Source: Inspection	
1983 D509002 EMERGENCY LIGHTING & POWER General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	20,392 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1983 D509006 ENERGY MANAGEMENT CONTROL SYSTEM	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	20,392 (SF)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	
1983 EL101 D101002 PASSENGER ELEVATORS Hydraulic	D10 CONVEYING	D1010 ELEVATORS AND LIFTS	1 (EA)
Last Inspection Date: 09-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G-	Used Sampling? No Inspection Source: Inspection	



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

Section Description

System

Component

Quantity (UM)

"identification only"

Appendix H

System Inventory Report

"identification only"



System Inventory Report



Camp Ederle

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1958 B201001 EXTERIOR CLOSURE E.I.F.S.	9,280 (SF)	2000	2015
	B2010 EXTERIOR WALLS	1958 B201001 EXTERIOR CLOSURE Stone Veneer w/CMU Backup	538 (SF)	2000	
	B2010 EXTERIOR WALLS	1958 B201006 BALCONY WALLS & HANDRAILS Handrailing	60 (LF)	1988	
	B2010 EXTERIOR WALLS	1958 B201007 EXTERIOR SOFFITS General	874 (SF)	2000	2015
	B2010 EXTERIOR WALLS	1958 B201010 EXTERIOR JOINT SEALANT General	1,500 (LF)	2000	
	B2020 EXTERIOR WINDOWS	1958 B202001 WINDOWS Aluminum Windows	74 (EA)	1990	
	B2030 EXTERIOR DOORS	1958 B203001 SOLID DOORS Aluminum	2 (EA)	2000	
	B2030 EXTERIOR DOORS	1958 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door	8 (EA)	2000	
B30 ROOFING	B3010 ROOF COVERINGS	1958 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	5,268 (SF)	2010	
	B3010 ROOF COVERINGS	1958 B301003 ROOF INSULATION & FILL General	5,688 (SF)	1958	
	B3010 ROOF COVERINGS	1958 B301004 FLASHINGS & TRIM Flashings - Base	30 (LF)	1996	
	B3010 ROOF COVERINGS	1958 B301004 FLASHINGS & TRIM Flashings - Cap	80 (LF)	1996	
	B3010 ROOF COVERINGS	1958 B301004 FLASHINGS & TRIM Flashings - Embedded Edge Metal	550 (LF)	1996	
	B3010 ROOF COVERINGS	1958 B301005 GUTTERS & DOWNSPOUTS Downspouts	270 (LF)	1996	
	B3010 ROOF COVERINGS	1958 B301005 GUTTERS & DOWNSPOUTS Gutters	530 (LF)	2006	
	B3010 ROOF COVERINGS	1958 B301006 ROOF OPENINGS AND SUPPORTS Gravity Ventilator - 12" x 12"	1 (EA)	2006	
	B3010 ROOF COVERINGS	1958 B301006 ROOF OPENINGS AND SUPPORTS Gravity Ventilator - 6" Diameter	20 (EA)	1958	
	B3010 ROOF COVERINGS	1958 B301090 OTHER ROOFING Walkway Protection	32 (SF)	2006	
	B3010 ROOF COVERINGS	1958 A B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	420 (SF)	1996	
C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	1958 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	25,000 (SF)	1958	2012
	C1010 PARTITIONS	1958 C101005 INTERIOR WINDOWS Interior Windows	39 (EA)	2008	
	C1010 PARTITIONS	1958 A C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	5,800 (SF)	2016	2016
	C1020 INTERIOR DOORS	1958 C102001 STANDARD INTERIOR DOORS Wood Door/Metal Frame	1 (EA)	2016	
	C1020 INTERIOR DOORS	1958 C102001 STANDARD INTERIOR DOORS Wood Door/Wood Frame	6 (EA)	2008	
	C1020 INTERIOR DOORS	1958 C102002 GLAZED INTERIOR DOORS General	35 (EA)	2008	
	C1020 INTERIOR DOORS	1958 A C102002 GLAZED INTERIOR DOORS General	12 (EA)	2016	
	C1030 SPECIALTIES	1958 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions	6 (EA)	1998	
	C1030 SPECIALTIES	1958 C103002 TOILET & BATH ACCESSORIES General	17 (EA)	2001	
	C1030 SPECIALTIES	1958 C103003 MARKER BOARDS & TACK BOARDS General	23 (EA)	2008	
	C1030 SPECIALTIES	1958 C103008 COUNTERS Laminated Plastic	30 (LF)	1988	
	C1030 SPECIALTIES	1958 C103009 CABINETS Other	75 (LF)	2008	



System Inventory Report



Camp Ederle

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	C1030 SPECIALTIES	1958 A C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions	6 (EA)	2016	
	C1030 SPECIALTIES	1958 A C103002 TOILET & BATH ACCESSORIES General	12 (EA)	2016	
C20 STAIRS	C2010 STAIR CONSTRUCTION	1958 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete (12 Riser Flight)	2 (EA)	1958	
	C2010 STAIR CONSTRUCTION	1958 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete (24 Riser Flight)	1 (EA)	1958	
	C2010 STAIR CONSTRUCTION	1958 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	2 (EA)	2008	
	C2010 STAIR CONSTRUCTION	1958 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General	169 (LF)	2000	
C30 INTERIOR FINISHES	C3010 WALL FINISHES	1958 C301004 TILE & TERRAZZO WALL FINISHES Tile	1,400 (SF)	2008	
	C3010 WALL FINISHES	1958 A C301004 TILE & TERRAZZO WALL FINISHES Tile	500 (SF)	2016	
	C3020 FLOOR FINISHES	1958 C302001 TILE FLOOR FINISHES Ceramic Tile	7,000 (SF)	2008	
	C3020 FLOOR FINISHES	1958 A C302001 TILE FLOOR FINISHES Ceramic Tile	3,000 (SF)	2016	
	C3030 CEILING FINISHES	1958 C303001 ACOUSTICAL CEILING TILES & PANELS General	7,000 (SF)	1996	
	C3030 CEILING FINISHES	1958 C303005 SUSPENSION SYSTEMS General	7,000 (SF)	1996	
	C3030 CEILING FINISHES	1958 A C303001 ACOUSTICAL CEILING TILES & PANELS General	2,000 (SF)	2016	
	C3030 CEILING FINISHES	1958 A C303005 SUSPENSION SYSTEMS General	2,000 (SF)	2016	
D20 PLUMBING	D2010 PLUMBING FIXTURES	1958 D201001 WATERCLOSETS General	11 (EA)	1998	
	D2010 PLUMBING FIXTURES	1958 D201002 URINALS General	5 (EA)	1998	
	D2010 PLUMBING FIXTURES	1958 D201004 SINKS General	9 (EA)	1998	
	D2010 PLUMBING FIXTURES	1958 D201004 SINKS Stainless	2 (EA)	1998	
	D2020 DOMESTIC WATER DISTRIBUTION	1958 D202001 PIPES & FITTINGS General	3,304 (LF)	1958	
	D2020 DOMESTIC WATER DISTRIBUTION	1958 M101 D202003 DOMESTIC WATER EQUIPMENT Storage Tank - Galvanized steel, 400 gallon, 36" diameter, 100" L x 36" W	1 (EA)	2000	
	D2030 SANITARY WASTE	1958 D203001 WASTE PIPE & FITTINGS General	1,652 (LF)	1958	
	D2030 SANITARY WASTE	1958 D203002 VENT PIPE & FITTINGS General	402 (EA)	1958	
	D2030 SANITARY WASTE	1958 D203003 FLOOR DRAINS General	6 (EA)	1958	
D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General	280 (MBH)	1977	
	D3040 DISTRIBUTION SYSTEMS	1958 M101 D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 3" size, 5 HP, to 225 GPM	1 (EA)	2000	
	D3040 DISTRIBUTION SYSTEMS	1958 M101 D304003 HOT WATER DISTRIBUTION SYSTEMS Heat Exchanger, Shell & Tube - 600 GPM	1 (EA)	2010	
	D3050 TERMINAL & PACKAGE UNITS	1958 D305002 UNIT HEATERS Hydronic - 300 MBH	58 (EA)	1980	
	D3050 TERMINAL & PACKAGE UNITS	1958 ROOFTOP D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled Condenser - 5 TN	4 (EA)	2015	



System Inventory Report



Camp Ederle

307 - DoDEA Europe South DSO Bldg 307

DoDEA Europe South DSO (HE5468)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D3050 TERMINAL & PACKAGE UNITS	1958 ROOFTOP A D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled Condenser - 2 TN	1 (EA)	2009	
	D3050 TERMINAL & PACKAGE UNITS	1958 ROOFTOP B D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled Condenser - 2 TN	2 (EA)	2016	
	D3050 TERMINAL & PACKAGE UNITS	1958 ROOFTOP C D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled Condenser - 2 TN	2 (EA)	2005	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYSTEMS	1958 D401001 FIRE ALARM DISTRIBUTION Other	11,193 (SF)	1996	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1958 D501002 SERVICE ENTRANCE EQUIPMENT Electrical Service, 3 Phase, 120/208 V, 1200 A	1 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1958 D501004 PANELBOARDS Main lugs, 120/208 V, 225 amp, NQ, 0D	6 (EA)	1996	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1958 D501004 PANELBOARDS Main lugs, 400 amp	1 (EA)	2015	
	D5020 LIGHTING & BRANCH WIRING	1958 D502001 BRANCH WIRING General	11,193 (SF)	1996	
	D5020 LIGHTING & BRANCH WIRING	1958 D502002 LIGHTING EQUIPMENT Exit Lighting	10 (EA)	1980	
	D5020 LIGHTING & BRANCH WIRING	1958 D502002 LIGHTING EQUIPMENT General	11,193 (SF)	2015	
	D5030 COMMUNICATIONS & SECURITY	1958 D503002 PUBLIC ADDRESS SYSTEMS 30 outlets	1 (EA)	2015	
	D5090 OTHER ELECTRICAL SERVICES	1958 D509002 EMERGENCY LIGHTING & POWER General	11,193 (SF)	2015	
	D5090 OTHER ELECTRICAL SERVICES	1958 D509003 GROUNDING SYSTEMS General	1 (EA)	1958	



System Inventory Report



Camp Ederle

358 - DoDEA Europe South DSO Bldg 358

DoDEA Europe South DSO (HE5468)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1995 B201001 EXTERIOR CLOSURE E.I.F.S.	1,200 (SF)	1995	1995
	B2010 EXTERIOR WALLS	1995 B201010 EXTERIOR JOINT SEALANT General	140 (LF)	1999	
	B2020 EXTERIOR WINDOWS	1995 B202001 WINDOWS Aluminum Windows	6 (EA)	1995	
	B2030 EXTERIOR DOORS	1995 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door	2 (EA)	1995	
B30 ROOFING	B3010 ROOF COVERINGS	1995 B301001 STEEP SLOPE ROOF SYSTEMS Preformed Metal - Metal Panel	840 (SF)	1995	
	B3010 ROOF COVERINGS	1995 B301003 ROOF INSULATION & FILL General	840 (SF)	1995	
	B3010 ROOF COVERINGS	1995 B301004 FLASHINGS & TRIM Flashings - Cap	36 (LF)	1995	
	B3010 ROOF COVERINGS	1995 B301004 FLASHINGS & TRIM Flashings - Embedded Edge Metal	85 (LF)	1995	
	B3010 ROOF COVERINGS	1995 B301005 GUTTERS & DOWNSPOUTS Downspouts	30 (LF)	1995	
	B3010 ROOF COVERINGS	1995 B301005 GUTTERS & DOWNSPOUTS Gutters	85 (LF)	1995	
C10 INTERIOR	C1010 PARTITIONS	1995 C101001 FIXED PARTITIONS Wall - Drywall w/Stud Framing	1,000 (SF)	1995	2016
C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	1995 C302001 TILE FLOOR FINISHES Ceramic Tile	808 (SF)	1995	
	C3030 CEILING FINISHES	1995 C303001 ACOUSTICAL CEILING TILES & PANELS General	808 (SF)	1995	
	C3030 CEILING FINISHES	1995 C303005 SUSPENSION SYSTEMS General	808 (SF)	1995	
D30 HVAC	D3050 TERMINAL & PACKAGE UNITS	1995 D305006 PACKAGE UNIT Split Unit, Split Systems w/ Air Cooled Condenser - 2 TN	2 (EA)	2010	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYSTEMS	1995 D401001 FIRE ALARM DISTRIBUTION Other	835 (SF)	1995	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1995 D501004 PANELBOARDS Main lugs, 125 amp	1 (EA)	1995	
	D5020 LIGHTING & BRANCH WIRING	1995 D502001 BRANCH WIRING General	835 (SF)	1995	
	D5020 LIGHTING & BRANCH WIRING	1995 D502002 LIGHTING EQUIPMENT General	835 (SF)	1995	
	D5090 OTHER ELECTRICAL SERVICES	1995 D509002 EMERGENCY LIGHTING & POWER General	835 (SF)	1995	
	D5090 OTHER ELECTRICAL SERVICES	1995 D509003 GROUNDING SYSTEMS General	1 (EA)	1995	



System Inventory Report



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1958 B201001 EXTERIOR CLOSURE Brick Veneer w/CMU Backup	525 (SF)	1958	
	B2010 EXTERIOR WALLS	1958 B201001 EXTERIOR CLOSURE CIP Concrete	11,200 (SF)	1958	2014
	B2010 EXTERIOR WALLS	1958 B201001 EXTERIOR CLOSURE Glass Block	72 (SF)	1958	
	B2010 EXTERIOR WALLS	1958 B201001 EXTERIOR CLOSURE Wall Louver	74 (SF)	1980	1999
	B2010 EXTERIOR WALLS	1958 B201004 PARAPETS General	645 (LF)	1995	
	B2010 EXTERIOR WALLS	1958 B201007 EXTERIOR SOFFITS General	3,068 (SF)	1980	2007
	B2010 EXTERIOR WALLS	1958 B201010 EXTERIOR JOINT SEALANT General	6,100 (LF)	1994	
	B2010 EXTERIOR WALLS	1958 A B201006 BALCONY WALLS & HANDRAILS Handrailing	40 (LF)	1980	2007
	B2010 EXTERIOR WALLS	1983 B201001 EXTERIOR CLOSURE E.I.F.S.	50,665 (SF)	1983	2007
	B2010 EXTERIOR WALLS	1983 B201001 EXTERIOR CLOSURE Metal Panel	480 (SF)	1988	
	B2010 EXTERIOR WALLS	1983 B201001 EXTERIOR CLOSURE Stone	1,700 (SF)	1983	
	B2010 EXTERIOR WALLS	1983 B201005 EXTERIOR LOUVERS & SCREENS General	12 (SF)	1983	
	B2010 EXTERIOR WALLS	1983 B201006 BALCONY WALLS & HANDRAILS Handrailing	138 (LF)	1983	2007
	B2010 EXTERIOR WALLS	1983 B201006 BALCONY WALLS & HANDRAILS Ladder	10 (LF)	1988	
	B2010 EXTERIOR WALLS	1983 B201007 EXTERIOR SOFFITS General	1,188 (SF)	1983	2007
	B2010 EXTERIOR WALLS	1983 B201010 EXTERIOR JOINT SEALANT General	69 (LF)	1983	
	B2020 EXTERIOR WINDOWS	1958 B202001 WINDOWS Aluminum Windows	259 (EA)	1991	
	B2020 EXTERIOR WINDOWS	1958 B202002 STOREFRONTS General	260 (SF)	1994	
	B2020 EXTERIOR WINDOWS	1958 B202003 CURTAIN WALLS General	319 (SF)	1991	
	B2020 EXTERIOR WINDOWS	1983 B202001 WINDOWS Aluminum Windows	33 (EA)	1983	
	B2030 EXTERIOR DOORS	1958 B203001 SOLID DOORS Aluminum	8 (EA)	1998	
	B2030 EXTERIOR DOORS	1958 B203001 SOLID DOORS Steel	6 (EA)	1998	
	B2030 EXTERIOR DOORS	1958 B203002 GLAZED DOORS General	3 (EA)	1994	
	B2030 EXTERIOR DOORS	1958 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door	34 (EA)	1998	
B30 ROOFING	B3010 ROOF COVERINGS	1958 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	91,000 (SF)	1995	
	B3010 ROOF COVERINGS	1958 B301003 ROOF INSULATION & FILL General	91,000 (SF)	1995	
	B3010 ROOF COVERINGS	1958 B301004 FLASHINGS & TRIM Flashings - Cap	560 (LF)	1995	
	B3010 ROOF COVERINGS	1958 B301004 FLASHINGS & TRIM Flashings - Embedded Edge Metal	2,428 (LF)	1995	
	B3010 ROOF COVERINGS	1958 B301004 FLASHINGS & TRIM General	763 (LF)	1995	
	B3010 ROOF COVERINGS	1958 B301005 GUTTERS & DOWNSPOUTS Downspouts	970 (LF)	1995	
	B3010 ROOF COVERINGS	1958 B301005 GUTTERS & DOWNSPOUTS Gutters	2,292 (LF)	1995	
	B3010 ROOF COVERINGS	1958 B301006 ROOF OPENINGS AND SUPPORTS Gravity Ventilator - 36" Diameter	12 (EA)	1995	
	B3010 ROOF COVERINGS	1958 B301006 ROOF OPENINGS AND SUPPORTS Gravity Ventilator - 6" Diameter	49 (EA)	1995	
	B3010 ROOF COVERINGS	1958 B301006 ROOF OPENINGS AND SUPPORTS Skylights	130 (SF)	1995	



System Inventory Report



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	B3010 ROOF COVERINGS	1983 B301002 LOW SLOPE ROOF SYSTEMS Built-Up	7,200 (SF)	2006	
	B3010 ROOF COVERINGS	1983 B301002 LOW SLOPE ROOF SYSTEMS Modified Bitumen	1,925 (SF)	2006	
	B3010 ROOF COVERINGS	1983 B301003 ROOF INSULATION & FILL General	9,125 (SF)	2006	
	B3010 ROOF COVERINGS	1983 B301004 FLASHINGS & TRIM Flashings - Cap	580 (LF)	2006	
	B3010 ROOF COVERINGS	1983 B301006 ROOF OPENINGS AND SUPPORTS Skylights	192 (SF)	1983	
C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	1958 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	140,000 (SF)	1958	2010
	C1010 PARTITIONS	1958 A C101005 INTERIOR WINDOWS Interior Windows	100 (EA)	1998	
	C1010 PARTITIONS	1958 B C101005 INTERIOR WINDOWS Interior Windows	16 (EA)	2016	
	C1010 PARTITIONS	1983 C101001 FIXED PARTITIONS Wall - Plaster w/Stud Framing	20,000 (SF)	1983	2003
	C1010 PARTITIONS	1983 C101005 INTERIOR WINDOWS Interior Windows	2 (EA)	1983	
	C1020 INTERIOR DOORS	1958 C102001 STANDARD INTERIOR DOORS Wood Door/Wood Frame	67 (EA)	2006	
	C1020 INTERIOR DOORS	1958 C102006 INTERIOR GATES General	2 (EA)	1998	
	C1020 INTERIOR DOORS	1958 A C102002 GLAZED INTERIOR DOORS General	48 (EA)	2000	
	C1020 INTERIOR DOORS	1958 B C102003 GLAZED INTERIOR DOORS General	16 (EA)	2016	
	C1020 INTERIOR DOORS	1983 C102001 STANDARD INTERIOR DOORS Wood Door/Metal Frame	14 (EA)	1986	
	C1020 INTERIOR DOORS	1983 C102002 GLAZED INTERIOR DOORS General	23 (EA)	1986	
	C1030 SPECIALTIES	1958 C103003 MARKER BOARDS & TACK BOARDS General	150 (EA)	1999	
	C1030 SPECIALTIES	1958 C103005 LOCKERS General	530 (EA)	1999	
	C1030 SPECIALTIES	1958 A C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions	50 (EA)	1998	
	C1030 SPECIALTIES	1958 A C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Urinal Screen	17 (EA)	1998	
	C1030 SPECIALTIES	1958 A C103002 TOILET & BATH ACCESSORIES General	160 (EA)	1998	
	C1030 SPECIALTIES	1958 A C103008 COUNTERS Laminated Plastic	780 (LF)	2000	
	C1030 SPECIALTIES	1958 A C103009 CABINETS Other	500 (LF)	2000	
	C1030 SPECIALTIES	1958 B C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions	7 (EA)	2016	
	C1030 SPECIALTIES	1958 B C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Urinal Screen	4 (EA)	2016	
	C1030 SPECIALTIES	1958 B C103002 TOILET & BATH ACCESSORIES General	20 (EA)	2016	
	C1030 SPECIALTIES	1958 B C103008 COUNTERS Stone	15 (LF)	2016	
	C1030 SPECIALTIES	1958 B C103009 CABINETS Other	30 (LF)	2016	
	C1030 SPECIALTIES	1983 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Toilet Partitions	8 (EA)	1983	
	C1030 SPECIALTIES	1983 C103001 COMPARTMENTS, CUBICLES & TOILET PARTITIONS Urinal Screen	3 (EA)	1998	
	C1030 SPECIALTIES	1983 C103002 TOILET & BATH ACCESSORIES General	29 (EA)	1983	



System Inventory Report



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
C20 STAIRS	C2010 STAIR CONSTRUCTION	1958 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Steps - Concrete	6 (EA)	1998	
	C2010 STAIR CONSTRUCTION	1958 C201001 INTERIOR AND EXTERIOR STAIRS Interior Stairs	17 (EA)	1958	
	C2010 STAIR CONSTRUCTION	1958 C201001 INTERIOR AND EXTERIOR STAIRS Interior Steps	13 (EA)	2006	
	C2010 STAIR CONSTRUCTION	1958 C201090 STAIR HANDRAILS, GUARDRAILS AND ACCESSORIES General	770 (LF)	2006	
	C2010 STAIR CONSTRUCTION	1983 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete (12 Riser Flight)	4 (EA)	1998	
	C2010 STAIR CONSTRUCTION	1983 C201001 INTERIOR AND EXTERIOR STAIRS Exterior Stairs - Concrete (24 Riser Flight)	1 (EA)	1958	
C30 INTERIOR FINISHES	C3010 WALL FINISHES	1958 A C301004 TILE & TERRAZZO WALL FINISHES Tile	10,000 (SF)	2003	
	C3010 WALL FINISHES	1958 B C301004 TILE & TERRAZZO WALL FINISHES Tile	1,000 (SF)	2016	
	C3010 WALL FINISHES	1983 C301004 TILE & TERRAZZO WALL FINISHES Tile	2,400 (SF)	2003	
	C3020 FLOOR FINISHES	1958 C302003 WOOD FLOORING General	6,200 (SF)	2007	
	C3020 FLOOR FINISHES	1958 C302004 RESILIENT FLOOR FINISHES Composition Sheet	8,100 (SF)	2007	
	C3020 FLOOR FINISHES	1958 C302005 CARPETING Carpet Tile	700 (SF)	2007	
	C3020 FLOOR FINISHES	1958 A C302001 TILE FLOOR FINISHES Ceramic Tile	64,000 (SF)	2007	
	C3020 FLOOR FINISHES	1958 B C302001 TILE FLOOR FINISHES Ceramic Tile	5,500 (SF)	2016	
	C3020 FLOOR FINISHES	1983 C302001 TILE FLOOR FINISHES Ceramic Tile	9,200 (SF)	1983	
	C3020 FLOOR FINISHES	1983 C302004 RESILIENT FLOOR FINISHES Composition Sheet	2,376 (SF)	1983	
	C3020 FLOOR FINISHES	1983 C302005 CARPETING General	4,400 (SF)	1983	
	C3030 CEILING FINISHES	1958 C303003 PLASTER CEILING FINISHES General	600 (SF)	1958	1958
	C3030 CEILING FINISHES	1958 C303090 OTHER CEILING & CEILING FINISHES Other	2,800 (SF)	1958	
	C3030 CEILING FINISHES	1958 A C303001 ACOUSTICAL CEILING TILES & PANELS General	75,000 (SF)	2008	
	C3030 CEILING FINISHES	1958 A C303005 SUSPENSION SYSTEMS General	75,000 (SF)	2008	
	C3030 CEILING FINISHES	1958 B C303001 ACOUSTICAL CEILING TILES & PANELS General	5,500 (SF)	2016	
	C3030 CEILING FINISHES	1958 B C303005 SUSPENSION SYSTEMS General	5,500 (SF)	2016	
	C3030 CEILING FINISHES	1983 C303001 ACOUSTICAL CEILING TILES & PANELS General	13,000 (SF)	1983	
	C3030 CEILING FINISHES	1983 C303003 PLASTER CEILING FINISHES General	1,300 (SF)	1983	
	C3030 CEILING FINISHES	1983 C303005 SUSPENSION SYSTEMS General	13,000 (SF)	1983	
D10 CONVEYING	D1010 ELEVATORS AND LIFTS	1983 EL101 D101002 PASSENGER ELEVATORS Hydraulic Elevators - 1500 lb, 2 floors	1 (EA)	1983	
D20 PLUMBING	D2010 PLUMBING FIXTURES	1958 D201001 WATERCLOSETS General	59 (EA)	1994	
	D2010 PLUMBING FIXTURES	1958 D201002 URINALS General	24 (EA)	1994	
	D2010 PLUMBING FIXTURES	1958 D201004 SINKS General	46 (EA)	1994	
	D2010 PLUMBING FIXTURES	1958 D201004 SINKS Kitchen Sink	8 (EA)	1994	



System Inventory Report



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D2010 PLUMBING FIXTURES	1958 D201004 SINKS Laboratory Sink	25 (EA)	1994	
	D2010 PLUMBING FIXTURES	1958 D201090 OTHER PLUMBING FIXTURES Emergency Eye Wash	2 (EA)	1998	
	D2010 PLUMBING FIXTURES	1958 D201090 OTHER PLUMBING FIXTURES Emergency Shower	2 (EA)	1998	
	D2010 PLUMBING FIXTURES	1983 D201001 WATERCLOSETS General	13 (EA)	1983	
	D2010 PLUMBING FIXTURES	1983 D201002 URINALS General	4 (EA)	1983	
	D2010 PLUMBING FIXTURES	1983 D201003 LAVATORIES General	18 (EA)	1983	
	D2010 PLUMBING FIXTURES	1983 D201004 SINKS Service Sink	1 (EA)	1983	
	D2020 DOMESTIC WATER DISTRIBUTION	1958 D202001 PIPES & FITTINGS General	27,083 (LF)	1958	
	D2020 DOMESTIC WATER DISTRIBUTION	1958 D202003 DOMESTIC WATER EQUIPMENT Water Heaters, Commercial, Electric - 80 gal, 36 KW, 147 GPH	2 (EA)	2000	
	D2020 DOMESTIC WATER DISTRIBUTION	1958 M201002 D202003 DOMESTIC WATER EQUIPMENT Storage Tank - Galvanized steel, 80 gallon, 20" diameter, 64" L.O.A.	1 (EA)	2000	
	D2020 DOMESTIC WATER DISTRIBUTION	1958 M201003 D202003 DOMESTIC WATER EQUIPMENT Storage Tank - Glass lined, PE, 605 gallon, 48" diameter, 87" L.O.A.	2 (EA)	2000	
	D2020 DOMESTIC WATER DISTRIBUTION	1983 D202001 PIPES & FITTINGS General	5,944 (LF)	1983	
	D2030 SANITARY WASTE	1958 D203001 WASTE PIPE & FITTINGS General	13,540 (LF)	1958	
	D2030 SANITARY WASTE	1958 D203002 VENT PIPE & FITTINGS General	3,293 (EA)	1958	
	D2030 SANITARY WASTE	1958 D203003 FLOOR DRAINING General	46 (EA)	1958	
	D2030 SANITARY WASTE	1983 D203001 WASTE PIPE & FITTINGS General	2,972 (LF)	1983	
	D2030 SANITARY WASTE	1983 D203002 VENT PIPE & FITTINGS General	723 (EA)	1983	
	D2030 SANITARY WASTE	1983 D203003 FLOOR DRAINS General	4 (EA)	1983	
D30 HVAC	D3020 HEAT GENERATING SYSTEMS	1958 D302001 BOILERS Gas/Oil, Hot Water - 3,000-4,250 MBH	1 (EA)	2001	
	D3020 HEAT GENERATING SYSTEMS	1958 D302004 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	2 (EA)	2000	
	D3020 HEAT GENERATING SYSTEMS	1983 D302004 AUXILIARY EQUIPMENT Expansion Tank - 15 gal	1 (EA)	1983	
	D3020 HEAT GENERATING SYSTEMS	1983 D302004 AUXILIARY EQUIPMENT Expansion Tank - 20 gal	2 (EA)	2015	
	D3030 COOLING GENERATING SYSTEMS	1958 A D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 40 TN	1 (EA)	2017	
	D3030 COOLING GENERATING SYSTEMS	1958 B D303001 CHILLED WATER SYSTEMS Chiller, Reciprocating, Air Cooled - 40 TN	1 (EA)	2010	
	D3040 DISTRIBUTION SYSTEMS	1958 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	17,043 (LF)	1958	
	D3040 DISTRIBUTION SYSTEMS	1958 D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 3" size, 5 HP, to 225 GPM	6 (EA)	2000	
	D3040 DISTRIBUTION SYSTEMS	1958 D304003 HOT WATER DISTRIBUTION SYSTEMS General	2,287 (MBH)	1958	
	D3040 DISTRIBUTION SYSTEMS	1958 D304003 HOT WATER DISTRIBUTION SYSTEMS Heat Exchanger, Shell & Tube - 600 GPM	2 (EA)	2001	



System Inventory Report



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D3040 DISTRIBUTION SYSTEMS	1958 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	229 (TON)	2010	
	D3040 DISTRIBUTION SYSTEMS	1958 D304007 EXHAUST SYSTEMS Fume Hood Exhaust System - 4', 2000 CFM	1 (EA)	1995	
	D3040 DISTRIBUTION SYSTEMS	1958 D304008 AIR HANDLING UNITS Central Station - 10000 CFM	1 (EA)	2010	
	D3040 DISTRIBUTION SYSTEMS	1983 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	3,799 (LF)	1958	
	D3040 DISTRIBUTION SYSTEMS	1983 D304003 HOT WATER DISTRIBUTION SYSTEMS Circulating Pump, End Suction - 4" size, 7-1/2 HP, to 350 GPM	4 (EA)	2015	
	D3040 DISTRIBUTION SYSTEMS	1983 D304003 HOT WATER DISTRIBUTION SYSTEMS General	510 (MBH)	1983	
	D3040 DISTRIBUTION SYSTEMS	1983 D304003 HOT WATER DISTRIBUTION SYSTEMS Heat Exchanger, Shell & Tube - 240 GPM	1 (EA)	2015	
	D3040 DISTRIBUTION SYSTEMS	1983 D304006 CHILLED WATER DISTRIBUTION SYSTEMS General	51 (TON)	1958	
	D3050 TERMINAL & PACKAGE UNITS	1958 D305001 UNIT VENTILATORS Air Curtain	10 (LF)	2000	
	D3050 TERMINAL & PACKAGE UNITS	1958 D305002 UNIT HEATERS Hydronic - 150 MBH	9 (EA)	2005	
	D3050 TERMINAL & PACKAGE UNITS	1958 D305006 PACKAGE UNITS A/C Unit, Split Systems w/ Air Cooled Condenser - 110	104 (EA)	2003	
	D3050 TERMINAL & PACKAGE UNITS	1958 D305006 PACKAGE UNITS Packaged A/C, Air Cooled, Elec Heat - 5 ton	3 (EA)	2013	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYSTEMS	1958 D401001 FIRE ALARM DISTRIBUTION Other	91,475 (SF)	1983	
	D4010 FIRE ALARM AND DETECTION SYSTEMS	1983 D401001 FIRE ALARM DISTRIBUTION Other	20,392 (SF)	1998	
	D4030 STANDPIPE SYSTEMS	1958 D403001 STANDPIPE EQUIPMENT & PIPING Riser - 4" diam	9 (EA)	1958	
	D4090 OTHER FIRE PROTECTION SYSTEMS	1958 D409004 HOOD & DUCT FIRE PROTECTION General	2 (EA)	2000	
D50 ELECTRICAL	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1958 D501004 PANELBOARDS Main lugs, 120/208 V, 225 amp, NQOD	13 (EA)	1983	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1958 D501004 PANELBOARDS Main lugs, 400 amp	3 (EA)	2000	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1958 D501004 PANELBOARDS Switchgear - 800 Amp	5 (EA)	2000	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1958 D501005 ENCLOSED CIRCUIT BREAKERS Main circuit breaker, 120/208 V, 225 amp, NQOD	4 (EA)	2000	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1983 D501004 PANELBOARDS Main lugs, 120/208 V, 225 amp, NQOD	10 (EA)	1983	
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1983 D501004 PANELBOARDS Main lugs, 400 amp	3 (EA)	2000	



System Inventory Report



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D5010 ELECTRICAL SERVICE & DISTRIBUTION	1983 D501004 PANELBOARDS Switchgear - 800 Amp	3 (EA)	2000	
	D5020 LIGHTING & BRANCH WIRING	1958 D502001 BRANCH WIRING General	91,475 (SF)	1958	
	D5020 LIGHTING & BRANCH WIRING	1958 D502002 LIGHTING EQUIPMENT Exit Lighting	42 (EA)	1983	
	D5020 LIGHTING & BRANCH WIRING	1958 D502002 LIGHTING EQUIPMENT General	91,475 (SF)	1983	
	D5020 LIGHTING & BRANCH WIRING	1983 D502001 BRANCH WIRING General	20,392 (SF)	1983	
	D5020 LIGHTING & BRANCH WIRING	1983 D502002 LIGHTING EQUIPMENT Exit Lighting	20 (EA)	1983	
	D5020 LIGHTING & BRANCH WIRING	1983 D502002 LIGHTING EQUIPMENT General	20,392 (SF)	1983	
	D5030 COMMUNICATIONS & SECURITY	1958 D503002 PUBLIC ADDRESS SYSTEMS 100 outlets	1 (EA)	1983	
	D5030 COMMUNICATIONS & SECURITY	1958 D503003 INTERCOMMUNICATIONS SYSTEMS 100 stations	1 (EA)	1998	
	D5030 COMMUNICATIONS & SECURITY	1958 D503007 CLOCK & PROGRAM SYSTEMS General	1 (EA)	1983	
	D5030 COMMUNICATIONS & SECURITY	1983 D503004 PUBLIC ADDRESS SYSTEMS 30 outlets	1 (EA)	1998	
	D5030 COMMUNICATIONS & SECURITY	1983 D503003 INTERCOMMUNICATIONS SYSTEMS 25 stations	1 (EA)	1998	
	D5090 OTHER ELECTRICAL SERVICES	1958 D509002 EMERGENCY LIGHTING & POWER General	91,475 (SF)	1983	
	D5090 OTHER ELECTRICAL SERVICES	1958 D509003 GROUNDING SYSTEMS General	1 (EA)	1998	
	D5090 OTHER ELECTRICAL SERVICES	1958 D509006 ENERGY MANAGEMENT CONTROL SYSTEM General	91,475 (SF)	2000	
	D5090 OTHER ELECTRICAL SERVICES	1983 D509002 EMERGENCY LIGHTING & POWER General	20,392 (SF)	2000	
	D5090 OTHER ELECTRICAL SERVICES	1983 D509006 ENERGY MANAGEMENT CONTROL SYSTEM General	20,392 (SF)	1983	
E10 EQUIPMENT	E1090 OTHER EQUIPMENT	*CONVECTION OVEN DOUBLE A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2005	
	E1090 OTHER EQUIPMENT	*CONVECTION OVEN DOUBLE B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2005	
	E1090 OTHER EQUIPMENT	*CONVECTION OVEN SINGLE A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2005	
	E1090 OTHER EQUIPMENT	*CONVECTION OVEN SINGLE B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2005	
	E1090 OTHER EQUIPMENT	*DEEP FRYER E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2005	
	E1090 OTHER EQUIPMENT	*DISH MACHINE E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2005	
	E1090 OTHER EQUIPMENT	*FIRE SUPPRESSION SYSTEM E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2005	



System Inventory Report



Camp Ederle

309 - Vicenza HS Bldg 309

Unassigned

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	E1090 OTHER EQUIPMENT	*FREEZER REACH IN 1 DR E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2005	
	E1090 OTHER EQUIPMENT	*MIXER FLOOR MOUNTED E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2005	
	E1090 OTHER EQUIPMENT	*RANGE 12 INCH ELECTRIC E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2005	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2 DR A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2005	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 2 DR B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2005	
	E1090 OTHER EQUIPMENT	*REFRIGERATOR REACH IN 6 DR E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2005	
	E1090 OTHER EQUIPMENT	*SERVING LINE COOLER E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2005	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN A E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2005	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN B E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2005	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN C E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2005	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN D E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2005	
	E1090 OTHER EQUIPMENT	*STEAM COUNTER ELECTRIC MULTI BASIN E E109002 FOOD SERVICE EQUIPMENT General	1 (EA)	2005	