Steps to Writing a Good Spec

(1) Gather stakeholder requirements.

(2) Draw an upper-level system

- take care to define system inputs and outputs (interface)
- draw only function at this point

(3) Modularize your functional block diagram.

- divide the system into rational sub-functions
- remember that there is more than one way to divide a system

(4) Using (1), (2), + (3) and the Recursive Kernel write:

- Functional + Testing Requirements for:
  - + The top level system (requirements general to everything)
  - + Each module
- Interface + Testing Requirements for:
  - + External Interfaces
  - + Inter-Modular Interfaces


Steps to Writing a Good Spec cont.)

(4) cont.)

- Non-Functional + Testing requirements for each module
  + Use the recursive kernel for categories
  + Continue until the requirements are testable + unambiguous

→ Non-Functional means Functional support

Recursive Kernel - Systems are Systems of Systems



The small squares describe non-functional (functional support) requirements.

Ask the same 8 questions for each sub-system.