




VARMETRO O VARÍMETRO


$$M = \frac{dM}{2d\theta} \cdot i \cdot I \cdot \cos \beta$$

$$\beta = (90^{\circ} - \phi)$$

$$M = \frac{dM}{2d\theta}$$
. U. I. sen $\phi = K_Q$. Q [VAR]










FASORIAL





LABORATORIO DE MEDICIONES 2016©

LIC. PROF. RICARDO DEFRANCE

rdefrance@hotmail.com