WARNING: Allow unit to cool for 30 minutes before servicing.

CAUTION: Do not use abrasive cleaners on the sensor housing.