

Second-order phasor
First-order phasor (dual-order fit)
P-class limit (5 % of the step)
(a) Magnitude step of +10 %
7.3 %
(b) Phase step of +10°
7.1 %
Normalized response
Normalized response
1
0.5
0
1
0.5
0
−30
−20
−10
0
10
20
30
Time from the step (ms)