Statistical analysis to define appropriate alarm & alert boundary

PIC: Pakorn L.

Issue/Problem : Current limitation points from standard are improperly defined -- too wide. Sensor value have never reached the limit and it may


results in machine breakdown before detection.

Solution : Find normal operation range from statistical value calculated by using actual read data from sensor in PI system and use it as


alarm boundary.

Result :

Vibration sensor PVC9-VI4501A2



Current sensor PVC9-EIC4501B





Remark: data from the past 6 months

Concern : The data range is not accurate because the data is not cover all normal situation.

Improvement: Expand period of retrieving data.