US Department
of Transportation
Federal Aviation
Administration

Form Approved OMB No. 2120-0020 2/28/2011	Electronic Tracking Number
i i	For FAA Use Only

US Departmen				C KEPAIK A									For FAA Us	se Only	
of Transportation Federal Aviation Administration (Airframe, Powerplant, Prop						Jen	er, or App	nance							
instruction		ition of thi	s form.	es. See Title 14 This report is re											
	Nationalit	y and Reg	istratio	n Mark				Serial	No.						
1. Aircraft N267RH Make								1828	2208						
								Model					Series		
	Cessna	_						182T	•						
	Name (A:	s shown o	regist	ration certificate)				•		-	istration	certificate,)	
2. Owner									POB		2				
								City	Bristo					State <u>VA</u>	
	PXW S	ervices						Zip	<u>20136</u>	5-080	2	Cour	ntry USA	=	
						3. F	For FAA Use	Only							
4. Ty	/ре					5. l	Unit Identifica	ation							
Repair	Alteration	Un	it		Ма	ke				Mod	el			Serial No	
	7	AIRFRAI	ME					(As described i		ed in It	em 1 a	bove)			
		POWER	PLANT												
		PROPEL	LER												
				Туре											
		APPLIAN	NCE	Manufacturer											
				<u> </u>	6	. Co	onformity Sta	tement					· · · · · · · · · · · · · · · · · · ·		
A. Agency's	Name and A	ddress				В.	Kind of Agend	у							
Name Philip		-1.01			_	\checkmark	U. S. Certific				Manufacturer				
	Dallas Cre Collins	ek Coun		State CO	_	Н	Foreign Certi Certificated F					C. Certificate No.			
zip 8052		untry USA		_ 31816 CO	_	Н	Certificated N			ination	 on A&P 3292572 IA				
D. 1 certif	y that the rep been made in	pair and/or accordan	ce with	ion made to the the requiremen to the best of my	ts of	Part	entified in item t 43 of the U.S	1 5 above	e and de	escribe	ed on the	he rever	se or attac	hments here	to
Extended ra	nge fuel	· ···	Sign	ature/Date of Au	thori	zed	Individual	 							
per 14 CFR App. B			Ph	ilip Glas	go	W	9/5/20	12	M	bξ		\sim)		
							val for Return		jce –		, <u> </u>				
		, .		ons specified b ministration and		, th		ied in i Appro			nspecte Rejecte		ne mannei	r prescribed	by the
1 in	AA Fit. Stand	dards	Mar	nufacturer		М	aintenance Or	ganizatio	on			ns Approv	ed by Cana Transport	dian	
BY	AA Designee		Rep	air Station	✓	In	spection Auth	orization		Othe	r (Spec	cify)			
Certificate or Designation			Sign	ature/Date of Au	thori	zed	Individual			7	1/1	•			
A&P 3292	2572 IA		Ph	ilip Glas	gc	W	9/5/20	12	1	\mathcal{M}	T/L				

FAA Form 337 (10-06)

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

escription of Work Accomplished f more space is required, attach additional sheets. Identify with a		
	N267RH	9/5/2012
	Nationality and Registration	Mark Date
talled Gomolzig Flugzeug-und Maschinebau GmbF	H Muffler IAW STC SA01096W1.	
dated weight & balance records.		
EN	ND	

cityma, to estat & batink

Department of Transportation -- Hederal Abiation Administration

Supplemental Type Certificate **IMPORT**

Number SA01096WI

This wete fines as well to

Gomolzig Flugzeug-und Maschinenbau GmbH Loher Strasse 1/ Gebaude 38 D-58332 Schwelm, Germany

vertifies that the change in the type design for the following product with the binutations and conditions therefore as grees frest house a west the aircrothures requirements of Part 23 of the Federal Aviation Regulations. Luftlahn-Bundesami (LBA) originally certificated this modification under German LBA EMZ (STC) No. SA 0672. The FAA validated this modification under U.S. Supplement Type Certificate No. SA01095WI. Effective September 28, 2003, the European Aviation Safety Agency (EASA) began oversight of this modification on behalf of Luftfahn-Bundesami.

Congresol Freduct - Type Vertificate Sumber

3A13

Muke

Cessna

Halel

182S, 182T

Description of Typer Design Change: Installation of Gomolzig C182R-606550 engine exhaust system silencer. Data Required: (1) Gomolzig Flugzeug und Maschinenbau GmbH Installation Instructions, dated October 1, 200), stamped FAA Approved July 3, 2002, or later FAA approved revisions; and (2) Gomolzig Flugzeug-und Maschinenbau GmbH Pilot's Operating Handbook and FAA Approved Airplane Flight Manual Supplement dated July 3, 2002, or later FAA approved revisions.

Limitations and Conditions: Compatibility of this design change with previously approved modifications must be determined by the installer. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This STC is not to be transferred since its issuance was in accordance with 14 CFR 21.29 and is based upon a validation of the German LBA EM2 No. SA 0672.

This vertificate and the supporting data which is the basis for approval shall canain in effort until succentered, suspended verselved or a transmitten date is otherwise established by the Aderinistrator of the Federal Aciatica Aderiaistration

Late of aggleration

December 17, 2001

Tute reissurd March 20, 2007

Date of mount July 3, 2002

Fate unresided

By direction of the Administrator

Original signed by Eual Condin

(Signature)

Eual M. Condin. Jr.

Associate ACO Manager, Airframe & Services

Wichita Aircraft Certification Office


(Tille)

For Proceedings of the Constitute of general Early of the Constitutions (E.O.), or registered and excelenting Experience to Pro-

THE SEW BILLOS STAFF FROM I THE STAFF STAFF

The constant by the similaries in incidence with 12 C

			r	a.



		*

US Department
of Transportation
Federal Aviation
Administration

MAJOR REPAIR AND ALTERATION (Airframe, Powerplant, Propeller, or Appliance)

Form Approved OMB No. 2120-0020	Electronic Tracking Number
2/28/2011	
, , , , ,	For FAA Use Only

Administratio			•									
instructions		ition of this	s form. This report is red								bsequent revision thereof) for esult in a civil penalty for each	
- Jucii violat		-		_			Serial N	io.				
		1 1										
1. Aircraft Make						-	18282 Model				Series	
	Cessna						182T					
			registration certificate)					s (As sh	own on reg	istration	certificate)	
2 0								PO Box				
2. Owner			·.			î	· ·	<u>Bristow</u>			. State <u>VA</u>	
	PXW S	ervices						20136-0	0802	Cou	ntry <u>USA</u>	
•					3. F	or FAA Use	Only					
The technical data identified herein has been found to comply with the applicable airworthiness requirements and is hereby approved for use only on the above described aircraft, subject to conformity inspection by a person authorized in CFR title 14, Part 43, section 43.7. Approving Inspector: Author Date: 9/7/2012 Denver FSDO, NM-03												
4. Ty	ре				5. l	Jnit Identifica	ation				·	
Repair	Alteration	Uni	t	Mal	ke		Model				Serial No.	
·□	V	AIRFRAN	1E				(As described in Item 1 above)					
		POWERF	PLANT									
		PROPEL	LER							*		
· 🗀		APPLIAN	CE Manufacturer									
				6.	. Co	nformity Sta	tement					
A. Agency's		ddress	,		B.	Kind of Agend						
	Glasgow	alı Cavat		-	\	<u> </u>				Manufacturer		
Address 2533 City Fort (Collins	ek Court	State Co	-	Н	Foreign Cert Certificated F				C. Certi	ficate No.	
zip 80528		untry USA	Ciero CO	-	\vdash	Certificated I			ation	A&P 3:	292572 IA	
have b	een made in	accordance	alteration made to the ur se with the requirements prect to the best of my k	of F	Р́аrt	43 of the U.S			cribed on t	ne rever	se or attachments hereto	
Extended rar per 14 CFR I App. B			Signature/Date of Auth Philip Glaso			Individual) (4-10-1	フ		
	· · · · · · · · · · · · · · · · · · ·		<u> </u>	_	_	al for Return	U U		, 107	۷		
				ow,				m 5 wa	inspecte		ne manner prescribed by the	
l In	AA Flt. Stand spector	lards	Manufacturer		Ma	aintenance Or	ganization				ved by Canadian Transport	
BY F	AA Designee		Repair Station	✓	Ins	spection Auth	orization		Other (Spec	cify)		
Certificate or Designation N	No.		Signature/Date of Auth				//	١				
A&P 3292	572 IA		Philip Glase	30	W	/lly	h	/ · ·	9-10-1	17		

FAA Form 337 (10-06)

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8.	Description	n of W	ork Acco	mplished

(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)

N267RH

9-10-12

Nationality and Registration Mark

Date

Installed Equipment.

Installed Paravion Technology C182-100 Infrared Camera provisions IAW STC SA00294DE.

Ref Paravion Engineering Report ER-C182ELP-2 Rev N/C.


- -Installed a Paravion Technology Augmented Reality System (ARS) IAW Paravion Installation Drawings ARS 303 & 213. The ARS is powered from the Avionics Buss and is protected using a 15 AMP Klixon C/B switch P/N 7270-1-15 labeled "ARS". The ARS is interfaced to FLIR Camera system IAW the above mentioned Paravion Installation Dwgs ARS 303 & 213.
- -The ARS ECU is mounted in the baggage compartment at station 130".
- -The ARS is secured to the rear baggage compartment shelf using two quick disconnect controller mount rails. Ref attached Paravion Technology Inc drawing ARS 4130 sheet 3 for fabrication of controller rails. Attached the controller mount rails to two existing structures in the aircraft using 4X Screws P/N MS27019-1-10, 7 X washers P/N NAS1149F0332P & 3 X nuts P/N MS21042-L3.
- -Fabricated a new cover plate for the ARS. Ref Paravion Technology Dwg # ARS 4130 sheet 2. Attached fabricated cover with 8 X Screws P/N MS35206-231. Instructions for continued airworthiness for the augmented Reality System are contained in Paravion Document PR-ARS-120M. Ref 8110-3 dated 3/30/11 and Paravion report ARS-4004-901 for structural mounting
- -Mounted the Inertial Navigation Unit (IMU) on top of the fabricated cover plate and secured with 4 X IR-620 spacers, 4 X MS35207-265 screws & 4 X MS21042L3 nuts. The IMU is powered from the above ARS ECU and is protected using a 2 amp internal fuse to the ARS ECU.
- -Mounted the INS RS232 control box to the fabricated cover plate using a plate with is attached to the above mentioned cover plate using 4 X MS35206-226 screws. Ref Paravion Technology Dwg 4130 Sheet 4 item -12 for full fabrication details. Attached the INS RS232 control box to the above mentioned plate using 4 X MS35206-226 screws. -Mounted The GMS Downlink Control ECU to the above mentioned cover plate using 6 X MS35206-226 screws. Installed the GMS Down link IAW manufacturers Dwgs 100-W0062X1. System is protected using a Klixon C/B switch P/N 7270-1-10 and is labeled "Down Link" Mounted two antennas on the bottom of the aircraft. Mounted the first antenna at station 145.0" on the bottom of the aircraft to the R/H side of the aircraft center line. Fabricated a doubler from 6061 T6 aluminium 4" X 5". Attached the antenna to the aircraft using 4 X P/N MS51987-48 screws, 4 X P/N AN960C8 washers & 4 X P/N MS21042-L08 nuts. Mounted the second antenna to the bottom of the aircraft at station 125.0" to the L/H side of the center line. Fabricated a doubler from 6061 T6 aluminium 4" X 5". Attached the antenna to the aircraft using 4 X P/N MS51987-48 screws, 4 X AN960C8 P/N washers & 4 X P/N P/N MS21042-L08 screws. Mounted the control head to the center console using 4 X P/N MS35206-215 screws, 4 X MS21042L04 nuts & 4 X AN960JD3 Washers.
- -Installed 2 X Video Accessory Corporation Video Distribution Amplifiers P/N 11-524-104 Ref Paravion Technology Inc Dwg # C182 ARS-1000 item -14 for fabrication details of the supporting bracket. Attached the Video Distribution Amplifiers support brackets to the shelf using 2 X MS27039-0807 screws, 2 X MS21042-L08 nuts & 4 X NAS1149FN832P washers. Attached the distribution Amplifiers to the brackets using 4 X MS24693S27 screws. Power is supplied from the avionics buss and the amplifiers are protected using a 1 Amp Klixon C/B P/N 7277-2-1 C/B Labeled"Video Dstrb"


NOTICE


Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.


8. Description of Work Accomplished (If more space is required, attach additional sheets. Identify with aircraft nation	nality and registratio	n mark and date	work completed.)	
	N267RH		9-10-17	
Installed 2 X Video Accessory Corporation Video switches P/N 1 and is protected using a 1 Amp Klixon C/B P/N 727721-1. Contr switches one labeled "Downlink Video & ARS or FLIR". The sec are collectively labeled "Video switching". These switches are lo switch panel is secured to the overhead interior panel using 4 X FLIR control switch, Laser Interlock control switch & the FLIR Ar	olling the 2 X Vi ond switch is lal cated in the upp 632 clip nuts &	ver is supplied deo switches beled "MFD voer center ov 4 X MS3520	s by installing 2 X Rotary Video & PRI or SEC" The erhead panel. Fabricated 6-228 screws Located th	ey da ne
The monitor is mounted to the instrument panel on the R/H side MS21049-L3 nut plates to the instrument panel using 6 X MS21 provided power from the avionics buss and is protected using a	426-3-4 counter	sunk rivets.	The primary display is	er''
Fabricated a center console and installed in the aircraft. Ref Parref attached conformity reports for material used. Ref Paravion fabrication details of the attaching brackets for the above mention MS20426AD3-3.5 Rivets X 24.	Technology Dra	wing ARS18	2-1000 sheet 3 for	
Installed 2 X Aux Foot switches on the floor at station location 2 material as mentioned above for the center console and installe Foot switch housing Using 2 x MS35206-228 screws and 2 X AI N MS21075L06 & 1 X MS21069L06 nut plate. Attached the nut	d a 2 X switches N960JD6L wash	s P/N M8805 ners. to the fl	/55-001 X 2. Attached the por using 3 X Nut plates	P/
Installed two USB connectors on the fwd slopping face which is	integrated to the	e ARS unit.		
Mounted an existing Motorola radio on the above mentioned ce from 6061 T6 aluminum 2" X 4" .063". Used 1 X AN3-3A bolt an console.				∍d
Wire gauge selection was done in accordance with AC43-13-1B (wiring rating) paragraphs 11-66, 11-67 section 6 (Aircraft Electron)				
An electrical load does not exceed limitations of AC43-13-1b Ch (generator) and 428 (determination of electrical load).	napter 11, parag	ıraphs 424 (E	Electrical load limits), 425	5
The Instructions for Continued Airworthiness (ICA) contained in Airworthiness (HBAW-8900.1) are not applicable as these compReplace" items only.				Ł
Aircraft weight & balance and equipment list amended as requir	ed.			
Nothing follo	ws		·	


. . , .
















































MAIN IMAGER FLIR GIMBAL CABLE





GIMBAL SIDE OF LASER/GPS/DE-ICE CABLE





NOTES:

- 1. COAX SOCKET COMES WITH CRIMP INSTRUCTIONS.
- 2. ALL OTHER SCOKETS ARE: M39029/56-352 (USE CRIMPER M22520/1-01 DIE M22520/1-01).

			TOLERANCES EXCEPT WHERE NOTED:	DRAWN BY	CHK D BY	APRVD. BY:	DATE	
			.X = ±.1 .XX = ±.05 ~	TN			4/13/2012	
			XXX= ± 010					Ĺ
1	-CONFEDERINAL INFORMATION-	PROTO	ANGLES-# 1' T		DO NO.	SCALE	DRAWING	l
Į	THE HEDWINDOW AND DATA CONTAMED HEREIN IS PROPHEETING AND IS SUBMITTED IN CONFEDENCE; AND SHALL HOT ISE DISCUSSED, USED OR		THREADS:	SRD ANGLE			TECH INC.	ı
į	DUPLICATED FOR ANY PLAPPINE WASHINGTON MICHOLA THE PRIOR WRITTEN PERMISSION OF PROMISON TECHNOLOGY, MC.	[-]		PROJECTION	PARAVIO		RADIOMARIK OF	1

Paravion® Inc.

DIMENSIONS IN INCHES

TITLE
POWER BUS
FBI C182 HAWK OWL
PROJECT


DRAWING NUMBER


MASTER ELECTRICAL

ECO


SHEET

14 OF 16





SHEET	REV	DATE	DESCRIPTION	BY	APR	CHK
1	Α	9/8/2011	ADDED -2 ASSY.	TN		



-2 ASSEMBLY (PICTURE FOR REFERENCE ONLY SEE SHT 2 FOR DETAILS)

20 MS3367-4-0 4" WIRE TIE 19 ARS-3610-3 CABLE ASSEMBLY ARS-3610-2 CABLE ASSEMBLY 18 1 17 ARS-3610-1 CABLE ASSEMBLY 16 NAS1149DN632J WASHER 3 3 15 25004 3/8 NYLON CLAMP 8 MS35206-231 14 SCREW 6 13 MS35206-226 SCREW 4 MS21042L3 NUT 4 12 4 NAS1149D0332J WASHER 11 4 SCREW MS35207-265 4 2 SCREW ZINC PLATED OR S.S. (COMMERCIAL 9 M4 X 8mm C.S. PH 4 8 MS27039-08-05 SCREW 7 NOT USED 4 4 6 IR-620-2 SPACER 5 ARS-4130-12 PLATE 4 ARS-4130-10 PLATE 3 MCHPTCBOS3N21 DOWNLINK BOX (COBHAM CMS PROD.) (CUSTOMER SUPPLIED) HG1700-H58 IMU- LASER RING GYRO UNIT PROPAK-V3-RT2I GPS INTERFACE -1 ITEM PART NUMBER DESCRIPTION DRAWING NUMBER Paravion® YTO YTO IMU, GPS, & DOWNLINK ASSEMBLY √Technology ARS-232 DIMENSIONS IN INCHES TOLERANCES EXCEPT WHERE NOTED: ARS CONTROLLER DRAWN CHKD APRVD. BY BY BY REV ECO DATE

THREADS: INTERNAL: CLASS 2B EXTERNAL CLASS 2A

 $X = \pm .1$

XX - ±.05

.XXX= ±.010 ANGLES=± 1°


ΤN DO NOT SCALE DRAWING © 2009 PARAVION TECH, INC. PARAVION IS A TRADEMARK OF PARAVION TECHNOLOGY INC. 3RD ANGLE PROJECTION


SHEET 1 OF 2


3/15/11


NOTES:


APPLY LOCTITE 640 (P/N:64031) THREAD LOCKING COMPOUND.






















-19 BRACKET

MAT'L: .063" THK 6061-T6 ALUMINUM OO-A-250/11
FINISH: BLACK POLYURETHANE POWDER COAT CARDINAL C241-BK303
(BUILD 2 PER AIRCRAFT)
(MOUNTS CONSOLE TO FLOOR)




<u> </u>		.XX = ±.05 .XXX= ±.01
-COMPRESIONAL INFORMATION- THE INFORMATION WID DATA CONTINUED HERSIN IS PROPRESTARY AND IS	PROTO	ANGLES=±
Substitud in compodence, and small not be discussive, used of lipulated for any purpose whatsopage without the production possession of paramon tedhnology, ac.	-	THREADS: INTERNAL: CLASS EXTERNAL: CLASS

Paravion® Technology	ıc.	FBI HAWK OWL				DRAWING NUMBER C182ARS-1000		
DIMENSIONS IN INCHI	ES .		PROJE	CT				
TOLERANCES EXCEPT WHERE NOTED:	「 「	DRAWN BY	BA CHK D	APRVD. BY	DATE	REV	ECO	
$.X = \pm .1$ $.XX = \pm .05$	[TN	TN	REB_	1/17/11	С		
.XXX= ±.010	4	\						
ANGLES=± 1°	Ψ)	$\forall \Box$	DO NO.	T SCALE	DRAWING	SHI	EET	
THREADS: INTERNAL CLASS 2B EXTERNAL CLASS 2A		ANGLE	PARAVIO	PARAVION N IS A TR N TECHNO	5 01	- 13		




-20 BRACKET

SUGGESTED MAT'L: .08" THK 5061-T6 ALUMINUM 00-A-250/11 FINISH: BLACK POLYURETHANE POWDER COAT CARDINAL C241-BK303 (BUILD 1)




-21 BAR

SUGGESTED MAT'L: 0.50° 5061-T6 ALUMINUM 00-A-200/8 FINISH: BLACK POLYURETHANE POWDER COAT CARDINAL C241-BK303 (BUILO 1)




-22 BAR

SUGGESTED MAI'L: .38° X .25° SO 6061-15 ALUMINUM 00-A-200/8 FINISH: BLACK POLYURETHANE POWDER COAT CARDINAL C241-8K303 (BUILD 1)



-23 DOUBLER


SUGGESTED MAT'L: .05° THK 6061-T6 ALUMINUM QQ-A-250/11
FINISH: BLACK POLYURETHANE POWDER COAT CARDINAL C241-BK303
(BUILD 1)





THE STORAGION NO DISCONDED HERD IS SECRETARY NO S
SUBMITOR IN CONFEDENCE IN SPACE IN THE ROOM STORAGE
SUBMITOR IN CONFEDENCE IN SPACE IN THE COLLISSE OF SHAPE IN THE ROOM STORAGE
SUBMITOR FOR MIN PLANESS OF SHAPE IN THE COLLISSE OF SHAPE IN THE ROOM STORAGE IN THE R


3RD ANGLE PRAVING © 2009 PARAVION TECHNOLOGY DIC.
PROJECTION PARAVION TECHNOLOGY DIC.


5 OF 13














COMPLETED PART


-30 PLACARD

SUGGESTED MAT L: .04" THK 6061-T6 ALUMINUM 00-A-250/11
FINISH: BLACK POLYURETHANE POWDER COAT CARDINAL C241-BK303

(BUILD 1)

	Paravion® Inc Technology	_ F	TITLE MOUNT PARTS FBI HAWK OWL _PROJECT				C182ARS-1000		
	TOLERANCES EXCEPT WHERE NOTED:	DRAWN BY	CHK D	APRVD. BY	D.	ATE	REV	EC0	
	.X = ±.1 .XX = ±.05	TN	TN	REB	1/1	7/11	С		
T	.XXX= ±.010 ANGLES=± 1*	$\triangle \Box$	DO NO	T SCALE	חם	ALUAC:	SHI	P.T	
PROTO	THREADS:	\mathfrak{P}					SHEEL		
	INTERNAL CLASS 2B 3	RD ANGLE ROJECTION				MARK OF 12 OF		F 13	

-CONFEDENTIAL REQUIRED HE PROPRIETOR HE DE PROPRIETOR HE DES CONFEDENT HED DE SUBJECT HE DESCRIPTION HE DE PROPRIETOR HE DESCRIPTION HE PROPRIETOR HE PROPRI



(APPLICABLE TO: C206 STATIONAIRE ONLY)

SUGGESTED MAT'L: .04" THK 6061-T6 ALUMINUM 00-A-250/11

FINISH: BLACK POLYURETHANE POWDER COAT CARDINAL C241-BK303

(BUILD 1)

-CONTODUTAL INFORMATION-	PROTO	١
THE MEDIBALTION AND DATA CONTAINED HEISON IS PROPRETARY AND 5. SUBMITTED IN COMPODING: AND SHALL NOT BE DISCLOSED, LISED OF CUPILSTED FOR ANY PURPOSE WHITSOCKER WITHOUT THE PRIOR WRITTEN.	_	
PETMISSION OF PHREVION TECHNOLOGY, NC.		l

						_			
Paravion® 1			LITTLE		DRAV	DRAWING NUMBER			
Paravion® Technology	10.	MOUNT PARTS FBI HAWK OWL C18			32ARS-1000				
DIMENSIONS IN INCHI	ES		PROJE	<u>CT</u>					
TOLERANCES EXCEPT WHERE NOTED:	r {	DRAWN BY	CHK D	APRVD. BY	DATE	REV	ECO		
$.X = \pm .1$ $.XX = \pm .05$		TN	TN	REB	1/17/11	C			
.XXX= ±.010	1						L		
ANGLES=± 1°	(()	DO NO	TSCALE	DRAWING	SHI	SHEET		
THREADS: INTERNAL: CLASS 2B EXTERNAL: CLASS 2A		ANGLE	PARAVIO:	PARAVION N IS A TR N TECHNO	13 0	F 13			

			·
		•	

35 CT4B CABLE TIE 7 34 CTB7 CABLE TIE 33 CTM2B CABLE TIE MOUNT 6 32 MS35206-227 SCREW 15 STAINLESS STEEL SCREW 31 4 X 1/2 PHPN 14 KEYBOARD ASSY 30 | SL-75-0EM-USB 5 29 CPX076 FEMALE CONTACT -1 ПЕМ PART NUMBER DESCRIPTION QTY

28 CPX075-1 HEADER CONNECTOR 27 | 17-200121 (REF.) USB CABLE (PROVIDED W/KEYBOARD) 26 MS21042L08 NUT 2 25 S-5030-12 SPRING 4 24 NAS1149DN832J WASHER 23 MS27039-08-15 SCREW WASHER 22 NAS1149FN632P 21 MS35206-226 SCREW 4 20 17-200161 RECEPTICLE 19 NAS1149F0332P WASHER 1 2 18 NAS1149FN432P WASHER 1 17 AN3-5A BOLT 16 MS21042L04 NUT SCREW 15 MS35206-215 14 NAS1149DN432J WASHER 13 M3 X 0.5X8mm PAN HEAD SCREW 12 C182IRC-3000-1 CONSOLE WIRING 1 11 DOWNLINK RCU-V GMS UNIT (CUSTOMER SUPPLIED) 1 10 2000-7000 NANO FLASH RDR (CUSTOMER SUPPLIED) MOTOROLA XTVA CONVERTER COMM. UNIT (CUSTOMER SUPPLIED) 1 8 C182ARS-1000-26 TRIM 7 C182ARS-1000-25 BASE PLATE C182ARS-1000-23 DOUBLER 1 C182ARS-1000-17 BRACKET C182ARS-1000-20 BRACKET 1 3 C182ARS-1000-22 BAR C182ARS-1000-21 BAR 1 1 C182IRC-1000-50 CONSOLE -1 ITEM PART NUMBER DESCRIPTION ASSY DRAWING NUMBER TITLE Paravion® OTY C182 CONSOLE -Inc. √Technology C182IRC-1000 DIMENSIONS IN INCHES TOLERANCES EXCEPT WHERE NOTED:

— COMPERIAL MEDISARDA PROPRIEDAR NO R SUBSTITO IN CONTRESIO, REGIS IR PROPREDIAR NO R SUBSTITO IN CONTRESIO, REGIS IN CONTRESIO, UND OR CUPULDOS POR NO FUNCIONE VANCIONE VANCION NO.

ANGLES-± 1° PROTO THREADS: INTERNAL: CLASS 2B EXTERNAL CLASS 2A PROJECTION

 $.X = \pm .1$

 $.XX = \pm .06$.XXX- ±.010

DO NOT SCALE DRAWING © 2009 PARAVIOR TECH. DIC. SRD ANGLE PARAVION IS A TRADEMARK OF PARAVION TECHNOLOGY DIC.

DRAWN CHK'D APRVD. BY BY BY

TN

1 OF 4


DATE


8/15/2011


REV


SHKET


BCO











-1 CONSOLE ASSEMBLY

THE SECRECULAR SECRECU

Paravion® In	nc.	С	182 CON				C182IRC-1000		
DIMENSIONS IN INCH									
TOLERANCES EXCEPT	T	DRAWN BY	CHK D	APRVD. BY	ם	ATE	REV	BC 0	
$.X = \pm .1$ $.XX = \pm .05$		TN			8/1	5/2011	_		
.XXX= ±.010	1/1								
ANGLES-± 1°	l (₫)) [DO NO.	T SCALE	DR	VADIC	SHI	क्र	
THREADS: INTERNAL: CLASS 2B EXTERNAL: CLASS 2A		D ANGLE	PARAVIO	PARAVION N IS A 12 N TECHNO	ADE	MEE OF	4 0	F 4	

DOCUMENT NO. ER-ARS-214-2; INSTALLATION STRUCTURAL ANALYSIS

6 October 2011, Robert E. Bristol

Paravion Technology, Inc.

Reference Installation Drawing ARS-214-1 Rev. B dated 07-28-2011, ARS4004-1 Controller Unit Rev. A, ARS232-2 IMU/GPS/Downlink Assy Rev. A

Calculations show that Margins-of-Safety are large reference strength of screws and components of mounting fixture. Minimum Mount Shelf 0.010 thickness, based only on ultimate strength (no rigidity needs addressed).

Actual installation mounted to shelf (2024-T3, 0.032 sheet), ARS-4130-1 brackets supported on aluminum angles (3/4"-x-3/4"-x-0.095") installed using (4 ea.)MS27039-0808, (8 ea.) NAS1149FN832P, (4 ea.) MS21042L08 exceeding requirements of this analysis.

Minimum Margin-of-Safety (35%) is based on bending in Roll-Pin Retention Slot at Ultimate 18g Sideward inertial acceleration.

INPUT: **Unit Weights**

$$Wt_1 := 16.25$$

$$4t_2 = 6.00$$
 in

Hardware
$$Wt_3 := 0.88$$
 lb.

Fasteners

MS24693 (#8-32)

n := 2 per comer

 $\phi 8 := 0.16$

These screws attach ARS4130-13 plates to ARS4004-1 assy

Tensile Strength, TS8:= 840 lb. MINIMUM

Minimum C'Sink Diameter: $\Phi8 := 0.285$

MS24693 (#10-32) N.:= 1 per comer $\phi 10 := 0.19$

These screws attach ARS4130-14 feet to ARS4130-13 plates

Tensile Strength, TS10:= 1200 lb. MINIMUM

Minimum C'Sink Diameter: Φ10:= 0.333

Materials

Ref. ARS-4130-13 Mount Plate, 6061-T6 Thickness := 0.125 in.

Fsu := 20000 psi

(Fsu Conservative, app'l to all ARS-4130 components)

Ref. CFR14, FAR23, 23.561(b)(3)(ii), Amendment 23-48;

Worst-Case Ultimate inertial loading, gLoad := 18 g's

CALCULATIONS:

$$Wt_{0} := \sum_{i=1}^{3} Wt_{i}$$

$$CG := \frac{Wt_{1} \cdot \frac{Ht_{1}}{2} + Wt_{2} \cdot \left(Ht_{1} + \frac{Ht_{2}}{2}\right)}{Wt_{0}} = 5.6$$

Moment := $gLoad \cdot Wt_0 \cdot CG = 3953$ in-lb

Set
$$k := 1..4$$

$$x_1 := 0.225$$

$$x_2 := 1.023$$

$$x_2 := 10.470$$

Set
$$k := 1..4$$
 $x_1 := 0.225$ $x_2 := 1.025$ $x_3 := 10.470$ $x_4 := 11.270$

Fastener Tension:

Tension8 :=
$$\frac{\text{Moment} \cdot x_4}{\sum_{k} (x_k)^2} + \frac{\text{Wt}_0 \cdot \text{gLoad}}{4 \cdot \text{n}} = 275$$
 lb./screw (#8-32 rated 840 lb.)

Margin-of-Safety, MS8 :=
$$\frac{TS8}{1.15(Tension8)} - 1 = 165.\%$$
 Including ref. to 23.625(a)(2) Fitting Factors, Amdt 23-7

Set
$$j := 1...2$$

$$\chi_1 := 0.62$$

$$\chi_1 := 0.625$$
 $\chi_2 := 10.870$

Fastener Tension:

Tension 10 :=
$$\frac{\text{Moment-}\chi_2}{2 \cdot \left[\sum_{j} \left(\chi_j\right)^2\right]} + \frac{\text{Wi}_0 \cdot \text{gLoad}}{4 \cdot \text{n}} = 269 \text{ lb./screw (#10-32 rated 1200 lb.)}$$

$$\frac{\text{COMBINED LOADING}}{\text{COMBINED LOADING}}$$

Margin-of-Safety,
$$MS10 := \frac{TS10}{1.15(Tension10)} - 1 = 287.\%$$
 Including ref. to 23.625(a)(2) Fitting Factors, Amdt 23-7

Foot Shear Area:
$$SA := \frac{0.533 + 0.710}{2} \cdot 0.089 + 0.710 \cdot 0.030 = 0.07\$q$$
. in. (Shear Area of "foot")

$$FSS := \frac{Tension10}{SA} = 3515 \quad psi, \quad Fsu = 20000 \quad psi$$

Margin-of-Safety, MSS :=
$$\frac{Fsu}{1.15(FSS)}$$
 = 395.% Including ref. to 23.625(a)(2)

Fitting Factors, Amdt 23-7

Shear8 :=
$$\frac{Wt_0 \cdot gLoad}{4 \cdot p} = 88$$

Shear 8 :=
$$\frac{Wt_0 \cdot gLoad}{4 \cdot n}$$
 = 88 Shear 10 := $\frac{Wt_0 \cdot gLoad}{4 \cdot N}$ = 176

Because screw shear load is much much less than 1/2 of screw tensile strength and tension load is much much less than screw tensile strength, caluclation of allowable shear using calculated tension load (Ref. Bruhn Chapt. D1) is unnecessary.

"TEAR-OUT", -13 PLATE

ShearStress8 :=
$$\frac{\text{Tension8}}{\pi \Phi 8 \cdot (\text{Thickness})} = 2461 \text{ psi}, \quad \text{Margin} = \frac{\text{Fsu}}{1.15 \cdot \text{ShearStress8}} - 1 = 607 \cdot \%$$

ShearStress10 :=
$$\frac{\text{Tension10}}{\pi \Phi 10 \cdot \text{(Thickness)}} = 2059psi$$
, Margin = $\frac{\text{Fsu}}{1.15 \cdot \text{ShearStress10}} - 1 = 745 \cdot \%$

ROLL-PIN INSTALLATION:

(Considedred in Worst-Case, as though at greatest distance from hinge point)

Ref. MS16562-32 Roll Pin, rated 2100 lb. Double Shear;
$$DS := \frac{Moment}{(2) \cdot (11.29)} = 175 \text{ lb.}$$

Where 11.29 = Moment Arm of Roll Pin, Opposite foot contribution neglected.

Shear Stress in "Beam":
$$SSB := \frac{DS}{2 \cdot (Width) \cdot (Height)} \approx 6253$$
 psi

ShearMargin :=
$$\frac{\text{Fsu}}{1.15 \cdot (\text{SSB})} - 1 = 178 \cdot \%$$

Ref. Installation Drawing ARS-214, Roll-Pin load is imposed at 0.075 inch from end of slot. Bending Stress is calculated as though DS/2 is imposed at 0.1 inch from "square" slot end.

Second Moment-of-Area,
$$l := \frac{\text{Width-Height}^3}{12} = 14.63 \times 10^{-6}$$
 in.^4

Slot Length,
$$Ln := 0.613$$
 Load Appl'n, $a := 0.10$ $b := Ln - a$

Ref. Mach. Hdbk Strength of Materials: Max. Bending Stress = $BS := \frac{Load \cdot a \cdot b^2 \cdot ch}{l \cdot (Ln)^2} = 23461$

Where
$$F_{ty} := 35000$$
 psi $BendingMargin := \frac{F_{ty}}{1.15 \cdot BS} - 1 = 30 \cdot \%$

IMU, TOP PLATE INSTALLATION:
$$Wt_2 = 22$$
 lb. $gLoad = 18$

Installed using 8 ea. MS24693 (#8-32) screws:
$$\frac{W_{12}}{8} \cdot \text{gLoad} = 50 \text{ lb.}$$
 Tension/Shear per Screw

REFERENCE AIRCRAFT INSTALLATION:

<u>Fastener Tension</u> $xa_1 := 0.340$ $xa_2 := 9.908$ <u>Worst-Case Fastener Locations</u>

TensionShelf :=
$$\frac{\text{Moment-xa}_2}{4 \cdot \left[\sum_{j} \left(xa_{j}\right)^2\right]} + \frac{\text{Wt}_0 \cdot \text{gLoad}}{8} = 188 \text{ lb./screw (#8-32 rated 840 lb. min.)}$$

$$\frac{\text{COMBINED LOADING}}{\text{Assumed 4 ea. #8 screws fastening Mount Fixture}}$$

<u>Assumed</u> 4 ea. #8 screws fastening Mount Fixtures to Shelf

Actual Installation included 2 ea.#10, 2 ea. #8

Note that MS21042L08 nuts are rated 1670 lb. axial load.

Minimum Mount Shelf Thickness, based on equivalent Shear Area, material, is calculated as follows:

$$Shelf := \frac{TensionShelf}{(\pi \cdot 0.375) \cdot Fsu} = 0.008 \text{ inch Based on NAS1149, \#8 Washer, 0.375" OD)}$$

ShearShelf :=
$$\frac{\text{Wt}_0 \cdot \text{gLoad}}{8 \cdot (\varphi 8) \cdot \text{Shelf}} = 69082 \text{ psi}$$

$$\text{Fbru} := 67000 \text{ psi,}$$

$$\text{ref. MMPDS, 6061-T6, 0.010 sheet,}$$

$$e/D = 1.5$$

The above "Minimum Shelf Panel Thickness DOES NOT consider shelf rigidity need. Calculation of minimum shelf panel ref. shear pull-through agrees approximately with calculation ref. bearing strength.

Regulatory requirements are satisfied when ARS 4004 and IMU combined assembly is mounted to a shelf greater than 0.010 inch thick, manufactured from 6061-T6 or stronger material, using 8 ea. MS24694, #8-32 or equivalent strength screws.

ENGINEERING REPORT ER-IR2300-2; STRUCTURAL ANALYSIS OF EQUIPMENT SHELF IR-2300-1 ASSEMBLY

Prepared by Robert E. Bristol, 7 October 2011

Page 1

The following calculations verify very large structural Margin of Safety reference requirements of CFR14, Part 23, 23.561 (b)(3), 23.625, reference FLIR TALON Control Electronics Unit installation on IR-2300-1 Equipment Shelf installed to C182IR-1012-1 Support Assembly.

SUMMARY: The calculations show greatest calculated bolt tension, reference 18g Forward inertial loading, to be 85 lb. imposed on #8-32 screw rated to 840 lb. and 15 lb. imposed on #6-32 screw rated 725 lb.

REF. IR-2300-1: With Talon CEU installed

LOAD LOCATION VECTORS DEFINITION

$$X_0 := \begin{pmatrix} 0 \\ 0 \\ 0 \end{pmatrix} \quad \text{[Bolt Pattern Center, IR-2100-1 Mount Plate (IR-2000-1 "Buttons")]}$$

$$X_1 := \begin{pmatrix} -0.28 \\ 0.00 \\ 3.10 \end{pmatrix} \quad \text{[Center-of-Gravity, Talon CEU P/N23364-200]}$$

$$\text{REF. MFR'S DATA}$$

$$X_2 := \begin{pmatrix} -4.05 \\ 0 \\ 0 \end{pmatrix} \quad \text{[Bolt Pattern Center, Talon CEU "Clamp Mount"]}$$

$$\text{REF. DWG. IR-2300-1}$$

$$X_3 := \begin{pmatrix} 5.65 \\ 0 \\ 0 \end{pmatrix} \quad \text{[Bolt Pattern Center, Talon CEU "Pin Mount"]}$$

$$\text{REF. DWG. IR-2300-1}$$

CEU Weight := 13 lb.; [Weight of P/N23364-200 CEU] REF. MFR'S DATA

(1) CEU Inertial Loads

Ref. 14CFR, Part 23, Section 23.561(e), (b3):

Ultimate Load Factors:
$$n_{up} := 3.0$$
 $n_{forward} := 18.0$ $n_{side} := 4.5$

LOAD MAGNITUDE VECTORS DEFINITION

$$PV_{1} := \begin{pmatrix} 0 \\ 0 \\ -n_{up} \cdot Weight \end{pmatrix} = \begin{pmatrix} 0.00 \\ 0.00 \\ -39.00 \end{pmatrix} \qquad PV_{2} := \begin{pmatrix} 0 \\ -n_{forward} \cdot Weight \\ -Weight \end{pmatrix} = \begin{pmatrix} 0.00 \\ -234.00 \\ -13.00 \end{pmatrix}$$

REF. UPWARD INERTIAL LOAD IN RELATION TO AIRPLANE

REF. FORWARD INERTIAL LOAD IN RELATION TO AIRPLANE

$$PV_{3} := \begin{pmatrix} n_{side} \cdot Weight \\ 0 \\ -Weight \end{pmatrix} = \begin{pmatrix} 58.50 \\ 0.00 \\ -13.00 \end{pmatrix}$$

REF. SIDEWARD INERTIAL LOAD IN RELATION TO AIRPLANE

Set

$$i := 1..4$$
 $x_1 := 2.015$ $y_1 := 2.150$ $x_3 := -2.015$ $y_3 := 2.150$
 $x_2 := 2.015$ $y_2 := -2.150$ $x_4 := -2.015$ $y_4 := -2.150$

[Bolt Pattern, IR-2100-1 Mount Plate (IR-2000-1 "Buttons")]

$$\begin{pmatrix}
MX_{1,1} \\
MY_{1,1} \\
MZ_{1,1}
\end{pmatrix} := X_1 \times PV_1 = \begin{pmatrix}
0.00 \\
-10.92 \\
0.00
\end{pmatrix} \quad \text{lb.-in.; [Moment on Mt. Plate Bolt Pattern due to up g-load]}$$

$$n_{up} = 3.00$$

$$\begin{pmatrix}
MX_{1,2} \\
MY_{1,2} \\
MZ_{1,2}
\end{pmatrix} := X_1 \times PV_2 = \begin{pmatrix}
725.40 \\
-3.64 \\
65.52
\end{pmatrix} \text{lb.-in.; [Moment on Bolt Pattern due to fwd g-load]}$$

$$n_{\text{forward}} = 18.00$$

$$\begin{pmatrix}
MX_{1,3} \\
MY_{1,3} \\
MZ_{1,3}
\end{pmatrix} := X_1 \times PV_3 = \begin{pmatrix}
0.00 \\
177.71 \\
0.00
\end{pmatrix} \text{lb.-in.; [Moment on Bolt Pattern due to side g-load]}$$

$$n_{\text{side}} = 4.50$$

Based on upward inertial load, ref. Bruhn Chapter D1

$$TX_{1,i} := \frac{x_i MY_{1,i}}{\sum_i (x_i)^2} \qquad TY_{1,i} := \frac{y_i MX_{1,i}}{\sum_i (y_i)^2} \qquad BT_{1,i} := (TX_{1,i} + TY_{1,i}) + \frac{n_{up} Weight}{4}$$

[Ultimate Bolt Tension, IR-2000-1 Button Installation, Upward Inertial Load]

BTmax := max(BT) = 11 lb. [MS24693 (#8-32) rated to 840 lb. Tension ref. MS24693] [MS21042L08 rated to 1670 lb. Tension ref. MS21042]

$$MS_1 := \frac{840}{1.15 \cdot BTmax} - 1 = 6478 \cdot \%$$
 Ref. FAR23.625 Fitting Factor [Extremely High]

Where: $\Phi A := 0.285$ Minimum Head Dia., MS24693 (#8-32) Ref. Specification MS24693 $Th_0 := 0.080$ Material Thickness, Ref. Drawing IR-2300-1

Based on Forward inertial load, ref. Bruhn Chapter D1

$$TX_{2,i} := \frac{x_i \cdot MY_{1,2}}{\sum_i (x_i)^2} \qquad TY_{2,i} := \frac{y_i \cdot MX_{1,2}}{\sum_i (y_i)^2} \qquad BLT_{2,i} := (TX_{2,i} + TY_{2,i})$$

[Ultimate Bolt Tension, IR-2000-1 Button Installation, Forward Inertial Load]

BltTmax := max(BLT) = 85 lb. [MS24693 (#8-32) rated to 840 lb. Tension ref. MS24693] [MS21042L08 rated to 1670 lb. Tension ref. MS21042]

$$MS_3 := \frac{840}{1.15 \cdot BltTmax} - 1 = 761 \cdot \% \quad \text{Ref. FAR23.625 Fitting Factor}$$
[High]

Where: $\Phi B := 0.16$ Dia., MS24693 (#8-32) Ref. Specification MS24693 $Th_0 = 0.080$ Material Thickness, Ref. Drawing IR-2300-1

Bearing Load = BL :=
$$n_{\text{forward}} \cdot \frac{\text{Weight}}{4} = 58.50$$
 lb./screw

Bearing Area =
$$BA := \Phi B \cdot (Th_0) = 0.013$$
 sq. in. per screw

Fbru := 88000 psi, Ref. MMPDS, 3.6.2.0(b1)

$$MS_4 := \frac{Fbru}{1.15 \cdot \sigma bearing} - 1 = 1574 \cdot \%$$
 Ref. FAR23.625 Fitting Factor [Extremely High]

$$\begin{pmatrix}
MX_{1,3} \\
MY_{1,3} \\
MZ_{1,3}
\end{pmatrix} := X_1 \times PV_3 = \begin{pmatrix}
0.00 \\
177.71 \\
0.00
\end{pmatrix}$$
Ib.-in.; [Moment on Bolt Pattern due to Side g-load]
$$n_{side} = 4.50$$

$$TX_{3,i} := \frac{x_i \cdot MY_{1,3}}{\sum_i (x_i)^2} \qquad TY_{3,i} := \frac{y_i \cdot MX_{1,3}}{\sum_i (y_i)^2} \qquad BOLT_{3,i} := (TX_{3,i} + TY_{3,i})$$

:	x	y	$TX_{3,i} =$	$TY_{3,i} =$	j	BOLT _{3,i} =	\sum bolt, i
	2.02	2.15	22.05	0.00	[22	Z BOE 3,i
	2.02	-2.15	22.05	0.00		22	$\frac{1}{n_2} = 0.00$
	-2.02	2.15	-22.05	0.00		-22	Must equal zero
	-2.02	-2.15	-22.05	0.00	į	-22	

BoltTmax := max(BOLT) = 22 lb. [MS24693 (#8-32) rated to 840 lb. Tension ref. MS24693] [MS21042L08 rated to 1670 lb. Tension ref. MS21042]

$$MS_5 := \frac{840}{1.15 \cdot BoltTmax} - 1 = 3213 \cdot \%$$
 Ref. FAR23.625 Fitting Factor [Extremely High]

 $\Phi A = 0.285$ Minimum Head Dia. $Th_0 = 0.080$ Material Thickness Ashear = 0.072

Fsu = 27000 psi; 6061-T6 Sheet, Ref. MMPDS, 3.2.6.0(b1)

$$MS_6 := \frac{Fsu \cdot Ashear}{1.15 \cdot 1.5 \cdot BoltTmax} - 1 = 4985 \cdot \%$$
 Ref. FAR23.625 Fitting Factor [Extremely High]

The above completes analysis of attachment tof the shelf to C182IR-1012-1 Support Assy.

Ref. (8 ea.) MS24693S51 (#8-32) screws, rated 840/2 = 420 lb. shear) to attach the Mount Pin Blocks to the IR-2300-1 plate, (4 ea.) MS24693Sbased on 18.0 Forward inertial loading (13 lb. at 3.10 inches above the shelf).

Ref. Figure 1,
$$M_X := (3.10) \cdot (n_2 \cdot Weight) = 725$$
 in.-lb., where: $n_2 = 18.00$ Weight = 13.00

$$Y_1 := 1.79$$
 $Y_2 := 2.24$ $Y_3 := 7.58$ $Y_4 := 8.28$

$$VT_{i} := \frac{Y_{i} \cdot Mx}{\sum_{i} (Y_{i})^{2}}$$

$$Y_i = VT_i = VT_i = \begin{bmatrix} 1 & 1.79 & 10 \\ 2 & 2.24 & 12 \\ \hline 3 & 7.58 & 41 \\ 4 & 8.28 & 45 \end{bmatrix}$$

Up Load on each ECU Tie-DownPoint Due to Forward Inertia Load,18g Ultimate

By Inspection Max Load = $ML := VT_4 = 45$ lb.

Ref. Fig. 1,
$$T_{max} := \frac{1}{2} \cdot \frac{\left[0.81 \cdot \left(1.19 \cdot VT_4\right)\right]}{\left(0.31^2 + 0.81^2\right)} \cdot 1.15 = 33 \text{lb.}$$
 Ref. FAR23.625 Fitting Factor Ref. MS24693S51 (#8-32); rated 840 lb.

By Inspection Secondary Load = $M2 := VT_3 = 41$ lb.

Ref. Fig. 1,
$$T2max := \frac{\left[0.68 \cdot \left(0.24 \cdot VT_3\right)\right]}{\left(0.25^2 + 0.68^2\right)} \cdot 1.15 = 15 \text{lb.}$$
 Ref. FAR23.625 Fitting Factor Ref. MS24693S27 (#6-32); rated 725 lb.

These calculations show that Margins-of-Safety reference FLIR TALON ECU installation on IR-2300-1equipment shelf assembly, FAR requirements 23.561, 23.625 are extremely large.

·			
	•		

U		DATE							
STATEMENT OF COMPLIANCE WITH FEDERAL AVIATION REGULATIONS AIRCRAFT OR AIRCRAFT COMPONENT IDENTIFICATION March 30 2011									
		AIRCRAFT COME	PONENT IDENTIFICA						
MAKE	MODEL NO.	TYPE (Airplane, F etc.)	Radio, Helicopter.	NAME OF	APPLICANT				
Cessna Aircraft	182T		plane	Parav	vion Technology, Inc.				
		LIST OF D							
IDENTIFICATION			TITLE						
Report:									
ARS-4004-901 Date: March 29, 2011		Structural Substantiation Equipment Installation							
Notes:									
			he above data are a ering design data.	approved	herein. This				
			for Cessna Aircraft ed in support of the						
		S/N: 18282177 and is issued in support of the alteration of the aircraft. 3. Except as noted, all applicable requirements are to amendment levels established in TCDS 3A13, Revision 69.							
				·					
PURPOSE OF DATA In support of avionics equip	ment installation.								
APPLICABLE REQUIREMENTS (List specific sections)		·					
FAR 23.301, 23.303, 23.3	05, 23.307, 23.34	41, 23.561, 23.6	601, 23.603, 23.605	, 23.613					
of appointment under Part 183 horizontal have to requirements of the Federal Art (We) Therefore Record Reco	CERTIFICATION - Under authority vested by direction of the Administrator and in accordance with conditions and limitations of appointment under Part 183 of the Federal Aviation Regulations, data listed above and on attached sheets numbered								
SIGNATURE (S) OF DESIGNATED EN	GINEERING REPRESI	ENTATIVE (SE	DESIGNATION NUMB	ER(ST	CLASSIFICATION				
Contat Ramad	10.11ch Venk	at Ramachandran	DERT-635514-	NM	Structures				

		•	
•			
	,		
	•	•	

Haita) States of America

Appartment of Transportation_Hederal Abiation Administration

Supplemental Type Certificate

Number SA00294DE

This certificate, issued to

Paravion Technology, Inc.

2001 Airway Avenue Fort Collins, CO 80524

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations.

Original Product - Type Certificate Number:

3A13

Make:

Cessna

Model:

R182, 182R, 182T, T182T, 182Q, & 182S

Description of the Type Design Change:

Installation of an external Infrared Imaging System in accordance with Paravion Technology Master Drawing List Report No. DL-C182IR-100, Revision N/C, dated March 19, 1997, or later FAA approved revision.

Limitations and Conditions:

- 1. Compatibility of this design change with previously approved modifications must be determined by installer.
- 2. A copy of this certificate and Flight Manual Supplement must be maintained as part of the permanent records for the modified aircraft.
- FAA approved Aircraft Flight Manual Supplement, PR-C182IR-100M, Revision 0, dated June 6, 1997, or later FAA approved revision is required.
- 4. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application.

January 10, 1997

Date reissued

Date of issuance:

June 10, 1997

Date amended: 2/18/98; 4/8/04; February 17, 2009

By direction of the Administrator

Melissa Sandow (Signature) Program Manager

Northwest Mountain Region

Denver Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

			•		

PARAVION TECHNOLOGY, INC. 2001 AIRWAY AVENUE FT. COLLINS, COLORADO 80524

ER-C182ELP-2

Rev. N/C

Structural Substantiation Engineering Report for FLIR TALON Installation on Cessna Model 182 Aircraft

Prepared by:

Robert F Bristol

Date:

Robert E. Bristoi

Date:

Reviewed by Larry Stark

Revision History

Revision	Date	Detail of Changes	Ву
N/C	10-12-2011	Original REB	REB

Acronyms

AC	Advisory Circular		
A/C	Aircraft		
ACO	Aircraft Certification Office		
CFR	Code of Federal Regulations		
CP	Certification Plan		
DER	Designated Engineering Representative		
FAA	Federal Aviation Administration		
KEAS	Knots Equivalent Airspeed		
KIAS	Knots Indicated Airspeed		
STC	Supplemental Type Certificate		
TBD	To Be Determined		
TC	Type Certificate		
TCDS	Type Certification Data Sheet		

Based on model R182

V_A	Design Maneuvering Speed = 112 knots (Ref. TCDS 3A13)
V_c	Design Cruising Speed = 160 knots (Ref. Cessna Literature)
V_{NE}	Never Exceed Speed = 182 knots (Ref. TCDS 3A13)
V_D	Dive Speed; 230 knots Ref. CFR14, 23.335

References

Document No.	Document Title	
TCDS 3A13 Revision 69,	Type Certification Data Sheet for Cessna Model 182	
April 20, 2009		
AC 23-19A	Airframe Guide for Certification of Part 23 Airplanes	
Ref. 1	MMPDS-03, "Metallic Materials and Elements for Flight Vehicle Structures", U.S. Government Printing Office, Washington, D.C.	
Ref. 2	Fluid Dynamic Drag, Hoerner, S.F.	
Ref. 3	NACA-TN 2960 "Drag of Circular Cylinders for Wide Range of Reynolds Numbers and Mach Numbers"	
	"Airframe Stress Analysis and Sizing", 2nd Edition, Michael C. Y. Niu, Hong Kong Conmilit Press, Ltd.	
	"Analysis and Design of Flight Vehicle Structures", E. F. Bruhn, Jacobs Publishing, Inc.	
	"Stress Concentration Factors", R.E. Peterson, John Wiley & Sons, 1974	
	"Introduction to Flight", J. D. Anderson, McGraw-Hill Book Company	

1.0 Introduction

1.1 Purpose and Scope

This report presents structural substantiation for the C182ELP-100 External Loads Provision Installation as installed to support FLIR Talon imaging unit installation. This report shows compliance to 14 CFR 23.301(a)(b)(c), 23.303, 23.305, 23.307(a), 23.321, 23.333, 23.335(a)(b), 23.337(a)(b), 23.341, 23.441(a), 23.443(a)(c), 23.471, 23.473(a)(d)(e)(g), 23.479, 23.481(a)(b), 23.483, 23.485,23.493, 23.613, 23.619 and 23.625(a). All regulations are as set forth in Amendment 61 to CFR14, Part 23.

Representative External Loads Provision Installation, with reference load installed, is shown in Figure 1.




Figure 1 - External Loads Provision Installation

The External Loads Provision is mounted to the floor of the Cargo compartment of Cessna 182 aircraft, and extends through a hole cut through the Cargo compartment door. This mount accepts a second mount bracket, which is designed to accept a mount plate to which the external load is attached. This report documents loading (load weight, shape, and mount plate configuration) applicable to use with FLIR TALON system installed.

1.2 Compliance Summary

The design and analysis of the modification shows that the installation meets all applicable structural requirements identified below. The minimum margin-of-safety for each installation is shown in Table 1. Analysis begins at the FLIR TALON imager unit installation and proceeds installation of the Support Assembly (C182IR-1012) to the Cargo Compartment floor.

. Margin-of-safety greater than 500% is reported as HIGH. Minimum Margin of Safety Summary

Section	Description	Mode of Failure	Margin
	SX5-606-1 Support Plate (1/4-inch 6061-T6)	Shear-Thru	High
Attached	SX5-606-1 Support Plate, Load Attaching Bolt	Tension	411%
Calculations	IR-4301- 10 Adapter Plate (Outer Bolt Circle)	Attaching Bolt Tension	High
	IR-4301- 10 Adapter Plate (Outer Bolt Circle)	Attaching Bolt Tear-Thru	High
Attached Calculations	IR-1040 Support Assy (Mount Bracket) Channel Rivets Installation Bracket Installation, AN525-10 Screws Torsional Stress Bending Rotation Lock	Shear Shear Shear Tension Static Friction	132% High 491% High 98%
Attached Calculations	IR-1060-1 Bolt (1/4-28, 303 Stainless)	Tension, assuming 50-70 in-lb Wrench Torque	6%
Attached Calculations	C182IR-1012 Support Assy Instr Tube Torsional Stress Attaching Screws, IR-1032, NAS1303 Cargo Floor Screws MS35207-264, Tension	Shear Shear Tension	High 77% 259%

Regulatory compliance for this change is based on the following:

14 CFR; Part 23 including Amendments 23-1 through 23-61.

Table 1 - Compliance Summary

14 CFR	Title	Amdt.	Compliance Statement
	Subpart C - Structure		
	GENERAL		
23.301 (a)(b)(c)	Loads.	23-48	The installation is analyzed for limit loads as calculated in this document. Appropriate Factor of Safety and Fitting Factor are included as part of this analysis
23.303	Factor of safety.	23-0	All limit loads are multiplied times a 1.5 factor of safety.
23.305	Strength and deformation.	23-45	Analysis shows that the modified structure is able to support limit loads without detrimental or permanent deformation.
23.307 (a)	Proof of structure.	23-0	Analysis using reliable methods shows that strength and deformation requirements for 23.305 are met for all load cases in 23.301.
	FLIGHT LOADS		
23.321	General.	23-45	Flight load factors for critical altitudes and weights for the flight envelope defined in the POH are used in the analysis. Compressibility effects are not significant.
23.333	Flight envelope.	23-34	Installation of Talon System does not alter the flight characteristics of the OEM aircraft. A flight envelope for use in applied loads on ELP is generated in a conservative manner.
23.335(a)(b) (c)(d)	Design airspeeds.	23-48	The installation of Talon System does not alter the design airspeeds of the aircraft. A flight envelope for use in applied loads is generated in a conservative manner.
23.337(a)(b)	Limit maneuvering load factors.	23-48	Limit maneuver load factors as prescribed in the regulation for normal category aircraft are used in the analysis with FLIR Talon System installed.

23.341(c)	Gust load factors.	23-48	Limit gust load factors as calculated per 23.341(c) are used in the analysis with FLIR Talon System installed.
	VERTICAL SURFACES		
23.441(a)	Maneuvering loads.	23-48	Maneuvering loads based on vertical surface area with FLIR Talon System installed are used in the analysis.
23.443(a)(c)	Gust loads.	23-48	Gust loads based on vertical surface area with FLIR Talon System installed are used in the analysis.
	GROUND LOADS		
23.471	General.	23-0	Installation does not alter the ground loads of the OEM aircraft. A conservative estimate of loads for use in applied loads is used in the analysis.
23.473(a)(d) (e)(g)	Ground load conditions and assumptions.	23-48	Installation does not alter the ground loads of the OEM aircraft. A conservative estimate of loads for use in applied loads is used in the analysis
23.479	Level landing conditions.	23-45	Installation does not alter the ground loads of the OEM aircraft. A conservative estimate of loads for use in applied loads is used in the analysis.
23.481(a)(b)	Tail down landing conditions.	23-0	Installation does not alter the ground loads of the OEM aircraft. A conservative estimate of loads for use in applied loads is used in the analysis
23.483	One-wheel landing conditions.	23-0	Installation does not alter the ground loads of the OEM aircraft. A conservative estimate of loads for use in applied loads is used in the analysis
23.485	Side load conditions.	23-45	Installation does not alter the ground loads of the OEM aircraft. A conservative estimate of loads for use in applied loads is used in the analysis.
23.493	Braked roll conditions.	23-0	Installation does not alter the ground loads of the OEM aircraft. A conservative estimate of loads for use in applied loads is used in the analysis.

	Subpart D – Design and Construction		
23.601	GENERAL	23-0	N/A
23.613	Material strength properties and design values.	23-45	Statistically based material strength properties from MMPDS are used in the analysis. 'A' basis values are used for single member structural elements and 'B' basis values are used for redundant structure.
23.619	Special factors.	23-45	Standard analysis and aerospace grade materials are used for the design so no special factors of safety are required to address uncertainty, deterioration or appreciable variability.
23.625 (a)	Fitting factors.	23-7	A fitting factor of 1.15 was applied to each fitting substantiated by analysis. No additional fitting factor is required for continuous joints with multiple fasteners and section properties typical of the member being spliced.

Analysis is based on ultimate maneuvering load factor, gust load factor requirements, and ground loading requirements. It is shown that external load installation within loading limits will not have detrimental or permanent deformation during flight operations within certificated aircraft limitations.

FLIGHT EN	FLIGHT ENVELOPE					
RESULTS SUMMARY:	("Maneuvering"	V _p =	n _p =			
	"Cruise"	160	5.62			
Margins-of-Safety: $Cd = 0.85$	"Dive"	230	4.32			
MS ₁ = 1054% (HIGH) Mount Plate Shear Thru Vel =	"Maneuvering"	112	-1.57			
MS ₁₁ = 5857 % Tear-Thru, IR4301 Skirt	"Cruise"	160	-3.62			
MS ₂ = 413.% Mount Plate Screws, Tension	"Dive"	230	-2.32			
MS ₂₁ = 1317% AN3, IR-4301 Skirt	("Landing")	49	2.05			
$MS_3 = 132\%$ Rivet Shear, Channels Instn						
$MS_4 = 557\%$ (HIGH) Screw Shear, Bracket Instn[AN525]						
$MS_5 = 491\%$ Torsional Stress, Inner Spt Tube						
MS ₈ = 507.% (HIGH)Bending Stress, Inner Spt Tube						
$MS_6 = 857\%$ (HIGH) Torsional Stress, Outer Support Tul	oe					

MS₇ = 98 % Based on Friction Lock at Tapered Collar, IR-1060-1 Bolt at 50-70 in.-lb. Wrench Torque(40000 psi Tension)

MS₇₁ = 9.% Based on Shear(MS27039-1-11) Anti-Rotation Lock Screw Only

 $MS_{90} = 139\%$ Cargo Compartment Mount Bracket Screws, Shear, Based on MS27039, #10-32

MS₉₂ = 488 % MS35207-264 Cargo Compartment Mount Bracket Screws, Tension

 $MS_{10} = 6.\%$ Tension Stress, IR-1060-1 Bolt at 50-70 in.-lb. wrench torque.

NOTE: Worst-Case Tension Loading imposed on the (10)CR3214-4 Rivets fastening the inboard end of the C182IR-1022 Support to the Cargo Floor is 27 lb. (3 lb. per rivet). These rivets are rated to 250 lb. tension each rivet.

Worst-Case Tension Loading imposed on the (4) #10 screws at the outboard end is 165 lb. (42 lb. per screw). These screws are rated to 1200 lb. tension.

2.0 External Loads

2.1 Model Information

This document is applicable to:

Cessna model 182; 182Q, 182R, 182S, 182T, T182T, R182*

Type Certificate (TC) Holder:

Cessna Aircraft Company

P. O. Box 7704

Wichita, Kansas 67277

Type Certification Data Sheet (TCDS):

3A13 Revision 69, April 20, 2009

Basic Aircraft Information from TCDS- Model 182:

Lycoming 0-540., 235 Horsepower at 2400 rpm (R182)

Maneuver speed. $V_A = 112 \text{ KIAS (R182)}$

Never Exceed Speed, $V_{NE} = 182 \text{ KIAS (R182)}$

Maximum Takeoff Weight = 3,100 Lbs.

Maximum Landing Weight = 2,950 Lbs.

Basic Aircraft Information for Cessna website:

Maximum Useful load = 1,030 Lbs.

Wing Span = 36 Ft.

Standard Empty Weight = 2,095 Lbs.

Wing Area = 174 sq. ft.

Wing Loading = 3100 Lb./174 sq. ft. = 17.816 Lbs/sq ft

Stall Speed = 49 KCAS

R182 is shown as worst-case

2.2 Load Axis System

The loads axis system is a "right-handed" system defined in the aircraft (A/C) coordinate system as follows:

- X: (+) LH Outboard normal to the A/C centerline of the fuselage
- Y: (+) Aft along A/C centerline of the fuselage
- Z: (+) Up normal to A/C centerline along the fuselage

Acceleration loads are provided as accelerations in "G" and are aircraft accelerations. For example;

Nz = 5.0 means aircraft is accelerated 5 g's vertically upward

In evaluating an item of mass, inertial load on the part is calculated as:

 $Fz = -5.0g \times (Wt of part)$

whereby a positive acceleration imparts a negative direction inertial force.

The state of the s

FIGURE 2, LOAD AXIS SYSTEM

2.3 Design Airspeeds

The flight envelope is per 23.333 and TCDS information:

Design Maneuvering Speed, V_A = 112 KIAS

Minimum design cruising speed calculated per 14 CFR 23.335(a):

Where: W = 3100

S = 174 V h = 182 KIAS (V_{NE}, R182)

Ref. 23.335(a)(1) $Vc := 33 \cdot \sqrt{\frac{W}{S}} = 139$ KEAS

MINIMUM;

Vc = 159 KEAS, Ref. Cessna Literature

Ref. 23.335(a)(2)

$$\frac{W}{S}$$
 = 17.82 < 20 (multiplier 33 is required.)

Ref. 23.335(a)(3) V_C need not be greater than $0.9*V_H = 0.9*182 = 164$ KEAS, Sea Level

Therefore Vc is set to 164 KIAS = 277 ft./sec. for this analysis

Dive speed is calculated from 23.335(b):

Ref. 23.335(b)(2)(i)

 $V_D = 1.4*V_c = 230 \text{ KEAS}$

Ref. 23.335(b)(3)

$$\frac{W}{S}$$
 = 17.82 <20 (multiplier 1.4 is required)

Therefore V_D is set to 230 KEAS = 388 ft./sec. for this analysis

2.4 **Limit Maneuvering Load Factors**

The maximum limit load factors at maneuvering speed Vc per 14 CFR 23.337 for normal category aircraft are used:

Ref. 23.337(a)(1)

$$n:=2.1+\frac{24000}{GW+10000}=3.93$$
 Positive, need not be greater than 3.8

Pitch, yaw and rolling accelerations due to abrupt maneuvers are relatively small for this installation due to proximity or the installation to the aircraft center of gravity. Therefore the principle loads due to maneuver are as defined by 23.337.

2.5 **Limit Gust Load Factors**

Maximum limit gust load factors are calculated per the method in 14 CFR 23.341. A conservative airplane normal force coefficient is assumed:

$$a := 2 \cdot \pi = 6.28$$
 /radian (Note: $a \cdot \frac{\pi}{180} = 0.11$ /degree)

<u>g</u> := 32.2

feet per second per second

 $\rho := 0.00238$ lb-sec^2/ft^4 (slug/ft^3)

Where: MFW = 2095 + 180 = 2275 lb. (Std Empty Weight + 1 Crew)

$$\mu g := 2 \cdot \frac{\left(\frac{MFW}{S}\right)}{\rho \cdot Ch \cdot a \cdot g} = 11.24$$
 $Kg := \frac{0.88 \, \mu g}{5.3 + \, \mu g} = 0.60$

Using

Vc := 164 knots

NpositiveCruise := 1 +
$$\frac{\text{Kg} \cdot \text{Udec} \cdot \text{Vc} \cdot \text{a}}{498 \cdot \left(\frac{\text{MFW}}{\text{S}}\right)}$$
 = 5.73 NnegativeCruise := 1 - $\frac{\text{Kg} \cdot \text{Udec} \cdot \text{Vc} \cdot \text{a}}{498 \cdot \left(\frac{\text{MFW}}{\text{S}}\right)}$ = -3.73

Using

NpositiveDive := 1 +
$$\frac{Kg \cdot U \text{ded} \cdot V \text{d} \cdot a}{498 \cdot \left(\frac{MFW}{S}\right)}$$
 = 4.32 NnegativeDive := 1 - $\frac{Kg \cdot U \text{ded} \cdot V \text{d} \cdot a}{498 \cdot \left(\frac{MFW}{S}\right)}$ = -2.32

Limit Ground Load Factors 2.6

The descent velocity in feet per second per 23.473(d) is;

$$Vg = 4.4 \left(\frac{w}{s}\right)^{1/4} = 9.0 \text{ ft./sec.}$$
 where W = 3100 lb., S = 174 sq. ft.

Need not exceed 10 ft./sec., may not be less than 7 ft./sec.

The landing gear static gear deflection is measured at 2.50 inches at MTOW. This indicates that the landing gear spring rate is:

$$K = \frac{2950}{2.5} = 1,180 lb. per inch$$

The landing gear is modeled as a simple spring mass system as shown in Figure 2 – Landing Gear System.




Figure 3 - Landing Gear System

The diagram above represents the airplane and landing gear at the point of initial contact with the ground where the downward velocity is 9 ft/s and the spring force is zero. Maximum acceleration occurs at the bottom of the stroke when downward velocity is zero and the spring compression and therefore resulting force and acceleration are maximum. Maximum spring compression is conservatively found by assuming the work done by the airplane is converted to spring energy. Such that;

 $U = \Delta KE + FX = \Delta SE$; Work done by the aircraft = Spring Energy increase.

 $\Delta KE = \frac{1}{2} \frac{GW}{g} (v^2)$ Where v = vertical velocity at contact, reduced to 0 at maximum compression, GW = aircraft gross weight at touchdown, g = acceleration of gravity.

 $FX = \frac{GW}{3}Y1$ Where wing lift equal to 2/3 of airplane weight (GW) is assumed per 23.477(e).

 $\Delta SE = \frac{1}{2}KY1^2$ Where K = Spring Constant (=GW/Yo), Yo = Static Gear Deflection at aircraft weight GW, and Y1 = maximum gear deflection during landing (vertical velocity = 0)

Using the above equations, the following quadratic equation can be written:

$$Y1^2 - 2\left(\frac{\gamma_0}{3}\right)Y1 - \left(\frac{\gamma_0}{g}v^2\right) = 0$$

Therefore;
$$Y1 = \left(\frac{\gamma_o}{3}\right) + \sqrt{\left(\frac{\gamma_o}{3}\right)^2 + \left(\frac{\gamma_o}{g}v^2\right)}$$

Solving for the Vertical Force on the aircraft at maximum gear deflection Y1,

$$F1 = \frac{GW}{g}Y1 + \frac{2}{3}GW$$

And:
$$\frac{d^2}{dx^2}y = \frac{F1}{\sqrt{\frac{GW}{g}}} = \left[\frac{\gamma_1}{\gamma_0} + \frac{2}{3}\right]g$$

= Maximum vertical acceleration in units of g.

Where: Yo = 2.50 inches (= 0.21 ft Static Deflection) and v = 9 ft/sec., maximum vertical aircraft acceleration (inertia load factor) is calculated to be 2.1 g.

2.7 Limit Longitudinal Airloads

Limit drag load is calculated by the following equation:

$$F_Y = \frac{1}{2} \rho V^2 S C_d = \frac{1}{2} (0.00238) (v)^2 (S) (Cd)$$

Where: v = airspeed in ft/sec, S = Load frontal area in sq. ft (0.83),

$$Cd = 0.85$$

2.8 Limit Lateral Maneuver and Gust Airloads

External loads can also have an exposed vertical surface which results in a side or lateral load.

These calculations are based on flat area as above (side area projection of Talon installation is equivalent to frontal projection. Drag coefficient used for sideward flow is 0.85. Forces can be resolved into a normal force or lateral load on the external load by the using the cross-flow principle in Ref 2.

$$F_N = qSC_N$$

Where the q, the dynamic pressure is:

$$q = \frac{1}{2}\rho V^2$$

The normal force coefficient for a body inclined to the flow at an angle of attack is given by.

$$C_{N} = C_{Dbasic}(\sin^{2} \alpha)$$

$$Fx = qSC_{d}(\sin^{2} \beta)$$

Lateral maneuver load at speeds up to V_A is calculated per 23.441 using:

Static freestream sideslip angle equal to 15 degrees per 23.441(a)(3).

Overswing angle 1.5 times static per 23.441(a)(2).

Assuming sidewash factor equal to 2.0 to account for local flow around the fuselage side due to sideslip maneuver.

$$\beta_{max} = 15 \times 1.5 \times 2.0 = 45 \ deg.$$

Lateral gust load at speeds up to V_C is calculated per 23.443 using:

 $U_{de} = 50 \text{ ft./sec.}$ at VC per 23.333(c

 $V_C = 164 \text{ knots} = 277 \text{ ft/sec.}$

Equivalent sideslip angle:

$$\beta = tan^{-1} \left(\frac{Ude}{Vc} \right) = tan^{-1} \left(\frac{50}{277} \right) = 10.2 deg.$$

Assuming a sidewash factor equal to 2.0 to account for local flow around the fuselage side due to side gust:

$$\beta_{max} = \beta(2.0) = 10.2(2.0) = 20.4 deg.$$

Lateral gust loads at speeds up to V_D are conservatively included by using the gust velocity per 23.333(c) of 25 fps.

$$V_D = 371 \, fps \, \text{Vd} = 230 \, \text{knots} = 388 \, \text{ft./sec.}$$

Equivalent sideslip angle:

$$\beta = tan^{-1} \left(\frac{Ude}{Vd} \right) = tan^{-1} \left(\frac{50}{388} \right) = 3.7 deg.$$

$$\beta_{max} = \beta(2.0) = 3.7(2.0) = 7.4 deg.$$

Therefore the limit lateral load for maneuver and gust conditions is as shown below, in Table 3:

Condition	V (fps)	β _{MAX} (deg)	q (psf)	S (ft²)	C _D	F _x (Lbs)	F _Y (Lbs)
Maneuver (V _A)	189	45	42.5	0.83	0.85	15	30
Gust (V _C)	270	20.4	86.8	0.83	0.85	8	61
Gust (V _D)	388	7.4	179	0.83	0.85	2	126
Landing (V _S)	83	45	8.14	0.83	0.85	3	6

2.9 <u>Limit Inertia Loading</u>

The Turret Weight used in this analysis is 35 lbs. The Support Assembly weight used is 5 lb. The Electronic Control Unit weight is 13 lb.

Resulting applied vertical load is computed based on the maximum N_z load factors found in sections 2.4, 2.5 and 2.6., by the following equation:

$$F_Z = -N_Z.(35)$$

2.10 Net Applied External Loads

The air loads and inertia loads for a component of maximum area and weight combined for each corner of the V-n diagram are shown in Table 3.

Table 3 - Net Limit Loads at Centroid of External Load

Case - Condition	F _x (lbs)	F _Y (lbs)	F _z (lbs)
1 - V _{A-positive}	15	30	-138
2 - V _{C-positive}	8	61	-197
3 - V _{D-positive}	2	126	-151
4 - V _{A-negative}	15	30	+55
5 - V _{C-negative}	8	61	+127
6 - V _{D-negative}	2	126	+81
7 - V _{S-Landing}	3	6	-72

These loads are applied at the center of area for the external load (~7.9 inches below the Support Mount Plate for the Talon installation).

Applied direct loads and Moments at evaluation locations are defined in the Calculations (MathCad Format) attached to this report. Annotations are contained in the calculations listing to define the purpose of calculations. These calculations are therefore not repeated in the body of this report.

Table 4 - Net Limit Loads at Mount Plate Surface Center

Case - Condition		Direct Loads			Torsional Moment		
	Nz	P _x (lbs)	P _Y (lbs)	P _z (lbs)	M _x (in-lbs)	M _Y (in-lbs)	M _z (in-lbs)
1 - V _{A-positive}	+3.93	15	30	-138	227	-114	0
2 - V _{C-positive}	+5.62	8	61	-197	463	-59	0
3 - V _{D-positive}	+4.32	2	126	-151	957	-16	0
4 - V _{A-negative}	-1.57	15	30	+55	227	-114	0
5 - V _{C-negative}	-3.62	8	61	+127	463	-59	0
6 - V _{D-negative}	-2.32	2	126	+81	957	-16	0
7- V _{S-Landing}	+2.05	3	6	-72	43	-22	0

These loads are representative of the FLIR Talon installation, 35 lb. Turret, 0.83 square feet projected area and 0.85 Drag Coefficient.

3.0 Allowables

3.1 Materials

All materials used in the design are specified by industry material specification with statistically based material strength properties included in the MMPDS (Ref. 1). For the analysis 'A' basis values are used for single member structural elements and 'B' basis values maybe used for redundant structure. Aerospace grade materials with proven methods of corrosion protection are used for the design so no special factors of safety are required to address uncertainty, deterioration or appreciable variability. The environmental temperatures in the area of the design are well within the allowable range for the aluminum structure used. Therefore, no correction is required to account of the effects of temperature.

Applicable material allowables from MMPDS for the materials used in the design are summarized in Table 5.

Table 5 – Material Allowables

Material	Туре	Specificatio n	F _{tu} (ksi)	F _{cy} (ksi)	F _{su} (ksi)	F _{bru} (ksi) e/D= 2	E (msi)	MMPDS
6061-T6	Sheet 0.010-0.249	AMS- QQ-A- 250/11	42	35	27	88	9.9	3.6.2.0(b ₁)
6061-T62 & T6511	Plate; 0.25-2.0 in.	AMS- QQ-A- 250/11	42	36	27	88	9.9	3.6.2.0(b ₂)
6061-T6, & T62	Tube and Pipe 0.025 - 0.50 Wall Thick	AMS- WW- T-700/6	42	34	27	88	9.9	3.6.2.0(c ₁)

Mechanical properties for the minimum strength direction are used unless otherwise noted. Bearing allowables are based on 2.0 e/D.

3.2 Fasteners

All fasteners used in the design are specified by military or industry specification with statistically based material strength properties included in the MMPDS or the fastener specification. The fasteners are aerospace grade which are well proven in this type of application. No special factors of safety are required to address uncertainty, deterioration or appreciable variability. The environmental temperatures in the area of the design are well within the allowable range for fasteners used and no correction is required to account of the effects of temperature.

Fastener allowables from MMPDS or the fastener specification are summarized in Table 6.

Table 5 – Material Allowables

Material	Туре	Specificatio n	F _{tu} (ksi)	F _{cy} (ksi)	F _{su} (ksi)	F _{bru} (ksi) e/D= 2	E (msi)	MMPDS
6061-T6	Sheet 0.010-0.249	AMS- QQ-A- 250/11	42	35	27	88	9.9	3.6.2.0(b ₁)
6061-T62 & T6511	Plate; 0.25-2.0 in.	AMS- QQ-A- 250/11	42	36	27	88	9.9	3.6.2.0(b ₂)
6061-T6, 8 T62	Tube and Pipe 0.025 - 0.50 Wall Thick	AMS- WW- T-700/6	42	34	27	88	9.9	3.6.2.0(c ₁)

Mechanical properties for the minimum strength direction are used unless otherwise noted. Bearing allowables are based on 2.0 e/D.

3.2 Fasteners

All fasteners used in the design are specified by military or industry specification with statistically based material strength properties included in the MMPDS or the fastener specification. The fasteners are aerospace grade which are well proven in this type of application. No special factors of safety are required to address uncertainty, deterioration or appreciable variability. The environmental temperatures in the area of the design are well within the allowable range for fasteners used and no correction is required to account of the effects of temperature.

Fastener allowables from MMPDS or the fastener specification are summarized in Table 6.

These loads are applied at the center of area for the external load (~7.9 inches below the Support Mount Plate for the Talon installation).

Applied direct loads and Moments at evaluation locations are defined in the Calculations (MathCad Format) attached to this report. Annotations are contained in the calculations listing to define the purpose of calculations. These calculations are therefore not repeated in the body of this report.

Table 4 – Net Limit Loads at Mount Plate Surface Center

Case - Condition		Direct Loads			Torsional Moment			
	Nz	P _x (lbs)	P _Y (lbs)	P _z (lbs)	M _x (in-lbs)	M _Y (in-lbs)	M _z (in-lbs)	
1 - V _{A-positive}	+3.93	15	30	-138	227	-114	0	
2 - V _{C-positive}	+5.62	8	61	-197	463	-59	0	
3 - V _{D-positive}	+4.32	2	126	-151	957	-16	0	
4 - V _{A-negative}	-1.57	15	30	+55	227	-114	0	
5 - V _{C-negative}	-3.62	8	61	+127	463	-59	0	
6 - V _{O-negative}	-2.32	2	126	+81	957	-16	0	
7- V _{S-Landing}	+2.05	3	6	-72	43	-22	0	

These loads are representative of the FLIR Talon installation, 35 lb. Turret, 0.83 square feet projected area and 0.85 Drag Coefficient.

3.0 Allowables

3.1 Materials

All materials used in the design are specified by industry material specification with statistically based material strength properties included in the MMPDS (Ref. 1). For the analysis 'A' basis values are used for single member structural elements and 'B' basis values maybe used for redundant structure. Aerospace grade materials with proven methods of corrosion protection are used for the design so no special factors of safety are required to address uncertainty, deterioration or appreciable variability. The environmental temperatures in the area of the design are well within the allowable range for the aluminum structure used. Therefore, no correction is required to account of the effects of temperature.

Applicable material allowables from MMPDS for the materials used in the design are summarized in Table 5.

Table 6 – Fastener Allowables

Fastener	Туре	Nominal Diameter (in)	Tension (lbs)	Single Shear (lbs)	Ref
MS27039-1-11	Screw	0.190	2500	2125	Specification MS27039
MS35207-264	Screw	0.190	1200	600 (1/2 Tension)	Specification MS35207
AN4-10A	Bolt, Steel	0.250	4080	3680	Specification AN3 – AN20
AN3-10A	Bolt, Steel	0.190	2210	2125	Specification AN3 – AN20
AN525-10	Screw, Washer Head	0.190	4780	2125	MMPDS, AN525 EngrsEdge.com Tensile Thrd Area
MS20426AD4 MS20470AD4	Rivet	0.125	N/A	319	26000 psi Mil-R-5674F

4.0 STRESS ANALYSIS

4.1 SX5-606-3 Support Plate




Figure 4 – SX5-606-1 Support Plate

Plate Material: 6061-T6 aluminum alloy Fsu = 27 ksi (A) 28 ksi (B)

Ftu = 42 ksi (A) 43 ksi (B) Ref. MMPDS, 3.6.2.0(b₁)

4.2 IR-1040 Mount Bracket




Figure 5 – Load Support Fixture (IR-1040-(X)

Note: SX5-606-1 (For FLIR Talon installation) is approximately centered in the channels shown above.




Figure 6 – Representative Load Support Installation: IR-431-1 Assembly (Gimbal attached to IR-4301-10 and SX5-606-1), IR-1040-(X), C182IR-1012-1




FIGURE 7, Guide Collar Detail




FIGURE 8, IR-4301-10 Plate

<u>Plate Material: 6061-T6 aluminum alloy</u> Fsu = 27 ksi (A) 28 ksi (B)

Ftu = 42 ksi (A) 43 ksi (B) Ref. MMPDS, 3.6.2.0(b₁)

	•	

Rept: ARS-4004-901 Page 1 of 3

Paravion Technology, Inc. Fort Collins, CO

Report No. ARS-4004-901

Structural Substantiation Equipment Installation

March 29, 2011

This report substantiates the installation of three pieces of equipment on the baggage compartment (FS 124 to FS134) shelf of a Cessna 182 aircraft. Figure 1 shows the equipment installation of the rails and the installation of the equipment on the rails.




Figure 1 – Equipment Installation

Each rail is installed with two screws to the forward end of the shelf and two screws to the aft angle of the baggage shelf. The IMU is attached to the rails using four feet as shown in Figure 2. The feet are locked in place using locking blocks and roll pins.




Figure 2 - Equipment Installation - Side View




Figure 3 - Equipment Installation - DETAIL

The baggage area is placarded for 80 lbs per Cessna Pilot Operating Handbook (POH). Therefore, the vertical load is not a concern for the shelf.

The most critical condition will be the emergency forward 18.0 g's per FAR 23.561.

Max. Weight of equipment = 37.0 lbs.

Max. C.G. of equipment above shelf = 8.0 inches

Horizontal Reaction $R_H = 18.0 \times 37.0 = 666 \text{ lbs.}$

This load is reacted primarily by two MS16998-31 screws in compression. The secondary load path is two MS16562-38 pins. We can conservatively assume that only the weaker of the two load path transfers load.

Single shear rating of each roll pin = 1050 lbs.

M.S. = (2*1050/666) - 1 = + HIGH

Vertical Reaction $R_V = (18.0 \text{ x}' 37.0 \text{ x} 8.0")/(10.25") = 520 \text{ lbs.}$

This load is reacted by the foot in two rails.

Shear area of foot = 0.07 in 2

Shear stress in foot fs = 520/2/0.07 = 3715 psi.

The foot is made using 6061-T6 aluminum, Fsu = 27000 psi.

$$M.S. = (27000/3715) - 1 = + HIGH$$

Load is transferred to baggage shelf using screws that attach the rails to shelf.

Tensile load on screws = $(18.0 \times 37.0 \times 8.0^{\circ})/(4*10.0^{\circ}) = 133 \text{ lbs}.$

Tensile Strength of MS35206 #8-32 screws (Ftu = 60 ksi) = 730 lbs.

$$M.S. = (730/133) - 1 = + HIGH$$

Based on positive strength margins of the installation, the equipment installation is adequate to meet the strength requirements of the aircraft.

PARAVION TECHNOLOGY, INC. 2001 AIRWAY AVENUE FT. COLLINS, COLORADO 80524


INSTRUCTIONS FOR CONTINUED AIRWORTHINESS AUGMENTED REALTIY SYSTEM INSTALLATION

This document is applicable to systems certificated under the following Supplemental Type Certificates:

SR00682DE

The above certification documents include approval for Augmented Reality System (ARS) installation to the following aircraft:

Bell 206A/B Bell 206L, L-1, L-3, L-4 Bell 407 Page A PR-ARS-120M Rev. 1, 04/08/08



RECORD OF REVISIONS

REVISION NO.	ISSUE DATE	DATE INSERTED	ВҮ
0	Not Distributed		
1			
		-	

REVISION CONTROL PROCEDURE

Revisions to this document are mailed to owner of record. Before inserting a change, ensure this manual is correct. Check the existing List of Effective Pages in this manual to ensure that all prior revisions are inserted. Do not insert this revision if prior revisions are not inserted.



LIST OF EFFECTIVE PAGES

PAGE NO.	REVISION	DATE
COVER	1	04/08/08
A	1	04/08/08
i	1	04/08/08
ji	I	04/08/08
1]	04/08/08
2	1	04/08/08
· 3	1	04/08/08
4	1	04/08/08
5	1	04/08/08
6]	04/08/08
7	1	04/08/08
8	1	04/08/08
9	1	04/08/08
10	1	04/08/08
11	1	04/08/08
12]	04/08/08
A-1	1	04/08/08
A-2	1	04/08/08
B-1	1	04/08/08
		· · · · · · · · · · · · · · · · · · ·
<u> </u>		

Page ii PR-ARS-120M Rev. 1, 04/08/08



TABLE OF CONTENTS

TABLE OF CO AIRWORTHIN 1.0 SYSTEM 2.0 INSPECTI 3.0 COMPON 4.0 COMPON	CTIVE PAGES	PAGE A i i i 2 3 3 4
TABLE I II	LIST OF TABLES WEIGHT & BALANCE DATA TROUBLESHOOTING PROCEDURES & LED DEFINITIONS	<u>PAGE</u> 2 4
FIGURE 0 1 2	LIST OF FIGURES CONFIGURATION: SYSTEM INSTALLATION AIRCRAFT-SIDE WIRE HARNESS CONTROLLER INSTALLATION	<u>PAGE</u> 8 9 11
<u>appendix</u> A B	LIST OF APPENDICES STANDARD TORQUE VALUE CHART PERIODIC INSPECTION CHECKLIST	APPENDIX A APPENDIX B

ADDITIONAL REFERENCE

AC43.13-2B Acceptable Methods, Techniques and Practices - Aircraft Alterations



AIRWORTHINESS LIMITATIONS

The Airworthiness Limitations Section is FAA approved and specifies inspections and other maintenance required under §§ 43.16 and 91.403 of the Federal Aviation Regulations unless an alternative program has been FAA approved.

No airworthiness limitation associated with this type design change.

This system has no life-limited components.

REVISION	DATE	APPROVED
0	03/20/08	
j i	04/08/08	

Page 2 PR-ARS-120M Rev. 1, 04/08/08



1.0 SYSTEM DESCRIPTION

The Paravion Technology, Inc./Churchill Navigation Augmented Reality System (ARS) is an accessory to certain infrared and visible light imaging system installations installed under separate certification, to add display of parcel and address overlay information to the monitor screen. The Augmented Reality System is operated by the assigned observer in accordance with imaging system certification instructions.

This accessory to the previously certificated imaging system is designed as an aid to surveillance operations, requires no pilot action, and is non-essential to safety-of-flight.

The ARS uses GPS input, to determine imaging system location and viewpoint. Touch screen commands are used to enable its various options (See Users Handbook). It is designed to consume less than 4.5 amp (28VDC), and to be powered through the imaging system circuit breaker.

1.1 The ARS installation includes the following major components:

- A. Controller Assembly, 6 lbs. (2.7 kg)
- B. Serial Bypass Switch, 1.2 lbs. (0.5 kg)
- C. Inertial Measurement Unit, 5 lbs. (2.2 kg)
- D. GPS Antenna, 0.3 lbs. (0.1 kg)
- E. Cables Installation, est. 3 lbs. (~1.4 kg estimate)
- F. Monitor Mount Installation (Ref.), 1.7 lbs. (0.8 kg)
- G. Monitor Assembly (Ref. DBM-100-5T), 5.3 lbs (2.4 kg)

TABLE I

WEIGHT & BALANCE DATA					
		LONGITUDINAL		LATERAL	
ІТЕМ	WEIGHT (lbs)	F.S. (in)	MOMENT (in-lbs)	B.L. (in)	MOMENT (in-lbs)
ARS-4000 Controller Assembly	6.0				
ARS-3500 Serial Bypass Switch	1.2				
ARS-3600 IMU ASSEMBLY	5.5				
GPS Antenna	0.3				
Cables Installation	3				
Monitor Installation	7				

Note: This table is to be completed upon system installation.

Component Weight & Balance data completed	Date:
	<u>Aircraft</u>
	By



2.0 INSPECTION AND MAINTENANCE

It is the objective of this inspection and maintenance procedure to ensure that component installations are secure and that the electrical system is airworthy. Table II, TROUBLE SHOOTING GUIDE, refers to the most likely problems that may be encountered, and outlines the appropriate corrective actions. Appendix B, Inspection Checklist should be referenced during periodic Airworthiness inspections. All loose and/or replaced fasteners should be tightened per the torque requirements outlined in Appendix A.

3.0 COMPONENT REMOVAL AND REPLACEMENT

The major components of the ARS (Controller Unit and Inertial Measurement Unit) are mounted in the baggage area of the aircraft, in accordance with certificated installation data. The monitor is mounted for operation by observer in accordance with certificated installation data. The GPS antenna is mounted to the aircraft exterior in accordance with approved data.

Electrical power for the Augmented Reality System is obtained from the power supply installed to provide power to the imaging system to which the system has been added. Data transmission wiring is routed to the monitor and imaging system according to aircraft requirements in accordance with certificated ARS installation data.

Assure that imaging system power supply is switched to OFF and that electrical wires are disconnected and capped before removing any component of the system.

Component removal/re-installation order does not affect system performance after completion of the work.

NOTE: When mounting components are removed and replaced, follow torque recommendations given in Appendix A for fastener installation. Remove installed wire caps and re-install wiring. Refer to AC43.13-2B guidelines for installation of GPS antenna and other alterations as needed.

4.0 COMPONENT SERVICE PROCEDURE

If troubleshooting results in the finding of faults in the system components the Augmented Reality System must be disabled before the faulty unit is removed. Aircraft Weight and Balance should be adjusted accordingly, reference Table I of this document. The faulty component must be returned to Paravion Technology, Inc. for repair or replacement.



5.0 SYSTEM TESTING/TROUBLESHOOTING PROCEDURES


TABLE II TROUBLE SHOOTING GUIDE

PROBLEM	ADDITIONAL SYMPTOMS	POSSIBLE CAUSE	CORRECTIVE ACTION
No video.	Cooling fans do not run	No power to ARS	Ensure that the aircraft is providing power to the ARS.
	Cooling fans may or may not run	ARS internal breakers	Ensure that the 3 circuit breakers mounted to the ARS unit are not tripped. If tripped, reset. If circuit breaker fails to reset, remove ARS unit from aircraft and send to Paravion for service.
	Cooling fans run, no beeping sound as unit powers on, no lights on IMU	12V power supply breaker blown	Reset breaker. If problem persists, remove ARS Controller unit and IMU from aircraft and send to Paravion for service.
	Cooling fans	Monitor off	Ensure monitor is ON
	running	Proper video input not selected	Press "Source" on the monitor until video is shown (usually with the on-screen designation "PC" or "VGA")
		Video wiring	Inspect video wiring from ARS to monitor.
Video shows ARS controls, but no camera		Camera off or camera in standby Video wiring	Turn camera ON and wait for initialization to complete. Ensure camera is operational. Inspect video wiring from camera to ARS.
video.			
Video indicates "NO CAMERA"		Camera off or camera in standby	Turn camera ON and wait for initialization to complete. Ensure camera is operational.
		Serial connection from camera is bad	Inspect wiring between camera serial port output and ARS.
		ARS Controller Unit internal	Remove unit from aircraft and return to Paravion for service.
		component or wiring faulty,	Field repair of the ARS Controller Unit should not be attempted.
		possible software fault.	



PROBLEM	ADDITIONAL SYMPTOMS	POSSIBLE CAUSE	CORRECTIVE ACTION
Camera does not turn on or hand	Hand controller backlight is off.	No power to camera	Ensure camera has aircraft power.
controller is unresponsive.	·	Hand controller wiring bad	Inspect wiring between hand controller and camera. If plugging the hand controller directly in to the camera solves the problem, then inspect aircraft-side wiring and replace as necessary. System will be usable in this state, but geo-pointing functions (if available) will not work.
	Hand controller backlight is on. Serial Bypass Switch (ARS- 3100-1) has no LEDs lit.	Serial Bypass Switch does not have power.	Inspect wiring between Serial Bypass Switch and camera. Ensure power is available on the bypass switch (pin 1=ground, pin 2=+5v DC +/- 10%). As a temporary solution, the hand controller may be plugged directly in to the camera, or a plug shorting pins 3 and 9 may be used in place of the serial bypass switch, but geopointing functions (if available) will not work.
		Serial Bypass Switch has failed	Disconnect the serial bypass switch and manually short pins 3 and 9 on the cable harness. Do not touch pin 2 (+5v power). If the camera can be turned on, then replace the serial bypass switch. As a temporary solution, the hand controller may be plugged directly in to the camera, or a plug shorting pins 3 and 9 may be used in place of the serial bypass switch, but geopointing functions (if available) will not work.
	Hand controller backlight is on. Serial bypass switch has one LED lit.	Wiring bad	Inspect wiring between hand controller, serial bypass switch, and camera. If plugging the hand controller directly in to the camera solves the problem, then inspect aircraft-side wiring and replace as necessary. The system will be usable in this state, but geo-pointing functions (if available) will not work.
		Serial bypass switch has failed	Disconnect the serial bypass switch and manually short pins 3 and 9 on the cable harness. Do not touch pin 2 (+5v power). If the camera can be turned on, then replace the serial bypass switch. As a temporary solution, the hand controller may be plugged directly in to the camera, or a plug shorting pins 3 and 9 may be used in place of the serial bypass switch, but geopointing functions (if available) will not work.

Page 6 PR-ARS-120M Rev. 1, 04/08/08



PROBLEM	ADDITIONAL	POSSIBLE	CORRECTIVE ACTION
Video indicates	SYMPTOMS	IMU not	The aircraft must move at least 10 knots before
"INVALID		initialized	the IMU initializes.
IMU"		No GPS signal	Ensure that the GPS antenna has an unobstructed view of the sky. The IMU will not work inside a hanger.
		GPS antenna is connected improperly	Ensure that the antenna is connected to IMU connector marked "Primary" and not the one marked "Secondary".
		GPS antenna and/or cable is faulty	With the aircraft outside and the ARS powered ON for at least 5 minutes, verify that the GPS light on the IMU is red or orange. No light indicates that the antenna, antenna cable, or IMU is bad and should be replaced.
Video indicates "NO IMU"	·	No signal from IMU	Ensure that the data cable (marked "Ethernet" on the IMU) is securely connected.
		lMU has no power.	If the IMU "Power" LED is not on, then verify wiring. Power cable should have 9-15 volts.
		IMU Failure	If the power cable has 9-15 volts and the IMU "Power" LED remains off, then replace the IMU. Contact Paravion Technology, Inc. for system recalibration instructions.
Touch screen not responsive		Wiring bad	Inspect wiring between touch screen and ARS.
Touch screen inaccurate	Fingers operate incorrect button, or finger must be in the wrong place to operate button	Touch screen needs recalibration	Contact Paravion Technology, Inc. for touch screen calibration instructions.
Road/Video alignment poor		Camera mount and/or IMU have been moved with respect to airframe since last calibration.	Contact Paravion Technology, Inc. for system calibration instructions.



IMU (ARS-3600-1): LED Definitions:

LED	Color	Condition	
	Off	IMU Booting	
	Red Flash	Running, but not yet operational. GPS has not yet output a valid time.	
SdNav	Red	Running, but not yet operational. GPS has a valid time, but has not initialized. Waiting for the vehicle to travel > 5 m/s.	
Orange Green		Operational, but data is not yet real-time. This condition should not last more than 10 seconds.	
		Operational.	
	Off	Off GPS does not have a valid position.	
GPS Red Flash Operational check (startup only)		Operational check (startup only)	
GPS [Red	GPS has a standard position solution (SPS). This is the default state.	
Orange GPS has a differential solution (SBAS). Th		GPS has a differential solution (SBAS). This is normally not used.	
	Off	No power to the system.	
Power	Green	System is powered; 5v internal voltage is active.	
rowei	Orange	System is powered; Outputting data to serial port. This is normally not used.	

FIGURES




FIGURE 0: Suggested Installation, Bell 407 shown







FIGURE 1: Aircraft-Side Wire Harness FLIR U8000/U8500 SERIES IMAGING SYSTEM

Page 10 PR-ARS-120M Rev. 1, 04/08/08



COMPONENTS, FIGURE 1

ITEM NO	PN	DESCRIPTION	OTY.	<u>TYP</u>
0*		Existing Imaging System Circuit Breaker	REF	
1	ACC02E16-9S-003	CONNECTOR (Blkd Receptacle)	1	EA.
2	ARS-3600-1	INERTIAL MEASUREMENT UNIT	3	EA.
3	ES54100-2	ANTENNA, GPS	1	EA.
4	ARS-3500-1	SERIAL BYPASS SWITCH	1	EA.
5	MS27474E20F41S	CONNECTOR (Blkd Receptacle)	}	EA.
	M85049/41-12A	BACKSHELL		
6	ARS-3100-1	CABLE, PASS-THRU	1	EA.
7	ARS-3011-1	VIDEO CABLE ASSY	}	EA.
8	ARS-3011-2	TOUCHSCREEN CABLE ASSY	1	EA.
9	ARS-3010-1	POWER CABLE ASSY, IMU	1	EA.
10	ARS-3010-2	SIGNAL CABLE ASSY, IMU	}	EA.
11	ES56221-1	MONITOR POWER CABLE	1	EA.
12	ES58110-1	FUSE HOLDER	1	EA.
	AGC-3	FUSE, 3 AMP]	EA.
13	MS27467T15B18P	CONNECTOR	1	EA.
	M85049/49-2-14W	BACKSHELL	1	EA.
14	AIM-97095	CONNECTOR (Or equiv. DE-9 Female)	1	EA.
15	MS27467T9B35P	CONNECTOR	1	EA.
	MS27506-B-9-2	BACKSHELL (Alt: MS27506-F-9-2)	1	EA.
16	V75268	75 OHM COAXIAL CABLE (Or equiv.)	15	FT.
ATTACHING	G HARDWARE,			
-	ARS-3600-2	HAT SECTION ASSEMBLY	2	EA.
-	MS20470AD4-X	RIVET (Length may vary)	16	EA.
-	MS35206-08XX	SCREW	4	EA.
-	NAS1149CN616R	WASHER	4	EA.
-	MS27039-08XX	SCREW (Length may vary)	4	EA.
-	MS21042L08	SELF LOCKING NUT	4	EA.
-	MS35206-XXX (#4-4	0)SCREW (Length may vary)	4	EA.

WIRING SPECIFICATION:

Circuit Breaker rating must be 20A or lower

System electrical power and ground, Connector 1 Pins A and C, are M22759/16-14 or equivalent.

All other (data transmission) wires are M22759/16-22 or equivalent

NOTE: The Inertial Measurement Unit, Serial Bypass Switch, & GPS Antenna are supplied as Line Replaceable Units, assembled and calibrated at the factory. Field maintenance of these units should not be attempted.







FIGURE 2: Augmented Reality System Controller Installation



COMPONENTS, FIGURE 2

ITEM NO	PN	DESCRIPTION	OTY	TYP
1	ARS-4000-1	CONTROLLER ASSEMBLY	1	EA.
2	MS27484E20F41PN	CONNECTOR	1	EA.
3	ACC02E16-9S-003	CONNECTOR	1	EA.
ATTACHIN	G HARDWARE,			
• •	MS27039-08XX	SCREW (Length may vary)	4	EA.
-	MS35333-106	LOCK WASHER	4	EA.

<u>NOTE</u>: The Controller Assembly is supplied as a Line Replaceable Unit, assembled and calibrated at the factory. Field maintenance of the unit must not be attempted.



APPENDIX A STANDARD TORQUE VALUE CHART



Appendix A

RECON	MENDED TORQUE VA	LUES (inch-pounds)	
(Refe	rence AC 43.13-1B, Chang	e 1, Dated 9/8/98)	
	CAUTION		
			BLE TIGHTENING
•	S LOADED PRIMARILY IN	TORQUE LIMITS	
			Nuts: MS20364,
			MS21245, MS17826,
			AN320
(40,000 psi in bolts)			(54,000 psi in bolts)
		RIES	
12-15	7-9	20	12
20-25	12-15	40	25
50-70	30-40	100	60
100-140	60-85	225	140
160-190	95-110	390	240
450-500	270-300	840	500
480-690	290-410	1100	660
800-1000	480-600	1600	960
1100-1300	600-780	_2400	1400
2300-2500	1300-1500	5000	3000
2500-3000	1500-1800	7000	4200
3700-5500	2200-3300*	10,000	6000
5000-7000	3000-4200*	15,000	9000
9000-11000	5400-6600*	25000	15000
	COARSE THREAD S	SERIES	·
12-15	7-9	20	12
20-25	12-15	35	21
40-50	25-30	75	45
80-90	48-55	160	100
160-185	95-100	275	170
235-255	140-155	475	280
400-480	240-290	880	520
500-700	300-240	1100	650
700-900	420-540	1500	900
1150-1600	700-950	2500	1500
2200-3000	1300-1800	4600	2700
	(Refe LLOWING TORQUE VA TORQUE LIMITS RECO INSTALLATION (BOLT: SHEAR) Tension type nuts: MS20365, MS21042, MS17825, AN310 (40,000 psi in bolts) 12-15 20-25 50-70 100-140 160-190 450-500 480-690 800-1000 1100-1300 2300-2500 2500-3000 3700-5500 5000-7000 9000-11000 12-15 20-25 40-50 80-90 160-185 235-255 400-480 500-700 700-900 1150-1600	(Reference AC 43.13-1B, Change CAUTION LLOWING TORQUE VALUES ARE DERIVED FROM TORQUE LIMITS RECOMMENDED FOR INSTALLATION (BOLTS LOADED PRIMARILLY IN SHEAR) Tension type nuts: Shear type nuts: MS20365, MS21042, MS20364, MS21245, MS17825, AN310 (24,000 psi in bolts) FINE THREAD SE 12-15 7-9 20-25 12-15 50-70 30-40 100-140 60-85 160-190 95-110 450-500 270-300 480-690 290-410 800-1000 480-600 1100-1300 600-780 2300-2500 1300-1500 2500-3000 1500-1800 3700-5500 2200-3300* 5000-7000 3000-4200* 9000-11000 5400-6600* COARSE THREAD SE 12-15 7-9 20-25 12-15 40-50 25-30 80-90 48-55 160-185 95-100 235-255 140-155 400-480 240-290 500-700 300-240 700-900 420-540 1150-1600 700-950	TORQUE LIMITS RECOMMENDED FOR MAXIMUM ALLOWA INSTALLATION (BOLTS LOADED PRIMARILY IN SHEAR) Torque Limits Shear type nuts: Ms20365, Ms21042, Ms20364, Ms21245, Ms20365, Ms21042, Ms17826, AN320 (40,000 psi in bolts) (24,000 psi in bolts) (90,000 psi in bolts) FINE THREAD SERIES

The above torque values may be used for all cadmium-plated steel nuts of the fine or coarse thread series which have approximately equal number of threads and equal face bearing areas.

This table includes standard nut and bolt combinations, currently used in aviation maintenance. For further identification of hardware, see AC 43.13-1B, Chapter 7.

^{*} Estimated corresponding values.



APPENDIX B

ANNUAL/300 HR. INSPECTION CHECKLIST

	INSPECTION (Infrared Camera System)	COMMENTS	INITIALS
1.	Check for mount fasteners security (GPS antenna and other exterior installations, interior installations). Inspect equipment and adjacent aircraft structure for condition.		
2.	Torque all fasteners in accordance with Appendix A.		
3.	Inspect electrical cabling for security and insulation damage. Evaluate cable routing to avoid heat and movement.		
4	Inspect Controller Assembly and surrounding area for airflow obstruction. Clean heat radiation surfaces as needed. Verify cooling fans operation.		

	,			
·				

Form Approved

U.S Departm							ND ALTERA		11/30/		20-0020		
Transportatio Federal Avia	on	(/	Airfr	ame, Pov	verplan	t, P	ropeller, or A	Appliance)			For F	FAA Use Only	
Administration					•								
and disc	UCTIONS: Printsposition of this hauch violation	form. This	is repo	ort is required b	by law (49 L	U.S.C	Appendix B, and AC C. 1421). Failure to	243.9-1 (or subsection report can result in	quent revi n a civil p	ision t enalty	hereof) for in not to exce	nstructions ed \$1,000	
	IUSA	ality and R N267R		ration Mark				Serial No. 18282208					
1. Aircraft	Make CESSNA							Model 182T			Series SKY	s 'LANE	
				egistration cert				Address (As show	vn on regi	stratio	on certificate)	
2. Owner	CES	3NA AIF	₹CR∕	AFT COMF	,ANA			Address ATTN: I				State KANSAS	<u> </u>
							3. For FAA Use O	zip <u>67215-1400</u> nlv	<u> </u>		Country_US/	<u> </u>	
4.	. Type		_				5. L	Init Identification					
Repair	Alteration		Un	nit		Make Model		del			Serial Number		
		AIRFR	AME		_			(As described in	n Item 1 a	bove)			
		POWE	RPLA	ANT									
		PROPE	ELLE	R								· · ·	
		APPLIA	₹NCE	:	Type Manufacture	rer						11 - Sec. 11 - 12 - 12 - 12 - 12 - 12 - 12 - 12	
						6	i. Conformity Stat	ement					
	's Name and Ad						(ind of Agency						
	SLING AVIA]		U.S. Certificated I			لتل	Manufactur Certificate N		
Address <u>ZU1</u> City <u>WICHI</u>	10 AIRPORT	I KUAL	ī	ملاو	ŀ		Foreign Certificate				I8R621Y	10.	
			10.4	State <u>KS</u>	}	Ø				RADIO CLASS 1,2,3			
have	tify that the repa	accordance	alterati ce with	h the requirem	nents of Part	rt 43 c	Certificated Maint ed in item 5 above of the U.S. Federal		the revers	se or a	attachments	hereto	
Extended ra		rue anu co	rrect				ed Individual	,	-				
Арр. В				Cla	exilo(S	nes Ix	3/26/	18_				
			_		7	/. Ap	proval for Return	to Service					
	t to the authority rator of the Fed			•		_	tified in item 5 was I PROVED RE	Inspected in the magnetic in t	anner pre	scribe	d by the		-
ву	FAA Flt Star Inspector	ndards		Manufacture	r		Maintenance Orga	anization		•		proved by Canadian it of Transport	i
БТ	FAA Designe	ee	Х	Repair Statio	nc		Inspection Author	ization	C	Other	(Specify)		
Certificate o Designation YN8R62	n No.		Sign	nature/Date of	Authorized	Indiv	idual		26/1	10			

NOTICE

(if more space is required, attach additional sheets.	Identify with aircraft nationality and registration r	nark and date work completed.)
	USA N267RH	3/26/10
	Nationality and Registration Mark	Date
Cessna 182T–18282208– N267RH		
INSTALLED SYSTEMS: • Installed Yingling Aviation Installation of	of Cabin Skylights IAW STC SA01569WI	,
 CONTINUED AIRWORTHINESS INSTRUCT Reference Yingling Aviation Document Installation of Skylights in the Cessna 18 	No. 5640-F182-06 Rev. A, for Instruction	s for Continued Airworthiness
WEIGHT & BALANCE and EQUIPMENT LI Weight & Balance records for details.	IST: Revised Aircraft Weight & Balance a	nd Equipment List. See Aircraft
The above installation meets the requirements for through 114. No changes were noted to the compaNVI 10069.		
>>>>>>>>>	END<	

U.S Department of Transportation
Federal Aviation Administration

MAJOR REPAIR AND ALTERATION

Form Approved OMB No. 2120-0020 11/30/2007

U.S Departr	ment of	,	A :	Da		4 F	D		A	11/00/2007	<u> </u>
Transportati Federal Avi	ion	(.	АІП	rame, Po	werpia	пі, г	горе	eller, or <i>i</i>	Appliance)		For FAA Use Only
Administra							_				
and dis		form. Thi	is rep	ort is required	by law (49	U.S.0					thereof) for instructions y not to exceed \$1,000
	IUSA	Nationality and Registration Mark USA N5267RH							Serial No. 18282208		
1. Aircraft	Make CES	SNA							Model 182T		Series SKYLANE
Name (As shown on registration certificate) CESSNA AIRCRAFT COMPANY							Address (As shown on registration certificate) Address ATTN: DEPT 093 3 CESSNA BLVD City WICHITA State KANSAS Zip67215-1400 Country USA				
							3. For	FAA Use O	nly		
4	. Type	<u> </u>						5. U	nit Identification		
Repair	Alteration		υ	nit			Make		Model		Serial Number
		AIRFR	AME		_				(As described in Ite	m 1 above)	
		POWE	RPL/	ANT							
		PROPE	ELLE	R							
		APPLIA	ANCE	=	Type Manufacturer						
						6	. Conf	ormity State	ment		
	s Name and Ad					B. K		Agency			
	SLING AVIA						+	Certificated M			Manufacturer
ddress <u>201</u> ity <u>WICHI</u>	10 AIRPORT	ROAD	<u>)</u>	a K0		무	 	on Certificate		Certificate No.	
ip <u>67277</u>	117		1C A	State <u>KS</u>			 -		epair Station YN8R621Y RADIO CLASS 1,2,3		
D. I certi	ify that the repa been made in shed herein is t	accordanc	alterat	h the requirem	ents of Pa	rt 43 c	ed in ite	em 5 above a	enance Organization and described on the r Aviation Regulations a	everse or a	ttachments hereto
xtended ra er 14 CFR	ange fuel		J1,666	Signature/I		<u> </u>	ed Indiv	ridual	3/26/10		
						7. Ap	provaí	for Return t	ó Service		
	to the authority rator of the Fed	•		•	R		ified in : PROVE		espected in the manne ECTED	er prescribe	d by the
BV	FAA FIt Star	dards		Manufacture			Mainte	enance Orga	nization		Person Approved by Canadian Department of Transport
BY -	FAA Designe	ee	х	Repair Statio	'n		Inspec	ction Authoriz	zation	Other (Specify)
ertificate o esignation N8R62	No.		Sign	nature/Date of	Authorized	Indivi	ridual		3/26/10		

N	0	~	\sim	
N			C	-

Description of Work Accomplished		
(If more space is required, attach additional sheets. Id	dentify with aircraft nationality and registration n	nark and date work completed.)
	USA N267RH	3/26/10
	Nationality and Registration Mark	Date
essna 182T–18282208– N267RH		
NSTALLED SYSTEMS: • Installed Yingling Aviation Installation o	f Cabin Skylights IAW STC SA01569WI	
 ONTINUED AIRWORTHINESS INSTRUCT Reference Yingling Aviation Document I Installation of Skylights in the Cessna 183 	No. 5640-F182-06 Rev. A, for Instructions	s for Continued Airworthiness
VEIGHT & BALANCE and EQUIPMENT LIST /eight & Balance records for details.	ST: Revised Aircraft Weight & Balance and	nd Equipment List. See Aircra
he above installation meets the requirements for rough 114. No changes were noted to the compa VI 10069.		
	:	
>>>>>>>	END<<<	
	•	
П	Additional Sheets Are Attached	

U.S Department of Transportation
Federal Aviation

Form Approved OMB No. 2120-0020

U.S Depa	dmant of							NU ALIEKA		11/30/200	7		
Transportation (Airframe, Power) Federal Aviation Administration							nt, P	ropeller, or <i>i</i>	Appliance)		For FAA Use Only		
and c	disposition	of this i	form. This	s repo	ries. See FAF rt is required t ederal Aviation	v law (49	U.S.C	Appendix B, and A C. 1421). Failure to	2 43.9-1 (or subseque report can result in a	ent revision civil penal	thereof) for in ty not to excee	estructions ed \$1,000	
1 Airon			ality and R N267RH		ration Mark				Serial No. 18282208				
i. Aircra	1. Aircraft Make CESSNA								Model 182T		Series SKYL	LANE	
2. Owne	er				egistration cert AFT COMF								
							;	3. For FAA Use O	nly		.,,		
	4. Type							5. L	init Identification				
Repair	r Alte	ration	Unit			P	Make Model			Serial Number			
. 🗆		X	AIRFRAME -					(As described in It	em 1 above	9)			
	[POWERPLANT										
			PROPE	PROPELLER									
			APPLIA	NCE		Type Manufactu	ırer						
							6	. Conformity Stat	ement				
	y's Name						B. K	(ind of Agency					
	IGLING							U.S. Certificated I	Mechanic		Manufacture		
	010 AIR	PORT	ROAD	<u>!</u>	140			Foreign Certificate	ed Mechanic		Certificate No). 	
city <u>WICI</u> zip <u>6727</u>			CountryU	SA	State <u>KS</u>			Certificated Repa	r Station enance Organization	R	YN8R621Y RADIO CLASS 1,2,3		
D. I ce	ertify that t	nade in	ir and/or a	lterati e with		ents of Pa	dentific art 43 c	ed in item 5 above	and described on the Aviation Regulations	reverse or		nereto	
Extended	range fue R Part 43					pate of Au	thorize		126/19				
					specified belo	w, the uni	ident		nspected in the mann	ner prescrib	ped by the		
	FAA Inspe	Fit Stan	dards		Manufacture			Maintenance Orga	anization			roved by Canadian of Transport	
BY -	FAA	Designe	ee	X	Repair Statio	n		Inspection Author	zation	Other	Other (Specify)		
Certificate Designation	on No.			Sign	ature/Date of	Authorizer	d Indiv	idual	3/20./10				

		USA N267RH	3/26/18
		Nationality and Registration Mark	Date
ESSNA 182T –182	82208- N267RH		
		for future install of an Aileron Servo Disable A #1, GIA #2 and the Avionics Dimming Po	
EFERENCES: O Number 182-0364 essna Drawing 3924 essna Drawing 0797	163 dated 5/28/09		
C43.13-1B			
urther details are on	file at C.R.S. # YN8R6	21Y under W.O. # AVI 10069.	
	>>>>>>	>>>>>END<	

U.S Department of Transportation
Federal Aviation

Form Approved OMB No. 2120-0020

U.S Departn	ment of						NUALIE			11/30/2	007		ļ		
Transportation (All Harrie, Power pla							ant, Propeller, or Appliance)				For FAA Use Only			У	
and dis	sposition of th	is form. Thi	s repo	ries. See FAF ort is required l dederal Aviatio	ov law (49	U.S.C	Appendix B, a C. 1421). Faile	nd AC ure to r	43.9-1 (or subsection can result in	quent revis n a civil pe	ion th	ereof) for in: not to excee	structions ed \$1,000		
4 Aircraft	US.	onality and f A N267R		ration Mark			Serial No. 18282208								
1. Aircraft	Mak	e SSNA					Model 182T			Series SKYL					
2. Owner	Name (As shown on registration certificate CESSNA AIRCRAFT COMPANY										n on registration certificate) DEPT 093 3 CESSNA BLVD State KANSAS 0 Country USA				
							3. For FAA L	Jse On							
4	l. Type							5. U	nit Identification					W-1	
Repair	Alteratio	1	Unit				Make		Mod	del		Serial Number			
	Ø	AIRFR	IRFRAME				····	69	(As described in	(As described in Item 1 above)					
		POWE	RPLA	ANT		***									
		PROPI	ELLE	R											
		APPLIA	ANCE		Type Manufactu	irer									
						6	. Conformity	State	ment						
	's Name and					B. K	(ind of Agency	y							
	GLING AV						U.S. Certific	ated M	lechanic			Manufacture			
	10 AIRPO	RT ROAL	<u>)</u>				Foreign Cer	tificate	d Mechanic			ertificate No). 		
city <u>WICH</u> zip <u>67277</u>		Country <u>l</u>	ISA	State <u>KS</u>			Certificated		Station nance Organizati	00	YN8R621Y RADIO CLASS 1,2,3				
D. I cert	tify that the re	pair and/or in accordan	alterat		ents of Pa	dentifi rt 43 d	ed in item 5 a	bove a	nd described on t	he reverse			nereto		
Extended raper 14 CFR App. B	ange fuel				Date of Au	thorize	ed Individual	0	3/26/10			<u> </u>	***************************************		
				specified belo Iministration a	w, the unit	ident		eturn t	o Serviće spected in the ma	anner pres	cribed	by the			
D./	FAA Fit S Inspector	tandards		Manufacture	r		Maintenance	e Orga	nization				oved by Car of Transport		
BY -	FAA Desi	gnee	X	Repair Statio	ın		Inspection A	uthoriz	Other (S			Specify)			
Certificate of Designation	n No.		Sign	nature/Date of	Authorized	d Indiv	vidual		3/1/10	<u> </u>					

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8. Description of Work Accomplished		· · · · · · · · · · · · · · · · · · ·
	eets. Identify with aircraft nationality and registration	mark and date work completed.)
		3/24/10
	USA N267RH	Date
	Nationality and Registration Mark	Date
CESSNA 182T –18282208– N267RH		
INSTALLED SYSTEMS: The following a SA01552WI. Amendment date November 1	vionics equipment was installed IAW Yingling 2, 2009.	Aviation STC Number
Audio Radio Interface, 3 ea Sandia Card En	(A711) Expansion Panels, NAT Audio Control colosures (SRU-1), 3 ea Sandia Relay Cards (SR Marker Beacon Antenna Splitter CI509, and 2 ea	-54), KGS Model RG28 DC to
OPERATIONAL GROUND CHECKS : Reproperly.	Required ground tests were performed and all eq	uipment was found to operate
CONTINUED AIRWORTHINESS INST C for Instructions for Continued Airworthin	RUCTIONS: Reference Yingling Aviation Documents.	cument ICA 23507-F206-04 Rev
WEIGHT & BALANCE and EQUIPMENT Weight & Balance records for details.	NT LIST: Revised Aircraft Weight & Balance a	and Equipment List. See Aircraft
AFMS: FAA Approved Flight Manual Supp 12, 2009 inserted in the Airplane Flight Man	olement Doc. No. AFMS Document 23507-F200 nual.	6-08, Rev. A, dated November
	ats for static loading in accordance with A.C.43. compass system. Further details are on file at C.	
>>>>>>	>>>>>END<	

Additional Sheets Are Attached

U.S Department of Transportation
Federal Aviation Administration

Form Approved OMB No. 2120-0020

US Caracter							NU ALIER		11/30/2	007		
U.S Departm Transportation	าก	()	Airfr	ame, Pov	verplai	nt, P	ropeller, c	or Appliance)		For FAA		AA Use Only
Federal Avia Administrati								•				
and dis	position of this	form. This	s repo		y law (49	U.S.C		AC 43.9-1 (or subseque to report can result in				
1. Aircraft		ality and F N267RI		ation Mark				Serial No. 18282208				
i. Aircrait	Make CES	SNA						Model Series SKYLANE			ANE	
2. Owner		Name (As shown on registration certificate) CESSNA AIRCRAFT COMPANY						Address (As shown on registration certificate) Address ATTN: DEPT 093 3 CESSNA BLVD City WICHITA State KANSAS				
								zip <u>67215-14</u> 0	400 country <u>USA</u>			
						:	3. For FAA Us	e Only				
							···········	· .				
4.	Туре				<u> </u>			5. Unit Identification				
Repair	Alteration	Unit					Make	Mode	Model			Serial Number
		AIRFRAME						(As described in Item 1 above)				
		POWE	POWERPLANT									
		PROPE	ELLE	R								
		APPLIA	NCE		Type Manufacturer							
							. Conformity S					
	s Name and A						(ind of Agency			= 1		
	LING AVIA						U.S. Certificat			C Cedil		
CityWICHI	0 AIRPOR	I RUAL	<u>,</u>	StateKS	•		 	cated Mechanic		C. Certificate No. YN8R621Y		
zip <u>67277</u>	шД	Country <u>L</u>	10 1	StateIXO			Certificated R	·	RADIO CLASS 1.2.3			
D. I certi have	been made in	air and/or a	alterat		ents of Pa	irt 43 d	ed in item 5 abo	aintenance Organization ove and described on the eral Aviation Regulation	e reverse			ereto
Extended raper 14 CFR App. B	inge fuel		(Pate of Au	thorize	ed Individual	3/26/10 urn to Sérvice				
				specified belo Iministration a				as inspected in the mai	nner pres	cribed by	the	
ву —	FAA FIt Sta Inspector	ndards		Manufacture	-		Maintenance Organization			Dep	artment (oved by Canadian of Transport
	FAA Design	nee	Х	Repair Statio	n		Inspection Au	thorization	O	Other (Specify)		
Certificate of Designation	No.		Sign	ature/Date of	Authorize	dindiv	ridual	- -	i lin			

(If more space is required, attach additional sheets	. Identify with aircraft nationality and registratio	n mark and date work completed)
in mere apade to regarded, attach additional directs		3/24/10
	Nationality and Registration Mark	Date
essna 182T–18282208– N267RH		
ISTALLED SYSTEMS: Installed Precise Flig	ght Pulselite Control unit IAW STC SA400	05NM.
PERATIONAL GROUND CHECKS: Requormally IAW Precise Flight Installation Manu		
ONTINUED AIRWORTHINESS INSTRUGENCE (STRUCTURE) STRUCTURE (STRUCTURE) STRUCTURE (STRUCTURE) AIRWORTHINESS.	CTIONS: Reference Document No. 000P	MAN0002 Rev. D (7/07) for
FMS: FAA Approved Flight Manual Supplen ight Manual.	nent Doc. No. 000PMAN0001Rev. A (7/2	4/03) was inserted into the Aircra
EIGHT & BALANCE and EQUIPMENT leight & Balance records for details.	LIST: Revised Aircraft Weight & Balance	e and Equipment List. See Aircraf
ne above installation meets the requirements for cough 114. No changes were noted to the com VI 10069.		
>>>>>>>	>>END<<<<	
r	Additional Sheets Are Attached	

MAJOR REPAIR AND ALTERATION

Form Approved OMB No. 2120-0020 11/30/2007

Transpor			(P	littr	ame, Pov	verplan	it, P	ropeller, or <i>i</i>	Appliance)		For FAA Use Only		
Adminis													
and	disposition	of this f	orm. This	repor		y law (49 l	U.S.C		43.9-1 (or subsequer report can result in a c		ereof) for instructions not to exceed \$1,000		
1. Aircra	afe .		lity and Ro N267RH		ation Mark				Serial No. 18282208				
I. Aircra	ait	Make CESSNA							Model 182T		Series SKYLANE		
					gistration cert			Address (As shown on registration certificate) Address ATTN: DEPT 093 3 CESSNA BLVD					
2. Own	er	CESS	INA AIN		AFT COMP	AINT			3 CESSNA BLVD StateKANSAS				
									City WICHITA Zip 67215-1400	c	ountry USA		
	·						3	. For FAA Use O) <u></u>		
	4. Type							5. l	nit identification				
Repa	ir Alte	eration	tion Unit				N	lake	Model		Serial Number		
			AIRFRAME						(As described in Item 1 above)				
	1		POWEF	RPLA	NT					· · · · · ·			
			PROPE	LLEF	₹								
			APPLIA	NCE		Type Manufactu	rer						
								Conformity Stat					
A. Agen	cy's Name	and Ad	dress					ind of Agency	anent .				
Name <u>YI</u>	NGLING	AVIA	TION		· · · · · · · · · · · · · · · · · · ·			U.S. Certificated	Mechanic		Manufacturer		
	010 AIF	RPORT	ROAD					Foreign Certificat	ed Mechanic	C. C	Certificate No.		
City <u>WIC</u>					State <u>KS</u>		☒	Certificated Repa	r Station		BR621Y DIO CLASS 1,2,3		
zip <u>6727</u>			CountryU						enance Organization				
h	ave been n	nade in :	accordanc	e with		ents of Pa	rt 43 c		and described on the r Aviation Regulations a				
	d range fue				Signature/D	ate of Aut	horize	d Individual		, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
App. B	FR Part 43	3			$\bigcap Z$	بر دکور کارد ا	6 C	his Is	3/26/10				
					/			proval for Return					
					specified belo				nspected in the manne	er prescribed	I by the		
_{DV}		Flt Stan	dards		Manufacture			Maintenance Org	anization		Person Approved by Canadian Department of Transport		
BY	FAA	Designe	e	Х	Repair Statio	n		Inspection Author	zation	Other (Specify)		
Certifica Designa YN8R(tion No.			Sign	ature/Date of	Authorized	//		- 3/26	lio			

	_	-		_	
N			П		

(If more space is required, attach add		entify with aircraft nation	nality and registration i	mark and date work completed.)
, , ,		USA N267RH		3/26/10
		Nationality and Regi	stration Mark	Date
CESSNA 182T –18282208– N267	RH			
Provisions : Installed antenna doub 2 ea provisions at FSS 31.5 2 ea provisions at FSS 44.0	lers under the fu	selage for future inst	all of a Directional	Finder Antenna.
Cut 1 ea opening provision for DF installed cover plate.	antenna coax. Lo	ocated on pilot side ı	ander the fuselage a	t FSS 48.0. Fabricated and
Reference: AC 43.13-1B AC 43.13-2B Chap. 3				
The above installation meets the rec hrough 114. No changes were note AVI 10069.				
>>>>	·>>>>E	ND<<<<<	· <<<	
				•
	□Ac	dditional Sheets Are Att	tached	

U.S Department of
Transportation
Federal Aviation
Administration

MAJOR REPAIR AND ALTERATION

Form Approved OMB No. 2120-0020

U.S Departm	cent of	,								11/30/20	07				
Transportation	on	()	Airtr	ame, Pov	verplar	ıt, P	ppliance)		F	or FAA Use Only	FAA Use Only				
Administrati															
and dis	UCTIONS: Pr sposition of this h such violatio	form. This	s repo	ort is required b	ov law (49	U.S.C	appendix B, and J. 1421). Failur	nd AC 4 ire to re	43.9-1 (or subseque eport can result in a	ent revisio civil pen	n thereof) alty not to e	for instructions exceed \$1,000			
4 41 5	lusa	nality and R		ration Mark					Serial No. 18282208						
1. Aircraft	Make	SNA							lodel 82T			Series SKYLANE			
	Name	(As showr	on re	gistration cert	tificate)			A	Address (As shown on registration certificate)						
2. Owner	CES	SNA AIF	₹CR/	AFT COMF	PANY			Address ATTN: DEPT 093 3 CESSNA BLVD City WICHITA State KANSAS							
									67215-1400		Country L				
						;	3. For FAA Us								
4.	. Type	+	•					5. Un	it Identification						
Repair	Alteration		Ur	rit 			Make		Model			Serial Number			
		AIRFR	AME					-	(As described in Ite	em 1 abo	ve)				
		POWE	RPLA	ANT			,								
		PROPELLER													
		APPLIA	NCE	:	Type Manufactu	cturer									
		<u> </u>				6	. Conformity	Stater	ment						
	's Name and A					B. K	(ind of Agency								
	SLING AVI					무	U.S. Certifica				acturer ate No.				
CityWICHI	10 AIRPOR ITA	RUAL	<u>?</u>	State <u>KS</u>			ForeignCertif					N8R621Y			
Zip <u>67277</u>		Country <u>U</u>	ISA	State			Certificated R		nance Organization		RADIO CLASS 1,2,3				
D. I certi have	tify that the rep	air and/or a	alteratice with	h the requirem	ents of Pa	dentificant 43 c	ed in item 5 ab	ove ar	nd described on the viation Regulations	reverse (or attachme the informa	ents hereto ation			
Extended ra per 14 CFR App. B	ange fuel		J. 100.		Date of Aut	thorize	ed Individual		In In						
				100	_//		proval for Re	turn to	Service						
	t to the authori	, -		•	w, the unit	t ident		was in:	spected in the mani	ner presc	ribed by the	e			
BY	FAA Fit Sta Inspector	ındards	dards Manufacturer				Maintenance	Organ	nization			Approved by Canadian ment of Transport			
В	FAA Design	nee	x Repair Station		วก		Inspection Au	ation	Oth						
Certificate of Designation	No.		Sign	nature/Date of	Authorized	d Indiv	ridual		~ / .						

P 1	$\overline{}$	-		_	ı
N			11	-	ı

8. Description of Work Accomplished		
(If more space is required, attach additional sheets. Iden	otify with aircraft nationality and registrat	ion mark and date work completed)
(,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
	USA N267RH	3/26/10
	Nationality and Registration Mark	Date
	,	
Cessna 182T- 18282208- N267RH		
Installation Description: The following equipment and the AC 43.13-2B. Using the existing mission rad Buss 3) thru a 5 Amp pull type circuit breaker. Installed Equipment: Wulfsberg P-2000VHF Digital/Analog Tactical FM Wulfsberg FM Transceiver P-2000VHF P/N Comant VHF FM (bent whip) Antenna P/N Comant VHF FM (bent whip) Antenna P/N	Radio: N 400-049200-11-011-2135-2135, 3 CI292-3, .5 lbs @ arm 60.7	ered from Mission Buss (Electrical
OPERATIONAL GROUND CHECKS: Post insta Wulfsberg Installation Drawing 150-049106 Rev F of		erence tests were performed IAW
EMI testing performed IAW YINGLING AVIATION found to be satisfactory.	N Emi Test Doc. 23507-F206-10 Ro	ev IR or Later on 03/26/10 and
CONTINUED AIRWORTHINESS INSTRUCTION or later.	ONS: Reference Wulfsberg ICA Dra	awing 100-049102 Rev A (12/13/03)
WEIGHT & BALANCE and EQUIPMENT LIST Weight and Balance records for details.	: Revised Aircraft Weight & Baland	ce and Equipment List. See Aircraft
Operators Manual: Wulfsberg Flexcom 2000 (P-2	000/C2000/RT2000) Manual No. 15	50-049105 Rev D or Later
The above installation meets the requirements for stathrough 114. Electrical load Calculation was perform of electrical system capacity. No changes were noted YN8R621Y under W.O. # AVI 10069.	ned IAW AC43.13-1B Chap 11 Par	a 36 and found to be less than 80%

>>>>>>END<

FAA FORM 8130-6, APPLICATION FOR U.S. AIRWORTHINESS CERTIFICATE

Form Approved O.M.B. No. 2120-0018

																						12/31/2010	
U.S. AIRWORTHINESS										INSTRUCTIONS - Print or type. Do not write in shaded areas; these are for FAA use only. Submit original only to an authorized FAA Representative. If additional space is required, use attachment. For special flight permits complete Sections II, VI and VII as applicable.													
F Q	1. REGISTRATION MARK N267RH 2. AIRCRAFT BUILDER'S NAME (Make) Cessna Aircraft Company										3. AIRCRAFT MODEL DESIGNATION 4. YR MFR 2010						FAA CODING						
L AIRCRAFT DESCRIPTION	5. AIRCRAFT SERIAL NO. 6. ENGINE BUILDER'S NAME (Make) Lycoming Engines									7. ENGINE MODEL DESIGNATION IO-540-AB1A5							. The state of the						
76	8. NUMBER OF ENGINES One 9. PROPELLER BUILDER'S NAME (Make) McCauley Propeller Systems APPLICATION IS HEREBY MADE FOR: (Check applicable items)									OPELLER 036C43						IRCRAFT IS (Check if applicable) IMPORT							
			_									_	-			T							
	A; 1 x STANDARD AIRWORTHINESS CERTIFICATE (Indicate category) x NORMAL										Ш.	UTILITY	^	ACROB/	TIC	TRAN	ISPORT.	c	OMMUTE	R	BALLOON	OTHER	
	В	\Box	13	PECIA	AIRWORTHINESS CE	RTIFICATE (Ch	ock ap	proprie	ate items)														
			9		PRIMARY LIGHT-SPORT (Indicat	e Class)	1	AIRPL	ANE	POWER-PAR	RACHUT		WE	IGHT-8H	IFT CO	NTROL			GLIDER		LIGH	ITER THAN AIR	
			5		PROVISIONAL (Indicat	te class)	1/		Class I						_								
			\$	1-1			2	-	Class II														
j			2.	1	RESTRICTED (Indicate	operation(s)	1	\vdash	AGRICULTURE			DL .			2	+	AL SURVEY	_			AL ADVERTISI		
8			3	.{ }	to be conducted)		4		FOREST (Wildli	fe conservati	ion)				5	PATR	OLLING	} •	3]]	WEA.	EATHER CONTROL		
EST			4	igspace			0		OTHER (Specif	y)		_							- T				
2				1			1 ;		RESEARCH AN	ID DEVELOP	MENT				2	AMAT	EUR BUILT	3	1	EXHI	BITION		
ž .			- 4	1	PUNCHIAPATAL AND		4.2	AIR RACING							5	CREV	YTRAINING	3 6		MARKET SURVEY			
¥			4	r I	EXPERIMENTAL (Indic operation(s)	care	0		TO SHOW COM	IPLIANCE W	/ITH THE	CFR			7	OPER	LATING (Pri	mary C	ategory) K	IT BUI	LT AIRCRAFT		
CERTIFICATION REQUESTED			h 4	4.	to be conducted)				OPERATING	BA .	$\overline{}$				vorthines	ss certifica	te & do not	meet §	103.1				
) H			1	1			8		LIGHT-SPORT	SPORT 8B Operating Light-													
11				-			- 1	\vdash		8C								egory a	Irworthine	ss certi	ficate under § 2	1.90	
							1		FERRY FLIGH					TENAN	E, OR	BTORAGE							
)				1	SPECIAL FLIGHT PER (Indicate operation (s)		2,				or me thanks british												
1	6 conducted, then complete Section or VII as applicable on reverse six						4		OPERATION I			IUM CERTI	FICATE	D TAKE	-QFF W								
	G VII as approans on reverse sk							-	DELIVERING C	_				.5	Р	RODUCTIO	N FLIG	HT TEST	ING				
	8 L. CUSTOMER DEMONSTRA										ATION FLIGHTS and "Standard" or "Limited" as applicable)												
	C A.	B REGIS	TER						OVE: Resulcied			CHECK HE		з врриса	1010)			-		x			
	A. REGISTERED OWNER (As shown on certificate of aircraft registration). IF DE NAME Cessna Aircraft Company											DRESS	ıss N	Meye	r Blv	d., PO	Box 19	96, 1	Indep	ende	nce, KS	67301	
	B. AIRCRAFT CERTIFICATION BASIS (Check applicable blocks and complete items as indicated)																						
	AIRCRAFT SPECIFICATION OR TYPE CERTIFICATE DATA SHEET (Give No. and												AIRWORTHINESS DIRECTIVES (Check if all applicable AD's are complied with and give the									give the	
8	X	Ke	18101	No.)	341	3 – Revis	lon'	::R9::			number of the last AD SUPPLEMENT av						ENT available in the biweekly series as of the date of application)						
5	_	AIF	CRA	FT LIS	TING (Give page num		1011		·										ATE (List number of each STC incorporated)				
CERTIFICATION						N/A					N/A												
	C.	AIRC	RAF	T OPER	RATION AND MAINTE	NANCE REC	ORDS																
OWNER'S	X	co	MPL		ORDS IN WITH 14 CFR	TOT	AL AI	RFRA	ME HOURS].		XPERIME	NTAL ON	LY (En	ter hours	flown	since last cert	ificate issued or	
邑	D.	CER	TIFI	CATIO	N -I hereby certify that the 49 of the United S	at I am the re	giste	red ov	vner (or his ag	3.5 ent) of the a	aircraft	described	above	e, that t	he airc	raft is rec	gistered w	ith the	Federal	Aviat	ion Administr	ation in	
	air	worth	ines	s certif	icate requested.				== and abbilds		** WAIRE	on n a gula	moris,	and th	# (U10 E	ancran na	as been in	specie	eu and is	airwc	oruny and eligi	ible for the	
				PLICA* 2010	TION	Da	vid '	W. L	LE (Print or type .aPierre						Sig	gnature		er.	10.0 D :	, .			
<u> </u>	A.	THE	AIRC	RAFT	DESCRIBED ABOVE	HAS BEEN IN	SPEC	TED 4	uality, inde	SWODING	BY (Car	nolete the	april -	onh. #	14 CEP	2 post 21 1		lion)					
	2		14	CFR PA	RT 121 CERTIFICATE H			. 3.		ATED MECH					**************************************				STATION	V (Ghe	Certificate No.)		
INSPECTION AGENCY VERSECATION	5				Icate No.) MANUFACTURER (GM	e name or firm		. 3,		 -					;.6,					. , 3,70			
SPEC Z	-1		, and											<i></i>			<u> </u>						
2 7	DA'		L ao	olicabia	block items A and B)		ITLE					1	T				1 Mra raik						
	Α. Ι	find th	at th	alrorafi	described in Section I o	r VII meets requ	ireme	nts for	<u>.</u> _ • •			4 ×					TED	URREN	T AIRWO	RTHIN	ESS CERTIFICA	ATF	
₹8				r a spec	ial flight permit under Se	ction Vil		Π	FAA INSPE	CTOR						SIGNEE				1 1674	JENTIFIC	,,,,,	
V. FAA REPRESENTATIVE CERTIFICATION	*		uU	u uy.				<u></u>	CERTIFICA	TE HOLDER	UNDER			++	14 CEP	part 65 ::	14.05	D par	121 or 135		14.055		
> 5 E	_		_			T 81								$\perp \perp$	7	part 05	1.01	v bau	121 OF 135	٠	14 CFR p	мап 145	
9 8	DAT			040	MIDO/FSDO	DESIG	NEE'	s sign	ATURE AND NO	11	LA	0			[,	FAA INS	PECTOR'S	SIGNA	TURE				
Į	re	ור ס	, 2	010	CE-43	N 1	~ · ·	· E	ma 004 4	25/47	K.	an		_	1							ł	
						I KOD	sit K	<u>. ⊏va</u>	ins ODA-1	UU 129-C	<u> </u>				l la	`							

ware e

	A	MANUFACTURER		Alley Arity .												
	N/	AME														
				- K- W												
VI PRODUCTION FLIGHT TESTING	В.	PRODUCTION BASIS (Спеск аррііса	ible item)												
DOUC TTES		PRODUCTIO	N CERTIFICA	ATE (Give pro	oduction cer	rtificate number	r)			→	5 1					
APP.		TYPE CERTI	FICATE ONL'	Y							THE LONG A CHAIN	. <u> </u>				
- u.		APPROVED									ATTENDED TO THE STATE OF THE ST					
		GIVE QUANTITY OF C	ERTIFICATES				s			hioi	NATIOE					
	DA	ATE OF APPLICATION		NAME A	ND TILE (Print or type)				SIG	NATURE					
		DESCRIPTION OF AIR	CRAFT				ADDRE	SS								
		·			·	1 10										
	BU	JILDER (Make)					MODEL	•			•					
	SE	RIAL NUMBER					REGIST	TRAT	TON MARK			- · · · · · · · · · · · · · · · · · · ·				
	_	DESCRIPTION OF FLIG	CUT		CUSTOM	ER DEMONST	BATION	ELV	CUTC []			·				
	FRO				COSTÓNI	ER DEMONST	TO	FLIC	SHTS (Check if	applicable)					
											<u></u>					
	VIA						DEPAR	TUR	E DATE	P	DURATION					
					ا المجاورة						144					
EST	C.	CREW REQUIRED TO		O-PILOT	T AND ITS I	FLIGHT EN	CINEE	<u>. </u>	OTHER (Spe	noifu)	.,1.					
GHT	В	. THE AIRCRAFT DOES			ABLE AIRW						12 Mariana					
Š	-										Company of the compan					
C IO											Seminar of the on-					
30										WCH .						
AN					-						en entre general de la company					
ER											िक्रिंग के					
E O						* * *					ANT → W					
38											er en					
PE																
SPECIAL FLIGHT PERMIT PURPOSES OTHER THAN PRODUCTION FLIGHT TEST																
¥	E.	THE FOLLOWING RES	STRICTIONS	ARE CONSID	DERED NE	CESSARY FOR	R SAFE OPERATION: (Use attachment if necessary)									
F.											The state of the s					
CIAL					414.	19 6 W. C.										
S. SPE						mo ma						1				
Ę												J				
					-											
					***						an contraction of					
												•				
	ı											:				
	F-	- CERTIFICATION - I he	reby certify the	at I am the re	gistered ow	ner (or his age	ont) of the	e airc	raft described above;	; that the	aircraft is registered with the Federal Aviation					
	A	dministration in accordar afe for the flight describe	nce with Title 4	49 of the Unit	ted States C	ode 44101 et s	seq. and	appi	icable Federal Aviatio	on Regula	ations; and that the aircraft has been inspected	and is				
	DAT	E		NAME AND	TITLE (Pri	nt or type)				SIGNA	TURETER					
										O.O.W.	TOKET, .					
	X	A. Operating Limitatio	ns and Markin	Markings in Compliance with 14 CFR section				_								
8	\dashv	as Applicable						4	G- Statement of Conformity, FAA Form 8130-9 (Attach when required) H. Foreign Airworthiness Certification for Import Aircraft							
ω E		B. Current Operating I	Limitations Att	ached	in decer	e e je e e kale ea	{	ļ	(Attach when requir	ired)	eruncation-tot-import Aircraft					
VOESI	C. Data, Drawings, Photographs, etc. (Attach when required)								I. Previous Airworthiness Certificate issued in Accordance with							
	x	D. Current Weight and	i Balance Info	rmation Avel	lable in Airo	raft	-	14 CFR Section CAR(Original attack								
VIII AIRMORTHUNESS DOCUMENTATION/FAADESIGNEE use onby)	-	- Tolgin dik		nce Information Available in Aircraft												
		E. Major Repair and A	Iteration, FAA	on, FAA Form 337 (Attach when required)				х			ertificate Issued in Accordance with					
ğ	↲						4	14 CFR Section 21		ement of Compliance, FAA Form 8130-15 (Attac						
	X	F. This inspection Rec	orded in Aircr	aft Records					required).	an 3(816	эшель от Compilance, FAA Form 8130-15 (Attac	n when				

Miles Miles

UNITED STATES OF AMERICA DEPARTMENT OF TRANSPORTATION-FEDERAL AVIATION ADMINISTRATION

to which issued has been inspected and found to conform to the type certificate therefor, to be in condition for safe operation, and has been shown to meet the requirements of the applicable comprehensive and detailed airworthiness code as provided by Annex 8 to the Convention

Unless sooner surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator, this airworthiness certificate is effective as long as the maintenance, preventative maintenance, and alterations are performed in accordance with Parts 21, 43,

Any alteration, reproduction, or misuse of this certificate may be punishable by a fine not exceeding \$1,000 or imprisonment not exceeding 3 years or both. THIS CERTIFICATE MUST BE DISPLAYED IN THE AIRCRAFT IN ACCORDANCE WITH APPLICABLE FEDERAL AVIATION REGULATIONS.

STANDARD AIRWORTHINESS CERTIFICATE

1 NATIONALITY AND 2 MANUFACTURER AND MODEL 3 AIRCRAFT SERIAL REGISTRATION MARKS NUMBER

Cessna Aircraft Company

on international Civil Aviation, except as noted herein.

None

₃Ñ267RH

Exceptions:

DATE OF ISSUANCE

6 TERMS AND CONDITIONS

Feb 18, 2010

FAA Form 8100-2 (3-08)

5 AUTHORITY AND BASIS FOR ISSUANCE

This airworthiness certificate is issued pursuant to the Federal Aviation Act of 1958 and certifies that, as of the date of issuance, the aircraft

FAA REPRESENTATIVE

Robert R. Evans

and 91 of the Federal Aviation Regulations, as appropriate, and the aircraft is registered in the United States.

13282208

DUPLICATE

4 CATEGORY

DESIGNATION NUMBER

ODA-100129-CE

Normal

