

SOP-VIB-A — High-Vibration Response

Purpose

Standard operating procedure SOP-VIB-A defines the field response to a high-vibration alarm on rotating equipment. Compliant with OISD-105 general safe-operating requirements.

Procedure

1. Acknowledge the alarm and record the velocity reading (mm/s).
2. Classify the band per the equipment vibration table.
3. Inspect bearing housing temperature and grease condition.
4. Inspect the mechanical seal and coupling bolt torque.
5. Cross-check the last three trend readings for rate of rise.
6. If in the alert band, continue with monitoring every 30 min.
7. If shutdown band is reached, trip and isolate immediately.

SOP-VIB-A — High-Vibration Response

Escalation

If velocity rises more than 1.0 mm/s within one shift, escalate to the reliability engineer regardless of absolute band. Log the escalation in the shift handover under OISD-105 record-keeping.

Records

Retain the vibration log, the inspection checklist, and any corrective work order for a minimum of two years.