

WM300 Premium Washer

User Manual Version 1.0

Features

- **Steam Wash**
- **Auto-Dose Detergent**
- **Advanced Sensor Technology**

Error Codes

E21

E21 indicates motor overload condition.

Steps:

- 1. Remove excess laundry.**
- 2. Wait 10 minutes.**
- 3. Restart cycle.**

SUDS

SUDS indicates sensor-detected foam overflow.

Child Lock

Press Options and Delay Start simultaneously for 4 seconds.

Maintenance

- **Clean steam generator every 60 cycles.**
- **Inspect inlet filters every 6 months.**