

WM400 Smart Washer

Version 1.0

Features

- Wi-Fi Connectivity
- Mobile App Integration
- Automatic Detergent Dosing

Error Codes

E21

E21 indicates pump communication failure.

Resolution

1. Restart washer.
2. Verify communication cable.
3. Update firmware.

SUDS

SUDS indicates excessive detergent concentration.

Child Lock

Press Temp and Spin together for 4 seconds.

Maintenance

Clean detergent drawer every month.

Update firmware quarterly.