

WM400 Smart Washer

Version 2.0

Features

- Wi-Fi Connectivity
- Real-Time Monitoring
- AI Wash Optimization

Error Codes

E21

E21 indicates motor overload.

Resolution

1. Reduce laundry load.
2. Wait 10 minutes.
3. Restart cycle.

SUDS

SUDS indicates foam sensor overflow.

Child Lock

Press Temp and Spin together for 6 seconds.

Maintenance

Firmware updates are automatic.

New Features

- AI Cycle Detection
- Auto Maintenance Alerts