

WM500 Premium Steam Washer

Version 1.0

Features

- Steam Wash
- Auto Balance
- Energy Saver Mode

Error Codes

E21

E21 indicates drainage filter obstruction.

Resolution

1. Open service hatch.
2. Clean drainage filter.
3. Restart cycle.

SUDS

SUDS indicates detergent residue buildup.

Child Lock

Press Steam and Delay Start for 3 seconds.

Maintenance

Clean drainage filter every month.

Run Steam Clean every 50 cycles.