

MKV ENGINEERING AND TRADING SERVICES PTE LTD

NO : 10 KAKI BUKIT ROAD 1 #03-12 KB INDUSTRIAL BUILDING SINGAPORE - 416175 TEL: 6283 9289 FAX: 6283 9286 Email: info@mkv.com.sg

M & E INSPECTION FORM (SPECIALIST) - SMOKE CONTROL SYSTEMS

ANNEX D7_5

Month: July 2019

SITE: New Town Primary School 300, Tanglin Halt Rd, Singapore 148812

S/N	ITEM	DONE? (Y or N or NA)	Date Done	Remarks
3/14	SERVICING, INSPECTION AND TESTING OF	. , ,		
1	SYSTEM	SWORE CONTROL 3131EW/EN	IGINEERED	SIMORE CONTROL
1	Check the functionality of Master Smoke control panel before the test	✓ Yes ☐ No ☐ N/A	04/09/2019	
2	Check and ensure the alarm signal is working and status indicated at the Master Smoke Control Panel is correct	✓ Yes ☐ No ☐ N/A	04/09/2019	
3	Check and ensure the alarm signal is working and status indicated at the Mimic panel is correct	✓ Yes ☐ No ☐ N/A	04/09/2019	
4	Check and ensure Ventilation system is working during the test	✓ Yes ☐ No ☐ N/A	04/09/2019	
5	Check and ensure all smoke extract fans is working during the test	✓ Yes ☐ No ☐ N/A	04/09/2019	
6	Check and ensure the smoke curtain is working during the test	✓ Yes ☐ No ☐ N/A	04/09/2019	
7	Check and ensure the Air Handling Units (AHU) serving the smoke control zone will shut down automatically during the test	✓ Yes ☐ No ☐ N/A	04/09/2019	
8	Check and ensure the automatic swing door is working during the test	✓ Yes ☐ No ☐ N/A	04/09/2019	
9	Check and ensure all alarm is reset and all systems is back to normal after the test	✓ Yes ☐ No ☐ N/A	04/09/2019	
Checked By Verified		I Ву	Endorse	d By
	52	B		8
(sdfsdfs) (fdgdfgf			(sfgdfd)	· · · · · · · · · · · · · · · · · · ·
THE CONTRACTOR MANAGE		SEMENT AGENT	USER	
Date: 04/09/2019 Date: 04		4/09/2019	Date: 04/09/2019	