

S/N

## MKV ENGINEERING AND TRADING SERVICES PTE LTD

NO : 10 KAKI BUKIT ROAD 1 #03-12 KB INDUSTRIAL BUILDING SINGAPORE - 416175 TEL: 6283 9289 FAX: 6283 9286 Email: info@mkv.com.sg

DONE? (Yor Nor NA)

M & EINSPECTION FORM (SPECIALIST) - SMOKE CONTROL SYSTEMS

ANNEX D7\_5

SITE: Dunman High School 10 Tanjong Rhu Road, Singapore 436895

ITEM

Month: April 2021

Remarks

		$\rho \sim$	tomod by			
Check	ed By Endors	ed By	Verified By			
	Check and ensure all alarm is reset and all systems is back to normal after the test	Yes No NA	07/04/2021			
8	Check and ensure the automatic swing door is working during the test	Yes No NA	07/04/2021			
7	Check and ensure the Air Handling Units (AHU) serving the smoke control zone will shut down automatically during the test	✓ Yes 🗌 No 🦳 N/A	07/04/2021			
6	Check and ensure the smoke curtain is working during the test	✓ Yes No No NA	07/04/2021			
5	Check and ensure all smoke extract fans is working during the test	✓ Yes ☐ No ☐ N/A	07/04/2021			
4	Check and ensure Ventilation system is working during the test	▼ Yes □ No □ N/A	07/04/2021			
	Check and ensure the alarm signal is working and status indicated at the Mimic panel is correct	Yes No NA	07/04/2021			
2	Check and ensure the alarm signal is working and status indicated at the Master Smoke Control Panel is correct	✓ Yes ☐ No ☐ N/A	07/04/2021			
1	Check the functionality of Master Smoke control panel before the test	✓ Yes No No NA	07/04/2021			
1	SERVICING, INSPECTION AND TESTING OF SMOKE CONTROL SYSTEM/ ENGINEERED SMOKE CONTROL SYSTEM					

12 1/9

(Raja/Deva)

THE CONTRACTOR Date: 07/04/2021

Date. 07/04/202

Remarks:

(Dennis) USER

Date: 15/05/2021

Remarks:

MANAGEMENT AGENT

Date:

Date Done

Remarks: