

Sevatas Advanced Validation



Independent Inspection on behalf of: **Volkswagen Group UK Ltd**

Sevatas Claim ID: **984413**

Date of Validation:	10/10/2024	Dealer/Repairer Name:	VWG Test Dealer
Make & Model:	Volkswagen - Golf Estate	Claiming Market:	United Kingdom
VIN No:	WVGXXC14RY002165	Estimate Type:	New

No.	Damage Location	Damage Type
1	Carpet	Breakage
2	Aerial Mast	Bank Charges

Engineer's Comments

(Large empty box for comments)

Estimate Currency

GBP

Repair Category

As New

Dealer Repair Costs

	Hourly Rate	Hours	Cost
Labour Costs	70.00	4.0	280.00
Paint Labour Costs	70.00	6.0	420.00
Total Hours		10.0	700.00
Paint and Material Costs			40.00
Parts Costs			428.66
Other (Inc. sundries)			60.00
Total Estimated Amount		10.0	1247.09

Authorised Repair Costs

	Hourly Rate	Hours	Cost
Labour Costs	70.00	4.0	280.00
Paint Labour Costs	70.00	6.0	420.00
Total Hours		10.0	700.00
Paint and Material Costs			40.00
Parts Costs			428.66
Other (Inc. sundries)			60.00
Total Authorised Amount		10.0	1247.09

Category Comments

Sevatas Inspector Details

Matt Holmes

10/10/2024

This repair validation is our consideration of a fair and appropriate repair method and cost. It is not an instruction to you to disregard any standing instructions, guidelines or processes set by the manufacturer and/or their local Sales Company / importer / distributor which take precedent.



Provision of service provided by Contior