Cyber Dawn, Phase 1 bench: every connection on one sheet

A dot is a joint. A line that hops over another does not touch it. Thick = wire you solder or plug. Brass = the STEMMA QT chain. Dotted = later phase. Ground symbols all mean the controller's GND pins.

