Brass battery sleeve · cutting pattern · 1:1

Print at Actual size on Letter. Check the 50 mm bar with the caliper before cutting. Solid = cut. Dashed = fold; score on this face. Stick this sheet to the brass with glue stick or Kapton at the corners, cut through both, then peel.





50 mm: measure this with the caliper; 49–51 is a good print

fish paper jacket · 84 × 63 · dashed = fold