





Xiao RP2040
* original model
* dual USB-C
* could use the DAC to control max motor current














PCB Tests:

* check max motor current vs. 5V draw

* is DC PSU OC resistor rating correct? What should it be?

* after check above, check polyfuse rating