

# LEKTION 3: FAROR I ARBETSMILJÖN

# Repetition

Lektion 2 handlade om....

# Svensk lagstiftning

|                                        |                                                      |                                                                                                                   |
|----------------------------------------|------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------|
| Sjölagen (1994:1009)                   | Övergripande/Ekonomisk                               | Befälhavarens ansvar 6 kap. §1 och §14                                                                            |
| Fartygssäkerhetslagen (2003:364)       | Säkerhet                                             | Säkerhetsorganisation (SMS, kap. 3. Arbetsmiljö, 4 kap: AML, ansvar, minderåriga, skyddsombud, 5 kap §1: Tillsyn) |
| Sjömanslagen (1973:282)                | Arbetsvillkor, sjömans rättigheter, disciplinärenden | §9 och §11 frånträde, §18–28 franskiljande och fartygsnämnd, §45–48 fartygsarbete                                 |
| Lagen om vilotid för sjömän (1998:958) | Vilotid                                              | §1–7 vilotidskrav, §9–10 krav på arbetsordning                                                                    |

# IMO // Internationellt

|                                                     |                                                                                                 |                                                                                                                                                    |                              |
|-----------------------------------------------------|-------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|
| ISM-koden<br>(SOLAS<br>Chapter IX)                  | Herald of Free<br>Enterprise                                                                    | Ökad säkerhet genom<br>införlivande av Safety<br>Management Systems<br>(ansvar, procedurer,<br>riskhantering, auditering,<br>rapportering/lärande) | EG<br>förordning<br>336/2006 |
| MLC –<br>Maritime<br>Labour<br>Convention<br>(2006) | Sammanslagning av<br>olika tidigare<br>konventioner samt<br>etablera modernare<br>“minsta” krav | Att reglera arbetsvillkor,<br>anställningsvillkor,<br>bostadsutrymmen ombord,<br>mat ombord, sjukvård<br>ombord mm.                                | TSFS<br>2013:68              |

# Föreskrifter

# LEKTION 3: FAROR I ARBETSMILJÖN

## Gruppövning

AML. 3 Kap. §2-§2a: Vad innebär dessa två paragrafer i praktiken?

# Plan - Do - Check - Act



# SAM




## Gruppövning

I par om två: Skriv ner så många faror för människors hälsa ni kan komma på i arbetsmiljön ombord på ett fartyg.

Marine report 2024/04

**A crew member fell overboard while working to move the gangway on board at Invergordon, Scotland.  
The person died as a result of the injuries.**

Report on very serious occupational accident, on the fishing vessel Øyværing east of Kabelvåg on 1. March 2024



## Investigation of an occupational accident east of Malta, Mediterran sea

The Norwegian Safety Investigation Authority (NSIA) have decided to investigate the work accident on board the bulk carrier Spar Scorpio on 17 February 2026, where a crew member lost their life after falling overboard.

VERY SERIOUS MARINE CASUALTY | May 2025

Sophia Z

Electrocution on 30 August 2024

1: Kurs: ...2: Medarb...3: Kalend...4: Swiss ...5: Good a...6: Seriou...7: what i...8: !g saf...9: Articl...10: Välj ...11: 24 id...

GOV.UK

Menu

[Home](#) > [Marine Accident Investigation Branch reports](#)

# Serious injury to a crew member on board the scallop dredger Jacoba (BM77)

Location: 29 nautical miles south-south-east of Beachy Head, England.

---

From: [Marine Accident Investigation Branch](#)

Published: 25 June 2026

Vessel type: [Fishing vessel](#)

Report type: [Investigation report](#)

Date of occurrence: 10 May 2025

Contents

- [Accident Investigation Report 14/2026](#)
- [Safety issues](#)
- [Recommendations](#)
- [Related publications](#)

## Accident Investigation Report 14/2026

Read our marine accident investigation report, which includes what happened, subsequent actions taken and recommendations:

[MAIB investigation report 14-2026: Jacoba](#)



<https://www.gov.uk/maib-reports/serious-injury-to-a-crew-member-on-board-the-scallop-dredger-jacoba-bm77> [top] [6/11]

# STOCKHOLM – Man över bord i Svalbard

I samband med underhållsarbete under gång föll en besättningsmedlem över bord. Besättningsmedlemmen räddades av andra besättningsmedlemmar med hjälp av en av fartygets RIB-båtar. Besättningsmedlemmen var nedkyld men i övrigt oskadd.

## **Serious injury to a crew member on board the scallop dredger Jacoba (BM77)**

Location: 29 nautical miles south-south-east of Beachy Head, England.





Hunts Point on July 7, 2018 before the explosion. (Source: Frank Joniak, shipspotting.com)

## Explosion aboard Sludge Vessel Hunts Point

# Marine Safety Investigation Rep

VERY SERIOUS MARINE CASUALTY | **January 2024**

**Constellation**

Steam release fatality 10 February 2024



Passenger Vessel *World Explorer* after the small boat capsized.

## Capsizing of Small Boat from Passenger Vessel World Explorer

**Händelsedatum:** 13 oktober 2023

 S-191/23

# Personolycka i samband med lastning på MS Eckerö i Grisslehamn

VERY SERIOUS MARINE CASUALTY | January 2024

**Constellation**  
Steam release fatality 10 February 2024

1 May 2023

**Fatality of deck cadet onboard Strategic Harmony at sea [PDF, 1.3 MB]** 

Ship type **CS: Cargo ship**

Status **Past Reports**

Strategic Harmony [Cargo Ship]

Very Serious Marine Casualty

# WORLD PRIZE – En person omkom efter att ha fallit överbord

Händelsen utreds gemensamt av haverikommissionerna i Storbritannien och Sverige


**Utredande stat:** Storbritannien

I samband med att en lotslejdare riggades ombord på fartyget WORLD PRIZE, föll en besättningsman överbord och omkom.

Händelsen inträffade efter att fartyget lämnat Rönnskär, Skellefteå, och betecknas som en mycket allvarlig sjöolycka.

Utredningen leds av den engelska olycksutredningsmyndigheten MAIB i samarbete med SHK.

Report on very serious occupational accident, on the fishing vessel Øyværing east of Kabelvåg on 1. March 2024


















# Risk

# Risikförståelse

























## **Very serious casualty: falling from height during inspection of water ballast tank**


### **What happened?**

On board a 37,000 gt containership whilst at sea, the chief officer entered into a water ballast tank for a routine inspection. Before the entry, he measured the tank's atmosphere. He descended through the open manhole into the darkened tank, holding the lit torch in one hand. The bosun stood at the tank access monitoring the chief officer's progress and an AB stood behind the bosun. The chief officer stopped at the fifth or sixth rung of the vertical ladder, almost level with a transverse stringer through which the ladder continued. He took another reading from the gas analyser and informed the bosun that the oxygen level was between 20.8 per cent and 20.9 per cent.

The chief officer then stepped to his left onto the stringer. At the same time, the bosun stepped back from the access and started


talking to the AB. A few seconds later, there was a loud crashing sound in the tank. The bosun illuminated the tank with his torch and saw the chief officer lying at the bottom of the tank. The officer was

## PDCA



## Åtgärdstrappan

### Åtgärdstrappan – administrativa åtgärder



# Permit to Work System

# Permit to Work System

Work Permit

Risk Assessment  
(TRA, SJA, RA)

Checklists

Enclosed Space Entry  
Certificate

Toolbox Talk  
(före-jobb samtal)

Rutiner för  
administration, träning  
och auditering



## Permit to Work

*“A permit to work system is a formal written system that controls certain types of work...”*

## Ett permit to work"-system syftar till att:

- Korrekt godkännande av arbetsaktiviteter,
- tydliggöra för de som utför uppgiften vilka faror som finns relaterat till uppgiften,
- definiera skyddsåtgärder,
- försäkra sig om att ansvarig personal vet om aktiviteten,
- tillse kontinuerlig kontroll och uppföljning,
- hantera potentiella konflikter (SIMPOS)



# Permit to work

## **Very serious casualty: falling from height during inspection of water ballast tank**

### **Why did it happen?**

The precautions taken by the Chief Officer before entry into the tank fell significantly short of the requirements of the vessel's procedures, the expectations of the vessel's managers, and industry best practice.

The chief officer did not follow the permit to work system on board for entering into enclosed spaces.


The danger of falling during tank inspections had not been recognized or considered as no permits to work aloft were issued for tank entries on board.

### **What can we learn?**

- It is important to follow the permit to work system for entering into enclosed spaces on board and that if there is a danger of

falling from height, the precautions for working aloft must also be considered.

## Isolering av farligt ämne eller medium



## Gruppövning

Ni ska utföra ett av följande:

- Arbete i ballasttank eller,
- 2000-timmarsservice på en huvudmaskin.

Hur kan ni i praktiken lösa en isolation?

# Maersk Interceptor





## Avslut vecka 1

### Mål med veckan

- Få en grundläggande förståelse för regler som styr arbetsmiljön
- Få en grundläggande förståelse för de risker som finns ombord
- Orientering kring hur man arbetar med arbetsmiljö ombord

Inlämningsuppgift 1: Deadline Torsdag 10/9



## Nästa föreläsning

- Riskanalys
- Skyddsombud

Speaker notes