



ITEM NO.	Description	Length	Width	THK	QTY.
1	Work Surface_1	99.875	42.855	1.205	1
2	Work Surface_2	76.624	36.767	1.205	1
3	End Panel_1	29.960	27.795	1.205	1
4	End Panel_2	29.960	27.795	1.205	1
5	Wall Kerf_1	114.135	23.795	0.460	1
6	Wall Kerf_2	81.169	23.795	0.460	1
7	Access Panel_1	25.420	16.699	0.830	6
8	Access Panel_2	25.420	14.236	0.830	5
9	HRZ Member_1	95.169	25.233	0.720	2
10	HRZ Member_2	72.620	14.816	0.720	2
11	HRZ Member_3	98.406	25.202	0.720	1
12	HRZ Member_4	75.104	14.157	0.720	1
13	HRZ Member_5	98.406	25.482	0.720	1
14	HRZ Member_6	75.104	14.522	0.720	1
15	HRZ Member_7	92.780	23.727	0.720	1
16	HRZ Member_8	70.786	13.310	0.720	1
17	HRZ Member_9	98.406	27.273	0.720	2
18	HRZ Member_10	75.104	16.856	0.720	2
19	HRZ Member_11	98.993	25.090	0.720	1
20	HRZ Member_12	107.657	30.550	0.720	1
21	HRZ Member_13	108.176	29.552	0.720	1
22	HRZ Member_14	108.966	30.051	0.720	1
23	VRT Member_1	24.540	5.442	0.720	19
24	VRT Member_2	20.626	7.209	0.720	1
25	VRT Member_3	20.622	7.209	0.720	1
26	VRT Member_4	20.305	7.209	0.720	1
27	VRT Member_5	19.488	7.209	0.720	1
28	VRT Member_6	18.196	7.209	0.720	1
29	VRT Member_7	16.489	7.209	0.720	1
30	VRT Member_8	14.480	7.209	0.720	1
31	VRT Member_9	12.308	7.209	0.720	1
32	VRT Member_10	10.215	7.209	0.720	1
33	VRT Member_11	10.128	7.209	0.720	1
34	Transaction Top	109.419	34.261	1.205	1
35	Transaction End Panel_1	11.960	22.788	0.790	1
36	Transaction End Panel_2	11.955	12.200	0.790	1
37	Transaction Wall Kerf	123.879	22.066	0.500	1
38	Toe Kick Kerf_1	110.470	4.000	0.500	1
39	Toe Kick Kerf_2	78.551	4.000	0.500	1
40	TackBoard	110.208	10.795	0.500	1
41	Laminate Wall Kerf_1^091120-02 Monterey Reception Desk	115.414	20.750	0.040	1
43	Laminate Wall Kerf_3^091120-02 Monterey Reception Desk	82.467	10.063	0.040	1
44	Laminate Wall Kerf_4^091120-02 Monterey Reception Desk	82.467	20.450	0.040	1
45	Laminate Toe Kick Kerf_1^091120-02 Monterey Reception Desk	111.788	4.000	0.040	1
46	Laminate Toe Kick Kerf_2^091120-02 Monterey Reception Desk	79.849	4.000	0.040	1
47	Laminate Transaction Wall Kerf_1^091120-02 Monterey Reception Desk	126.449	16.603	0.040	1
48	Laminate Transaction Wall Kerf_2^091120-02 Monterey Reception Desk	126.445	6.640	0.040	1
49	Laminate End Panel_1^091120-02 Monterey Reception Desk	29.960	29.000	0.040	1
50	Laminate End Panel_2^091120-02 Monterey Reception Desk	25.200	29.960	0.040	1
					_





ITEM NO.	Description	Length	Width	THK	QTY.
1	3Drawer Box_LH Side Panel	27.670	17.085	0.770	1
2	3Drawer Box_RH Side Panel	27.670	17.085	0.750	1
3	3Drawer Box_Back Panel	27.670	13.480	0.750	1
4	3Drawer Box_Bottom Panel	16.335	13.480	0.750	1
5	3Drawer Box_Top Panel	16.335	13.480	0.750	1
6	3Drawer Box_Top and Middle Dr, Front	6.000	14.750	0.790	2
7	3Drawer Box_Bottom Dr. Front	9.045	14.750	0.790	1
8	3Bottom Drawer LH and RH Side	14.000	7.000	0.500	2
9	3Bottom Drawer Front and Back Panel	11.480	7.000	0.500	2
10	3Top and Middle Drawer LH and RH Side	14.000	4.000	0.500	4
11	3Top and Middle Drawer Front and Back	11.480	4.000	0.500	4
12	3Drawer Bottom	13.500	11.980	0.250	3
13	3Drawer Toe-Kick	15.000	4.000	0.770	1
14	2HAP 304 Handle	128mm Center	-	-	3
15	3Drawer Top Fascia	14.750	2.000	0.790	1
ı		1	1	I .	1

ITEM NO.	Description	Length	Width	THK	QTY.
1	2Drawer Box_LH Side Panel	27.670	17.085	0.750	1
2	2Drawer Box_RH Side Panel	27.670	17.085	0.770	1
3	2Drawer Box_Back Panel	27.670	13.480	0.750	1
4	2Drawer Box_Bottom Panel	16.335	13.480	0.750	1
5	2Drawer Box_Top Panel	16.335	13.480	0.750	1
6	2Drawer Box_Top Dr. Front	10.585	14.750	0.790	1
7	2Drawer Box_Bottom Dr. Front	10.585	14.750	0.790	1
8	2Bottom Drawer LH and RH Side	14.000	8.000	0.500	4
9	2Bottom Drawer Front and Back Panel	11.480	8.000	0.500	4
10	2Drawer Bottom	13.500	11.980	0.250	2
11	2Drawer Toe-Kick	15.000	4.000	0.770	1
12	3HAP 304 Handle	128mm Center	-	-	2
13	2Drawer Top Fascia^2 Drawer Box	14.750	2.000	0.790	1

