

SCANASSIST ENGINEER REPORT

Generated:

2026-09-14 16:47:47

Machine:

mri

Model:

mri-x100

Error:

Cooling System Warning

Risk:

Medium

Category:

Cooling

Severity:

60/100

Estimated Resolution Time:

10 mins

Completed Steps:

[DONE] Check room temperature

[DONE] Check air vents

[DONE] Restart cooling unit

Status:

UNRESOLVED

Recommendation:

Engineer Inspection Required