

SCANASSIST ENGINEER REPORT

Generated:

2026-09-14 15:37:48

Machine Type:

mri

Machine Model:

mri-x100

Error:

Cooling System Warning

Risk Level:

Medium

Completed Steps:

[DONE] Check room temperature

[DONE] Check air vents

[DONE] Restart cooling unit

Status:

UNRESOLVED

Recommendation:

Engineer Inspection Required