# **Doupe Services**

## C150 N23322 NORMAL CHECKLIST

## **BEFORE STARTING ENGINES**

Pre-flight Inspection	COMPLETE
Passenger Briefing	
Seats	.POSITION & LOCK
Seat Belts & Shoulder Harnesse	sCHECK
Brake	TEST & SET
Avionics Switches	OFF
Circuit Breakers	CHECK
Fuel Selector Valve	ON
Master Switch	ON
Fuel Quantity Indicators	CHECK
Checklist	COMPLETE

### **STARTING**

Mixture Control	RICH
Throttle	1/4 IN. OPEN
Carb Heat	COLD
Primer	AS REQUIRED
Ignition Switch	ВОТН
Prop area	CLEAR
Start ButtonPUSH to	
Warm-up	800 to 1000 RPM
Mixture	
All Engine Indicators	CHECK
Amp Meter	
Checklist	COMPLETE

## AFTER STARTING AND TAXI

**NOTE**: Do not operate engine above 1200 RPM until oil temperature reaches 75°F.

Lights	AS REQUIRED
Brakes	CHECK
Steering	CHECK
Checklist	COMPLETE

### **RUNUP**

Parking Brake	AS REQUIRED
Flight Controls	
Mixtures	RICH
Throttle	1700 RPM
Suction Gauge	4.6-5.4
Load meters and Engine Gauge	
Magnetos	
Carb Heat	
Throttles	IDLE
Carb Heat	OFF
Throttles	800-1000
TrimAS REQUIRED	FOR TAKEOFF
Flaps	CHECK
Flight Instruments and Radio	
Doors & Windows	,
Parking Brake	OFF
Checklist	

## BEFORE TAKE OFF

Flaps	SET
Heading Indicator Compass	CHECK

#### AFTER CLEARED ONTO RUNWAY

Landing Lights/Pulse Lights	ON
Pitot Heat	AS REQUIRED
Transponder	ON/ALT
Mixtures	RICH
Checklist	COMPLETE

### **TAKEOFF**

Take-Off Power	FULL THROTTLE
Rotate	50 MPH
Airspeed	CLIMB at 73 MPH
Checklist	COMPLETE

Flaps,	UP
Carb Heat,,,	
Brakes	HOLD
Throttle	FULL OPEN
Brakes	RELEASE
Elevator ControlSLIGH	TLY TAIL LOW
Airspeed	57 MPH
After Clearing obstacles Airspeed	73 MPH
Checklist	COMPLETE

### **CLIMB CHECK**

Power	FULL OPEN
	AS REQUIRED
	75-80 MPH
	COMPLETE

### **CRUISE**

Maximum Cruise	2750 rpm
Recommended Cruise	2300 rpm
Economy Cruise	2100 rpm
Throttles	SET AS DESIRED
Mixture	LEAN AS REQUIRED
Checklist	COMPLETE

### **BEFORE LANDING**

Seat Belts	FASTENED
Seat Backs	UPRIGHT
Fuel Indicator Valves	CHECK
Lights	AS REQUIRED
Mixtures	RICH
Carb Heat	ON
Airspeed	65-75 MPH
Flaps	APPROACH /15° POSITION
Airspeed	60-70 MPH
Flaps	FLAPS EXTENDED
Airspeed at 50ft	60 MPH
Checklist	COMPLETE

## NORMAL LANDING

Airspeed	60 MPH
Flaps	30° POSITION
	MAIN WHEELS FIRST
Landing RollLOW	ER NOSE WHEEL gently
Braking	MINIMUM REQUIRED
Checklist	COMPLETE

## SHORT FIELD LANDING

Throttle	IDLE
Airspeed	58 MPH
	40° POSITION
	MAIN WHEELS FIRST
Landing Roll	LOWER NOSE WHEEL
Flaps	UP
Braking	HEAVY as REQUIRED
Checklist	COMPLETE

### SOFT FIELD LANDING

Airspeed	58 MPH
	40° POSITION
	MAIN WHEELS FIRST
Throttle	IDLE
Landing Roll	ELEVATOR FULL UP
	AS REQUIRED
	OFF
Checklist	COMPLETE

## BALKED LANDING/GO AROUND

Power	FULL
Carb heat	OFF
Flaps	20°
Airspeed	
FlapsSLOWLY RETR	
Airspeed	57 MPH
After Clearing obstacles Airspeed	73 MPH
Checklist	COMPLETE

## AFTER LANDING

I 1: 17 : I : 14	A C DECLUDED
Landing and Taxi Lights	AS REQUIRED
Pitot Heat	OFF
Strobe Lights	OFF
Flaps	
Carb heat	OFF
Trim Tabs	SET TO ZERO
Checklist	COMPLETE

## **SHUTDOWN**

Brakes	SET
Throttles	1000 RPM
Avionics Switch	OFF
Mixtures	IDLE CUT-OFF
Magneto Switches	OFF
Master/Battery	OFF
Controls	LOCKED
Tie-Down, Chocks	REPLACE
Parking Brake	RELEASE
Checklist	COMPLETE

## MISCELLANEOUS INFORMATION

Useful Load	lbs.
Empty Weight	lbs.
Moment	
IMM Unicom	122.9
IMM ATIS	118.52
Curtis Doupe	(516) 818-5003

"V" SPEEDS	(MPH IAS)
Vs1	55
Vso	49
Vr	50
Vx	57
Vy	73
Va	
Vno	120
Vne	162
Vfe	100
Glide	65

<sup>\*</sup>This checklist does not relieve the Pilot in Command from knowing the expanded procedures.