

GENERAL DIRECTORATE OF CIVIL DEFENSE — KINGDOM
OF SAUDI ARABIA

المديرية العامة للدفاع المدني — المملكة العربية السعودية

FIRE & LIFE SAFETY SITE INSPECTION REPORT

Report No.	CD-RYD-2026-0311
Project	Riyadh Heights Residential Towers
Inspection Date	11 March 2026
Inspector	Capt. Abdullah Al-Otaibi, Riyadh Region Civil Defense
Scope Consultant of Record	Falcon Fire & Safety Consultants
Overall Result	PASSED WITH MINOR OBSERVATIONS (3 items — see below)
Next Scheduled Inspection	Not yet scheduled at time of this report

Observations:

1. Fire extinguisher signage missing on Level 4 stairwell B — rectify within 14 days.
2. Emergency lighting battery backup tested at 78% of rated duration — replace battery packs on Level 7.
3. Fire door on Level 2 plant room found wedged open during inspection — immediate corrective action required.

Note: As of the date of this document set, no Civil Defense inspection report has been issued for Riyadh Heights Residential Towers in the most recent calendar month. This is the most recent report on file.